SPI–06: Mann–Kendall (TFPW Method)

Trend–Free Pre–Whitened Analysis (p < 0.05)

Northing (m)

Easting (m)

ssification

Wetting Tren

Drying Trend

1.0
0.5
0.0
−0.5
−1.0