INFORMATION DISPLAY DIVISION

4052/54 +15V REGULATOR CIRCUIT #M39801 CORRECTION

The article "4052/54 +15V Regulator Circuit #M39801" in issue 10-9, May 2, 1980 of the Wizard Workshop requires correction. Please note that mod 39801 does not address the 4054. The +15 volt regulator change, is being made only to the 4052.

In addition the 10K and 7.5K resistor part numbers are incorrect. The 10K resistor should be a 308-0054-00 instead of the 321-0289-03, and the 7.5K resistor should be a 308-0206-00 instead of a 321-0277-00. The suffix of the modified board will change from the -00 to a -01.

--Darrell McGiverin 63/503, ext. 3786

4663 FLEX STRIP TERMINATION CIRCUIT BOARD KIT

The Flex Strip Termination circuit board, 670-5859-00, has been upgraded to increase the 4663 Pen Arms' immunity to environmental and operator induced static charges. Use of the new board, 670-5859-01, in instruments with a serial number of B020300 or less is not possible without a new Flex Strip Cable Tray and some associated hardware. The new board and everything needed to install it comes as a field installable kit, P/N 050-1234-01. If this kit has already been installed in a 4663, or if the serial number is greater than B020300, the new 670-5859-01 can be installed by itself as a direct replacement.

--Larry North 63/503, ext. 3926

4633A, 4634: DISSASSEMBLY/REASSEMBLY VIDEO TAPES

A two part videotape set describing the dissassembly and reassembly of the 4633A and 4634 is now available. The part number of the two tape set is 068-9055-00.

--George Kusiowski 63/503, ext. 3928