In-Class Problem 1

Assume registers x18-x20 correlate to variables x, y, and z, and already have x=5 and y=6 loaded into the variables, compile the following C code to RISC-V Assembly and then to machine encoding.

z = x + y

Solution: 0000000 10011 10010 000 10100 0110011

In-Class Problem 2

Assume all values are already included in the appropriate registers, compile the following RISC-V Assembly to machine encoding.

1w x5, 0x20(x18)

Solution: 000000010100 10010 010 00101 0000011

In-Class Problem 3

Assume all values are already included in the appropriate registers, compile the following RISC-V Assembly to machine encoding.

sw x6, 24(x18)

Solution: 0000000 00110 10010 010 11000 0100011

In-Class Problem 4

Assume all values are already included in the appropriate registers, compile the following RISC-V Assembly to machine encoding.

beq x7, x10, 24

Solution: 0 | 000000 01010 00111 000 1100 | 0 1100011

In-Class Problem 5

Assume all values are already included in the appropriate registers, compile the following RISC-V Assembly to machine encoding.

lui x5, 0x7fff0

Solution:

01111111111111110000 00101 0100011