2025 REMAKE OF "Line 39 Label Printer 2013" PROGRAM

Inputs / Known Variables:

- 1. Take constant input from connected measurement hardware = "actual length"
 - a. Laser measuring device provides numerical distance input value.
- 2. Take user input from barcode scanner device = "desired length"
 - a. Currently code39 barcode format = numerical 1234.56 value only. Want to change this to code128 barcode format to potentially accept alphanumerical data of "desired length" + "work order number".
- 3. "off by distance" = "actual length" minus "desired length"
- 4. Fixed variable "green tolerance" = 0.1 (inches)
- 5. Fixed variable "yellow tolerance" = 6 (inches)
- 6. Boolean "allow print"
- 7. "LabelText" = "pre-defined sentence text here"

Function / Calculations Needed:

- 1. Laser input (probably in inches) should be converted to [Feet + Inches]
- 2. Barcode input (in inches) should be converted from [Inches] to [Feet + Inches]
- 3. If "off by distance" is greater than "yellow tolerance" or "desired length" = 0 or undefined, then display red box, set "allow print" to false
- 4. If "off by distance" is less than "yellow tolerance" but greater than "green tolerance" then display yellow box, set "allow print" to false
- 5. If "off by distance is less than "green tolerance" then display green box and set "allow print" to true

Graphic User Interface:

- 1. Always display "desired length"
- 2. Always display "actual length"
- 3. Always display "off by distance"
- 4. Include "X to Clear" button to set "desired length" to zero
- 5. Include "Spacebar to Print" button only if green box is displayed / boolean "allow print" equals yes

Output / Label Printing:

- 1. When green box is displayed and "allow print" = true, press spacebar to print label
 - a. Label should be 1" x 2" from Zebra GK420d USB connected printer
 - b. Label should print "LabelText" sentence, "desired length", and "actual length"
 - c. Example: Wespa USA Length Verification

WO#1234: 23 ft 8.75 in Produced: 23 ft 8.79 in Tolerance: 0.10 in Off by: 0.04 in

Other:

- 1. 2013 version includes button for "LaserOn / LaserOff", not sure how this works or if necessary for regular use, but should be included for testing
- 2. 2013 version includes "Printer Select" options and margins (good luck with that)
- 3. Don't need anything in metric, all printed values should be in either [Inches] or [Feet + Inches]
- 4. Need very simple/idiot-proof primary GUI for daily operator use, but require flexibility in adjusting variables, printer settings, laser settings, in a hard-to-access settings menu or separate detailed config file.

5. Would like to allow for potential in future to: change barcode input from numerical to alphanumerical, change printed label output text/size/spacing, include newly generated barcode on the printed label output (taking data from alphanumerical barcode input), etc.





