Product Name Colour Masterbatch			PF	ต้นฉบับ	
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action
		Start			
1		Raw Material Received	Scales	 Code No., Quantity Weighting ± 1 % / Container 	Return Supplier / Record Incoming Material (WH-F-002)
2		Incoming Inspection	Two Roll Mill Spectrophotometer	 Mixing RM Temperature 150-200 °C Delta E (Color Shade) 0.5-3.00 	Report To Warehouse
3		Material Preparation	Scales	 Weighting ± 0.5 g./ 7.5 kg. Weighting ± 0.01 kg./ 60 kg. 	
4		Mixing	High Speed Mixer	Max 100 kg./ BatchAmp Meter 20-70 Amp.	
5		Extrusion	Twin Screw Extruder	• 25-300 kg./ Hrs. • Temperature 100-300 °C	Rerun Process
6		Cooling & Pelletizing	Water bath & Pelletizer	• Speed 300-1,300 rpm.	Rerun Process
	Ť				

Product Name Colour Masterbatch		PROCESS FLOW CHART				
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action	
7		Final Inspection	Spectrophotometer Microscope Magnifier Karl Fischer Moisture Balance Bulk Density Tester Density Tester Furnance High Performance Liquid Chromatography (HPLC) Filter Test Film Blowing Differential Scanning	 Delta E (Color Shade) Dispersion Homogeneity Contamination Moisture Bulk Density Density Ash Content Additive Content Filter Value Dispersion Index 	Adjust/ Rerun/ Record QC-Report (LA-F-006)	
8		Packing End	Calorimeter (DSC) Scales	Oxidation Induction Time (O.I.T) Weighting/ Identify Tag & Lable	Standard Packaging Operation	