Product Name Black Masterbatch			DD	OCESS FLOW CHART	ต้นฉบับ
		FROCESS FLOW CHARI VIANDD			
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action
1		Start Raw Material Received	Scales	 Code No., Quantity Weighting ± 1 % / Container 	Return Supplier / Record Incoming Material (WH-F-002)
2		Incoming Inspection	Two Roll Mill Spectrophotometer	 Mixing RM Temperature 120-300 °C Delta E (Color Shade) 0.5-3.00 	Report To Warehouse
3		Material Preparation	Scales	 Weighting ± 0.5 g./ 7.5 kg. Weighting ± 0.01 kg./ 60 kg. 	
4		Mixing	High Speed Mixer	Max 100 kg./ BatchAmp Meter 20-70 Amp.	
5		Feeder	Gravimetric Feeder	• Max Load 80%	
6		Extrusion	Buss Kneader	• 500 - 1,200 kg./ Hrs • Temperature 160-300 °C	Rerun Process
7		Cooling & Pelletizing	Underwater Pelletizer	• Speed 500-3600 rpm.	Rerun Process

Product Name Black Masterbatch		DDOCESS EL OW CHADE				
		PROCESS FLOW CHART				
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action	
8		Final Inspection	Spectrophotometer	• Delta E (Color Shade)	Adjust/ Rerun/ Record QC-Report	
			Microscope	Dispersion	(LA-F-006)	
			Magnifier	Homogeneity Contamination		
			Karl Fischer Moisture Balance	Moisture		
			Bulk Density Tester	Bulk Density		
			Density Tester	• Density		
			Furnance	Ash Content		
			High Performance Liquid Chromatography (HPLC)	Additive Content		
			Filter Test	• Filter Value		
			Film Blowing	Dispersion Index		
			Differential Scanning	Oxidation Induction Time (O.I.T)		
			Calorimeter (DSC)			
9		Packing	Scales	Weighting/ Identify Tag & Lable	Standard Packaging Operation	
		End				