Product Name		PROCESS FLOW CHART			Prepared by Checked by Approved by	
Colour Masterbatch					DO NOT COPY	
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action	
		Start				
1		Raw Material Received	Scales	• Code No., Quantity • Weighting ± 1 % / Container	Return Supplier / Record Incoming Material (WH-F-002)	
2		Incoming Inspection	Two Roll Mill Spectrophotometer	• Mixing RM Temperature 150-200 °C • Delta E (Color Shade) 0.5-3.00	Report To Warehouse	
3		Material Preparation	Scales	<ul> <li>Weighting ± 0.5 g./ 7.5 kg.</li> <li>Weighting ± 0.01 kg./ 60 kg.</li> </ul>		
4		Mixing	High Speed Mixer	Max 100 kg./ Batch     Amp Meter 20-40 Amp.		
5		Extrusion	Twin Screw Extruder	• 25-300 kg./ Hrs. • Temperature 100-300 °C	Rerun Process	
6		Cooling & Pelletizing	Water bath & Pelletizer	• Speed 300-1,300 rpm.	Rerun Process	

Product Name  Colour Masterbatch		PROCESS FLOW CHART			Prepared by	Checked by Approved by	
Colour Masterbatch					DO NOT COPY		
Step	Graphical Symbol	Process Name	Equipment	Key Product & Key Control  Characteristics	Corrective Action		
7		Final Inspection	Spectrophotometer	• Delta E (Color Shade)	Adjust/ Rerun/ Record QC-Report		
			Microscope	• Dispersion	(LA-F-006)		
			Magnifier	<ul><li> Homogeneity</li><li> Contamination</li></ul>			
			Karl Fischer  Moisture Balance	•Moisture			
			Bulk Density Tester	• Bulk Density			
			Density Tester	• Density			
			Furnance	• Ash Content			
			High Performance Liquid	Additive Content			
			Chromatography (HPLC)				
			Filter Test	• Filter Value			
			Film Blowing	• Dispersion Index			
			Differential Scanning Calorimeter (DSC)	Oxidation Induction Time (O.I.T)			
8		Packing	Scales	Weighting/ Identify Tag & Lable	Stand	lard Packaging Operation	
		End					