Product Name				nn.	OCESS FLOW CHART	ต้นฉบับ
Additive Filler Masterbatch			ערשאוא			
Step	Graphical Symbol		Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action
			Start			
1			Raw Material Received	Scales	Code No., Quantity	Return Supplier / Record Incoming Material
1					• Weighting ± 1 % / Container	(WH-F-002)
2			Incoming Inspection	Two Roll Mill	• Mixing RM Temperature 120-300 °C	Report To Warehouse
				Spectrophotometer	• Delta E (Color Shade) 0.5-3.00	
3			Material Preparation	Scales	• Weighting \pm 0.5 g./ 7.5 kg.	
					• Weighting \pm 0.01 kg./ 60 kg.	
					• Max 250 kg./ Batch	
4			Mixing	High Speed Mixer	• Amp Meter 0-80 Amp.	
					• Speed 450 - 1750 rpm.	
5			Feeder	Gravimetric Feeder	• Max Load 80%	
6			Mixing	Kneader	• Max 750 rpm.	
7			Extrusion	Single Screw Extruder	• 1,300-2,700 kg./ Hrs.	Rerun Process
					• Temperature 100-260 °C	
8			Cooling & Pelletizing	Underwater Pelletizer	• Speed 1,000-3,500 rpm.	Rerun Process

Product Name			PROCESS FLOW CHART					
Additive Filler Masterbatch			TROCESS FLOW CHART					
Step	Graphical Sym	pol Process Name	Equipment	Key Product & Key Control Characteristics	Corrective Action			
9		Final Inspection	Spectrophotometer	• Delta E (Color Shade)	Adjust/ Rerun/ Record QC-Report			
			Microscope	• Dispersion	(LA-F-006)			
			Magnifier	Homogeneity Contamination				
			Karl Fischer Moisture Balance	•Moisture				
			Bulk Density Tester	Bulk Density				
			Density Tester	• Density				
			Furnance	• Ash Content				
			High Performance Liquid Chromatography (HPLC)	Additive Content				
			Filter Test	• Filter Value				
			Film Blowing	Dispersion Index				
			Differential Scanning Calorimeter (DSC)	Oxidation Induction Time (O.I.T)				
10		Packing	Scales	Weighting/ Identify Tag & Lable	Standard Packaging Operation			
		End						