FILE NUMBER : TLS-TH-23-4217

BOOKING NUMBER :

DRY / ~~REEFER~~

☐ ONHIRE

☒ CONDITION

UNIT NUMBER	SERVICE DATE	CUSTOMER	SURVEYOR
SIKU3033987	14/12/2023	SALEE COLOUR	Ekachai Y.

LOCATION / FACILITY	EQUIP. TYPE	SUB TYPE	REEFER	PHOTOS	RESULTS (ACP, RWK, REJ)
B.C. DEPOT-BKK	CTR	DV'20	-	13	ACEP

RELEASE NUMBER	OTHER USER	CSC DATE	MFR DATE	TARE WEIGHT	GROSS WEIGHT
		ACEP	Mar-11	2200	30480

PROGRAM	JOB	SERVICE TYPE	CUSTOMER REFERENCE
		CONDITION	-

TOP (T)



FRONT (F)



FORK POCKETS (P)



SILLS (S)



RIGHT SIDE (R)



BACK (B)



CROSS MEMBERS (C)



LEFT SIDE (L)



CROSS MEMBERS (C)



FLOOR INTERIOR (I)



DAMAGE CODES

Type of Damage		Affected Component	
Putty or Caulked Filled	A	A	Fork Pocket Strap
Broken/Cracked	B	B	Locking Bar
Compression Line	C	C	Crossmember
Dented	D	D	Door Handle
Replaced	E	E	Forkpocket Wall-Front
Frozen/Seized	F	F	Frame
Gouged/Scratched	G	G	Gusset
Holed	H	H	Hinge/Hinge Pin/Cam/Keeper
Improperly Repaired (Tech)	I	I	Forkpocket Wall-Rear
Delaminated	J	J	Threshold Plate
Loose/Separated	K	K	Door Tieback
Labels/Graffiti	L	L	Side Post
Missing	M	M	Marking/Decal/Data Plate
Burned	N	N	Gasket
Bad Odour	O	O	Door Rod Retainer/Guide
Damaged Coating or Paint	P	P	Panel
Leaking/Caulking Problem	Q	Q	Rain Gutter
Rusted/Corroded	R	R	Roofbow
Stained	S	S	Lashing Strap or Ring or Door Stiffener
Torn/Cut	T	T	Tarpaulin/TIR Cable
Distorted/Bent	U	U	Bracket/T-Clip/Corner Tab
Unpainted/Improper Material Used	V	V	Ventilator
Straighten/Weld/Paint Work	W	W	Floor or Liner
Debris/Dirty	X	X	Fastener or Weld
Outside Castings	Y	Y	Handle or Gasket Retainer
Inserted, Sectioned, Patched	Z	Z	Tunnel

Remarks

1.SURVEYED DUE TO:CARGOWORTHY CRITERIA.

BUREAU VERITAS PARIS 1828 SINGAPORE TLS16 EAST ASIA REGION

SURVEYOR :Ekachai Y.

WAIVER OF LIABILITY: Customer agrees that Bureau Veritas (BV) shall not be liable for any loss, claim, damage, liability or expense incurred in connection with or arising directly or indirectly or in connection with the performance of this survey and that BV shall in no event be liable for special, consequential, or exemplary damages.

Photo: SIKU3033987



Photo: SIKU3033987