ist of blue coax wire probes													
	Shear								FPO7				
b shear probe	SN	C(pF)	Sv	last Cal	State	note		nb Fpo7	SN	R(kohms)	last Cal	state	local temp
17	134	423	43.5		good			17		146		unknown	
	138	821	33.5		good	doubt on piezo ori	ientation			147 1	51 08/23/18	good	25°C
ood shear probes	136	737	42		good	piezo not parrallel	e to the flat part	good FPO7		149 1	43 08/23/18	good	25°C
10	139	838			unknown			13		140 1	18 08/23/18	good	25°C
nknown	122	756	60.5		good			unknown		139 1	08/23/18	good	25°C
3	130	781	70.39		good			3		145 1	90 08/23/18	good	25°C
ad	132	799			unknown			bad		143 1	68 08/23/18	good	25°C
4	131	132	0		broken			1		144 1	08/23/18	good	25°C
	125	806			unknown					125 1	26 08/23/18	good	25°C
	117	-35 mF	0		broken					136 2	10 08/24/18	unknown	20°C
	140	760	0		broken						73 08/24/18	good	20°C
	141	740	45		good						32 08/24/18	good	20°C
	105				good						62 08/24/18	-	20°C
	137				broken						08/25/18		20°C
	144				good						.3 08/25/18		20°C
	142				good							unknown	20°C
	133	833	67.81		good					133 2	10 08/25/18	good	20°C