# EX NO:1.2 DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELING SOFTWARE

## AIM:


To sketch the given drawing with dimensions using fusion 360 tool.

## REQUIREMENTS:

1.Autodesk fusion 360
2.Windows 11
3.16 GB of RAM (integrated graphics recommend 2 GB or more)
4.2.5 Mbps or faster download; 500 Kbps or faster upload

## PROCEDURE:


1.Open a new file and then select the sketch icon.
2.Select the plane for sketching.
3.Use sketching features (line, circle, arc, rectangle, polygon,etc.,) to draw the given sketch.
Lines / Outer Boundaries:
Length: 100 mm, Height: 50 mm]
Circles / Holes: Diameter: 25 mm]
Arcs / Fillets: Radius: 10 mm]





4.Use sketch modifying features (cut, trim, mirror, move, etc.,) to edit the sketch.





5.Use inspect feature to measure the dimensions of the sketch.





6.After finishing the sketch use the finish sketch option to finalize the sketch.





7.After finishing the sketch, switch to drawing mode to plot the sketch in ISO standard.





CREATE DRAWING
Drawing Type
Automatic
Manual
Contents
Destination
Drawing
Create New
Base Document
Standard
ISO
Units
mm
Sheet Size
A3
Width
420mm
Height
297mm
Orientation
Sheet Count
1
OK
Cancel

SKETCHES:


(R21.00)
(R20.00)
(R20.00)
(R21.00)
(Ø30.00)
100
(Ø30.00)
(R21.00)
50
(60.301)
(60.301)
(Ø30.00)
-150
-100
(60.301)
(Ø30.00)
(60.301)
(Ø30.00)
(Ø30.00)
(Ø32.00)
(R32.00)
(R20.00)
(R21.00)
(R21.00)

OUTPUT:




RESULT:

Thus the given sketch is drawn and drafted using fusion 360 tool.