




1 - USB-C PD INPUT




2 - 4-SWITCH BUCK-BOOST (MCU PWM - no switcher IC)




3 - LINEAR POST-REG + CURRENT SENSE



4 - +5 V LDO



5 - MCU



No switcher IC - the MCU drives all four gates. BUCK: leg A chops, Q4 parked on. BOOST: Q1 parked on, leg B chops. Dead-time and bootstrap refresh in firmware.

6 - PROG / UART

