ENGINEERING ASSESSMENT CELL (SYNTHETIC)

Structural Assessment Report

Report No: SR-2025-533

Prepared for: Delta Denim Ltd.

Emergency lighting, exit signage and the fire alarm panel were tested in the presence of factory management.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

Workers interviewed during the visit confirmed that evacuation routes are kept clear during working hours.

The inspection team visited all production floors, the cutting section, the finishing section and the store.

Emergency lighting, exit signage and the fire alarm panel were tested in the presence of factory management.

The electrical distribution boards were found labelled and covered; two loose cable trays were noted for repair.

Date of assessment: 27-03-2025

Next assessment due by: 27-03-2027

Signed: Nasrin Akter (synthetic)