	SSB
Con	ENGINEERS PUT LTD

DEVIATION NOTE

D.C.No :F/09/10

Issue No :01/15.01.10

Rev: 00

Sr No:

1

Date:

26.03.2025

Problem :(Brief Description)

RM - SAE8620H , Heat No. - 8335 , Dia - 80MM

Recived on - 22.03.2025 , required for production , but Inhose inspection not done & spectro report also not received

Time:

Detected by:

Amit Sharma

Deviation Required for :Part/Parameter/Process/Material/Document/Drawing etc

RM - SAE8620H , Required Conditionally Approved due to urgency of production

Time

Demanded by:

Amit Sharma

Deviation Approval given: YES/NO

Justification:

Due to Urgency Deviation provided by our internal XRF report

Steel checked internally By XRF Gon & Joud Okas ker Anit. Customed Kear approved also taken.
Looking into vigency and ok reposts. Steel approved for internal usage. heitered receiving I third party Speets

Date and Time :

26.03.2025

Approved by:

Deven Bhatia

14.01 71.

Anit: update on third bookly Report as