
After tip observation
Base compliance (m/N)
Bending compliance (m/N)
B
A
0.1
0.2
0.3
0.4
After calibrated push
Risk depends on the next action
Predicted failure probability
Before probe
After probe
Repeat tip
New load at 75%
0.0
0.2
0.4
0.6
0.8
1.0