## 2.2.8. Obsolete Extinguishers

- **2.2.8.1.** The following types of extinguishers are considered obsolete and should be removed from service and replaced:
  - a. Soda acid types
  - b. Chemical foam (excluding film-forming agents)
  - c. Vaporizing liquid
  - d. Cartridge-operated water
  - e. Cartridge-operated loaded stream
  - f. Copper or brass shell fire extinguishers (excluding pump tanks) joined by soft solder or rivets
  - g. Extinguishers rated prior to 1955 and marked B-1,C-1 on the nameplate
  - h. Fire extinguishers not listed or labeled
  - i. Halon 1211 and Halon 1301 Agents

## **2.2.9.** Training

- **2.2.9.1.** At least 10 % of the Security personnel, Occupants, Employees and Supervisory personnel of each occupancy shall be trained on basic fire awareness, types, use and operation of fire extinguishers in emergency situation.
- **2.2.9.2.** The training shall be conducted by an authorized agency by the Civil Defence or by the Civil Defence department personnel.

