

Figure 8.8.: Spacing of Spot Type Smoke Detector on Smooth Ceilings




Figure 8.9.: Spacing of Spot Type Smoke Detector on corner of Smooth Ceilings

Did You Know?

Ionization Type Smoke Detectors tend to produce more false alarms and fail in their sensitivity 7 times sooner than a Photoelectric Type Smoke Detector.

