


Product: RTL8812A USB Software Package - Linux Driver

Version: v5.13.6-15-gc40b977e2.20210629

Release History:

Kelease History.	T. 2
v4.2.0_6952.20130315	1. First release.
v4.2.0_7054.20130328	1. Fix LED behavior
v4.2.2_7502.20130517	1. Support 11AC for STA.
v4.2.3_8123.20130705	1. Update PHY parameters to improve throughput.
v4.3.2_11100.20140411	1. To fix p2p issues
	2. To improve throughput
	3. To update FW
v4.3.8_12175.20140912	1. Update PHY parameters to improve throughput.
	2. Update FW
	3. Support PMF
	4. Support WoWLAN
	5. Modify channel plan
	6. Fix MP issue
v4.3.13_14061.20150505	1. Update FW
	2. Update Phy parameters
	3. Support WOWLAN GTK offload
	4. Support Adaptivity
	5. Support 1T2R
	6. Support 8812AU-VN
	7. Fix scan timeout issue
	8. Fix RFE type error
	9. Fix Spur Calibration flow
	10. Fix some 802.11 logo issue.
	11. Fix some crush issues
v4.3.20_16317.20151231	1. Fix STBC issue
	2. Fix NDPA sounding issue
	3. Fix r/w rf register racing issue
	4. Fix kernel panic for BT & timer
	5. Fix memory leak for cmd thread
	6. Fix ADDBA flow
	7. Support Power limit
	8. Support USB mode switch
	9. Support Linux Kernel 4.2
	10. Update FW to v41
1000 1001 50100	11. Update PHY parameters to v55
v4.3.20_16317.20160108	1. Disable CONFIG_WIFI_TEST &
- 1 - 100 I - 00 I 00 00	CONFIG_WOWLAN in Makefile default
v5.1.5_19247.20160830	1. Update FW to v49
	2. Update PHY parameters v57
	3. Support TDLS
	4. Enable GTK offload under WOW
	5. Fix no scan results after resume
	6. Fix NDPA issue under scan
	7. Fix dynamic watchdog don't work
v5.2.9_22809.20170621	1. Update FW to v52.2





	2. Update PHYDM setting
	3. Support PNO
	4. Fix WOW issue
	5. Fix efuse issue
	6. Sync channel plan document
	7. Fix DFS issue
	8. Support NAPI & GRO
	9. Enable Power by rate
	10. Fix MP power tracking issue
	11. Fix potential memory out of range
	12 Support CE-RED. 2G: ETSI v2.1.1 / 5G: ETSI v2.1.0
v5.2.9.1_24461.20171018	1. (Do not use)
(Do not use)	
v5.2.9.2_24491.20171027	1. Remvoe test code
	2. Fix crash for BF function
	3. Fix wrong memory accesse
	4. Fix encrypt broadcast packet fail
	5. Fix crash for TDLS
v5.2.9.3_24903.20171101	1. Fixed WPA2 vulnerability - key reinstallation at-
	tacks(KRACKs)
v5.2.20_25672.20171213	Update PHYDM setting
75.2.25_2507 2.2017 1215	2. Update FW to v52.10
	3. Correct DFS master function
	S. Goirect Dr & muster runetion
	4. Fixed WPA2 vulnerability - key reinstallation at-
	tacks(KRACKs) (update)
v5.2.20.1_27761.20180508	Support WiFi-HAL for Android 8
v5.2.20.2_28373.20180619	
	Update phydm to improve TP stability Lindate Phydm yearing to x22
v5.6.4_33522.20190509	1. Update Phydm version to v33
	2. Update channel plan
	3. Support WiFi-HAL for Android 8
	4. Support Android 9.x
	5. Fix compile error for kernel 5.0.13
	6. Fix LPS issue
v5.6.4.1_33916.20190619	1. Support WPA3-SAE (Personal)
v5.6.4.2_35491.20191025	1. Support up to Android Q
	2. Support up to kernel 5.3
	3. Hotfix P2P NoA buffer potentially overflow
v5.9.3_36908.20200630	1. Support up to kernel 5.6
	2. Update FW to v52.14
	3. Update Phydm version to v42
	4. Fix WoWLAN FW issues
	5. Update channel plan
v5.9.3.2_37279.20201012	1. Support up to kernel 5.8
v5.13.6-15-gc40b977e2.20210629	1. Fix A-MSDU & fragment design flaw issue
	2. support up to kernel 5.11



Description:

Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL8812A USB WLAN series hardware on Linux based platforms.

Software Version:

RTL8812A USB Linux Driver Version: v5.13.6-15-gc40b977e2.20210629

Hardware Supported:

■ RTL8812AU

Platform Supported:

- Linux (kernel 2.6.24 ~ 5.11)
- Android 1.6 ~ 2.3, 4.0 ~11.x

CPU supported:

- x86
- ARM
- MIPS