		· Parts List - Feb 2010
Part	Substitute	Note
	Resistors	3
		See Notes
		See Notes
1M0		
10M		
100k	(for CV rejection)	Trimmers
	Capacitor	S
30pF	or rather: 33pF	cer.
47pF (*)		cer.
150pF		cer.
		MKT or MKS
		MKT or MKS
		MKT or MKS
220n		MKT or MKS
1uF		electrolyte (radial)
47uF		electrolyte (radial)
	Semi's	
LM3900	MC3401	14-p DIL
4558	TL072 (better)	8-p DIL
LM3080		8-p DIL
2N4250	BC560C, 2N5087	pnp
1N??	BZX79C4V7	zener, 4V7, 400mW, 5% tol.
1N914	1N4148 or similar	
	Misc.	
sockets		
DPDT tog	gle switch	
pots 50k Lin + knobs		
RES18 v1	.1 PCB	
	Notes	
	Notes	
,	Notes be replaced with a 6M8	8.
esistor needs to	be replaced with a 6M8	8. 3. See "Res18 V1.1 Mods".
esistor needs to	be replaced with a 6M8 be replaced with a 3M 7pF caps on the board (t	
	1M5 2M2 3M3 6M8 10M 100k 30pF 47pF (*) 150pF 10n (**) 47n 100n 220n 1uF 47uF LM3900 4558 LM3080 2N4250 1N?? 1N914	R330

Additional 330k & R220 resistors needed for wiring the panel.