

Turbofan engine RUL dashboard

Subset: FD001 | Engine: 90 | Model: LightGBM-FD001

Cycles observed

146

Predicted RUL

26.7 cyc

True RUL


28.0 cyc

Warning level


PLAN_MAINTENANCE

Recommended action: Schedule preventive maintenance within the next 10 operating cycles.


sensor_2




sensor_3




sensor_4



sensor_7



sensor_11



sensor_15

