




Hardware Activity 1



Receiver Circuit Layout




Receiver Circuit Manufacturing Top Side




Receiver Circuit Manufacturing Bottom Side


Step 1: Mount Components on Top Side




Step 2: Fix the circuit and complete using connecting wires




Hardware Activity 2



IR Circuit Layout




IR Circuit Manufacturing Top Side




IR Circuit Manufacturing Bottom Side

Step 1: Mount Components on Top Side



Step 2: Fix the circuit and complete us



ing connecting wire

Testing of IR circuit:




Fig. 5.10 Setup for testing of Receiver circuit when One IR pair on black and other on white surface





Fig. 5.11 Setup for testing of Receiver circuit when both IR pair on black surface




Fig. 5.12 Setup for testing of Receiver circuit when both IR pair on black surface


Step 1: Mount Components on Top Side




Step 2: Fix the circuit and complete using connecting wires



Hardware Activity 3



Transmitter Circuit Layout



Transmitter Circuit Manufacturing Top Side



Transmitter Circuit Manufacturing Bottom Side