VEHICLE HISTORY REPORT

Qty

Unit Price

(AS OF 09/10/2023, 15:51)

Chassis No. WP0ZZZ99ZVS370869

Customer CTM07862 SHEIKH FEISAL QASSIM F. T. AL-

Charge To CTM078 SHEIKH FEISAL QASSIM F. T. AL-THANI

Plate No. Reg. Date 10/05/1998 Service Advisor RAQUEL

- Check excessive oil leak underneath and

make sure there is oil in the engine before

CUSTOMER'S REQUEST

check-up. (1,790 Qrs.)

you start it.

Article Description

ADVISOR'S REMARKS

Total Price

Disc(Qrs) Disc(%)

Net

Service Date **08/03/2023**

Job Card # **R440856**

Inv. No. **J442917**

Inv. Date **05/09/2023**

IIV. Date 03/09/2023

Pay Mode CA
Mileage 34370

Article Code

1. Replace engine battery. (1,830 Qrs.)

NOTE: PAYMENT DONE BY SHEIKH
MOHAMMED FEISAL Q.F. AL-THANI WITH ID

NO: 28863404428

	•				D.00(Q.0)	D.00 (70)	1100
9999999	REPLACE ENGINE BATTERY	2.00	358.00	716.00	107.40	15.00	608.60
99999999	PERFORM 111 CHECKLIST POINTS	5.00	358.00	1,790.00	268.50	15.00	1,521.50
99999999	PERFORMED CLEANING FOR FURTHER	2.00	358.00	716.00	107.40	15.00	608.60
99999999	REPLACE ENGINE OIL AND FILTER	2.00	358.00	716.00	107.40	15.00	608.60
99999999	REPLACE OIL FILTER BELOW	4.00	358.00	1,432.00	214.80	15.00	1,217.20
99999999	REPLACE VALVE COVER GASKET BAN	5.00	358.00	1,790.00	268.50	15.00	1,521.50
99999999	REPLACE TURBO BANK 1	6.00	358.00	2,148.00	322.20	15.00	1,825.80
99999999	PERFORMED CLEANING FOR FRONT &	4.50	358.00	1,611.00	241.65	15.00	1,369.35
99999999	REPLACE FRONT AND REAR HOOD ST	2.50	358.00	895.00	134.25	15.00	760.75
99999999	REPLACE UNDERNEATH COVER	0.50	358.00	179.00	26.85	15.00	152.15
99999999	PERFORMED LUBRICATION ON HORN	1.50	358.00	537.00	80.55	15.00	456.45
SUB 05	FUEL	2.00	23.00	46.00			46.00
SUB 29	MATERIAL SUPPLY	1.00	15.00	15.00			15.00
PR9A7915105	BATTERY (O471198)	1.00	1,114.00	1,114.00	167.10	15.00	946.90
PR99310720304	OIL FILTER (O472368)	1.00	153.00	153.00	22.95	15.00	130.05
LPLIQUIMOLY_10W-60	SYNTHOIL RACE TECH 10W-60 5L PU4	2.00	365.00	730.00			730.00
LPBRAKECLEANER_SP	BRAKE CLEANER 500 ML WURTH	1.00	18.00	18.00			18.00
PR90012301130	SEALING RING (O472368)	1.00	16.00	16.00	2.40	15.00	13.60
PR99320720103	OIL FILTER (O472368)	1.00	108.00	108.00	16.20	15.00	91.80
PR90012311830	SEALING RING (O472368)	1.00	6.00	6.00	0.90	15.00	5.10
PR90007534501	HEXAGON-HEAD BOLT (O472368)	12.00	7.00	84.00			84.00
PR99351133100	GAS-FILLED STRUT (O472368)	2.00	140.00	280.00	42.00	15.00	238.00
PR91151233101	GAS FILLED STRUT (O472368)	2.00	124.00	248.00	37.20	15.00	210.80
PR94410719711	SEALING PLUG (O473781)	1.00	93.00	93.00	13.95	15.00	79.05
PR99970126940	O-RING (O473781)	1.00	44.00	44.00	6.60	15.00	37.40
PR99970731640	O-RING (O473781)	2.00	22.00	44.00	6.60	15.00	37.40
PR99970730940	O-RING (O473781)	1.00	12.00	12.00	1.80	15.00	10.20
PR99320736350	BELLOWS (O473781)	1.00	113.00	113.00	16.95	15.00	96.05
PR99310513502	GASKET (0473781)	1.00	131.00	131.00	19.65	15.00	111.35
PR99312301351	TURBOCHARGER (O473781)	1.00	21,240.00	21,240.00	3,186.00	15.00	18,054.00
PR96511120500	SEALING RING (O473781)	1.00	283.00	283.00	42.45	15.00	240.55
PR99970159840	O-RING (O473781)	1.00	22.00	22.00	3.30	15.00	18.70
PR96450412701	COVER (O473781)	1.00	1,702.00	1,702.00	255.30	15.00	1,446.70
PR90007607700	HEXAGON NUT (O474015)	8.00	7.00	56.00	8.40	15.00	47.60
PR92811142700	PIPE CLAMP (O474015)	2.00	239.00	478.00	71.70	15.00	406.30
PR90007425202	SCREW (0474015)	4.00	33.00	132.00	19.80	15.00	112.20
PR99902512501	WASHER (O474015)	8.00	10.00	80.00	12.00	15.00	68.00
PR94411120501	SEALING RING (O474015)	1.00	120.00	120.00	18.00	15.00	102.00
SORTKEY : SERVICE DA			WMSHISTORY	— Ра	age :	1	

 SORTKEY: SERVICE DATE
 WMSHISTORY
 — Page: 1

 Date: 09/10/2023
 — Time: 15:51:51

VEHICLE HISTORY REPORT

(AS OF 09/10/2023, 15:51)

Chassis No. WP0ZZZ99ZVS370869

PR92811124607 SEAL RING (O474015)				2.00	164.00	328.00	49.20	15.00	278.80
LPBRAKECLEANER_SP BRAKE CLEANER 500 ML WURTH				3.00	18.00	54.00			54.00
	Labour	12,530.00	Sublet	61.00	Gross Amount				40,280.00
	Parts	27,689.00	Consumables	0.00	Less: Promo/Segment Disc		;	5,899.95	
						Additional	Disc		0.00
					Net	Amount			34.380.05

Customer CTM07862 SHEIKH FEISAL QASSIM F. T. AL-Charge To **CTM078** SHEIKH FEISAL QASSIM F. T. AL-THANI

Plate No. Reg. Date 10/05/1998 Service Advisor RAQUEL

CUSTOMER'S REQUEST

ADVISOR'S REMARKS

Service Date 05/09/2023 1. Check engine overheating.

> 2. Check excessive smoke coming from the R443124

exhaust.

3. Check emmission very high.

REFER TO R440856

Inv. Date 19/09/2023

J443116

Pay Mode CA

Job Card #

Inv. No.

Mileage 34370

Article Code	Article I	Description		4.00 92.00	Unit Price 23.00	Total Price	Disc(Qrs) Disc(%)	Net 92.00
SUB 05	FUEL					92.00		
_	Labour	0.00	Sublet		Gross Amount			92.00
	Parts	0.00	Consumables	0.00		Less: Promo/S	Segment Disc	0.00
						Addition	al Disc	0.00
						Net Amount		92.00

SHEIKH FEISAL QASSIM F. T. AL-Customer CTM07862 Charge To **CTM078** SHEIKH FEISAL QASSIM F. T. AL-THANI

Plate No. Reg. Date 10/05/1998 Service Advisor RAQUEL

CUSTOMER'S REQUEST ADVISOR'S REMARKS

Service Date 19/09/2023

R443285

1. Check emmission very high.

Job Card # Inv. No.

Inv. Date 11

Pay Mode

Mileage 34370

Article Code	Article Description			Qty	Unit Price	Total Price	Disc(Qrs) Disc(%)	Net
PR99917019590 SPARK PLUG (O475008)			6008)	6.00	85.00	510.00		510.00
	Labour	0.00	Sublet	0.00	Gross Amount			510.00
	Parts	510.00	Consumables	0.00		Less: Promo/S	Segment Disc	0.00
						Addition	nal Disc	0.00
						Net Amount		510.00

^{***}Nothing Follows***

SORTKEY: SERVICE DATE **WMSHISTORY** — Page : Date: 09/10/2023 — Time: 15:51:51