

GNUSim8085 - 8085 Microprocessor Simulator

FileResetAssemblerDebugHelp

Registers

A05

BC0200

DE0000

HL0000

PSW0000

PC420C

SPFFFF

Int-Reg00

Flag

S0

Z0

AC0

P1

C0

Decimal - Hex Conversion

Decimal

Hex

0

0

To Hex

To Dec

I/O Ports

0

-

+

00

Update Port Value

Memory

0

-

+

00

Update Memory

Load me at:

1LDA 8050

2MOV B,A

3LDA 8051

4ADD B

5STA 8052

6HLT

DataStackKeyPadMemoryI/O Ports

Start8050OK

Address (Hex)	Address	Data
1F72	8050	2
1F73	8051	3
1F74	8052	5
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0
1F7E	8062	0
1F7F	8063	0

Line No	Assembler Message
0	Program assembled successfully

35°C
T-storms

Search

ENG
US

1:27 PM
7/10/2026

FileResetAssemblerDebugHelp

Registers

A05

BC0F00

DE0000

HL0000

PSW0000

PC420C

SPFFFF

Int-Reg00

Flag

S0

Z0

AC0

P1

C0

Decimal - Hex Conversion

Decimal

Hex

0

0

To Hex

To Dec

I/O Ports

0

-

+

00

Update Port Value

Memory

0

-

+

00

Update Memory

Load me at:

1LDA 8050

2MOV B,A

3LDA 8051

4SUB B

5STA 8052

6HLT

DataStackKeyPadMemoryI/O Ports

Start8050OK

Address (Hex)	Address	Data
1F72	8050	15
1F73	8051	20
1F74	8052	5
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0
1F7E	8062	0
1F7F	8063	0

Line No	Assembler Message
0	Program assembled successfully

Simulator: Idle

35°C
T-storms

Search

ENG
US

1:58 PM
7/10/2026



FileResetAssemblerDebugHelp

Registers

A0A

BC3205

DE0A00

HL0000

PSW0000

PC4219

SPFFFF

Int-Reg00

Flag

S1

Z0

AC0

P0

C1

Load me at:

1LDA 8050

2MOV B,A

3LDA 8051

4MOV C,A

5MVI D,00H

6MOV A,B

7LOOP: CMP C

8JNC STOP

9SUB C

10INR D

11JMP LOOP

12STOP: MOV A,D

13STA 8052

14HLT

Decimal - Hex Conversion

Decimal

Hex

00

To HexTo Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

GNUSim8085 - 8085 Microprocessor Simulator

DataStackKeyPadMemoryI/O Ports

Start8050OK

Address (Hex)	Address	Data
1F72	8050	50
1F73	8051	5
1F74	8052	10
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0
1F7E	8062	0
1F7F	8063	0

Line No	Assembler Message
0	Program assembled successfully

Simulator: Idle

35°C
T-storms

Search

ENG
US

2:07 PM
7/10/2026



FileResetAssemblerDebugHelp

Registers

A

2C

00

00

BC

22

0C

00

DE

2C

2C

00

PSW

00

00

00

PC

42

11

00

SP

FF

FF

00

Int-Reg

00

Flag

S

0

Z

0

AC

0

P

0

C

0

Decimal - Hex Conversion

Decimal

Hex

0

0

To Hex

To Dec

I/O Ports

0

-

+

00

Update Port Value

Memory

0

-

+

00

Update Memory

GNUSim8085 - 8085 Microprocessor Simulator

Load me at:

1

LHLD

8050

2

XCHG

3

LHLD

8052

4

MOV

A,

L

5

SUB

E

6

MOV

L,

A

7

MOV

A,

H

8

SBB

D

9

MOV

H,

A

10

SHLD

8054

11

HLT

Data

Stack

Keypad

Memory

I/O Ports

Start

8050

OK

Address (Hex)

Address

Data

1F72

8050

12

1F73

8051

34

1F74

8052

56

1F75

8053

78

1F76

8054

44

1F77

8055

44

1F78

8056

0

1F79

8057

0

1F7A

8058

0

1F7B

8059

0

1F7C

8060

0

1F7D

8061

0

1F7E

8062

0

1F7F

8063

0

Line No

Assembler Message

0

Program assembled successfully

Simulator: Idle

36°C

Partly sunny

Search

ENG

US

2:26 PM

7/10/2026





FileResetAssemblerDebugHelp

Registers

A19

BC2300

DE000E

HL0004

PSW0000

PC4210

SPFFFF

Int-Reg00

Flag

S1

Z0

AC0

P1

C1

Decimal - Hex Conversion

Decimal

Hex

00

To Hex

To Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

Load me at:

1LDA 8050

2MOV B,A

3LDA 8051

4CMP B

5JC STORE

6MOV A,B

7

8STORE: STA 8052

9HLT

DataStackKeyPadMemoryI/O Ports

Start8050OK

Address (Hex)	Address	Data
1F72	8050	35
1F73	8051	25
1F74	8052	25
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0
1F7E	8062	0
1F7F	8063	0

Line No	Assembler Message
0	Program assembled successfully

Simulator: Idle

35°C Sunny

Search

10:57 AM7/13/2026

FileResetAssemblerDebugHelp

Registers

A19

BC1900

DE000E

HL0004

PSW0000

PC420F

SPFFFF

Int-Reg00

Flag

S1

Z0

AC0

P1

C1

Decimal - Hex Conversion

Decimal

Hex

00

To Hex

To Dec

I/O Ports

0-+00

Update Port Value

Memory

0-+00

Update Memory

Load me at:

1LDA 8050

2MOV B,A

3LDA 8051

4STA 8050

5MOV A,B

6STA 8051

7HLT

DataStackKeyPadMemoryI/O Ports

Start8050OK

Address (Hex)	Address	Data
1F72	8050	35
1F73	8051	25
1F74	8052	0
1F75	8053	0
1F76	8054	0
1F77	8055	0
1F78	8056	0
1F79	8057	0
1F7A	8058	0
1F7B	8059	0
1F7C	8060	0
1F7D	8061	0
1F7E	8062	0
1F7F	8063	0

Line No	Assembler Message
0	Program assembled successfully

Simulator: Idle

35°C
Sunny

Search

ENG
US

11:08 AM
7/13/2026





