

KOTHARI PETROCHEMICALS LIMITED PIB PLANT, MANALI, CHENNAI-600068.

Work Permit No:

50

EMERGENCY CONTACT NUMBERS: 200, 218,230

 \checkmark

Cotton hand gloves

Full body harness

Electrical hand gloves

Chemical protective

Heat resistant hand

clothing

gloves

ESD Shoe

OHC /MEDICAL CENTRE/AMBULANCE CALL:208,209

JOBID

Ear plugs/Muff

Fluorescent jacket

Helmet with chin strip

cvbcv2

Hot WorkPermit

1	Validity From			17/10/2020 17:37:33	Validity			17/10/2020 18:00:00		
2 3		T ISSUER:		Karthiban M	PERMIT RECEIVER:			ewrwer		
3	DESCF WORK	RIPTION O	F	dfesdf						
4	LOCATION OF THE WORK			dfgvfdg	P_1002B-C4 EFFULENT TRANSFER PUMP					
5	NAME CONTR CODE	RACTOR /		safsdfsdf						
6		ing points ture of job		d be checked before issuir	ng the V	Vork Per	mit and ma	arked as () or (x) with reference to		
	Done	Not Required	Chec	kList		Done	Not Required	CheckList		
1	1		Lock	out the Electrical Equipment	2		✓	Tag and lock the Electrical Equipment		
3		1	Depre	essurize the equipment	4		1	Purge the equipment		
5		1	Verify	water jetting equipment cted	6		1	Valve isolation		
7		1	Cove	r all sewers/ drain	8		1	Verify mobile equipment inspected		
9		1	Doub	le valve isolation	10		1	Check area/ equipment clean of oil, combustibles		
			Work	Specific CheckList				Work Specific CheckList		
1	✓		(HOT area (check	WORK) Equipment / Work Checked: Surrounding area sed	2		√	Considered hazard from other routine / non routine operations and concerned persons alerted		
3		✓		unding area checked / cleand oil/rags/grass etc.	ed 4		1	Firewater system checked for readiness		
5		✓	_	ater hose/ DCP fire guisher provided	6		✓	Equipment properly drained and depressurized		
7		✓	Equip	ment properly purged	8		✓	Equipment electrically isolated & tagged (As per Part '8')		
9		✓		ment blinded / disconnected d / isolated / wedged/opened			✓	Adequate ventilation provided		
11		✓	Gas 7 '11')	ests (mention values in part	12		1	Standby attendant provided (Contractor / Process / Maintenance.)		
13		✓		r: manholes: etc. and hot ces nearby covered	14		✓	Precaution against public traffic taken		
15		✓	Checl equip	ked flame arrestor on mobile ment	16		1	Welding machine checked: earthed: fitted with proper flame traps & located at safe location		
17		1	Shield	d / booth against sparks ded	18		√	Return / Earthing to be connected closest & only to the equipment being welded.		
19		✓	outsic	en / Acetylene cylinder kept de Confined space (tank / el / Column etc.)	20		√	ELCB provided on portable electrical equipment		
21		✓		back arrestor provided on ga g set / Cylinders	as 22		✓	Proper lighting provided		
7	Specia	l Protectio	n / PP	E						

Dust Mask

Face shield

Gum Boot

	<u> </u>			I			Ta.			. 1			
	Nitrile hand gloves			Respiratory Protection (Circle type)			□ Shoes with conductive:				Solvent Mask		
	Splash goggles			Wristba	nd/Wristlets		Others ((specify)					
<u> Other</u>	rs:erwerwerwe												
7.1	Part 'A': GAS TES	ST RE	SULT	SUGGI	ESTED RETEST	ING F	REQUE	NCY IS E	VERY		HR	S / Online	
	Gas meter readin	g		1			·						
NO.	Values	%O2		%LEL	TOXIC GAS (PPM)	OTH GAS		NAME	SI	IGN	I	Date Time	
	ACCEPTABLE VALUES	19.5 - 22.5%		ZERO	Less than TLV	Less	than TLV	/					
				1									
	Permit Approvals	S:		Name	- M	Signature		Rer	Remarks		Date Time		
	Permit Issuer	(CP:tt I		Karthiban M Gokulavasan E									
	Permit Approver(Charge)	(Snitt i	n										
	Stand by Person			Mariyap									
	Safety officer			Karthiba									
	Process Manager				appan R								
	Electrical In char	_		Vinothra									
	Mechanical In ch				Kumar V								
	Instrumental In c	narge	`	vasantr	anathan L								
	GM Operations *	:!:											
	Engineer/Tech.of dept/Receiver.	recip	lent	ewrwer									
)	Permit Closure:C that the subject v been completed/	vork h	as	Name		Sign	ature	Rer	narks		Date Time	e	
	and area cleaned	l <u> </u>											
	by Receiver												
	Job taken over & Permit closed by issuer												
	Safety Officer Ap	prova	<u> </u>										
0.1	Contractor Rati			0									
	arks (if Red and Ye			Green									
Kem	arks (ii Red and Te	ellow 1a	ung).										
11	RENEWAL OF W					1	. 1		1	- 1			
Day/	ay/ Date/Time 1. LEL Lev (ZERO)			el Name& sign of shift In charge		sign of sign		ame& ign of	Name& sign of		Name& sign of	Name& sign of	
		2. % (22.5 %	02(19. %)	.5 -		safet char		tand by	Manage Process		GM	Receive	
First Day 1. Date: 2.													
· ·	nd Day	1.											
		2.											
									1				
•	I Dav												
hird	l Day	1.											
 Third Date: Fourt		1.											

Fifth Day Date:....

1. 2.

Sixth Day Date:	1.			
	2.			
Seventh Day Date:	1.			
Date:	2.			

** Renewal of Hot work permit is allowed only if the work is carried out in Workshop

	GENERAL INSTRUCTIONS:
1.	The work permit shall be filled up carefully and accurately in clear handwriting ensuring that complete information is provided in all sections / sub sections. Sketches should be provided wherever possible to avoid mis-communication
2.	The permit shall be in duplicate. Original copy is receiver's (display) copy; 2nd copy for issuer department. Display copy must be available at work site all the time. On expiry, this permit must be returned to issuer.
3.	Validity of Permit: 7 days from issue date. Renewal: The permit shall be renewed every shift by issuer, receiver in both copies.
4.	Responsibilities: Issuer is responsible for preparation of equipment /work site condition. Receiver is responsible for compliance conditions mentioned in work permit
5.	Contractor Supervisor should be available at work site, ensure use of PPEs and compliance of work permit conditions throughout the activity.
6.	In case of any abnormality noticed, release of liquid / gas release while carrying out the job, stop work immediately, inform concerned KPL / Operations personnel and seek advice
7.	In case of an Emergency or FIRE ALARM (Fire Siren), all jobs must be stopped, Fire Hydrant tapings should be shut off. Maintenance / Contractor personnel must leave work site and proceed to designated Assembly points.
8.	This Permit must ensure that all precautions mentioned herein are complied with and understood by the person while carrying out the job.
9.	Permit should be made separately based on related activity and specific location. Identify alternate escape route and keep access clear for emergency response.
10.	All engineering safety aspects should be ensured by executing agency. Lifting tools and tackles should have proper certification of testing & should be checked prior to use

PERMIT SPECIFIC INSTRCTIONS - Hot Work

Hot work: An activity that can produce a spark or flame or other source of ignition having sufficient energy to cause ignition, where the potential for flammable vapours, gase, or dust exists. Hot work includes welding, gas cutting, burning, grinding, shot blasting, drilling and excavation use of power tools.