User guide Advanced Data Analysis Tools


V1.2

Update: 2025/07/10 Author: SC Hsiao

Data Process
Exclude Duplicate Setup Spec Exclude Outlier
Process Capability
Normal distribution Best Fit
Panart Canarata
Report Generate
Please paste JSL code:
Generate in report format


Open Data

Step 2. Click Run Script




Data Process - Exclude Duplicate

Step 2. Click Run Script




Data Process - Setup Spec

Step 2. Click Run Script




Data Process - Exclude Outlier




Process Cability - Normal distribution


Step 2. Click Run Script




Process Cability - Best Fit distribution




Report Generate







Step3-4. Click **OK**



© Concat of segundo_blun...alReport_20250709.html

Automatically generate Process Cability(Best Fit distribution)

Concat of segundo_blun...alReport_20250709.png
 Concat of segundo_blun...alReport_20250709.pdf

A - Exclude Duplicate

Step 2. Click Run Script

