
User guide Data Analysis Tools

V1.2

Update: 2025/07/09 Author: SC Hsiao


Open Data

Step 2. Click Run Script




Data Process - Exclude Duplicate

Step 2. Click Run Script




Data Process - Setup Spec

Step 2. Click Run Script




Data Process - Exclude Outlier




Process Cability - Normal distribution


Step 2. Click Run Script




Process Cability - Best Fit distribution



Report Generate







Automatically generate Process Cability(Best Fit distribution)

A - Exclude Duplicate

Step 2. Click Run Script

