You can’t skip a level

The smart manufacturing maturity model



LEVEL

1 Initial

Paper travellers and whiteboards.

LEVEL

2 Managed

A few digital tools that each solve one problem.

LEVEL

3 Defined

Integrated systems and automatic data capture.

LEVEL

4 Quantified

A connected business. Maintenance scheduled by data.

LEVEL

5 Optimised

AI-enabled. Very few factories are really here.

Most factories are between 1 and 3

The jump from 2 to 3 is usually the biggest step in value.

AI starts paying back at Level 3.

That's where it finally has trustworthy data to learn from.

NEXT

Read the full article

Link in bio · shopfloormatters.com