

Winning and Growing Tier 1 Roofer Business
Product
Henry Provided Leads
Competitive Pricing
Relationship
Service
Quality
Full Systems
Availability/Lead Times
Silicone
Logistics
Customer Service
Warranty
Silicone
Acrylic
SPF
Urethane
Silicone
SPF
Tracking Info
Ease of placing an order
Proactive
Friendly to Customers
Warranty matters to building owners
Seam Treatments
Clumps
Seam Treatments
Accessories
Acrylic
Primers/Bleed Blockers
Acrylic
Emulsion
Deliver material on time
Deliver material undamaged
Requiring SKU #s when customer already named the product
Requiring our form when customer already gave all the info
Tracking Info Provided without Asking
Get product to customers so Henry never delays a job
Attitude
Show up their Henry rep via email
Easy warranty processing
Warranty claim process
Flexibility on Henry standard spec

Detractors – “Leaky Bucket”

Possible Detractor	Henry’s Position	NOTES	FIX
Service		Consistent feedback: we’re difficult to deal with	Hold people accountable
• Cumbersome order taking		Customer asks for “24 drums of white silicone”; CS replies with a 200-SKU Excel file asking for the SAP #	Take orders as written; call the customer if unclear. Hold customers to the Order Acknowledgement. Rely less on sales.
• Slow responses		Inquiries (not orders) can take 24+ hours	4-hour response on all emails
• Inflexible on requests (substitutions, alternate plants, expediting)		If Kingman is out of PG988 but Carson has it, CS should get it to the customer fast, especially when a date is requested	Give CS inventory visibility across all plants. Train staff on approved substitutions.
• Slow Warranty Sign-Offs		Some manufacturers sign off without walking the site	Sign off ASAP; walk the roof within the roofer’s 2-year leak window. Batch sign-offs 3+ hours from base to cut travel.
• Slow Warranty Claim Responses		Building owners expect action within 24 hours	Email acknowledgement in 4 hours; site visit in 4 days
Logistics		Feedback: we’re unreliable	Push roofers to distribution (solve pricing). Trackers on pallets. CS updates customers daily, unprompted.
• No notifications/tracking		Material arrives days or weeks early with no one to accept it. Mainly hurts the roofer, but makes Henry/Carlisle look unprofessional too.	
• Shipping at Henry’s convenience, not the customer’s		With no requested date, we set one on the OA, then ship early without notice. Sometimes no one is there to receive it.	Keep the customer informed. Ask before shipping early. Provide tracking and daily updates.

Detractors – “Leaky Bucket”

Possible Detractor	Henry’s Position	NOTES	FIX
Material and Systems			
• Material not ready to ship within 48 hours		Long-standing. Job-start items (primer, bleed blockers, mastics) must be in stock; trucks of 988 don’t help without primer.	Raise accessory minimums. Ramp production ahead of known storms and weather.
• Inflexible on scope/specs		Many manufacturers require “less.” We will flex.	
• Failures		Failures kill future work with building owners	Keep innovating
• Missing system components		No sprayable seam sealer for silicone systems; no cementitious coating for Arizona	
National Accounts			
• Leads that don’t close		National account leads close well; Facebook/website leads often don’t	None needed
• Not enough leads		We’re a strong lead provider, but Sherwin-Williams supplies more through paint contracts	Collaborate with other divisions. Free the national accounts team from firefighting and CS work to generate leads.
• Moisture Survey System		Some manufacturers offer contractors discounted thermal surveys through national agreements	John T Hull