

Section Test - MODULE & PARTS SUMMARY

PARTS SUMMARY

Total Parts (needed 10)

Part	Type	Needed	In Stock	Remaining to Order
Magnets	mechanical part	8	2	6
bottom plate	cnc metal	2	0	2

Mechanical Part: needed 8, in stock 2, to order 6

Cnc Metal: needed 2, in stock 0, to order 2

GRAND TOTAL NEEDED: 10

GRAND TOTAL IN STOCK: 2

GRAND TOTAL TO ORDER: 8

PARTS TO ORDER

Parts to Order (8)

Part	Type	Needed	In Stock	Remaining to Order
Magnets	mechanical part	8	2	6
bottom plate	cnc metal	2	0	2

TOTAL TO ORDER: 8

MODULES

Modules

Module Type	Count
MO:HEAT	1
tip holder 1000	1

TOTAL MODULES: 2

MODULE BREAKDOWN

Parts by Module Type - MO:HEAT (x1 modules)

Part	Type	Per Module	Total
Magnets	mechanical part	4	4
bottom plate	cnc metal	1	1

MODULE BREAKDOWN

Parts by Module Type - tip holder 1000 (x1 modules)

Part	Type	Per Module	Total
Magnets	mechanical part	4	4
bottom plate	cnc metal	1	1