

- 2 tap thru 1/4 NPT, start tap from the other side
- 2 tap thru 1/4-20
- 12 tap thru M5
- 6 tap thru M4
- 20 tap thru 4-40
- 29 blindtap 4-40