

Disaster Risk Priority Report (NCR)

Total Locations Analyzed: 935

Critical High Risk Areas: 383

Location	DPI	Risk Class	Recommendation
Barangay 12	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 18	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Santa Cruz	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 48	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 49	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 50	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 133	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 41	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 60	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 62	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 64	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 58	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 154	8.80	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 53	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 52	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 42	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 134	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 137	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 143	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 198	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 138	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 183	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 155	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 157	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 156	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 164	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 13	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 598	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 200	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 14	8.80	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 37	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 88	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 129	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 46	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 36	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 152	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 114	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 43	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 117	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 81	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 79	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 116	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 99	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 97	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 98	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 29	8.80	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 145	8.80	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 310	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 11	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 142	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 77	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 101	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 93	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 125	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 54	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 28	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 16	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Capri	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 82	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 132	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 122	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 112	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 80	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 85	8.05	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 83	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 43	8.05	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 109	7.75	High	Chronic Danger Zone: Immediate structural intervention required.
Santo Tomas	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 27	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 51	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
San Perfecto	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 24	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 20	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 16	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 8	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 56	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 63	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 54	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 139	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 162	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 160	7.60	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Tatalon	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 138	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 135	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 136	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 65	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 140	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 55	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 153	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 151	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 149	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 135	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 34	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 33	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 131	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 153	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 146	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 66	7.60	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 57	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 76	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 75	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 126	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 128	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Palatiw	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 78	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 93	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Sagad	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 32	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 74	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 30	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 31	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 90	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 89	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 51	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 196	7.60	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 187	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 199	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 158	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Katipunan	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 166	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 165	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 163	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Kasilawan	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 108	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 111	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 145	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 130	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Tonsuya	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 202-A	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 300	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Pio del Pilar	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 184	7.60	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Rizal	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 160	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 158	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 178	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 157	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 139	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 204	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 141	7.60	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 102	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 46	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 95	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 159	7.30	Moderate	Review evacuation routes and drainage capacity.
Barangay 120	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 103	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 117	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 126	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 69	7.30	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 31	7.30	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 66	6.85	Moderate	Review evacuation routes and drainage capacity.
Barangay 86	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 32	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 45	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 89	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 92	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 91	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 107	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Bagumbayan South	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 209	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 210	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Ilaya	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 206	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 173	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Hulo	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
NBBS Dagat-dagatan	6.85	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 180	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Longos	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 129	6.85	Moderate	Review evacuation routes and drainage capacity.
Barangay 125	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 8	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 4	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 628	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
San Vicente	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Santa Ana	6.85	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 130	6.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 32	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 12	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 5	6.55	Low	Monitor regularly; Low priority.
Barangay 181	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 37	6.55	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 132	6.55	Low	Monitor regularly; Low priority.
Barangay 92	6.55	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 115	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 26	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 36	6.55	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 119	6.55	Moderate	Review evacuation routes and drainage capacity.
Barangay 10	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Claro	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Talayan	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Masambong	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Doña Imelda	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 161	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
San Isidro	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Palanan	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 203	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 205	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Zapote	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Pulang Lupa Uno	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 156	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 202	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 154	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 177	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 176	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 175	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 174	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 172	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 171	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 170	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Wawang Pulo	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Tagalag	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Daang Bakal	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Bagong Silang	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Pasolo	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Isla	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
San Rafael Village	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Tinajeros	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Panghulo	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 9	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 15	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 6	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 201	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 197	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
La Huerta	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 159	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 167	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 168	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 169	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 140	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Maysilo	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Muzon	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Niugan	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 166	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Calumpang	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Concepcion Uno	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Mabini-J. Rizal	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Old Zañiga	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Dampalit	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Catmon	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 162	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 165	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 33	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 151	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 147	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 148	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Tumana	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Tañong	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Santo Niño	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 144	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
San Roque	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Nangka	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Malanday	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Jesus de la Peña	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 151	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 37	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 34	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Ibaba	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 134	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 136	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 137	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 49	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 124	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 114	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 132	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 133	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 43	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 100	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Maybunga	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Rosario	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Manggahan	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 35	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 28	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 146	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 144	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 61	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 59	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 57	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 147	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 155	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 152	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 150	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 148	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Santa Lucia	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
San Miguel	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 19	6.40	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Salapan	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Progreso	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Batis	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 3	6.40	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 72	6.25	Moderate	Review evacuation routes and drainage capacity.
Barangay 85	6.25	Low	Monitor regularly; Low priority.
Rincon	6.10	High	Chronic Danger Zone: Immediate structural intervention required.
Coloong	6.10	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 68	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 71	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 87	6.10	Moderate	Review evacuation routes and drainage capacity.
Poblacion	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 67	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 82	6.10	Moderate	Review evacuation routes and drainage capacity.
Alicia	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 163	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 26	6.10	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Barangay 56	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 59	6.10	High	Chronic Danger Zone: Immediate structural intervention required.
Maharlika Village	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 164	6.10	Moderate	Review evacuation routes and drainage capacity.
Bayan-bayanhan	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 109	6.10	Moderate	Review evacuation routes and drainage capacity.
Botocan	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 149	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 116	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 119	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 118	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 5	6.10	Moderate	Review evacuation routes and drainage capacity.
Barangay 25	5.80	Moderate	Review evacuation routes and drainage capacity.
Barangay 73	5.80	Low	Monitor regularly; Low priority.
Barangay 127	5.80	Moderate	Review evacuation routes and drainage capacity.
Barangay 111	5.80	Low	Monitor regularly; Low priority.
Barangay 17	5.80	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 102	5.80	Low	Monitor regularly; Low priority.
Barangay 52	5.80	Moderate	Review evacuation routes and drainage capacity.
Barangay 97	5.80	Low	Monitor regularly; Low priority.
Barangay 81	5.80	Low	Monitor regularly; Low priority.
Barangay 52	5.80	Low	Monitor regularly; Low priority.
Barangay 195	5.80	Low	Monitor regularly; Low priority.
Barangay 86	5.80	Low	Monitor regularly; Low priority.
Rivera	5.80	High	Chronic Danger Zone: Immediate structural intervention required.
Malanday	5.80	High	Chronic Danger Zone: Immediate structural intervention required.
Mariblo	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
New Zañiga	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Manuyo Uno	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Pamplona Uno	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Viente Reales	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Pulang Lupa Dos	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 115	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Palasan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Bangculasi	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Pulo	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
San Roque	5.65	Moderate	Review evacuation routes and drainage capacity.
Barangay 141	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangka	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 7	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Plainview	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 142	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
San Miguel	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 8	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Poblacion	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
NBBS Kaunlaran	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Calzada	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Martires del 96	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Palingon	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Santa Ana	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Ususan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 3	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Malinao	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Dela Paz	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Pinagbuhanan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Tuktukan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Aguho	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Wawa	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Damayang Lagi	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 21	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 17	5.65	Moderate	Review evacuation routes and drainage capacity.
Vitalez	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Moonwalk	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 11	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 106	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Pamplona Dos	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 94	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 96	5.65	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Bangkal	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
La Paz	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
San Antonio	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 101	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Saint Peter	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Santolan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
San Agustin	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Sienna	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Valenzuela	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Bambang	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Tejeros	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Bagong Katipunan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
West Kamias	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 55	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Caniogan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 128	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 100	5.65	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Barangay 161	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Santo Niño	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 72	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 127	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Santolan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
San Dionisio	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 63	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 126	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 44	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 41	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 39	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 47	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 49	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 35	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 38	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Tanza 2	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Bisig	5.65	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Concepcion	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Olympia	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 207	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 104	5.65	Moderate	Review evacuation routes and drainage capacity.
Barangay 58	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Tanza 1	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 186	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 185	5.65	Moderate	Review evacuation routes and drainage capacity.
Kabayanan	5.65	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 14	5.65	Moderate	Review evacuation routes and drainage capacity.
Barangay 15	5.50	Low	Monitor regularly; Low priority.
Barangay 129	5.50	Moderate	Review evacuation routes and drainage capacity.
Pariancillo Villa	5.35	Moderate	Review evacuation routes and drainage capacity.
Pag-aso	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 120	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 131	5.35	Moderate	Review evacuation routes and drainage capacity.
Balangkas	5.35	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Villa Maria Clara	5.35	Moderate	Review evacuation routes and drainage capacity.
Carmona	5.35	Moderate	Review evacuation routes and drainage capacity.
Arkong Bato	5.35	Moderate	Review evacuation routes and drainage capacity.
Maysan	5.35	Moderate	Review evacuation routes and drainage capacity.
Namayan	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 78	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 45	5.35	Low	Monitor regularly; Low priority.
Barangay 7	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 53	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 65	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 2	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 83	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 104	5.35	Low	Monitor regularly; Low priority.
Barangay 123	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 84	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 33	5.35	Low	Monitor regularly; Low priority.
San Jose	5.35	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Katuparan	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 1	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 125	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 122	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 50	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 17	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 113	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 108	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 107	5.35	Moderate	Review evacuation routes and drainage capacity.
Comembo	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 104	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 133	5.35	Moderate	Review evacuation routes and drainage capacity.
Tangos North	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 105	5.35	Moderate	Review evacuation routes and drainage capacity.
Pembo	5.35	Moderate	Review evacuation routes and drainage capacity.
Barangay 53	5.35	Moderate	Review evacuation routes and drainage capacity.
Ligid-Tipas	5.20	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

Ibayo-Tipas	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Vergara	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Libis	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Daanghari	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Buayang Bato	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Buli	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Bagumbayan	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Magallanes	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Industrial Valley	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Buting	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Santa Rosa	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Tambo	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Baclaran	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Kalawaan	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 10	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Napindan	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Bambang	5.20	High	Chronic Danger Zone: Immediate structural intervention required.

Disaster Risk Priority Report (NCR)

San Pedro	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Santo Rosario-Kanlur	5.20	High	Chronic Danger Zone: Immediate structural intervention required.
Barangay 35	5.05	Low	Monitor regularly; Low priority.
Barangay 88	5.05	Low	Monitor regularly; Low priority.
Tangos South	5.05	Low	Monitor regularly; Low priority.
Barangay 116	5.05	Low	Monitor regularly; Low priority.
Barangay 775	5.05	Low	Monitor regularly; Low priority.
Barangay 19	5.05	Low	Monitor regularly; Low priority.
Barangay 117	5.05	Low	Monitor regularly; Low priority.
San Jose	5.05	Moderate	Review evacuation routes and drainage capacity.
Barangay 106	5.05	Moderate	Review evacuation routes and drainage capacity.
Dalandanan	5.05	Moderate	Review evacuation routes and drainage capacity.
Barangay 87	5.05	Moderate	Review evacuation routes and drainage capacity.
San Isidro	4.90	Moderate	Review evacuation routes and drainage capacity.
Navotas East	4.90	Moderate	Review evacuation routes and drainage capacity.
Navotas West	4.90	Low	Monitor regularly; Low priority.
Del Monte	4.90	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

East Kamias	4.90	Moderate	Review evacuation routes and drainage capacity.
Damayan	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 4	4.90	Moderate	Review evacuation routes and drainage capacity.
Urdaneta	4.90	Moderate	Review evacuation routes and drainage capacity.
Batasan Hills	4.90	Moderate	Review evacuation routes and drainage capacity.
Concepcion Dos	4.90	Moderate	Review evacuation routes and drainage capacity.
Unang Sigaw	4.90	Moderate	Review evacuation routes and drainage capacity.
Tagumpay	4.90	Moderate	Review evacuation routes and drainage capacity.
Parada	4.90	Moderate	Review evacuation routes and drainage capacity.
Hulong Duhat	4.90	Moderate	Review evacuation routes and drainage capacity.
Baritan	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 131	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 110	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 141	4.90	Moderate	Review evacuation routes and drainage capacity.
Bagong Silangan	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 112	4.90	Moderate	Review evacuation routes and drainage capacity.
Silangan	4.90	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Barangay 111	4.90	Moderate	Review evacuation routes and drainage capacity.
Pinagkaisahan	4.90	Moderate	Review evacuation routes and drainage capacity.
Balingasa	4.90	Moderate	Review evacuation routes and drainage capacity.
Maytunas	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 42	4.90	Moderate	Review evacuation routes and drainage capacity.
Parang	4.90	Moderate	Review evacuation routes and drainage capacity.
Cembo	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 275	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 150	4.90	Moderate	Review evacuation routes and drainage capacity.
San Roque	4.90	Moderate	Review evacuation routes and drainage capacity.
Baesaa	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 21	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 46	4.90	Moderate	Review evacuation routes and drainage capacity.
Ugong	4.90	Moderate	Review evacuation routes and drainage capacity.
Apolonio Samson	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 13	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 124	4.90	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Pamplona Tres	4.90	Moderate	Review evacuation routes and drainage capacity.
Gulod	4.90	Moderate	Review evacuation routes and drainage capacity.
Maharlika	4.90	Moderate	Review evacuation routes and drainage capacity.
Malinta	4.90	Moderate	Review evacuation routes and drainage capacity.
San Isidro Labrador	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 70	4.90	Low	Monitor regularly; Low priority.
Quirino 3-A	4.90	Moderate	Review evacuation routes and drainage capacity.
Paso de Blas	4.90	Moderate	Review evacuation routes and drainage capacity.
Marulas	4.90	Moderate	Review evacuation routes and drainage capacity.
Hagdang Bato Libis	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 69	4.90	Moderate	Review evacuation routes and drainage capacity.
Masagana	4.90	Moderate	Review evacuation routes and drainage capacity.
Lingunan	4.90	Moderate	Review evacuation routes and drainage capacity.
Barangay 600	4.75	Low	Monitor regularly; Low priority.
Barangay 64	4.75	Low	Monitor regularly; Low priority.
Barangay 31	4.75	Low	Monitor regularly; Low priority.
Barangay 30	4.75	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 121	4.60	Moderate	Review evacuation routes and drainage capacity.
Mabolo	4.60	Moderate	Review evacuation routes and drainage capacity.
Balong-Bato	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 34	4.60	Low	Monitor regularly; Low priority.
Barangay 18	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 121	4.60	Low	Monitor regularly; Low priority.
Barangay 109	4.60	Low	Monitor regularly; Low priority.
San Isidro	4.60	Moderate	Review evacuation routes and drainage capacity.
Pitogo	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 130	4.60	Moderate	Review evacuation routes and drainage capacity.
South Cembo	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 182	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 56	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangka Ibaba	4.60	Moderate	Review evacuation routes and drainage capacity.
North Signal Village	4.60	Moderate	Review evacuation routes and drainage capacity.
Barangay 192	4.60	Moderate	Review evacuation routes and drainage capacity.
Ermitaño	4.45	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Elias Aldana	4.45	Moderate	Review evacuation routes and drainage capacity.
Sipac-Almacen	4.45	Moderate	Review evacuation routes and drainage capacity.
Guadalupe Viejo	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 59	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 76	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 102	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 91	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 12	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 75	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 22	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 47	4.45	Moderate	Review evacuation routes and drainage capacity.
Barangay 119	4.30	Low	Monitor regularly; Low priority.
Barangay 100	4.30	Low	Monitor regularly; Low priority.
Escopa IV	4.30	Low	Monitor regularly; Low priority.
Barangay 108	4.30	Low	Monitor regularly; Low priority.
North Daang Hari	4.30	Low	Monitor regularly; Low priority.
Escopa I	4.30	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 98	4.30	Low	Monitor regularly; Low priority.
Barangay 99	4.30	Low	Monitor regularly; Low priority.
Barangay 40	4.30	Low	Monitor regularly; Low priority.
Barangay 38	4.30	Low	Monitor regularly; Low priority.
Barangay 14	4.30	Low	Monitor regularly; Low priority.
Barangay 73	4.30	Low	Monitor regularly; Low priority.
Barangay 123	4.30	Low	Monitor regularly; Low priority.
Barangay 36	4.30	Low	Monitor regularly; Low priority.
Bignay	4.30	Moderate	Review evacuation routes and drainage capacity.
Barangay 155	4.30	Low	Monitor regularly; Low priority.
Magtanggol	4.15	Moderate	Review evacuation routes and drainage capacity.
Santo Rosario-Silang	4.15	Moderate	Review evacuation routes and drainage capacity.
Kapasigan	4.15	Moderate	Review evacuation routes and drainage capacity.
San Joaquin	4.15	Moderate	Review evacuation routes and drainage capacity.
Merville	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 76	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 23	4.15	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Sumilang	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 70	4.15	Moderate	Review evacuation routes and drainage capacity.
Don Galo	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 9	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 4	4.15	Moderate	Review evacuation routes and drainage capacity.
Bagumbuhay	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 2	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 6	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 9	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 19	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 20	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 57	4.15	Moderate	Review evacuation routes and drainage capacity.
Sucat	4.15	Moderate	Review evacuation routes and drainage capacity.
Bayanan	4.15	Moderate	Review evacuation routes and drainage capacity.
Alabang	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 24	4.15	Moderate	Review evacuation routes and drainage capacity.
Singkamas	4.15	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Barangay 128	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 40	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 96	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 22	4.15	Moderate	Review evacuation routes and drainage capacity.
Vasra	4.15	Moderate	Review evacuation routes and drainage capacity.
Kristong Hari	4.15	Moderate	Review evacuation routes and drainage capacity.
Culiat	4.15	Moderate	Review evacuation routes and drainage capacity.
Greenhills	4.15	Moderate	Review evacuation routes and drainage capacity.
Balong Bato	4.15	Moderate	Review evacuation routes and drainage capacity.
Cupang	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 48	4.15	Moderate	Review evacuation routes and drainage capacity.
Bahay Toro	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 60	4.15	Moderate	Review evacuation routes and drainage capacity.
Bagong Pag-asá	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 208	4.15	Moderate	Review evacuation routes and drainage capacity.
Talipapa	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 127	4.15	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

San Lorenzo	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 164	4.15	Moderate	Review evacuation routes and drainage capacity.
Talon Kuartro	4.15	Moderate	Review evacuation routes and drainage capacity.
Santa Lucia	4.15	Moderate	Review evacuation routes and drainage capacity.
Potrero	4.15	Moderate	Review evacuation routes and drainage capacity.
San Antonio	4.15	Moderate	Review evacuation routes and drainage capacity.
Santa Cruz	4.15	Moderate	Review evacuation routes and drainage capacity.
Santol	4.15	Moderate	Review evacuation routes and drainage capacity.
Santa Monica	4.15	Moderate	Review evacuation routes and drainage capacity.
Manuyo Dos	4.15	Moderate	Review evacuation routes and drainage capacity.
Daniel Fajardo	4.15	Moderate	Review evacuation routes and drainage capacity.
Quirino 2-C	4.15	Moderate	Review evacuation routes and drainage capacity.
Quirino 2-A	4.15	Moderate	Review evacuation routes and drainage capacity.
Paltok	4.15	Moderate	Review evacuation routes and drainage capacity.
Barangay 160	4.15	Moderate	Review evacuation routes and drainage capacity.
Talon Tres	4.15	Moderate	Review evacuation routes and drainage capacity.
Talon Dos	4.15	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Roxas	4.15	Moderate	Review evacuation routes and drainage capacity.
Mangga	4.15	Moderate	Review evacuation routes and drainage capacity.
Novaliches Proper	4.15	Moderate	Review evacuation routes and drainage capacity.
Nayong Kanluran	4.15	Moderate	Review evacuation routes and drainage capacity.
Old Capitol Site	4.15	Moderate	Review evacuation routes and drainage capacity.
Kalusugan	4.15	Moderate	Review evacuation routes and drainage capacity.
Fort Bonifacio	4.15	Moderate	Review evacuation routes and drainage capacity.
Kamuning	4.15	Moderate	Review evacuation routes and drainage capacity.
Hagonoy	4.15	Moderate	Review evacuation routes and drainage capacity.
Pinagsama	4.15	Moderate	Review evacuation routes and drainage capacity.
Flores	4.00	Moderate	Review evacuation routes and drainage capacity.
Barangay 29	3.85	Low	Monitor regularly; Low priority.
Barangka Drive	3.85	Low	Monitor regularly; Low priority.
Barangay 649	3.85	Low	Monitor regularly; Low priority.
Barangay 113	3.85	Low	Monitor regularly; Low priority.
Harapin Ang Bukas	3.85	Low	Monitor regularly; Low priority.
Addition Hills	3.85	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Commonwealth	3.85	Low	Monitor regularly; Low priority.
Barangay 29	3.85	Low	Monitor regularly; Low priority.
Barangay 3	3.85	Low	Monitor regularly; Low priority.
Barangay 39	3.85	Low	Monitor regularly; Low priority.
Barangay 1	3.85	Low	Monitor regularly; Low priority.
Barangay 167	3.85	Moderate	Review evacuation routes and drainage capacity.
Poblacion	3.85	Moderate	Review evacuation routes and drainage capacity.
Don Manuel	3.85	Moderate	Review evacuation routes and drainage capacity.
Lawang Bato	3.85	Moderate	Review evacuation routes and drainage capacity.
E. Rodriguez	3.85	Moderate	Review evacuation routes and drainage capacity.
Barangay 138	3.85	Moderate	Review evacuation routes and drainage capacity.
Barangay 103	3.85	Moderate	Review evacuation routes and drainage capacity.
Barangay 139	3.85	Moderate	Review evacuation routes and drainage capacity.
Amihan	3.85	Moderate	Review evacuation routes and drainage capacity.
San Antonio	3.85	Moderate	Review evacuation routes and drainage capacity.
Central	3.85	Moderate	Review evacuation routes and drainage capacity.
South Triangle	3.85	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Santa Teresita	3.85	Moderate	Review evacuation routes and drainage capacity.
Milagrosa	3.85	Moderate	Review evacuation routes and drainage capacity.
Ramon Magsaysay	3.85	Moderate	Review evacuation routes and drainage capacity.
Damar	3.85	Moderate	Review evacuation routes and drainage capacity.
Bagumbayan	3.70	Moderate	Review evacuation routes and drainage capacity.
Tugatog	3.70	Moderate	Review evacuation routes and drainage capacity.
Acacia	3.70	Moderate	Review evacuation routes and drainage capacity.
B. F. International	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 161	3.70	Moderate	Review evacuation routes and drainage capacity.
Almanza Uno	3.70	Moderate	Review evacuation routes and drainage capacity.
Dasmariñas	3.70	Moderate	Review evacuation routes and drainage capacity.
San Antonio	3.70	Moderate	Review evacuation routes and drainage capacity.
Fortune	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 77	3.70	Moderate	Review evacuation routes and drainage capacity.
Putatan	3.70	Moderate	Review evacuation routes and drainage capacity.
Poblacion	3.70	Moderate	Review evacuation routes and drainage capacity.
Bagong Ilog	3.70	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Barangay 6	3.70	Moderate	Review evacuation routes and drainage capacity.
Pineda	3.70	Moderate	Review evacuation routes and drainage capacity.
San Bartolome	3.70	Moderate	Review evacuation routes and drainage capacity.
Paraiso	3.70	Moderate	Review evacuation routes and drainage capacity.
Little Baguio	3.70	Moderate	Review evacuation routes and drainage capacity.
Pasadeña	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 18	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 2	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 143	3.70	Moderate	Review evacuation routes and drainage capacity.
Manresa	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 179	3.70	Moderate	Review evacuation routes and drainage capacity.
Barangay 38	3.55	Low	Monitor regularly; Low priority.
Barangay 120	3.55	Low	Monitor regularly; Low priority.
Barangay 50	3.55	Low	Monitor regularly; Low priority.
Barangay 176	3.55	Low	Monitor regularly; Low priority.
Barangay 175	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 170	3.40	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Karuhatan	3.40	Moderate	Review evacuation routes and drainage capacity.
Santa Cruz	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 147	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 124	3.40	Low	Monitor regularly; Low priority.
Barangay 110	3.40	Low	Monitor regularly; Low priority.
Talon Singko	3.40	Moderate	Review evacuation routes and drainage capacity.
West Rembo	3.40	Moderate	Review evacuation routes and drainage capacity.
Don Bosco	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 71	3.40	Moderate	Review evacuation routes and drainage capacity.
Bel-Air	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 171	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 173	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 172	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangka Itaas	3.40	Low	Monitor regularly; Low priority.
Gen. T. de Leon	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 61	3.40	Moderate	Review evacuation routes and drainage capacity.
B. F. Homes	3.40	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Mapulang Lupa	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 158	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 153	3.40	Moderate	Review evacuation routes and drainage capacity.
Pilar	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 162	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 159	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 178	3.40	Low	Monitor regularly; Low priority.
Talon Uno	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 169	3.40	Moderate	Review evacuation routes and drainage capacity.
Wack-wack Greenhills	3.40	Moderate	Review evacuation routes and drainage capacity.
Ugong	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 168	3.40	Moderate	Review evacuation routes and drainage capacity.
NBBS Proper	3.40	Moderate	Review evacuation routes and drainage capacity.
Bagbaguin	3.40	Moderate	Review evacuation routes and drainage capacity.
New Lower Bicutan	3.40	Moderate	Review evacuation routes and drainage capacity.
Upper Bicutan	3.40	Low	Monitor regularly; Low priority.
Barangay 44	3.40	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

San Jose	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 189	3.40	Low	Monitor regularly; Low priority.
Veterans Village	3.40	Moderate	Review evacuation routes and drainage capacity.
Valencia	3.40	Moderate	Review evacuation routes and drainage capacity.
North Fairview	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 25	3.40	Moderate	Review evacuation routes and drainage capacity.
Ugong Norte	3.40	Moderate	Review evacuation routes and drainage capacity.
Pasong Tamo	3.40	Moderate	Review evacuation routes and drainage capacity.
Phil-Am	3.40	Moderate	Review evacuation routes and drainage capacity.
Pinyahan	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 118	3.40	Low	Monitor regularly; Low priority.
U.P. Campus	3.40	Moderate	Review evacuation routes and drainage capacity.
San Agustin	3.40	Moderate	Review evacuation routes and drainage capacity.
Teachers Village Wes	3.40	Moderate	Review evacuation routes and drainage capacity.
Sikatuna Village	3.40	Moderate	Review evacuation routes and drainage capacity.
Pinagkaisahan	3.40	Moderate	Review evacuation routes and drainage capacity.
Quirino 2-B	3.40	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Nagkaisang Nayon	3.40	Moderate	Review evacuation routes and drainage capacity.
Western Bicutan	3.40	Moderate	Review evacuation routes and drainage capacity.
South Signal Village	3.40	Low	Monitor regularly; Low priority.
Loyola Heights	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 20	3.40	Moderate	Review evacuation routes and drainage capacity.
Horseshoe	3.40	Moderate	Review evacuation routes and drainage capacity.
Matandang Balara	3.40	Moderate	Review evacuation routes and drainage capacity.
Obrero	3.40	Moderate	Review evacuation routes and drainage capacity.
Fairview	3.40	Moderate	Review evacuation routes and drainage capacity.
Pag-ibig Sa Nayon	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 105	3.40	Moderate	Review evacuation routes and drainage capacity.
Santo Cristo	3.40	Moderate	Review evacuation routes and drainage capacity.
Tandang Sora	3.40	Moderate	Review evacuation routes and drainage capacity.
Project 6	3.40	Moderate	Review evacuation routes and drainage capacity.
Bagbag	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 7	3.40	Low	Monitor regularly; Low priority.
Bungad	3.40	Moderate	Review evacuation routes and drainage capacity.

Disaster Risk Priority Report (NCR)

Addition Hills	3.40	Moderate	Review evacuation routes and drainage capacity.
Sangandaan	3.40	Moderate	Review evacuation routes and drainage capacity.
Bayanihan	3.40	Moderate	Review evacuation routes and drainage capacity.
West Triangle	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 30	3.40	Low	Monitor regularly; Low priority.
Greater Lagro	3.40	Moderate	Review evacuation routes and drainage capacity.
Barangay 103	3.25	Moderate	Review evacuation routes and drainage capacity.
Barangay 190	3.10	Low	Monitor regularly; Low priority.
Barangay 191	3.10	Low	Monitor regularly; Low priority.
Barangay 10	3.10	Low	Monitor regularly; Low priority.
Barangay 193	3.10	Low	Monitor regularly; Low priority.
Isabelita	3.10	Low	Monitor regularly; Low priority.
West Crame	3.10	Low	Monitor regularly; Low priority.
Krus Na Ligas	3.10	Low	Monitor regularly; Low priority.
Barangay 123	3.10	Low	Monitor regularly; Low priority.
Hagdang Bato Itaas	3.10	Low	Monitor regularly; Low priority.
Barangay 152	3.10	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 106	3.10	Low	Monitor regularly; Low priority.
Post Proper Southsid	3.10	Low	Monitor regularly; Low priority.
Barangay 95	3.10	Low	Monitor regularly; Low priority.
Barangay 94	3.10	Low	Monitor regularly; Low priority.
Barangay 142	3.10	Low	Monitor regularly; Low priority.
Barangay 121	3.10	Low	Monitor regularly; Low priority.
Barangay 144	3.10	Low	Monitor regularly; Low priority.
Barangay 143	3.10	Low	Monitor regularly; Low priority.
Barangay 118	3.10	Low	Monitor regularly; Low priority.
Barangay 112	3.10	Low	Monitor regularly; Low priority.
South Daang Hari	3.10	Low	Monitor regularly; Low priority.
San Martin de Porres	3.10	Low	Monitor regularly; Low priority.
Escopa III	3.10	Low	Monitor regularly; Low priority.
Santo Niño	3.10	Low	Monitor regularly; Low priority.
Escopa II	3.10	Low	Monitor regularly; Low priority.
Barangay 110	3.10	Low	Monitor regularly; Low priority.
Barangay 165	3.10	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 166	3.10	Low	Monitor regularly; Low priority.
Barangay 154	3.10	Low	Monitor regularly; Low priority.
Punturin	3.10	Low	Monitor regularly; Low priority.
Burol	2.80	Low	Monitor regularly; Low priority.
San Roque	2.65	Low	Monitor regularly; Low priority.
Sauyo	2.65	Low	Monitor regularly; Low priority.
Barangay 44	2.65	Low	Monitor regularly; Low priority.
Paang Bundok	2.65	Low	Monitor regularly; Low priority.
Socorro	2.65	Low	Monitor regularly; Low priority.
Oranbo	2.65	Low	Monitor regularly; Low priority.
Lourdes	2.65	Low	Monitor regularly; Low priority.
Immaculate Concepcion	2.65	Low	Monitor regularly; Low priority.
Mariana	2.65	Low	Monitor regularly; Low priority.
Barangay 23	2.65	Low	Monitor regularly; Low priority.
Bagong Lipunan Ng Cr	2.65	Low	Monitor regularly; Low priority.
Holy Spirit	2.65	Low	Monitor regularly; Low priority.
White Plains	2.65	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Blue Ridge B	2.65	Low	Monitor regularly; Low priority.
Barangay 62	2.65	Low	Monitor regularly; Low priority.
Barangay 11	2.65	Low	Monitor regularly; Low priority.
Barangay 28	2.65	Low	Monitor regularly; Low priority.
New Alabang Village	2.65	Low	Monitor regularly; Low priority.
Barangay 67	2.65	Low	Monitor regularly; Low priority.
Sun Valley	2.65	Low	Monitor regularly; Low priority.
Salvacion	2.65	Low	Monitor regularly; Low priority.
Barangay 107	2.65	Low	Monitor regularly; Low priority.
Pansol	2.65	Low	Monitor regularly; Low priority.
Post Proper Northsid	2.65	Low	Monitor regularly; Low priority.
Barangay 122	2.65	Low	Monitor regularly; Low priority.
Forbes Park	2.65	Low	Monitor regularly; Low priority.
East Rembo	2.65	Low	Monitor regularly; Low priority.
Barangay 101	2.65	Low	Monitor regularly; Low priority.
Barangay 79	2.65	Low	Monitor regularly; Low priority.
Marcelo Green Villag	2.65	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 134	2.65	Low	Monitor regularly; Low priority.
Mauway	2.65	Low	Monitor regularly; Low priority.
Tabacalera	2.65	Low	Monitor regularly; Low priority.
Barangay 163	2.65	Low	Monitor regularly; Low priority.
Lower Bicutan	2.65	Low	Monitor regularly; Low priority.
Almanza Dos	2.65	Low	Monitor regularly; Low priority.
Barangay 105	2.65	Low	Monitor regularly; Low priority.
Barangay 145	2.65	Low	Monitor regularly; Low priority.
Barangay 177	2.65	Low	Monitor regularly; Low priority.
San Martin de Porres	2.65	Low	Monitor regularly; Low priority.
Barangay 90	2.65	Low	Monitor regularly; Low priority.
Tunasan	2.50	Moderate	Review evacuation routes and drainage capacity.
Bagumbayan North	2.50	Moderate	Review evacuation routes and drainage capacity.
Barangay 188	2.35	Low	Monitor regularly; Low priority.
Malamig	2.35	Low	Monitor regularly; Low priority.
Barangay 186	2.35	Low	Monitor regularly; Low priority.
Barangay 146	2.35	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 157	2.35	Low	Monitor regularly; Low priority.
Barangay 156	2.35	Low	Monitor regularly; Low priority.
Laging Handa	2.35	Low	Monitor regularly; Low priority.
Malaya	2.35	Low	Monitor regularly; Low priority.
Pedro Cruz	2.35	Low	Monitor regularly; Low priority.
Santa Lucia	2.35	Low	Monitor regularly; Low priority.
Barangay 1	2.35	Low	Monitor regularly; Low priority.
Camp Aguinaldo	2.35	Low	Monitor regularly; Low priority.
Teachers Village Eas	2.35	Low	Monitor regularly; Low priority.
Kaligayahan	2.35	Low	Monitor regularly; Low priority.
Marilag	2.35	Low	Monitor regularly; Low priority.
Barangay 26	2.20	Low	Monitor regularly; Low priority.
Barangay 5	2.20	Low	Monitor regularly; Low priority.
Barangay 27	2.20	Low	Monitor regularly; Low priority.
Barangay 16	2.20	Low	Monitor regularly; Low priority.
Barangay 25	2.20	Low	Monitor regularly; Low priority.
Payatas	2.20	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 60	2.20	Low	Monitor regularly; Low priority.
Barangay 80	2.20	Low	Monitor regularly; Low priority.
Barangka Ilaya	2.20	Low	Monitor regularly; Low priority.
Pleasant Hills	2.20	Low	Monitor regularly; Low priority.
Guadalupe Nuevo	2.20	Low	Monitor regularly; Low priority.
Poblacion	2.20	Low	Monitor regularly; Low priority.
Barangay 84	2.20	Low	Monitor regularly; Low priority.
Highway Hills	1.90	Low	Monitor regularly; Low priority.
Barangay 185	1.90	Low	Monitor regularly; Low priority.
Barangay 181	1.90	Low	Monitor regularly; Low priority.
Barangay 180	1.90	Low	Monitor regularly; Low priority.
Barangay 174	1.90	Low	Monitor regularly; Low priority.
Barangay 187	1.90	Low	Monitor regularly; Low priority.
Barangay 183	1.90	Low	Monitor regularly; Low priority.
Barangay 184	1.90	Low	Monitor regularly; Low priority.
Barangay 182	1.90	Low	Monitor regularly; Low priority.
Barangay 136	1.90	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 140	1.90	Low	Monitor regularly; Low priority.
Barangay 135	1.90	Low	Monitor regularly; Low priority.
Barangay 68	1.90	Low	Monitor regularly; Low priority.
Barangay 74	1.90	Low	Monitor regularly; Low priority.
Barangay 179	1.90	Low	Monitor regularly; Low priority.
Barangay 150	1.90	Low	Monitor regularly; Low priority.
Sacred Heart	1.90	Low	Monitor regularly; Low priority.
Paligsahan	1.90	Low	Monitor regularly; Low priority.
Barangay 55	1.90	Low	Monitor regularly; Low priority.
Barangay 58	1.90	Low	Monitor regularly; Low priority.
Barangay 48	1.90	Low	Monitor regularly; Low priority.
Barangay 47	1.90	Low	Monitor regularly; Low priority.
Barangay 51	1.90	Low	Monitor regularly; Low priority.
Barangay 54	1.90	Low	Monitor regularly; Low priority.
Barangay 137	1.90	Low	Monitor regularly; Low priority.
Kapitolyo	1.90	Low	Monitor regularly; Low priority.
Barangay 194	1.90	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 45	1.90	Low	Monitor regularly; Low priority.
Onse	1.90	Low	Monitor regularly; Low priority.
Corazon de Jesus	1.90	Low	Monitor regularly; Low priority.
Aurora	1.90	Low	Monitor regularly; Low priority.
Tibagan	1.90	Low	Monitor regularly; Low priority.
Doña Josefa	1.90	Low	Monitor regularly; Low priority.
Dioquino Zobel	1.90	Low	Monitor regularly; Low priority.
Kaunlaran	1.90	Low	Monitor regularly; Low priority.
Central Bicutan	1.90	Low	Monitor regularly; Low priority.
U.P. Village	1.90	Low	Monitor regularly; Low priority.
Blue Ridge A	1.90	Low	Monitor regularly; Low priority.
Barangay 15	1.90	Low	Monitor regularly; Low priority.
Saint Ignatius	1.90	Low	Monitor regularly; Low priority.
Barangay 39	1.90	Low	Monitor regularly; Low priority.
Duyan-duyan	1.90	Low	Monitor regularly; Low priority.
Barangay 188	1.60	Low	Monitor regularly; Low priority.
Barangay 42	1.15	Low	Monitor regularly; Low priority.

Disaster Risk Priority Report (NCR)

Barangay 13	1.15	Low	Monitor regularly; Low priority.
Barangay 41	1.15	Low	Monitor regularly; Low priority.
Barangay 148	0.70	Low	Monitor regularly; Low priority.
Barangay 149	0.70	Low	Monitor regularly; Low priority.