

LOW PRESSURE

LW

(TWO-SHEET TYPE)

Measurement pressure range: 2.5—10MPa

• Pressure application conditions

Time to reach the pressure to be measured: 2 min.


Time of retention at the pressure to be measured: 2 min.

Check if the temperature and humidity meet with the conditions above when the pressure is applied.

(For example, if the room temperature is 25°C and the humidity factor is 60%RH, acquire the pressure from the B curve in the standard chart.)

STANDARD CONTINUOUS PRESSURE CHART

GRAPH OF TEMPERATURE/
HUMIDITY CONDITIONS



STANDARD COLOR SAMPLE

1.5




1.3



1.1



0.9



0.7




0.5



0.3



0.1



As the pressure range indicated by the broken line in the graph may exceed the permissible error range, it should be used for reference purposes only.