

PRODUCT OBSOLESCENCE NOTICE

30th July 2010

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product is becoming obsolete with immediate effect:

76601/6C

It is due to material obsolescence that we are unable to support this product. There will be no opportunity for a last time or lifetime buy (LTB).

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at http://www.murata-ps.com/offices.html.