

UFE412 Rel. 4.2.1 1875 Release Notes

Issue No. 1: July 2013



Legal Information

Copyright

Copyright 2013 PMC-Sierra, Inc. All rights reserved.

The information in this document is proprietary and confidential to PMC-Sierra, Inc., and for its customers' internal use. In any event, no part of this document may be reproduced or redistributed in any form without the express written consent of PMC-Sierra, Inc.

Disclaimer

None of the information contained in this document constitutes an express or implied warranty by PMC-Sierra, Inc. as to the sufficiency, fitness or suitability for a particular purpose of any such information or the fitness, or suitability for a particular purpose, merchantability, performance, compatibility with other parts or systems, of any of the products of PMC-Sierra, Inc., or any portion thereof, referred to in this document. PMC-Sierra, Inc. expressly disclaims all representations and warranties of any kind regarding the contents or use of the information, including, but not limited to, express and implied warranties of accuracy, completeness, merchantability, fitness for a particular use, or non-infringement.

In no event will PMC-Sierra, Inc. be liable for any direct, indirect, special, incidental or consequential damages, including, but not limited to, lost profits, lost business or lost data resulting from any use of or reliance upon the information, whether or not PMC-Sierra, Inc. has been advised of the possibility of such damage.

Trademarks

For a complete list of PMC-Sierra's trademarks and registered trademarks, visit: http://www.pmcsierra.com/legal/

Other product and company names mentioned herein may be the trademarks of their respective owners.

Revision History

Issue No.	Issue Date	Details of Change	
1	July 2013	Changes made for 4.2.1 1875 release	

Contacting PMC-Sierra

PMC-Sierra PMC-Sierra, WIN Div. 8555 Baxter Place 6850 Austin Center Blvd. Burnaby, BC Suite 215 Canada V5A 4V7 Tel: +1 (604) 415-6000 Fax: +1 (604) 415-6200

Austin, TX 78731 USA Tel: +1 (512) 345-3808

PMC-Sierra Israel Ltd. 7 Arie Shenkar St. Gav-Yam Bldg 2 Herzliya 46120 Israel

Tel: +972 (9) 743-9998

International House, Stanley Blvd. Hamilton Int. Technology Park Blantyre, Glasgow. G72 OBN. **United Kingdom**

Tel: +44 (0) 1698-404889

PMC-Sierra, WIN Div.

Document Information: document@pmc-sierra.com Corporate Information: info@pmc-sierra.com **Technical Support:** apps@pmc-sierra.com Web Site: http://www.pmc-sierra.com



Table of Contents

Le	gal Inf	ormatior	٦	2		
	Copy	right		2		
	Discl	aimer		2		
	Trad	emarks .		2		
Re	vision	History.		2		
Со	ntactir	ng PMC-	-Sierra	2		
1	Abou	ıt this Re	elease	5		
2	Inclu	ded in th	nis Release	6		
	2.1	Releas	se Components	6		
	2.2	Docum	nentation	6		
		2.2.1	Product Brief	6		
		2.2.2	Data Sheet	6		
		2.2.3	Errata	6		
		2.2.4	Software Documentation	6		
		2.2.5	Application Note	6		
		2.2.6	Models	7		
		2.2.7	BSDL Files	7		
		2.2.8	Reference Design	7		
	2.3	Softwa	ıre Packages	7		
		2.3.1	UFE and Clock Recovery Add-On Modules	7		
	2.4	WDDS	S/UFE Reference Applications (Software Examples on myPMC)	7		
3	Insta	llation Ir	nstructions	8		
4	Testi	ng Statu	s of this Release	9		
	4.1	Testing	g Environment	9		
	4.2 Testing Platforms					
	4.3	UFE H	W Version	9		
	4.4	Develo	ppments Tool Chains	9		
5	Wha	t is New	?	11		
	5.1	In this	Release	11		
		5.1.1	Backhaul Market Applications	11		
6	Limitations & Restrictions					
7	Compatibility with Previous Releases					
	7.1 Software Compatibility					







1 About this Release

This UFE412 Rel. 4.2.1 1875 Release Notes is intended for use with the following devices:

- WinPATH-3 Rev-B2
- UFE412 version 4.2.1 from Mon Jul 15 09:33:50 IDT 2013



Included in this Release 2

Release Components 2.1

This release of the UFE SW/FW consists of the following components:

Component Name
Documentation
Software Packages (listed below), Build Number: 1875
Reference Applications

2.2 **Documentation**

2.2.1 Product Brief

UFE412 Product Brief (PMC-2110545)

2.2.2 Data Sheet

UFE412 Hardware Manual (PMC-2110181) **UFE412 Datasheet** (PMC-2110183)

2.2.3 Errata

UFE412 Known Issues (PMC-2132157)

2.2.4 Software Documentation

UFE4 Programmer's Manual (PMC-2110182) UFE4 Rel. 4.2.1 1875 Rel. Notes (PMC-2132156) UFE4 PWE3 CR User Guide (Std) (PMC-2111594)

2.2.5 Application Note

UFE3 Application Note	(PMC-2111136)
UFE3 Configuration Guide App Note	(PMC-2111143)
UFE3 Board Support App Note	(PMC-2111140)
PWE3 Clock Recovery UG for UFE3 and TDI	(PMC-2110456)
PWE3 Clock Recovery UG for UFE4	(PMC-2112001)
PWE3 CR Calculator for WDDI 4.2	(PMC-2112166)
CESOP/SATOP over MPLS/UDP TDM UFE4	(PMC-2113216)
HDLC/PPP over UFE4 Application Note	(PMC-2114555)
UFF4 APS App note (***)	

JFE4 APS App note (

UFE412 Diagnostic Test

UFE3 to UFE4 Migration Guide (PMC-2110190)



2.2.6 Models

UFE412 IBIS (PMC-2112225)

2.2.7 BSDL Files

UFE412 BSDL (PMC-2112226)

2.2.8 Reference Design

UFE4 Board Schematic -

Software Packages 2.3

2.3.1 UFE and Clock Recovery Add-On Modules 1

Software Package and Distribution File Name	Description	Supported WinPath Device
UFE	UFE sources for UFE3 and	WinPath 3 Rev-B2
1875_ufe_4.2.1.tgz	UFE412 core	
UFE4 Framer	Driver for UFE412	WinPath 3 Rev-B2
1875_ufe_framer_ufe412_4.2.1.tgz	framer driver	

WDDS/UFE Reference Applications (Software Examples on myPMC) 2.4

This release of the WDDS/UFE SW comes with the following reference applications:

PWE3-CES Demo for WDDS 4.2.1

Document No.: PMC-2132156, Issue 1

¹ UFE and Clock Recovery modules are available to UFE/licensed customers only. Please contact PMC-Sierra WIN for more information about available options.



3 Installation Instructions

- No special setup is required.
- Please refer the WDDS and UFE documentation for compilation and build instructions.



4 Testing Status of this Release

4.1 Testing Environment

WinPATH Device			VCORE	Number	IO	MIPS	PLL/Busses
Туре	ID	Rev		WinGines		Freq	FLL/Dusses
WinPATH 3	2C2	B1 & B2	1.1 V	12	3.3V	600 MHZ	400/533 MHZ host 100

4.2 Testing Platforms

WDS Board	BSP	BSP Version / Build		
WDS3 revB2	WINMON	v4.2.5		
	LINUX	Timesys ver. 2.6.29.4 for WDS3 build N 20111030		

4.3 UFE HW Version

UFE	Version
UFE412	Timestamp:
	1373870030
	Mon Jul 15 09:33:50 IDT 2013

4.4 Developments Tool Chains

Tool	Platform	Version		
WDDI Tool Chain				
C Compiler MIPS/WinMon		mips-sde-elf-gcc – gcc version 4.4.1 (Sourcery G++ Lite 4.4-87)		



C Compiler	MIPS/Linux	mipsisa32r2-timesys-linux-uclibc- gcc – gcc version 4.4.2 (GCC)		
	DPS Tool Chain			
WinDPL	Linux MS-Windows	114		
WINELF	Linux MS-Windows	114		
WInLNK	Linux MS-Windows	114		
WinCom Simulator				
WinSIM WinPATH 2	Linux MS-Windows	112		
WinSIM WinPATH 3	Linux MS-Windows	114		



5 What is New?

The following section lists what is new in this release.

This Section refer to the things that changed from 4.2.1 1865 release

5.1 In this Release

5.1.1 Backhaul Market Applications

The given release adds support for the following Backhaul functionality:

- TU-LOP/TU-AIS alarms may get stuck if the port optical signal is toggling in high frequency bug fix (bug number 7529)
- DS3\E3 with T1\E1 connection on the same optical port bug fix (bug number 7610)



6 Limitations & Restrictions

Please refer the UFE412 Known Issues document for detailed information about all known limitations and restrictions.

7 Compatibility with Previous Releases

7.1 Software Compatibility

UFE4 4.2.1 1875 release is compatible with previous release.

7.2 Hardware Compatibility

The 4.2.1 1875 release supports the following WP devices:

WinPath 3 Rev-B2