NO LOGO
UPLOADED

MSN PANEL BEATERS

15 Industrial Road, Johannesburg, Gauteng
011 438 7890 • office@example.com

REPAIR ESTIMATE

Customer document • Original

EST-000001

CUSTOMER DETAILS

Moses Moyana

061 443 8789

VEHICLE / REPAIR JOB

SWF 201 GP | Toyota | Corolla Verso

JOB	DATE	STATUS
JOB-000001	**2026/11/08**	**Submitted**

ASSESSMENT & REPAIR SCOPE

Front bumper scratches and cracked paint. Full bumper preparation, panel repair, refinishing and quality inspection. Bonnet requires polishing and paint restoration.

CATEGORY / REPAIR DESCRIPTION	QTY	UNIT PRICE	AMOUNT
PAINT LABOUR Bonnet & front bumper refinish - black	1	R 6 000,00	**R 6 000,00**

Subtotal	R 6 000,00
VAT (0%)	R 0,00
TOTAL	**R 6 000,00**

NOTES / TERMS

Validity: 14 days. Repair work commences after written approval and subject to parts availability.