


Before







PMV Comfort:16.9%

Adaptive Comfort: 17.9%





After



Windows Rate:

N: 0%

S: 20% E: 20%

W: 0%


Exterior Wall: R34.4


Exterior Windows: R1.7 SHGC 0.39

Exterior Roof: R34.4

Shading: Yes

PMV Comfort:29.235%





PMV Comfort