
OUTDOOR SHADING DESIGN


12 AM 12 PM 6 AM 12 AM Jan Feb Mar Apr May Jun Jul Aug Sep Oct Nov Dec

Thermal Stress

Fully Shaded




With Solar Radiation



With Solar Radiation and context of Meyerson & Fisher fine arts


_	-1 = Cold 0 = Comfort 1 = Hot
	1.00<=
	0.00
	<=-1.00

	Bench 1	Bench 2	Bench 3
Percent of time comfortable	40.5	40.38	38.02
Percent Heat Stress	6.65	6.47	10.06
Percent Cold Stress	32.40	32.68	32.64





Thermal Stress: Basic Shading


Bench 1




Bench 2








	Bench 1	Bench 2	Bench 3
Percent of time comfortable	42.2	42.21	42.45
Percent Heat Stress	3.66	3.65	3.21
Percent Cold Stress	32.77	32.93	32.99





Thermal Stress: Designed Shading






Bench 2







	Bench 1	Bench 2	Bench 3
Percent of time comfortable	42.2	42.21	41.27
Percent Heat Stress	3.66	3.65	3.13
Percent Cold Stress	32.77	32.93	34.33