## **ARCH-753-001-Building Performance Simulation Assignment-1**

East facing apartment

Direction of windows: East facing and provides a view of the 42<sup>nd</sup> South Street

## Problems faced:

- 1. Too much of sunlight during the morning hours and the glare also makes it difficult to work at study table
- 2. Low thermal comfort due to the change of temperature in the morning
- 3. Lot of noise due to the traffic

## Solutions:

- 1. Proper shading or overhang device should be installed
- 2. Use of interior blinds or curtains
- 3. Use of energy efficient window panels like insulated panels, high reflectivity films/films that can cut off the summer heat and mesh window screens which can diffuse the solar radiation
- 4. Insulating the walls can also help with both increase in thermal comfort and reduce the level of noise