



ARCH 753_BPS MEBD_FALL SEMESTER 2017 JOSÉ BARRÍA





Floor Layout





Main Concerns:

1_Sunlight warms bed area in the early morning.

Windows should have protection to shade adjacent surfaces.

- 2_Sunlight shines directly on TV and work station throughout the morning.

 Blinds should be installed.
- ${\tt 3_Entire}\ room\ is\ severly\ warmed\ throughout\ entire\ day\ (direct\ sunlight).$

Windows could be double pane or higher in R value.