
Fall 2016 ARCH 753



- 1. There is direct sunlight that causes glare on my work table in the afternoon and evening.

 The table's location cannot be changed because it is tied to the location of the Ethernet jack and the electrical outlet.
- 2. All the windows are on the same side of the room so there is no cross-ventilation. Even when the temperature outside is cooler than in my room, opening my windows does not cool my room down much.
- 3. There is a direct view into my room from the neighboring balcony.

Fall 2016 ARCH 753





- 1. Installing a "window-box" will cut glare and block the view from the neighboring balcony.

 The window box will consist of two vertical shades and one horizontal shade.
- 2. Installing an exhaust fan on the wall opposite the windows will create cross-ventilation.

 Placing the exhaust fan high on the wall will also help remove hot air.


Parameters





2. The depth of the window-box

Fall 2016 ARCH 753



3. The size and capacity of the exhaust fan.

