BUILDING PERFORMANCE SIMULATION ARCH-753 Fall 2017


ASSIGNMENT 6

Hwang, Youngjin

Construction Properties

Since I can not know exact construction detail of my building, I use default HB Constructions, especially for exterior wall and windows, I have used CBECS 1980-2004 code for climate zone 4A because the building was built in around the early 1980s in Philadelphia.





M11 100mm lightweight concrete
F05 Ceiling air space resistance
F16 Acoustic tile

U-VALUE: 1.45 W/m2K

M11 100mm lightweight concrete F05 Ceiling air space resistance F16 Acoustic tile

19mm gypsum board U-VALUE: 2.58 W/m2K


U-VALUE: 1.45 W/m2K

- 2. Wall air space resistance3. 19mm gypsum board
- 1. 1" Stucco U-VALUE: 0.76 W/m2K
- 2. 8" concrete HW RefBldg
- 3. Mass non-res wall insulation-1.47
- 4. 1/2" gypsum board

1. Simple glazing system U-VALUE: 3.35 W/m2K

Indoor Adaptive Comfort Analysis

This is the indoor adaptive comfort analysis without HVAC system. As you see the result, the room is dominated by seasons during winter and summer.



Adaptive Comfort for MY_ROOM (-1 = Cold, 0 = Comfortable, 1 = Hot) - Hourly Philadelphia International Ap PA USA TMY3


1 JAN 1:00 - 31 DEC 24:00

ercentage of time in comfortable condition	16%
Percentage of time in hot stress	40%
Percentage of time in cold stress	44%

The Change of Construction Properties


To improve the result, the properties of exterior wall and window are changed. The reference values are ASHRAE 189.1-2009 criterion

and high performance low-e double glazing.




Indoor Adaptive Comfort Analysis

In this process, I did not change any room geometry or shading to know how much building materials affect an indoor comfort without HVAC. As properties of exterior wall and windows are changed, comfort during winter has improved while comfort during summer has worsened because improved insulating value also affect heat emission to outdoor during summer. Finally, even though this room design had optimized illuminance level from the original design, but it doesn't meet well indoor comfort.



Adaptive Comfort for MY_ROOM (-1 = Cold, 0 = Comfortable, 1 = Hot) - Hourly Philadelphia International Ap PA USA TMY3

1 JAN 1:00 - 31 DEC 24:00



Adaptive Comfort for MY_ROOM (-1 = Cold, 0 = Comfortable, 1 = Hot) - Hourly Philadelphia International Ap PA USA TMY3

1 JAN 1:00 - 31 DEC 24:00