

MEYERSON - ORIGINAL MASSING

ORIENTATION

VALUE: -20222







MEYERSON - NEW MASSING

ORIENTATION

VALUE: +1994





THE NEW MASSING WAS ROTATED TO ORIENT TOWARDS TRUE SOUTH AND GIVEN A TRIANGULAR MASSING TO MINIMIZE THE COOLING EFFECTS DURING THE WINTER MONTHS. THE ORIENTATION VALUE FOR THE ORIGINAL MASSING IS NOT REFLECTIVE OF THE SHADING THE BUILDING USES, BUT THE NEW MASSING UTILIZES SHADING TO BLOCK HEAT GAIN IN THE SUMMER MONTHS.