
## Pinout CC2530 on E18-MS1-PCB





Pin №	Pin Item	Pin direction	Application
1	GND	Input	Ground
2	VDD	Input	Power supply, 2.0 ~3.6V
3	P22	Input / Output	MCU GPIO
4	P21	Input / Output	MCU GPIO
5	P20	Input / Output	MCU GPIO
6	P17	Input / Output	MCU GPIO
7	P16	Input / Output	MCU GPIO
8	NC	-	Reserved
9	NC	-	Reserved
10	P15	Input / Output	MCU GPIO
11	P14	Input / Output	MCU GPIO
12	P13	Input / Output	MCU GPIO
13	P12	Input / Output	MCU GPIO
14	P11	Output	MCU GPIO
15	P10	Output	MCU GPIO
16	P07	Input / Output	NC
17	P06	Input / Output	MCU GPIO
18	P05	Input / Output	MCU GPIO
19	P04	Input / Output	MCU GPIO
20	P03	Input / Output	MCU GPIO
21	P02	Input / Output	MCU GPIO
22	P01	Input / Output	MCU GPIO
23	P00	Input / Output	MCU GPIO
24	RESET	Input	Reset port