

```
-----
| ENDPOINT 0: 0x0016 (Root Node)
| ENDPOINT 0: 0x0012 (OTA Requestor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x0000001F (AccessControl)
|   Cluster 0x00000028 (BasicInformation)
|   Cluster 0x00000030 (GeneralCommissioning)
|   Cluster 0x00000031 (NetworkCommissioning)
|   Cluster 0x00000033 (GeneralDiagnostics)
|   Cluster 0x0000003C (AdministratorCommissioning)
|   Cluster 0x0000003E (OperationalCredentials)
|   Cluster 0x0000003F (GroupKeyManagement)
|   Cluster 0x00000029 (OtaSoftwareUpdateProvider)
|   Cluster 0x0000002A (OtaSoftwareUpdateRequestor)
| ENDPOINT 1: 0x0302 (Temperature Sensor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x00000003 (Identify)
|   Cluster 0x00000402 (TemperatureMeasurement)
|   Cluster 0x00000405 (RelativeHumidityMeasurement)
|   Cluster 0x00000403 (PressureMeasurement)
| ENDPOINT 2: 0x0302 (Temperature Sensor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x00000003 (Identify)
|   Cluster 0x00000402 (TemperatureMeasurement)
|   Cluster 0x00000405 (RelativeHumidityMeasurement)
|   Cluster 0x00000403 (PressureMeasurement)
|   Cluster 0x0000042E (RadonConcentrationMeasurement)
| ENDPOINT 3: 0x0302 (Temperature Sensor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x00000003 (Identify)
|   Cluster 0x00000402 (TemperatureMeasurement)
| ENDPOINT 4: 0x0302 (Temperature Sensor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x00000003 (Identify)
|   Cluster 0x00000402 (TemperatureMeasurement)
|   Cluster 0x00000405 (RelativeHumidityMeasurement)
| ENDPOINT 5: 0x002C (Air Quality Sensor)
|   Cluster 0x0000001D (Descriptor)
|   Cluster 0x00000003 (Identify)
|   Cluster 0x0000005B (AirQuality)
|   Cluster 0x0000040D (CarbonDioxideConcentrationMeasurement)
|   Cluster 0x0000040C (CarbonMonoxideConcentrationMeasurement)
|   Cluster 0x0000042E (RadonConcentrationMeasurement)
|-----
```