

# INTEGRATED CIRCUIT CROSS REFERENCE

9

## Integrated Circuits

### Replacement Part Cross Reference

When selecting replacement parts for your HP products, you may notice that many manuals list only an HP part number for the part, even though it appears that this part is manufactured by one of the large semiconductor manufacturers. Service personnel often ask why only HP part numbers are It is recommended that HP replacement parts be used to ensure that the original performance of the product will be obtained. While some parts used in HP instruments are identical to that which can be purchased at a local electronics distributor, many times parts will be selected for certain char

Therefore, we suggest obtaining replacement parts from HP to maintain the quality that you have paid for in your instrument. There may be situations however where HP replacement parts are not in stock and substituting parts will allow you to return the product to service immediately. In these c To help you in these situations, here's a cross-reference of HP integrated circuit part numbers to manufacturers "generic type" part numbers (whom in most cases is the originator of the part). Even though the cross-reference only lists one manufacturer, there may actually be several approved sc

### Manufacturers Code Number Cross Reference

| Number | Manufacturer                            | Location          | Number | Manufacturer                           | Location          |
|--------|-----------------------------------------|-------------------|--------|----------------------------------------|-------------------|
| 0039   | Nippon Electric Co.                     | Tokyo, JP         | 3334   | Amperex Elek. Corp. Semicon. & MC Div. | Slatersville, RI  |
| 00350  | Exar Integrated Systems Inc.            | Sunnyvale, CA     | 3406   | National Semiconductor Corp.           | Santa Clara, CA   |
| 00575  | Western Digital Corp.                   | Newport Beach, CA | 3545   | Teledyne Philbrick Nexus               | Dedham, MA        |
| 01590  | Plessey Semiconductors                  | Santa Ana, CA     | 3658   | Optimax Inc.                           | Colmar, PA        |
| 01698  | Texas Instr. Inc. Semicond. Cmpnt. Div. | Dallas, TX        | 3677   | American Micro Systems Inc.            | Santa Clara, CA   |
| 01795  | Synertek                                | Santa Clara, CA   | 3714   | Intersil Inc.                          | Cupertino, CA     |
| 01876  | HP Div. 02 Santa Clara IC's 86          | Santa Clara, CA   | 3755   | Hybrid Systems Corp.                   | Burlington, MA    |
| 01921  | RCA Corp. Solid State Div.              | Somerville, NJ    | 3758   | Electronic Arrays, Inc.                | Mountain View, CA |
| 01973  | GE Co. Semiconductor Prod. Dept.        | Auburn, NY        | 3780   | Intech Inc.                            | Santa Clara, CA   |
| 01991  | Transitron Electronic Corp.             | Wakefield, MA     | 3794   | Advanced Micro Devices Inc.            | Sunnyvale, CA     |
| 02023  | Illinois Tool Works Inc.Licon Div.      | Chicago, IL       | 3795   | Motorola Inc.                          | Franklin Park, IL |
| 02037  | Motorola Semiconductor Products         | Phoenix, AZ       | 3799   | Harris Semicon. Div. Harris-Intertype  | Melbourne, FL     |
| 02180  | Precision Monolithics Inc.              | Santa Clara, CA   | 3811   | Intel Corp.                            | Mountain View, CA |
| 02237  | Fairchild Semiconductor Div.            | Mountain View, CA | 4078   | Mostek Corp.                           | Carrollton, TX    |
| 02290  | Raytheon Co. Semiconductor Div. HQ      | Mountain View, CA | 4092   | Monolithic Memories Inc.               | Sunnyvale, CA     |
| 02569  | Crystalonics, Div. Teledyne             | Cambridge, MA     | 4183   | Nitron Div. McDonnell Douglas Corp.    | Cupertino, CA     |
| 02598  | Unitrode Corp.                          | Watertown, MA     | 4200   | Sprague Electric Co.                   | North Adams, MA   |
| 02634  | Sprague Elect. Co. Semiconductor Div.   | Concord, NH       | 5436   | Burr Brown Co.                         | Tucson, AZ        |
| 02713  | General Instr. Corp. Semicon. Prod. GP  | Hicksville, NY    | 6338   | SGS Ates                               | Milan, IT         |
| 02763  | Teledyne Semiconductor                  | Mountain View, CA | 6545   | Lambda Electronics Corp.               | Melville, NY      |
| 02838  | Dynamic Measurements Corp.              | Winchester, MA    | 6563   | Siemens Corp. Components Group         | Scottsdale, AZ    |
| 02882  | Zeltex Inc. Sub. of Redcor Corp         | Concord, CA       | 6852   | Data Delay Devices                     | Clifton, NJ       |
| 02883  | Siliconix                               | Santa Clara, CA   | 7653   | Zilog Inc.                             | Cupertino, CA     |
| 02910  | Signetics Corp.                         | Sunnyvale, CA     | 7810   | Texas Instruments France               | Nice, FR          |
| 03183  | HP Div. 22 Data Systems.                | Cupertino, CA     | 7915   | Hytek Microsystems Inc.                | San Diego, CA     |
| 03285  | Analog Devices Inc.                     | Norwood, MA       |        |                                        |                   |

| HP P/N    | Mfr. | Desc.                  | 1813-0040 | 2882 Z0440               | 1813-0067 | 3795 K1115A-10MHZ     |
|-----------|------|------------------------|-----------|--------------------------|-----------|-----------------------|
|           |      |                        | 1913-0041 | 3406 LH0042CH            | 1811-0082 | 2598 PIC646           |
| 0960-9566 |      | 3795 K1100A-10.0MHZ    | 1813-0043 | 3795 K1091A-10.485760MHZ | 1813-0083 | 2598 PIC601           |
| 0960-0567 |      | 3795 K1300A-5.216MHZ   | 1813-0045 | 3795 K1091A-5.0MHZ       | 1813-0084 | 2598 PIC611           |
| 0950-0569 |      | 5795 K1100A-22.8571MHZ | 1813-0046 | 3795 K1100A-15MHZ        | 1813-0089 | 3795 K11004-27MHZ     |
| 0960-0570 |      | 3795 K1114A-24.0MHZ    | 1813-0047 | 3795 K1091A-10.0MHZ      | 1813-0092 | 5436 DAC80-CCD-V      |
| 0960-0572 |      | 3795 K1100A-20.275MHZ  | 1813-0048 | 3285 751N                | 1813-0093 | 2237 UA78H12SC        |
| 096J-0581 |      | 3795 K1115A-1.0MHz     | 1813-0049 | 2763 2740I*              | 1813-0098 | 5436 ADCSOAG-12       |
| 0960-0631 |      | 3285 DA C16QM/C-8      | 1813-0052 | 3795 K1091A-7.50MHZ      | 1813-0100 | 2237 UA78H05SC        |
| 0960-0632 |      | 3285 DACI2QS/C-8       | lets-0053 | 3795 K1091A-6.9120MHZ    | 1813-0105 | 5436 DAC80-C8I-V      |
| 1813-0013 |      | 3285 40K               | 1813-0054 | 3406 AH0154D             | 1813-0109 | 2598 PIC625           |
| 1813-0016 |      | 5436 3112/12C          | 1913-0057 | 3406 LH0024CH            | 1913-0110 | 2598 PIC626           |
| 1813-0034 |      | 3714 IH5010CPD         | 1813-0058 | 3406 LH0021CK            | 1e13-0114 | 2598 PIC645           |
| 1913-0036 |      | 3755 DAC372-12-BCD     | 1813-0061 | 3795 K1100A-8.389MHZ     | 1813-0115 | 2598 PIC600           |
| 1813-0039 |      | 2892 Z0441             | 1813-0062 | 3795 K1100A-10.486MHZ    | 1813-0116 | 3795 K1100A-9.8304MHZ |

10

# INTEGRATED CIRCUIT CROSS REFERENCE

| HP P/N    | Mfr. | Desc.                  | 1816-1339      | 3406 DM8678CAB/N | 1818-0762 | 1698 TMS2532JL             |
|-----------|------|------------------------|----------------|------------------|-----------|----------------------------|
|           |      |                        | 1816-1358      | 1698 TBP14SA10N  | 1818-0772 | 3811 D21154                |
| 1813-0117 |      | 3795 K1100A-1.792MHZ   | 1816-1371      | 4092 6309-1N     | 1818-0794 | 3811 C2716                 |
| 1813-0119 |      | 3795 K1100A-40MHZ      | 1816-1382      | 3799 HM3-7621-5  | 1818-0849 | 2037 MCM2147C-70           |
| 1813-0120 |      | 6852 ODU-4-5100        | 1816-13880169B | TBP18S22N        | 1818-0850 | 3811 D2732                 |
| 1813-0121 |      | 3795 K1114A-10.1376MHZ | 1816-1390      | 2037 MCM10147L   | 1818-0851 | 1698 TMS2516-35JL          |
| 1813-0123 |      | 2237 UA78HGKC          | 1816-1398      | 6344 MB7072N     | 1818-0895 | 3811 P2142                 |
| 1813-0124 |      | 2237 UA78H15KC         | 1816-1406      | 3794 AM27S27DC   | 1818-0912 | 2037 MCM68A708L PROGRAMMED |
| 1813-0127 |      | 2237 UA79HGKC          | 1816-1415      | 6344 MB7042N     | 1818-0913 | 3794 AM9124BDC             |
| 1813-0128 |      | 3795 K1100A            | 1816-1416      | 3799 HMI-7611-5  | 1818-0955 | 3799 HM3-6514-9            |

|                |                        |                |                          |                 |                          |
|----------------|------------------------|----------------|--------------------------|-----------------|--------------------------|
| 1813-0129      | 3795 SP6235B           | 1816-1418      | 2910 N82SI29F            | 1818-0977       | 3811 C8755A              |
| 1813-0131      | 3795 K1135A            | 1816-1421      | 1698 SN74LS478N          | 1818-0989       | 3799 HM3-6514-5          |
| 1813-0133      | 2838                   | 7162 1916-1429 | 3199 MMI-76434-5         | 1818-0990       | 3799 KNI-6514-9          |
| 1813-0134      | 3795 K1100A-I.0MHZ     | 1816-1430      | 2037 MCM10145L           | 1818-1009       | 3714 IM65X61-CJN         |
| 1813-0135      | 3795 K100A-18.5MHZ     | 1816-1433      | 3714 IM5623CPE           | 1818-1012       | 2237 4725BPC             |
| 1813-0138      | 2037 MHW592            | 1816-1434      | 2037 MCM10146L           | 1818-1026       | 3811 D2125AL             |
| 1813-0139      | 3795 K100A-IO.0MHZ     | 1816-1435      | 2037 MCM10143L           | 1818-1027       | 3811 02147N-3            |
| 1813-0140      | 5436 SDM857KG          | 1816-1447      | 2037 MCM10139L           | 1818-1062       | 3811 D2758               |
| 1813-0142      | 3285 AD5228D           | 1816-1451      | 2290 29631ADC            | 1818-1090       | 3811 P2141L-3            |
| 1813-0144      | 3795 K1115A-2.5MHZ     | 1816-1456      | 2037 MCM10149L           | 1818-1114       | 4078 MK4118P-3           |
| 1813-0146      | 3795 K1144A-22.0164HZ  | 1816-1458      | 2910 N82S19I             | 1818-1153       | 3811 P2142L              |
| 1913-0147      | 4114 DAC-HA12DC        | 1816-1459      | 6347 HM1047D             | 1818-1162       | 4078 MK4118P-2           |
| 1813-0149      | 1417 HS-400-600KHZ     | 1816-1460      | 3406 DM10415AJ           | 1818-1177       | 4078 MK4118N-2           |
| 1913-0149      | 3795 K1148A-19.6608MHZ | 1816-1461      | 2910 10149F              | 1818-1178       | 4078 MK4118N-3           |
| 1813-0150      | 3714 ICM7209IPA        | 1816-1462      | 6344 MBM10422H           | 1818-1212       | 3811 02148H-3            |
| 1813-0153      | 3795 K11358            | 1816-1467      | 3799 HM3-7643-5          | 1818-1213       | 4018 MK4118P-4           |
| 1813-0154      | 3795 K1100A-29.7984MHZ | 1816-1468      | 1698 TBP18S030J          | 1818-1214       | 4078 MK4118N-1           |
| 1813-0156      | 3795 K1100A-20.0MHZ    | 1916-1469      | 2237 F100142DC           | 1818-1215       | 3811 D2141-2             |
| 1813-0160      | 3406 DH0034CD          | 1816-1475      | 2910 N82S137AN           | 1818-1238       | 3811 P2114AL-3           |
| 1813-0161      | 3444 CO-233ME-40.0MHZ  | 1816-1481      | 3799 HMI-7649-5          | 1818-1254       | 3811 D2732-6             |
| 1813-0162      | 3444 CO-233ME-80.0MHZ  | 1816-1482      | 2910 N82S131F            | 1818-1300       | 39 UPD2114L-3            |
| 1813-0163      | 3444 CO-233ME-8.0MHZ   | 1816-1492      | 6344 MBM10474            | 1818-1330       | 39 UPD444C-1             |
| 1813-0164      | 3795 K1100A-2.0MHZ     | 1816-1495      | 3794 AM27S07APC          | 1818-1334       | 4078 MK4332P-3           |
| 1813-0166      | 3795 K1145A-22.016MHZ  | 1819-0036      | 2910 CG725Y MASKED       | 1818-1335       | 8831 35392CP             |
| 1813-0167      | 1417 HS-200-1.8432MHZ  | L818-0061      | 3406 MM5241ABLN          | 1818-1336       | 3406 MM5204D             |
| 1813-0168      | 8661                   | 7516 1818-0093 | 2237 3341DC              | 1818-1346       | 39 UP0444/6514           |
| 1813-0170      | 1869 PE-21217          | 1818-0094      | 575 PR1472B-01           | 1818-1350       | 6354 TC5514P             |
| 1813-0189      | 7915 HY-5002           | 1819-0095      | 575 PT1482B-01           | 1818-1351       | 3714 IM6654-11JG         |
| 1813-0193      | 7397 TTLOM-200         | 1818-0102      | 1698 TMS4103NC           | 1818-1370       | 3799 HMI-6514-5          |
| 1813-0197      | 7397 TTLDM-100         | 1819-0103      | 1698 TMS4030JL           | 1818-13720407B  | MK4801P-90               |
| 1813-0199      | 7915 HY-5003           | 1818-0106      | 3406 MM5261N             | 1818-1396       | 39 UP416C-2(SELECTED)    |
| 1813-0211      | 2037 MWA110            | 1814-0107      | 3714 IM7512CPE           | 1818-1397       | 39 UP416C-3(SELECTED)    |
| 1813-0212      | 2037 MWA120            | 1918-0108      | 2037 6605L-1             | 1818-1398       | 1698 TMS4044NL-45        |
| 1813-0213      | 2037 MWA130            | 19113-011      | 4078 MK4096-3            | 1818-1424       | 3811 D2118-4 (SELECTED)  |
| 1813-0214      | 2037 MWA210            | 1818-0115      | 3677 P1103A              | 1818-1425       | 3811 D2118-7 (SELECTECI  |
| 1813-0215      | 2037 MWA220            | 1818-0128      | 3811 C2107B              | 1818-1467       | 39 UP416C-1(SELECTED)    |
| 1813-0216      | 2037 MWA230            | 1818-0134      | 3406 M141101A/ALN        | 1818-1468       | 3811 02148HL             |
| 1813-0217      | 2037 MWA310            | 1818-0135      | 2037 MCM68A10L           | 1818-1520       | 3714 IM6653JG            |
| 1813-0218      | 2037 MWA320            | 1818-0140      | 1795 SYP2112A-4          | 1818-1559       | 6347 HM4864-3 (SELECTED) |
| 1813-0219      | 2037 MWA330            | 1818-0146      | 1698 TMS4050JL SELCTD    | 1818-1581       | 1698 TMS2532JDL-35       |
| 1813-0229      | 7397 TTLDM-40          | 1818-0147      | 1698 TMS4050NL           | 1818-1583       | 6354 TC5504P-1           |
| 1816-0015      | 3799 HPROM1-1024-5B    | 1818-0155      | 2910                     | 26068 1818-1586 | 3811 D214713-1           |
| 1816-0016      | 2910 N82SI23F          | 1818-0165      | 1698 TMS4060JL SELECTED  | 1818-1596       | 6347 HM6147P-3           |
| 1816-0041      | 4092 6300-1J PROGRAMME | 1919-0181      | 1698 TMS4050-1JL SELCTD  | 1818-1611       | 6347 HM6116P-3           |
| 1816-0053      | 3714 IM5600CPE PROGRAM | 1819-0197      | 3794 AM91L11BDC          | 1918-1614       | 4078 MK4801AN-90         |
| 1816-0129      | 4092 6300-IJ           | 1818-0198      | 3406 MM2102AN-4L         | 1818-1616       | 8831 L8114-4CJ           |
| 1816-0217      | 3714 IM5610CPE         | 1819-0199      | 3794 AM9112APC           | 1818-1628       | 6347 HM4334P-3           |
| 1816-0348      | 4092 6330-1J           | 1818-0237      | 2713 R0-3-2513           | 1818-1633       | 3811 D2732A-3            |
| 1816-03550407B | MK2302P                | 1818-0238      | 3794 AM9102APC           | 1818-1638       | 3811 P2114AL-2           |
| 1816-0409      | 3799 MPROM-8256-50     | 1818-0247      | 1698 TMS4060-2JL         | 1818-1643       | 4078 MK4802-3N           |
| 1816-0439      | 4092 6340-IJ           | 1818-0250      | 3811 D2708               | 1818-1648       | 3811 D2732A              |
| 1816-0598      | 1698 SN74S200N         | 1818-0254      | 2910 2516N               | 1818-1660       | 3811 02125H-2            |
| 1816-0605      | 2910 N82S115F          | 1818-0277      | 3794 AM2813ADC           | 1818-1662       | 4078 AK4801AN-70         |
| 1816-0640      | 1698 SN74S189J         | 1814-0279      | 2237 3341ADC             | 1818-1663       | 3811 02125H-1            |
| 1816-0710      | 2910 N82S131F          | 1818-0289      | 3794 AM1702AHDC          | 1818-1667       | 6347 HM6147P             |
| 1816-0723      | 2237 93L415PC          | 1819-0294      | 3794 AM91L12CPC          | 1818-1717       | 6344 MB8164E(SELECTED)   |
| 1816-0724      | 1694 SN74S189N         | 1818-0313      | 3794 AM91L30EDC          | 1818-1718       | 4078 MK4802N-1           |
| 1816-0728      | 2910 N82S09I           | 1818-0317      | 1698 TMS4027-15JL SELCTD | 1818-1721       | 3811                     |
| 1816-0782      | 2910 N82SI29F          | 1818-0318      | 3794 C2101-1             | 1818-172203B11  | 27324                    |
| 1816-0787      | 1698 SN74S289N         | 1818-0319      | 3811 P5101L-3            |                 | 2764                     |
| 1816-0860      | 2037 MCM5004AL         | 1818-0320      | 3794 P2101-2             | 1818-2702       | 3811 D2716-2             |
| 1816-0868      | 3811 P3604L-6 MASKED   | 1819-0322      | 3794 AM91L12APC          | 1820-0001       | 1973 4JX19A555           |
| 1816-0913      | 3794 AM31L01PC         | 1818-0327      | 4078 MK4102P-6           | 1820-0006       | 1973 4JX19A519           |
| 1816-0914      | 2237 934150C           | 18113-032      | 2037 MCM6810AL           | 1820-0010       | 1973 4JX19A581           |
| 1816-0915      | 2910 N82S23F           | 1818-0332      | 3811 02115AL             | 1820-0013       | 2037 MC352G              |
| 1816-0916      | 2910 N82SI23F          | 1818-0334      | 1698 TMS4027-20JL SELCTD | 1820-0044       | 1973 RATA                |
| 1816-0917      | 2910 N82S126F          | 1818-0335      | 3794 AM9102BPC           | 1820-0046       | 1921 CA3005              |
| 1816-0918      | 2910 N82S130F          | 1818-0336      | 2037 MCM6572L            | 1820-0041       | 1921 CA3010              |
|                |                        |                |                          | 1820-0050       | 2037 MC1531G             |

|           |                    |                 |                          |           |                |
|-----------|--------------------|-----------------|--------------------------|-----------|----------------|
| 1816-0919 | 3811 D36244        | 1819-0340       | 1698 TMS4116-25JL SELCTD | 1820-0051 | 2237 702HC     |
| 1816-0928 | 2910 N82S140F      | 1819-0341       | 39 UPD416D-2             | 1820-0052 | 2237 923HC     |
| 1816-0929 | 2910 N82S141F      | 1818-0342       | 3811 P2101A-4            | 1820-0054 | 1698 SN7400N   |
| 1816-0930 | 2910 N82S136F      | 1918-0343       | 3794 AM9101DPC           | 1820-0055 | 1698 SM7490AN  |
| 1816-0931 | 2910 N82S137F      | 1918-0348       | 2237 2102LHPC            | 1820-0056 | 1698 SN7492AN  |
| 1816-0934 | 2237 9403PC        | 1814-0360       | 3794 AM9131CDC           | 1820-0058 | 1991 TOA 2709V |
| 1816-0987 | 3799 HMI-7644-5    | 1818-0381       | 1795 SYP2111A-2          | 1820-0063 | 1698 SN7451 N  |
| 1816-0993 | 2237 934480C       | 1818-0389       | 3794 AN9130EDC           | 1820-0065 | 1698 SN7470N   |
| 1816-0994 | 4092               | 63357 1818-0390 | 3714 IM6508IDE           | 1820-0067 | 2910 SP631N    |
| 1816-1008 | 1698 TBP18S42J     | 1818-0422       | 2237 33511DC             | 1820-0068 | 1698 SN741 0N  |
| 1816-1015 | 2237 93415PC       | 1818-0425       | 3811 P2101A-2            | 1820-0069 | 1698 SN7420N   |
| 1816-1032 | 2910 N82S123N      | 1818-0438       | 1698 TMS2114-45NL        | 1820-0070 | 1698 SN7430N   |
| 1816-1053 | 2037 MCM10144L     | 1818-0439       | 3799 MMI-65618-9         | 1820-0071 | 1698 SN7440N   |
| 1816-1054 | 2910 N82S185F      | 1818-0440       | 3406 MM5269N             | 1820-0072 | 1698 SN7450N   |
| 1816-1055 | 1698 TBP18S42N     | 1818-0443       | 39 UPD2114LC-1           | 1820-0074 | 1698 SN7454N   |
| 1816-1056 | 3799 HPROM1-0512-5 | 1818-0449       | 3811 P4002-1             | 1820-0075 | 1698 SN7473N   |
| 1816-1089 | 3406 DM74LS189N    | 1818-0491       | 1698 TMS27L08JL          | 1820-0076 | 1698 SN7476N   |
| 1916-1137 | 1698 TBP14S10N     | 1818-0492       | 3611 P2114A-4            | 1820-0077 | 1698 SN7474N   |
| 1816-1141 | 1698 SN74188AN     | 1818-0497       | 3799 HM-61351-9DIP       | 1820-0078 | 2910 SP620N    |
| 1816-1142 | 2910 N82S141F      | 1818-0498       | 1698 TMS2516JL           | 1820-0081 | 2237 911HC     |
| 1816-1152 | 3799 HMI-7641-2    | 1818-0508       | 3406 MM5280J-5           | 1820-0083 | 1698 SN7510L   |
| 1816-1153 | 1698 TBP18S03DN    | 1818-0509       | 1698 TMS4116-15JL SELCTD | 1820-0084 | 1698 SN7453N   |
| 1816-1157 | 4092 6350-1J       | 1818-0553       | 1795 SYP2112A            | 1920-0085 | 1698 SN7460N   |
| 1816-1160 | 2910 N82S181F      | 1818-0562       | 3811 P2114A-5            | 1820-0086 | 1698 SN15830N  |
| 1816-1162 | 2910 N82S181N      | 1818-0566       | 2713 ER2051              | 1820-0087 | 2037 MC850P    |
| 1816-1163 | 2910 N82S141F      | 1818-0630       | 4183 NCM7040L            | 1820-0088 | 1698 SN15851N  |
| 1816-1174 | 1698 TBP18SA030N   | 1818-0643       | 3406 MM21 14N-L          | 1820-0094 | 1698 SN15846N  |
| 1816-1193 | 2910 N82S2708F     | 1818-0695       | 2037 MCM145101-1P        | 1820-0095 | 1698 SN15848N  |
| 1816-1240 | 2910 N82S180F      | 1818-0700       | 2031 MCM6581P            | 1820-0096 | 1698 SN15832N  |
| 1816-1299 | 2910 N82S191I      | 1818-0701       | 2037 MCM68A10P           | 1820-0099 | 1698 SN7493N   |
| 1816-1308 | 2237 93L422PC      | 1818-0708       | 39 UPD5101LC             | 1820-0100 | 2037 MC7441AP  |
| 1816-1309 | 2237 93L412PC      | 1818-0735       | 3811 P8155               | 1820-0101 | 2037 MC1034P   |
| 1815-1329 | 1698 TBP18S46N     | 1818-0743       | 1698 TMS2716JL           | 1820-0102 | 2037 MC1013P   |
| 1816-1334 | 2237 93422 DC      | 1818-0753       | 3406 MM74C920N           | 1820-0104 | 2237 UA201HC   |
| 1816-1335 | 2037 MCM10152L     | 1818-0754       | 3406 MM74C910N           | 1820-0106 | 2037 MC816P    |
| 1915-1338 | 2237 10145APC      | 1818-0757       | 2237 21L02FPC            | 1820-0110 | 2237 9590C     |

# INTEGRATED CIRCUIT CROSS REFERENCE

| HP P/N    | Mfr.          | Desc. |           |               |           |                 |
|-----------|---------------|-------|-----------|---------------|-----------|-----------------|
|           |               |       | 1820-0346 | 1698 SN15833N | 1820-0517 | 2237 9865DC     |
|           |               |       | 1820-0348 | 1698 SN15844N | 1820-0518 | 2237 98530C     |
| 1820-0111 | 2037 MC8301P  |       | 1820-0349 | 1698 SN15849N | 1820-0519 | 2237 98220C     |
| 1820-0113 | 1991 TOA3709V |       | 1820-0350 | 1698 SN15861N | 1820-0520 | 2237 9806DC     |
| 1820-0121 | 2910 N8T90N   |       | 1820-0351 | 1698 SN15863N | 1820-0533 | 2037 MC838P     |
| 1820-0122 | 2037 MCS53P   |       | 1820-0352 | 1921 CA3018   | 1820-0535 | 1698 SN75451BP  |
| 1820-0123 | 3406 LM300H   |       | 1820-0357 | 2237 9304PC   | 1820-0536 | 2910 N8284N     |
| 1820-0125 | 2237 711HC    |       | 1820-0361 | 1698 SN4935N  | 1820-0537 | 1698 SN7413N    |
| 1820-0127 | 2237 9002D]   |       | 1820-0362 | 1698 SN7480N  | 1820-0538 | 1698 SN7423N 49 |
| 1820-0128 | 1698 SN15837N |       | 1820-0363 | 1698 SN7482N  | 1820-0539 | 1698 SN7437N    |
| 1820-0129 | 2237 90030C   |       | 1820-0364 | 1698 SN7491AN | 1820-0542 | 2910 N8234N     |
| 1820-0130 | 2237 9004DC   |       | 1820-0365 | 1698 SN7481AN | 1820-0543 | 2910 N8233N     |
| 1820-0131 | 2237 9009DC   |       | 1820-0366 | 1698 SN7494N  | 1820-0544 | 1698 SN74H103N  |
| 1820-0132 | 2237 90160C   |       | 1820-0367 | 1698 SN7495AN | 1820-0545 | 1698 SN74191N   |
| 1820-0134 | 2237 930OPC   |       | 1820-0368 | 1698 SN7496N  | 1820-0546 | 1698 SN74192N   |
| 1820-0137 | 1921 CA30288  |       | 1820-0370 | 1698 SN74H00N | 1820-0567 | 2037 MC4024P    |
| 1820-0138 | 3545 S52      |       | 1820-0371 | 1698 SN74H10N | 1820-0568 | 1698 SN75325N   |
| 1820-0140 | 2037 MC3026P  |       | 1820-0372 | 1698 SN74H11N | 1820-0569 | 2910 N82433     |
| 1820-0141 | 2037 MC3001P  |       | 1820-0373 | 1698 SN74H20N | 1820-0574 | 1698 SN74173N   |
| 1820-0142 | 2037 MC1004P  |       | 1820-0374 | 1698 SN74H21N | 1820-0575 | 2910 N8235N     |
| 1820-0143 | 2037 MC1027P  |       | 1820-0375 | 1698 SN14H30N | 1820-0577 | 1698 SN7416N    |
| 1820-0144 | 2037 MC1018P  |       | 1820-0376 | 1698 SN74H40N | 1820-0578 | 2037 MC1024P    |
| 1820-0145 | 2037 MC1010P  |       | 1820-0377 | 1698 SN74H50N | 1820-0579 | 1698 SN74123N   |
| 1820-0146 | 2037 MC1017P  |       | 1820-0378 | 1698 SN74H51N | 1820-0581 | 2037 MC1032P    |
| 1820-0147 | 2037 MC1007P  |       | 1820-0379 | 1699 SN74H52N | 1820-0582 | 2037 MC1011P    |
| 1820-0157 | 2037 MC1023P  |       | 1820-0380 | 1698 SN74H53N | 1820-0583 | 1698 SN74L00N   |
| 1820-0158 | 3406 LM302H   |       | 1820-0381 | 1698 SN74H54N | 1820-0584 | 1698 SN74L02N   |
| 1820-0160 | 2037 MC1431P  |       | 1920-0382 | 1698 SN74H55N | 1820-0585 | 1698 SN74L03N   |
| 1820-0162 | 3406 LM709H   |       | 1820-0383 | 1698 SN74H60N | 1820-0586 | 1698 SN74L04N   |

|           |                   |           |                |           |                |
|-----------|-------------------|-----------|----------------|-----------|----------------|
| 1820-0174 | 1698 SN7404N      | 1820-0384 | 1698 SN74H61N  | 1820-0587 | 1698 SN74L10N  |
| 1820-0175 | 1698 SN7405N      | 1820-0385 | 1698 SN74H62N  | 1820-0588 | 1698 SN74L20N  |
| 1820-0180 | 2037 MC1015P      | 1820-0386 | 1698 SN74H71N  | 1820-0589 | 1698 SN74L30N  |
| 1820-0181 | 2037 MC1433L      | 1820-0387 | 1698 SN74H72N  | 1820-0590 | 1698 SN74L51N  |
| 1920-0186 | 2237 98560C       | 1820-0391 | 1698 SN74H73N  | 1820-0591 | 1698 SN74L54N  |
| 1820-0187 | 2237 9852DC       | 1820-0396 | 1698 TL702CN   | 1820-0592 | 1698 SN74L55N  |
| 1820-0192 | 1921 CA 3001      | 1820-0397 | 1698 UA709CN   | 1820-0593 | 3406 DM74L71N  |
| 1820-0195 | 2910 N8T80N       | 1820-0398 | 1698 SN72710N  | 1820-0594 | 3406 DM74L 72N |
| 1820-0196 | 2037 MC1723CG     | 1820-0400 | 2910 N8281N    | 1820-0595 | 3406 DM74L73N  |
| 1820-0197 | 2237 709AHM       | 1820-0408 | 2237 727HL     | 1820-0596 | 3406 DM74L74N  |
| 1820-0200 | 2037 MC1030P      | 1820-0410 | 3406 MM507     | 1820-0597 | 3406 DM74L78N  |
| 1820-0201 | 2037 MC1439G      | 1820-0411 | 2037 MC817P    | 1820-0598 | 1698 SN74L86N  |
| 1820-0202 | 2910 SP3228       | 1820-0417 | 1921 CA3002    | 1820-0599 | 3406 DM74L95N  |
| 1820-0203 | 1921 CA741CT      | 1820-0418 | 2037 MC1812P   | 1820-0600 | 3406 DM74L90N  |
| 1820-0204 | 2037 MC3006P      | 1820-0419 | 2910 S8280F    | 1820-0601 | 3406 0M74L93N  |
| 1820-0205 | 2037 MC3003P      | 1820-0424 | 1698 SN74H04N  | 1820-0602 | 3406 DM74LI64N |
| 1820-0207 | 2037 MC8601P      | 1820-0425 | 1698 SN74100N  | 1820-0603 | 3406 DM74L85N  |
| 1820-0208 | 2910 N88264       | 1820-0427 | 2037 MC1496G   | 1820-0604 | 2037 MC3025P   |
| 1820-0211 | 1698 TMS3002LR    | 1820-0429 | 2910 LM309H    | 1820-0605 | 1698 SN74H01N  |
| 1820-0212 | 2037 MC1020P      | 1820-0430 | 2237 LM309K    | 1820-0606 | 1698 SN74181N  |
| 1820-0213 | 2037 MC1014P      | 1820-0433 | 1921 CA3023    | 1820-0607 | 2037 MC4012P   |
| 1820-0214 | 1698 SN7442AN     | 1820-0435 | 1698 SN74180N  | 1820-0608 | 2037 MC4006P   |
| 1820-0218 | 3285 106A         | 1820-0437 | 2037 MC4015P   | 1820-0609 | 2037 MC3061P   |
| 1820-0223 | 1921 CA301AT      | 1820-0439 | 2237 723PC     | 1820-0610 | 2037 MC8309P   |
| 1820-0224 | 3406 LH0002CH     | 1820-0440 | 2037 MC1016P   | 1829-0611 | 1698 SN74182N  |
| 1820-0231 | 2237 9316PC       | 1820-0441 | 2037 MC1801P   | 1820-0612 | 2237 90300C    |
| 1820-0233 | 1698 SN74193N     | 1820-0443 | 1698 SN74L93N  | 1820-0613 | 1698 SN74H05N  |
| 1820-0235 | 2037 MC1031P      | 1820-0444 | 2037 MC1025P   | 1820-0614 | 2237 93L08PC   |
| 1820-0238 | 2037 MC1810P      | 1820-0445 | 1698 SN5402N   | 1820-0615 | 2037 MC8312P   |
| 1820-0239 | 2037 MC3002P      | 1820-0446 | 1698 SN5474N   | 1820-0616 | 2237 9322PC    |
| 1820-0240 | 1921 CA3026       | 1820-0447 | 1698 SN5410N   | 1820-0617 | 2037 MC3022P   |
| 1820-0242 | 3406 LM301AH, 22V | 1820-0448 | 1698 SN5400N   | 1820-0618 | 1698 SN7417N   |
| 1820-0247 | 3406 LM305H       | 1820-0449 | 2037 MC3060P   | 1820-0619 | 1698 SN74H22N  |
| 1820-0249 | 1921 CA3051       | 1820-0450 | 2910 N8290N    | 1820-0620 | 1698 SN74153N  |
| 1820-0252 | 2037 MC1026P      | 1820-0451 | 2037 MC3062P   | 1820-0621 | 1698 SN7438N   |
| 1820-0253 | 2037 MC1035P      | 1820-0454 | 2037 MC1805P   | 1820-0622 | 1698 SN74151AN |
| 1820-0256 | 1698 SN15858N     | 1820-0455 | 2910 N8288N    | 1820-0623 | 3406 DM8200N   |
| 1820-0257 | 2037 MC857P       | 1820-0456 | 2910 N8855N    | 1820-0625 | 2037 MC666P    |
| 1820-0258 | 1698 SN15882N     | 1820-0457 | 2910 N8162N    | 1820-0626 | 2037 MC8314P   |
| 1820-0259 | 2037 MC840P       | 1820-0458 | 2910 N8816N    | 1820-0627 | 2237 95L01PC   |
| 1820-0260 | 2037 MC839P       | 1820-0459 | 2910 N8440N    | 1820-0628 | 1698 SN7489N   |
| 1820-0261 | 1698 SN74121N     | 1820-0460 | 2910 N84S0N    | 1820-0629 | 1698 SN74S112N |
| 1820-0262 | 3406 DM8590N      | 1820-0461 | 2910 N8880N    | 1820-0630 | 2037 MC4044P   |
| 1820-0269 | 1698 SN7403N      | 1820-0462 | 2910 N8251 N   | 1820-0631 | 1698 SN74H108N |
| 1820-0270 | 2237 733HC        | 1820-0463 | 2910 N8H70N    | 1820-0637 | 2910 N8875N    |
| 1820-0272 | 2037 MC1022P      | 1820-0464 | 2910 N8H90N    | 1820-0639 | 2037 MC4001P   |
| 1820-0273 | 2037 MC1806P      | 1820-0465 | 2910 Na*808    | 1820-0640 | 1698 SN74150N  |
| 1820-0274 | 2037 MC1808P      | 1920-0466 | 2910 N8825N    | 1820-0655 | 1698 SN7425N   |
| 1820-0275 | 2037 MC1039P      | 1820-0467 | 2910 N8881N    | 1820-0656 | 1698 SN74L98N  |
| 1820-0276 | 2037 MC1033P      | 1820-0468 | 1698 SN7445N   | 1820-0657 | 2237 9318PC    |
| 1820-0279 | 1698 TIXL105      | 1820-0469 | 1698 SN74H102N | 1820-0658 | 2237 93L12PC   |
| 1820-0281 | 1698 SN74107N     | 1820-0470 | 3285 118A      | 1820-0659 | 2237 93L00PC   |
|           |                   | 1820-0471 | 1698 SN7406N   | 1820-0661 | 1698 SN7432N   |
| 1820-0282 | 1698 SN7486N      | 1820-0472 | 2037 MC1001P   | 1820-0665 | 2037 MC1814P   |
| 1820-0287 | 2037 MC672P       | 1820-0473 | 2037 MC1048P   | 1820-0666 | 2037 MC1006P   |
| 1820-0288 | 2037 MC662P       | 1820-0474 | 1921 CA3012    | 1820-0667 | 2037 MC1040P   |
| 1820-0294 | 2237 74164PC      | 1820-0475 | 3406 LM306H    | 1820-0668 | 1698 SN7407N   |
| 1820-0297 | 1921 CA3000       | 1820-0476 | 2237 715HC     | 1820-0669 | 2237 93L10PC   |
| 1820-0298 | 1921 CA3020       | 1820-0477 | 39UPC301AC     | 1820-0681 | 1698 SN74S00N  |
| 1820-0301 | 1698 SN7475N      | 1820-0478 | 3406 LM308H    | 1820-0682 | 1698 SN74S03N  |
| 1820-0302 | 2910 SP670N       | 1820-0479 | 2037 MC835P    | 1820-0683 | 1698 SN74S04N  |
| 1820-0303 | 2910 SP680N       | 1820-0482 | 2237 98380C    | 1820-0684 | 1698 SN74S05N  |
| 1820-0304 | 1698 SN7472N      | 1820-0484 | 1698 SN7484AN  | 1820-0685 | 1696 SN74S10N  |
| 1820-0305 | 1698 SN7483AN     | 1820-0485 | 2237 98169C    | 1820-06H6 | 1698 SN74S11N  |
| 1820-0306 | 1921 CA3028A      | 1820-0486 | 2237 9834DC    | 1820-0687 | 1698 SN74S15N  |
| 1820-0307 | 1698 SN15836N     | 1820-0488 | 2237 98420C    | 1820-0688 | 1698 SN74S20N  |
| 1820-0308 | 1698 SN15845N     | 1820-0491 | 1698 SN74145N  | 1820-0689 | 1698 SN74S22N  |
| 1820-0309 | 2237 9600C        | 1820-0492 | 2910 N8291N    | 1820-0690 | 1698 SN74S40N  |

|           |                |           |                 |                |                |
|-----------|----------------|-----------|-----------------|----------------|----------------|
| 1820-0310 | 1698 SN15862N  | 1820-0493 | 3406 LM307N     | 1820-0691      | 1698 SN74S64N  |
| 1820-0313 | 2237 931HC     | 1820-0494 | 2585            | 2100 1820-0692 | 1698 SN74S65N  |
| 1820-0316 | 2037 MC1433G   | 1820-0495 | 1698 SN74154N   | 1820-0693      | 1698 SN74S74N  |
| 1820-0317 | 2037 MC1433P   | 1820-0497 | 1698 SN74L95N   | 1820-0694      | 1698 SN74S86N  |
| 1820-0318 | 2910 SP616N    | 1820-0498 | 4200 UM1500     | 1820-0695      | 1698 SN74S113N |
| 1820-0319 | 2910 SP629N    | 1820-0505 | 3406 DM8220N    | 1820-0696      | 1698 SN74S114N |
| 1820-0320 | 2910 SP659N    | 1820-0506 | 2037 MC8266P    | 1820-0697      | 1698 SN74S140N |
| 1820-0321 | 1698 SN72710L  | 1820-0507 | 2910 N8263N     | 1820-0700      | 2037 MC3029P   |
| 1820-0322 | 2910 N8280N    | 1820-0508 | 2910 N8202N     | 1820-0701      | 2237 93L14PC   |
| 1820-0323 | 2037 MC889P    | 1820-0509 | 2037 MC1488L    | 1820-0702      | 2237 93L11PC   |
| 1820-0324 | 2037 MC824P    | 1820-0510 | 2037 NC1489L    | 1820-0703      | 2910 N8292N    |
| 1920-0325 | 2037 MC815P    | 1820-0511 | 1698 SN7408N    | 1820-0704      | 1698 SN74122N  |
| 1820-0326 | 1921 CA3029    | 1820-0512 | 1698 SN 74H 74N | 1820-0705      | 2037 MC8310P   |
| 1820-0327 | 1698 SN7401N   | 1820-0513 | 1698 SN7409N    | 1820-0706      | 2237 9324PC    |
| 1820-0328 | 1698 SN7402N   | 1820-0514 | 1698 SN7426N    | 1820-0707      | 1698 SN74141N  |
| 1820-0341 | 1698 SN158094N | 1820-0515 | 2037 MC8602P    | 1820-0708      | 2237 93L09PC   |
| 1820-0342 | 1698 SN158097N | 1820-0516 | 2237 91120C     | 1820-0709      | 2237 93L28PC   |

12  
INTEGRATED CIRCUIT CROSS REFERENCE  
HP P/N Mfr.

| HP P/N         | Mfr. | Desc.          |                |                 |                |                        |
|----------------|------|----------------|----------------|-----------------|----------------|------------------------|
| 1820-0710      |      | 2237 93L22PC   | 1820-0897      | 2037 MC1047P    | 1820-1037      | 1698 SN7446AN          |
| 182D-0713      |      | 1698 SN74163N  | 1820-0898      | 2237 9305PC     | 1820-1038      | 1698 SN7448N           |
| 1820-0715      |      | 1698 SN74H106N | 1820-0899      | 1698 SN74160N   | 1820-1042      | 1698 SN74165N          |
| 1820-0716      |      | 1698 SN74161N  | 1820-0900      | 2910 SP370N     | 1820-1043      | 3406 DM5406N           |
| 1820-0717      |      | 3406 MM5052    | 1820-0902      | 1698 SN75450BN  | 1820-1044      | 2237 9621DC            |
| 1820-0718      |      | 3406 DS0025CN  | 1820-0903      | 1698 SN74L164N  | 1820-10450291D | N8273N                 |
| 1820-0719D2037 |      | MC7242P        | 1820-0904      | 2237 93L24PC    | 182D-1046      | 1698 SN74156N          |
| 1820-0720      |      | 1698 SN75183N  | 1820-0906      | 3406 DM8214N    | 1820-1047      | 3406 OM74L42AN         |
| 1820-0721      |      | 3406 DS8820AN  | 1820-0907      | 1698 SN7412N    | 1820-1048      | 2290 8T20              |
| 1820-0722      |      | 1698 SN75109N  | 1820-09080203T | MC7479P         | 1820-1049      | 1698 SN74367N          |
| 1820-0723      |      | 1698 SN75107AN | 1820-0909      | 1698 SN74167N   | 1820-1050      | 1698 SN75454BP         |
| 1820-0724      |      | 2037 MC4007P   | 1820-0910      | 1698 SN74LS83AN | 1820-1052      | 2037 MC10125L          |
| 1920-0725      |      | 1698 SN74170J  | 1820-0811      | 1698 SN74L192N  | 1820-1053      | 1698 SN7414N           |
| 1820-0726      |      | 1699 SN74199N  | 1820-0912      | 1698 SN74L193N  | 1820-1056      | 1698 SN74132N          |
| 1820-0727      |      | 2237 9321PC    | 182D-0913      | 1698 SN74L122N  | 1820-1057      | 3406 DM86L76N          |
| 1820-0730      |      | 2237 96L02DC   | 1620-0914      | 2037 MC8307P    | 1820-1062      | 3794 C2401             |
| 1820-0733      |      | 3406 MM1402AD  | 1820-0916      | 2037 MC1062P    | 1820-1063      | 2237 9313PC            |
| 1820-0734      |      | 1698 SN74190N  | 1820-0917      | 2037 MC1065P    | 1820-1064      | 1698 SN74164N          |
| 1820-0737      |      | 2237 9348PC    | 1820-0919      | 2037 MC1650L    | 1820-1065      | 3406 DS0026CG          |
| 1820-0738      |      | 1698 SN74155N  | 1820-092002D37 | MC1692L         | 1820-1066D2237 | 7411PC                 |
| 1820-0739      |      | 1698 SN74H101N | 1820-0921      | 1698 SN7485N    | 1820-1067      | 1698 SN54H11J          |
| 1820-0740      |      | 1698 SN74H87N  | 1820-0923      | 2037 MC3002P    | 1820-1068      | 1698 SN54H30J          |
| 1820-0741      |      | 2237 9328PC    | 1820-0924      | 1921 CD4038AE   | 1820-1069      | 1698 SN54H40J          |
| 1820-0742      |      | 2037 MC8308P   | 1820-0925      | 1921 CD4032AE   | 1820-1070      | 1698 SN5430J           |
| 1820-0743      |      | 1698 SN74194N  | 1820-0926      | 1921 CD4008AF   | 1820-1071      | 1698 SN54H74J          |
| 1820-0744      |      | 1698 SN7497N   | 1820-0927      | 1921 C04028AE   | 1820-1072      | 1698 SN74S139N         |
| 1820-0745      |      | 2237 90150C    | 1820-0928      | 1921 C04041AE   | 1820-1073      | 2910 N82S42N           |
| 1820-0751      |      | 1698 SN74196N  | 1820-0929      | 1921 CD4022BE   | 1820-1074      | 1698 SN74128N          |
| 1820-D752      |      | 1698 SN74H76N  | 1820-0930      | 1921 C04026AE   | 1820-1075      | 1698 SN75150P          |
| 1820-0762      |      | 1698 SN74157N  | 1820-0931      | 1921 CD4029BE   | 1820-1076      | 1698 SN74S174N         |
| 1820-0763      |      | 1795 SYM1404A  | 1820-0932      | 1921 CD4033AE   | 1820-1077      | 1698 SN74S157N         |
| 1820-D765      |      | 1698 SN74197N  | 1820-D933      | 1921 CD4017AE   | 1820-1078      | 2237 2102L-2PC         |
| 182D-0770      |      | 3406 MM5006H   | 1820-0934      | 1921 CD4018AE   | 1820-1D79D2037 | MC14501UBCP            |
| 1820-0774      |      | 2910 SP374N    | 1820-0935      | 1921 CD4020BE   | 1820-1080      | 1698 SN75121N SELECTED |
| 1820-0777      |      | 1698 SN74L42N  | 1820-0936      | 1921 C04024BE   | 1820-1081      | 2037 MC8T26AP          |
| 1920-0778      |      | 2237 93L16PC   | 1829-0937      | 1921 CD4040BE   | 1820-1082      | 1698 SN74147N          |
| 1820-0780      |      | 3406 DS8831N   | 1820-0938      | 1921 CD4027BE   | 1820-1083      | 1698 SN54199J          |
| 1820-0781D3714 |      | IM5013CDD      | 1820-0939      | 1921 CD4013BE   | 1820-1084      | 2910 N8T09N            |
| 1820-0782      |      | 1698 SN7427N   | 1920-0940      | 1921 CD4044AE   | 1820-1085      | 2237 9L24DC            |
| 1820-0783      |      | 1698 SN74200N  | 1820-0941      | 1921 CD4045AE   | 1820-1086      | 2634 UHP-408           |
| 1820-0786      |      | 2037 MC7250P   | 1820-0942      | 1921 CD4000AE   | 1820-1087      | 3811 P3208A            |
| 1820-0788      |      | 1698 SN74174N  | 1820-0943      | 1921 CD4023UBE  | 1820-1089      | 1698 SN74279N          |
| 1820-0789      |      | 2910 N8293N    | 1820-0944      | 1921 CD4025UBE  | 1820-1091      | 1698 SN5413J           |
| 1820-0T90      |      | 2037 MC1660L   | 1820-0945      | 1921 CD4037AE   | 1820-1092      | 1698 SN54121J          |
| 1820-0791      |      | 2037 MC1068P   | 1820-0946      | 1921 CD4001UBE  | 1820-1093      | 1698 SN5400J           |
| 1820-0T92      |      | 2037 MC1043P   | 1820-0947      | 1921 CD4030AE   | 1820-1094D1698 | SN5410J                |
|                |      |                | 1820-0948      | 1921 CD4002UBE  | 1820-1095      | 1698 SN5474J           |
|                |      |                | 1820-0949      | 1921 CD4011UBE  | 1820-1096      | 1698 SN54196J          |

|                |                |                |                |                |                 |
|----------------|----------------|----------------|----------------|----------------|-----------------|
| 1820-0793      | 2037 MC1674L   | 1820-0950      | 1921 CD4012UBE | 1820-1097      | 1698 SN5404J    |
| 1820-0794      | 2037 MC1670L   | 1820-0951      | 1921 CD4019BE  | 1820-1098      | 2910 S8292F     |
| 1820-0795      | 2037 MC1664L   | 1820-0952      | 2237 9520C     | 1820-1099      | 1698 SN5408J    |
| 1820-0796      | 2037 MC1662L   | 1820-0953      | 2237 9530C     | 1820-1100      | 1698 SN74298N   |
| 1820-0797      | 2037 MC1672L   | 1820-0954      | 2237 9540J     | 1820-1101      | 1698 SN5402J    |
| 1820-0799      | 1698 SN75452BP | 1820-0955      | 2237 955DC     | 1820-1106      | 2910 3101AN     |
| 1820-0801      | 2037 MC10101P  | 1820-0956      | 2237 9560C     | 1820-1107      | 1698 SN74166N   |
| 1820-0802      | 2037 MC10102P  | 1820-0957      | 2237 957DC     | 1820-1108      | 2037 MC1648P    |
| 1820-0803      | 2037 MC10105P  | 1820-0958      | 1921 CD4042AF  | 1820-1109      | 2037 MC4022P    |
| 1820-D804      | 2037 MC10106P  | 1820-0959      | 1921 CD4036AD  | 1920-1110      | 1698 SN75110AN  |
| 1820-0805      | 2037 MC10107P  | 1820-0960      | 1921 CD4039AD  | 1820-1111      | 2237 93L4000    |
| 1820-0806      | 2037 MC10109P  | 182D-0961      | 1921 CD4021AF  | 1820-1112      | 1698 SN74LS74AN |
| 1820-0807      | 2037 MC10110P  | 1820-0962      | 1921 CD4006AE  | 1820-1113      | 3406 DM8553N    |
| 1820-0808      | 2037 MC10111P  | 1820-0963      | 1921 CD4031AE  | 1820-1114      | 2037 MC14516BCP |
| 1820-0809      | 2037 MC10115P  | 1820-0964      | 2237 9640C     | 1820-1115      | 3406 DS8822N    |
| 1820-DBIO      | 2037 MC10116P  | 1820-0965      | 2237 965DJ     | 1820-1116      | 1698 SN74109N   |
| 1820-081102D37 | MC10117P       | 1820-0966      | 2237 9660C     | 1820-1117      | 2237 9L86PC     |
| 1820-0812      | 2037 MC10118P  | 1820-0967      | 2237 967DC     | 1820-1119      | 2037 MC1648L    |
| 1820-0813      | 2037 MC10119P  | 1820-0968      | 2237 9680C     | 1820-1120      | 2634 UHP-402    |
| 1820-0815      | 2037 MC10121P  | 1820-0969      | 1921 CD4035AE  | 1920-1121      | 1698 SN74125N   |
| 1820-0816      | 2037 MC10130P  | 1820-0970      | 1921 CD4014AE  | 1820-1122      | 2037 MC14518BCP |
| 1820-0817      | 2037 MC10131P  | 1820-0971      | 2237 9710C     | 1920-1123D4078 | MK5009N         |
| 1820-0818      | 2037 MC10133L  | 1820-0972      | 2237 9520C     | 1820-1124      | 1698 SN74334    |
| 1820-0819      | 2037 MC10134L  | 1820-0973      | 2237 9530C     | 1820-1129      | 2763 334CJ      |
| 1820-0820      | 2037 MC10135L  | 1820-0974      | 2237 9560C     | 1820-1130      | 1698 SN74S133N  |
| 1820-0821      | 2037 MC10136L  | 1820-0975      | 2237 967DC     | 1820-1131      | 3406 DMS160N    |
| 1820-0822      | 2037 MC10137L  | 1820-0976      | 1921 CD4015BE  | 1820-1132      | 2037 MC1690L    |
| 1820-0824      | 2037 MC10140AL | 1820-D977      | 1921 CD4034AE  | 1820-1137      | 1698 SN15809N   |
| 1820-0825      | 2037 MC10141L  | 1820-0978      | 1921 CD4007AE  | 1820-1140      | 2910 N82S62N    |
| 1820-0826      | 72037 NC10160L | 1820-0979      | 1921 C04009AF  | 1820-1141      | 1698 SN74185AN  |
| 1820-0827      | 2037 MC10161P  | 1820-0980      | 1921 CD4010AF  | 1820-1142      | 1698 SN74L46N   |
| 1820-0828      | 2037 MC10162P  | 1820-0981      | 1921 CD4016AE  | 1820-1143      | 3406 DM8552N    |
| 1820-0829      | 2037 MC10164L  | 1820-0984      | 2037 MC7270P   | 1820-1144      | 1698 SN74LS02N  |
| 182D-0830      | 2037 MC10179L  | 1820-09850203T | MC1800P        | 1820-1145      | 1921 CD4049UBE  |
| 1820-0831      | 2037 MC10181L  | 1820-0986      | 3406 DM86L75N  | 1820-1146      | 1921 CD4050BE   |
| 1820-0832      | 3406 MH0007C   | 1820-0987      | 2237 93L18PC   | 1820-1148      | 3406 DM8090N    |
| 1820-0833      | 2237 9334PC    | 1820-0988      | 2237 934100C   | 1820-1149      | 3406 MM5260N    |
| 1820-0834      | 2037 MC4038P   | 1820-0989      | 2910 N8271N    | 1820-115002D37 | MC145208CP      |
| 1920-0935      | 2910 N8267N    | 1820-0990      | 1698 SN75189AJ | 1820-1155      | 2910 N82S90N    |
| 1820-0836      | 2037 MC4010P   | 1820-0992      | 1698 SN5490N   | 1820-1156      | 2037 MC2257L    |
| 1820-08370291D | N8815N         | 1820-0993      | 4078 MK6036P   | 1820-1157      | 2037 MC2259L    |
| 1820-0839      | 1698 SN74175N  | 1820-0995      | 1698 SN7447AN  | 1820-1158      | 1698 SN74S51N   |
| 1820-0842      | 2037 MC4008P   | 1820-0998      | 1698 SN74S153N | 1820-1162D3406 | MM5057N         |
| 1820-0843      | 2037 MC4002P   | 1820-0999      | 1698 SN74S181N | 1820-1163      | 1698 SN74L153N  |
| 1820-0844      | 1698 SNG82N    | 1820-1002      | 1698 SN74104N  | 1820-1165      | 3406 MM5013N    |
| 1820-0845      | 2910 N822DN    | 1820-1004      | 1698 SN7404V   | 1820-1166      | 3406 0M85L51N   |
| 1820-0846      | 3406 DM8094N   | 1820-1005      | 2237 96240C    | 1820-1167      | 3406 DM81L23N   |
| 182D-0847      | 1698 SN74H183N | 1820-1006      | 3794 AM1101A   | 1820-1170      | 2037 MMH0026L   |
| 1820-0856      | 1698 SN7400J   | 1920-1007      | 2290 RC8T23MP  | 1820-1171      | 1698 SN74143N   |
| 1820-0857      | 1698 SN7420J   | 1820-1008      | 2910 3207N     | 1820-1172      | 2237 5416DM     |
| 1820-0858      | 1698 SN7476J   | 1820-1009      | 2237 95H9000   | 1820-1173      | 2037 MC10124L   |
| 1820-0859      | 1698 SN7474J   | 1820-1015      | 1698 SN74S158N | 1820-1174      | 1698 TMS-4024NC |
| 1820-0860      | 2037 MC851L    | 1820-1016      | 1698 SN75453BP | 1820-1175      | 2037 MC14522BCP |
| 1820-0861      | 2037 MC846L    | 1820-1017      | 2237 93L21PC   | 1820-1176      | 2037 MC14015BCP |
| 1. 820-0862    | 2037 MC848L    | 1820-10200203T | MCM4256AL      | 1820-1178      | 1698 TMS3122NC  |
| 1820-0863      | 2037 MC858L    | 1820-1021      | 3406 DS8800H   | 182D-11810203T | MC14522BAL      |
| 182D-0864      | 1698 SN7403J   | 1820-1022      | 1698 SN5404N   | 1820-1183      | 2037 MC4016P    |
| 1820-0865      | 2037 MC844L    | 1820-1023      | 1698 SN5493N   | 1820-1184      | 1698 SN7428N    |
| 1820-0866      | 2037 MC849L    | 1820-1024      | 1698 SN54160N  | 1820-1185      | 1698 SN74162N   |
| 1820-0867      | 1698 SN74H40J  | 1820-1025      | 2037 MC1210L   | 1820-1186      | 1698 TMS3113NC  |
| 1820-0868      | 2037 MC1801L   | 1820-1026      | 2037 MC1213L   | 1820-1187      | 2910 SP380N     |
| 1820-0869      | 2037 MC835L    | 1820-1027      | 1698 SN74195N  | 1820-1188      | 1921 CD4046AF   |
| 1920-0870      | 1698 SN7408J   | 1820-1030      | 2290 RC8T24MP  | 1820-1189      | 2037 MC14510BCP |
| 1820-0875      | 2237 960ODC    | 1820-1031      | 2037 MC3007P   | 1820-1190      | 3406 MM74C173N  |
| 1820-0876      | 1698 SN74L75N  | 1820-1032      | 1698 SN74198N  | 1820-1191      | 1698 SN74S175N  |
| 1820-0894      | 1698 SN7404J   | 1820-1036      | 2037 MC1019P   | 1820-1192      | 1698 SN74173N   |

INTEGRATED CIRCUIT CROSS REFERENCE

| HP P/N    | Mfr. | Desc.            |           |                   |                  |
|-----------|------|------------------|-----------|-------------------|------------------|
| 1820-1193 |      | 1698 SN74LS197N  | 1820-1310 | 1698 SN75108BN    | 1820-1445        |
| 1820-1194 |      | 1698 SN74LS193N  | 1820-1313 | 1921 CD4053BE     | 1820-1446        |
| 1820-1195 |      | 1698 SN74LS175N  | 1820-1314 | 1921 CD4052BE     | 1820-1447        |
| 1820-1196 |      | 1698 SN74LS174N  | 1820-1315 | 1921 CD4051BE     | 1820-1448        |
| 1820-1197 |      | 1698 SN74LS00N   | 1820-1316 | 1921 CD4048AE     | 1820-1449        |
| 1820-1198 |      | 1698 SN74LS03N   | 1820-1317 | 1921 CD4047AE     | 1820-1450        |
| 1820-1199 |      | 1698 SN74LS04N   | 1820-1318 | 1921 CD4045AE     | 1820-1451        |
| 1820-1200 |      | 1698 SN74LS05N   | 1820-1319 | 1698 SN74S151N    | 1820-1452        |
| 1820-1201 |      | 1698 SN74LS08N   | 1820-1320 | 2037 MC10216L     | 1820-1453        |
| 1820-1202 |      | 1698 SN74LS10N   | 1820-1321 | 1698 SN74S85N     | 1820-1454        |
| 1820-1203 |      | 1698 SN74LS11N   | 1820-1322 | 1698 SN74S02N     | 1820-1455        |
| 1820-1204 |      | 1698 SN74LS20N   | 1820-1323 | 1698 SN74S30N     | 1820-1456        |
| 1820-1205 |      | 1698 SN74LS21N   | 1820-1324 | 1698 SN74S124N    | 1820-1457        |
| 1820-1206 |      | 1698 S474LS27N   | 1820-1325 | 1921 CD4066AE     | 1820-1458        |
| 1820-1207 |      | 1698 SN74LS30N   | 1820-1327 | 2037 MC14530BCP   | 1820-1459        |
| 1820-1208 |      | 1698 SN74LS32N   | 1820-1328 | 2037 MC14526BCP   | 1820-1460        |
| 1820-1209 |      | 1698 SN74LS38N   | 1820-1329 | 2037 MC14515BCP   | 1820-1461        |
| 1820-1210 |      | 1698 SN74LS51N   | 1820-1330 | 2037 MC14507CP    | 1820-1462        |
| 1820-1211 |      | 1698 SN74LS86N   | 1820-1331 | 1921 CD4054BE     | 1820-1463        |
| 1820-1212 |      | 1698 SN74LS112AN | 1820-1332 | 2037 MC4018P      | 1820-1464        |
| 1820-1213 |      | 1698 SN74LS113AN | 1820-1334 | 2037 MC1694L      | 1820-1465        |
| 1820-1214 |      | 1698 SN74126N    | 1820-1336 | 2237 4011BDC      | 1820-1466        |
| 1820-1215 |      | 1698 SN74LS136N  | 1820-1337 | 2910 N8200N       | 2237 40174PC     |
| 1820-1216 |      | 1698 SN74LS138N  | 1820-1338 | 2910 N82S50N      | 2910 N82S83N     |
| 1820-1217 |      | 1698 SN74LS151N  | 1820-1340 | 2037 MC14585BCP   | 3406 DM8542      |
| 1820-1218 |      | 1698 SN74LS157N  | 1820-1344 | 2037 MC12040L     | 1698 SN74LS107AN |
| 1820-1219 |      | 575 TR1602A      | 1820-1346 | 1698 TMS3120NC    | 1820-1470        |
| 1820-1220 |      | 2910             | 1820-1347 | 2237 9356PC       | 1820-1471        |
| 1820-1221 |      | 3811 08008-1     | 1820-1348 | 3406 MM5307N      | 2037 MC14539BCP  |
| 1820-1222 |      | 2237 95040C      | 1820-1349 | 3406 DM85L54N     | 1820-1472        |
| 1820-1224 |      | 2037 MC10216P    | 1820-1353 | 3406 AH5024CN     | 3406 DM85L52N    |
| 1820-1225 |      | 2037 MC10231P    | 1820-1355 | 2037 MC14532BCP   | 1820-1473        |
| 1820-1227 |      | 2037 MC1037P     | 1820-1356 | 2037 MC14528BCP   | 1698 SN74LS93N   |
| 1820-1228 |      | 2910 2602N       | 1920-1357 | 3406 AM3705CD     | 2037 MC14553BCP  |
| 1920-1229 |      | 1698 SN74111N    | 1820-1358 | 2237 93L34PC      | 2037 MC6800L     |
| 1820-1230 |      | 1698 SN75491N    | 1820-1359 | 2037 MC10174P     | 1920-1481        |
| 1820-1231 |      | 1698 SN75492N    | 1820-1360 | 2910 N8T09N       | 2037 MC6821L     |
| 1820-1232 |      | 1698 TMS0105NC   | 1820-1361 | 2237 9374PC       | 2037 MC10211P    |
| 1920-1233 |      | 1698 SN74L47N    | 1820-1362 | 2838 220-VI2QZ    | 1921 CD4071BE    |
| 1820-1234 |      | 2569 IH5035CPA   | 1820-1563 | 3714 IM5013ACDD   | 2237 40098PC     |
| 1820-1235 |      | 2569 IH5018CPA   | 1820-1364 | 3406 MM5313N(75-) | 1820-1485        |
| 1820-1236 |      | 3406 MM5040H     | 1820-1365 | 3406 MM74C157N    | 3406 MM74C221N   |
| 1820-1237 |      | 3406 MM5050AH    | 1820-1366 | 2037 MMH0026CPI   | 1820-1486        |
| 1820-1238 |      | 1698 SN74LS253N  | 1820-1367 | 1698 SN74S08N     | 1921 CD4081BE    |
| 1820-1240 |      | 1698 SN74S138N   | 1820-1368 | 1698 SN74366N     | 1820-1488        |
| 1820-1241 |      | 1921 CD4512BE    | 1820-1370 | 3406 AH0134CD     | 1820-1490        |
| 1820-1242 |      | 2037 MC 12012L   | 1820-1371 | 3406 AH0152CD     | 1698 SN74LS90N   |
| 1820-1243 |      | 1698 SN74LS15N   | 1820-1372 | 2237 74S109DC     | 1820-1491        |
| 1820-1244 |      | 1698 SN74LS153N  | 1820-1373 | 2237 93S10DC      | 1698 SN74LS367AN |
| 1820-1245 |      | 1698 SN74LS155N  | 1820-1374 | 3285 AD7510DIJN   | 1820-1492        |
| 1820-1246 |      | 1698 SN74LS09N   | 1820-1575 | 2037 MC3103L      | 3406 MM74C163N   |
| 1820-1247 |      | 1698 SN74L123N   | 1823-1376 | 2237 93L10DM      | 2037 MC14020BCP  |
| 1820-1249 |      | 2910 N82S33N     | 1820-1377 | 2237 93L14DM      | 2037 MC14040BCP  |
| 1820-1250 |      | 1698 SN74136N    | 1820-1378 | 1698 SN54192N     | 2037 MC14027BCP  |
| 1920-1251 |      | 1698 SN74LS196N  | 1820-1379 | 1698 SN5408N      | 1820-1497        |
| 1820-1252 |      | 2883 LD110CJ     | 1920-1380 | 1698 SN5496N      | 2037 MC14013BCP  |
| 1820-1253 |      | 1698 SN54S00J    | 1820-1381 | 1648 SN5432N      | 2037 MC14025UBCP |
| 1820-1254 |      | 3406 DM8095N     | 1120-1383 | 2037 MC10138L     | 2037 MC14001UBCP |
| 1820-1255 |      | 1698 SN74368N    | 1820-1384 | 1590 SP8641H      | 2037 MC14016BCP  |
| 1820-1256 |      | 1698 SN7422N     | 1820-1385 | 2037 MC11502BCP   | 2037 MC14049UBCP |
| 1820-1257 |      | 1698 SN74159N    | 1820-1386 | 2037 MC14506BCP   | 2037 MC14024BCP  |
| 1820-1258 |      | 1698 SN74178N    | 1920-1387 | 2037 MC14519BCP   | 2037 MC14012UBCP |
| 1820-1259 |      | 1698 SN74179N    | 1820-1388 | 2037 MC14071CP    | 2037 MC140178CP  |
| 1820-1260 |      | 1698 SN74221N    | 1820-1389 | 2037 MC14583BCP   | 2037 MC14023UBCP |
| 1820-1261 |      | 1698 SN74283N    | 1820-1390 | 3406 MM74C160N    | 1921 CD4053BF    |
|           |      |                  | 1120-1391 | 3406 MM74C161N    | 2037 MC14002UBCP |
|           |      |                  | 1820-1392 | 3406 MM 74C89N    | 2037 MC14028BCP  |
|           |      |                  |           |                   | 1921 CD4051BE    |

|           |                  |           |                  |           |                 |
|-----------|------------------|-----------|------------------|-----------|-----------------|
| 1820-1262 | 1698 SM74290N    | 1820-1394 | 3406 DM86L99N    | 1820-1514 | 1921 CD4014BE   |
| 1820-1263 | 1698 SN74H15N    | 1820-1395 | 3811 P3404       | 1820-1515 | 1921 CD4556BE   |
| 1820-1264 | 1698 SN74293N    | 1820-1398 | 3794 AM2505PC    | 1820-1516 | 1921 CD4555BE   |
| 1820-1265 | 2037 PC 14527BCP | 1920-1399 | 2037 MC10176P    | 1820-1518 | 3406 DM74L00N   |
| 1820-1266 | 2237 40097PC     | 1920-1400 | 2037 MC10104P    | 1820-1519 | 2037 MC663P     |
| 1820-1267 | 1698 SN74184N    | 1820-1402 | 3406 MM8DC95N    | 1820-1520 | 2037 MC660P     |
| 1820-1268 | 1698 SN74L85N    | 1820-1403 | 1921 CD4072BE    | 1820-1521 | 2037 MC14050BCP |
| 1820-1269 | 1698 SN74L157N   | 1820-1404 | 1921 CD4069UBE   | 1820-1522 | 2037 MC3440P    |
| 1820-1270 | 1698 SN74L121N   | 1820-1405 | 1921 CD4075BE    | 1820-1524 | 2037 MC8602L    |
| 1820-1271 | 1698 SN74143J    | 1820-1407 | 1921 CD4078BE    | 1820-1525 | 2037 MC14008BCL |
| 1820-1272 | 1698 SN74L133N   | 1820-1408 | 1921 CD4073BE    | 1820-1526 | 2037 MC14028BCL |
| 1820-1273 | 1698 SN74LS28N   | 1820-1409 | 1921 CD4082BE    | 1820-1527 | 2037 MC14022BCL |
| 1820-1274 | 1698 SN74LS22N   | 1820-1410 | 1921 CD4068BE    | 1820-1528 | 1921 CD4029BF   |
| 1820-1275 | 1698 SN74S260N   | 1820-1411 | 1698 SN74LS75N   | 1920-1529 | 1921 CD4018AE   |
| 1820-1276 | 1698 SN74LS194AN | 1820-1412 | 2037 MC14556BCP  | 1820-1530 | 1921 CD4027AF   |
| 1820-1277 | 1698 SN74LS192N  | 1820-1413 | 1921 CD45118E    | 1820-1531 | 1921 CD4013AF   |
| 1820-1278 | 1698 SN74LS191N  | 1820-1414 | 1698 SN74LS12N   | 1820-1532 | 1921 CD4044AF   |
| 1820-1279 | 1698 SN74LS190N  | 1820-1415 | 1698 SN74LS13N   | 1820-1533 | 1921 CD4043AF   |
| 1820-1280 | 1698 SN74LS181N  | 1820-1416 | 1698 SN74LS14N   | 1820-1534 | 1921 CD4001AF   |
| 1820-1281 | 1698 SN74LS139N  | 1820-1417 | 1698 SN74LS26N   | 1820-1535 | 1921 CD4025AF   |
| 1820-1282 | 1698 SN74LS109AN | 1820-1418 | 1698 SN74LS42N   | 1820-1536 | 1921 CD4030AF   |
| 1820-1283 | 1698 SN74LS95BN  | 1820-1419 | 1698 SN74LS85N   | 1820-1537 | 1921 CD4002AF   |
| 1820-1284 | 1698 SN74LS55N   | 1820-1420 | 1698 SN74LS92N   | 1820-1538 | 1921 CD4011AF   |
| 1820-1285 | 1698 SN74LS54N   | 1820-1421 | 1698 SN74LS96N   | 1820-1539 | 1921 CD4012AE   |
| 1820-1286 | 1698 SN74LS40N   | 1820-1422 | 1698 SN74LS122N  | 1820-1540 | 1921 CD4042AE   |
| 1820-1287 | 1698 SN74LS37N   | 1820-1423 | 1698 SN74LS123N  | 1820-1541 | 1921 CD4015AF   |
| 1820-1288 | 2037 MMH0026CL   | 1820-1424 | 1698 SN74LS124N  | 1820-1542 | 1921 CD4049AF   |
| 1820-1289 | 2910 N8T14N      | 1820-1425 | 1698 SN74LS132N  | 1820-1543 | 1921 CD4050AF   |
| 1820-1290 | 2237 93S12DC     | 1820-1426 | 1698 SN74LS145N  | 1820-1544 | 1921 CD4076BF   |
| 1820-1291 | 3406 DM8554N     | 1820-1427 | 1698 SN74LS156N  | 1820-1545 | 1921 CD4053BY   |
| 1820-1292 | 3406 DMS520N     | 1820-1428 | 1698 SN74LS158N  | 1820-1546 | 2037 MC14052BCL |
| 1820-1293 | 3406 DM8130N     | 1820-1429 | 1698 SN74LS160AN | 1820-1547 | 2037 MC14051BCL |
| 1820-1294 | 3406 DM8123N     | 1820-1430 | 1698 SN74LS161AN | 1820-1548 | 1921 CD4066AY   |
| 1820-1295 | 3406 DM8121N     | 1820-1431 | 1698 SN74LS162AN | 1820-1549 | 2037 MC14539BCL |
| 1820-1296 | 1698 SN74LS295BN | 1820-1432 | 1698 SN74LS163AN | 1820-1550 | 1921 CD4071BF   |
| 1820-1297 | 1698 SN74LS266N  | 1820-1433 | 1698 SN74LS164N  | 1820-1551 | 1921 CD4081BF   |
| 1820-1298 | 1698 SN74LS251N  | 1820-1434 | 1698 SN74LS668N  | 1820-1552 | 1821 CD40238F   |
| 1820-1300 | 1698 SN74LS195AN | 1820-1435 | 1698 SN74LS669N  | 1820-1553 | 1921 CD4019AF   |
| 1820-1301 | 1698 SN74S257N   | 1820-1436 | 1698 SN74LS170N  | 1920-1554 | 1921 CD4035AF   |
| 1820-1302 | 1699 SN74S251N   | 1820-1437 | 1698 SN74LS221N  | 1820-1555 | 1921 CD4556BF   |
| 1820-1303 | 1698 SN74S195N   | 1820-1438 | 1698 SN74LS257AN | 1820-1556 | 1921 CD4555BF   |
| 1820-1304 | 1698 SN74SI94N   | 1820-1439 | 1698 SN74LS258AN | 1820-1557 | 3811 P8216      |
| 1820-1305 | 1698 SN74S182N   | 1820-1440 | 1698 SN74LS279N  | 1820-1558 | 2037 MC3441AP   |
| 1820-1306 | 1698 SN74S134N   | 1820-1441 | 1698 SN74LS283N  | 1820-1559 | 3406 MM74C164N  |
| 1820-1307 | 1698 SN74S132N   | 1820-1442 | 1698 SN74LS290N  | 1820-1560 | 3406 MM74C165N  |
| 1820-1308 | 2037 MC10116L    | 1820-1443 | 1698 SN74LS293N  | 1820-1561 | 3406 MM74C193N  |
| 1820-1309 | 1698 SN74S258N   | 1820-1444 | 1698 SN74LS298N  | 1820-1562 | 3406 MM74C175N  |

14  
INTEGRATED CIRCUIT CROSS REFERENCE  
HP P/N Mfr.

| HP P/N    | Mfr. | Desc.            | 1820-1753 | 3406 MM74C74N   | 1820-1930 | 2037 MC14078BCP |
|-----------|------|------------------|-----------|-----------------|-----------|-----------------|
|           |      |                  | 1820-1754 | 3677 52350-2    | 1820-1931 | 2037 MC14068BCP |
| 1820-1563 |      | 3406 MM74C14N    | 1820-1755 | 3406 MM5371N    | 1820-1932 | 2037 MC14538BCP |
| 1820-1568 |      | 1698 SN74LS125AN | 1820-1756 | 3406 MM5312N    | 1820-1933 | 3406 MM74C74J   |
| 1820-1569 |      | 2037 MC14538BCL  | 1820-1758 | 2037 MC3245L    | 1820-1934 | 2180 DAC-08EQ   |
| 1820-1570 |      | 2037 MC14532BCL  | 1820-1759 | 3406 DMBILS97N  | 1820-1935 | 3406 MM74C905J  |
| 1820-1573 |      | 2037 MC14558BCP  | 1820-1777 | 2910 N82S83N    | 1820-1936 | 2037 MC14093BCL |
| 1820-1574 |      | 1698 SN74LS73AN  | 1820-1778 | 3406 MM74C914N  | 1820-1937 | 3406 MM74C83J   |
| 1820-1575 |      | 3406 MM74C192N   | 1820-1779 | 2037 MC14411P   |           |                 |
| 1820-1576 |      | 3406 MM74C107N   | 1820-1780 | 2237 11C90DC    | 1820-1942 | 1698 SN74S163J  |
| 1820-1577 |      | 1921 CD4093BF    | 1820-1781 | 3799 H12-200-5  | 1820-1943 | 1698 SN74S169J  |
| 1820-1578 |      | 1921 CD4076BE    | 1820-1782 | 3794 AM26S02PC  | 1820-1944 | 2037 MC10130L   |
| 1820-1579 |      | 3794 AM2803HC    | 1820-1763 | 1698 TMSBOBOANL | 1820-1945 | 2037 MC10115L   |
| 1820-1580 |      | 1698 SN74247N    | 1820-1784 | 1698 SN74LS91N  | 1820-1946 | 2037 MC10117L   |
| 1820-1585 |      | 2910 74123N      | 1820-1785 | 1698 SN74LS261N | 1820-1947 | 2037 MC14490FP  |
| 1820-1586 |      | 2237 4512BPC     | 1820-1766 | 2037 MC3459CP   | 1820-1948 | 1698 TL607CP    |
| 1820-1587 |      | 3406 OM8859N     | 1820-1787 | 1698 SN7427J    | 1820-1949 | 1698 SN74L154N  |
| 1820-1588 |      | 2037 MC14566BCP  | 1820-1788 | 2237 F10016DC   | 1820-1950 | 2037 MC10212P   |



|           |                  |                  |                  |           |                   |
|-----------|------------------|------------------|------------------|-----------|-------------------|
| 1820-1590 | 3406 MM74C14J    | 1820-1789        | 3285 AD7530JN    | 1820-1955 | 1921 CD4008BE     |
| 1820-1591 | 2037 MC14518BCL  | 1820-1791        | 1698 SN74284N    | 1820-1956 | 1921 CD4042BE     |
| 1820-1592 | 2037 MC14069UBCL | 1820-1792        | 1698 SN74285N    | 1820-1957 | 1921 CD4511BE     |
| 1820-1594 | 1698 SN5495AN    | 1820-1793        | 1698 SN74116N    | 1820-1958 | 1921 CD4016BE     |
| 1820-1595 | 1698 SN54H106N   | 1820-1794        | 3406 DM81LS95N   | 1820-1959 | 1921 CD4508BE     |
| 1820-1600 | 1921 CD4093BE    | 1820-1795        | 3406 LF13331     | 1820-1960 | 2037 MC14012BCP   |
| 1820-1601 | 1921 CD4070BE    | 1820-1796        | 3406 DS3611N     | 1820-1961 | 2037 MC14023BCP   |
| 1820-1602 | 1698 SN74LS47AN  | 1820-1797        | 3406 DH0035CG    | 1820-1962 | 1921 CD4028BE     |
| 1820-1603 | 3406 MM74C08N    | 1820-1798        | 1698 SN54LS74AJ  | 1820-1963 | 1921 CD4013BAE    |
| 1920-1604 | 1698 SN74LS48N   | 1820-1799        | 1698 SN54LS02J   | 1820-1964 | 1921 CD4027BE     |
| 1820-1605 | 2037 MC668P      | 1820-1800        | 1698 SN75452BJG  | 1820-1965 | 2037 MC14025BCP   |
| 1820-1606 | 2037 MC667P      | 1820-1804        | 2037 MPQ6842     | 1820-1968 | 3794 AM93S48PC    |
| 1820-1608 | 2910 2533V       | 1820-1806        | 3406 MM74C85N    | 1820-1970 | 2037 MC14071BCP   |
| 1820-1611 | 1698 SN75367N    | 1820-1807        | 2883 DG2008A     | 1820-1971 | 2883 DG201CJ      |
| 1820-1612 | 3406 MM74C221J   | 1820-1810        | 2037 MC3460P     | 1820-1973 | 1698 TL604IP      |
| 1820-1613 | 3811             | 80809 1820-1813  | 2237 4027BDC     | 1820-1974 | 1698 SN74S181J    |
| 1820-1624 | 1698 SN74S241N   | 1820-1815        | 2037 MC14517BCP  | 1820-1975 | 1698 SN74LS165N   |
| 1820-1626 | 3406 MM74C20N    | 1820-1817        | 2910 N8T37N      | 1820-1976 | 1921 CD4050BE     |
| 1820-1627 | 3406 MM74C02N    | 1820-1821        | 1698 SN74LS113AN | 1820-1977 | 2037 MC12061P     |
| 1820-1628 | 350              | 92240% 1820-1823 | 3406 MM80C97J    | 1R20-1978 | 3794 AM25L04PC    |
| 1820-1632 | 2037 MC10178P    | 1920-1826        | 1698 SN75112N    | 1820-1979 | 2237 9368PC       |
| 1820-1633 | 1694 SN74S240N   | 1820-1827        | 3406 MM74C154N   | 1820-1980 | 2910 N82S31N      |
| 1820-1635 | 2037 MC14502BAL  | 1820-1828        | 2910 N8T28N      | 1820-1981 | 3794 AM25S09PC    |
| 1820-1637 | 3795 MC6870A     | 1820-1830        | 2037 MC10210L    | 1820-1982 | 1698 SN75363N     |
| 1820-1638 | 1698 SN74S280N   | 1820-1831        | 2037 MC10103L    | 1820-1984 | 3285 AD561KD      |
| 1820-1639 | 1698 SN74S135N   | 1820-1832        | 2037 MC10212L    | 1620-1985 | 3406 DM85S68J     |
| 1820-1640 | 1698 SN74LS366AN | 1820-1833        | 1698 SN75361AN   | 1820-1986 | 3406 LF13202N     |
| 1820-1641 | 1698 SN74LS365AN | 1820-1834        | 2237 11C70DC     | 1820-1987 | 1698 SN74LS299N   |
| 1820-1642 | 1698 SN74LS324N  | 1820-1838        | 3285 AD562J0/BIN | 1820-1988 | 3406 AH0019CD     |
| 1820-1643 | 1698 SN74LS249N  | 1820-1840        | 2883 DG201CJ     | 1820-1989 | 2237 74LS393PC    |
| 1820-1644 | 1698 SN74LS248N  | 1820-1841        | 2883 DG5068R     | 1820-1990 | 2037 MC10100L     |
| 1820-1645 | 1698 SN74LS126AN | 1820-1842        | 2037 MC3442P     | 1820-1991 | 1698 SN74LS390N   |
| 1820-1646 | 1921 CD4055BE    | 1820-1844        | 39 UPD8251D      | 1820-1992 | 3794 AM25LS160APC |
| 1820-1647 | 1698 SN74LS02J   | 1820-1845        | 3406 DS8834N     | 1820-1993 | 2037 MC10158L     |
| 1820-1648 | 350 XR-2207CP    | 1820-1849        | 2023 MM5873      | 1820-1994 | 1698 SN74LS243N   |
| 1920-1649 | 1921 CD4059AD    | 1820-1850        | 2037 MC145608CP  | 1820-1995 | 3285 9075508C     |
| 1820-1650 | 1921 CD4098BE    | 1820-1851        | 1698 SN74LS148N  | 1820-1997 | 1698 SN74LS374N   |
| 1820-1651 | 3406 MM74C901N   | 1820-1852        | 2037 MC1697P     | 1820-2001 | 3406 MM5307ABN    |
| 1820-1652 | 3406 MM74C902N   | 1820-1854        | 2237 34702DC     | 1820-2002 | 2237 9370PC       |
| 1820-1653 | 3406 MM74C903N   | 1920-1855        | 2037 MC14534BCP  | 1820-2005 | 39 UPD8253D       |
| 1820-1654 | 3406 MM74C904N   | 1820-1857        | 3406 DM8555N     | 1820-2006 | 3794 AM9080A-4DC  |
| 1820-1655 | 3406 MM74C906N   | 1820-1858        | 1698 SN74LS377N  | 1820-2007 | 1698 SN74365N     |
| 1820-1656 | 3406 MM74C907N   | 1820-1859        | 1698 SN74LS280N  | 1820-2008 | 2037 MC14015BCP   |
| 1820-1657 | 2037 MC14572UBCP | 1820-1862        | 2910 82S41A      | 1820-2009 | 2237 4049BPC      |
| 1820-1658 | 2037 MC14541BCP  | 1820-1863        | 2910 8T98B       | 1820-2013 | 2037 MC14051BCP   |
| 1820-1659 | 1921 CD40182BY   | 1820-1864        | 3811 P3212       | 1820-2014 | 2037 MC14069UBCP  |
| 1820-1660 | 1921 CD4067BE    | 1920-1865        | 3794 AM25LS08PC  | 1820-2015 | 2037 MC14070BCP   |
| 1820-1661 | 1921 CD4089BE    | 1820-1866        | 3794 AM25LS07PC  | 1820-2016 | 2237 9401PC       |
| 1820-1662 | 1921 CD4094BE    | 1820-1867        | 3794 AM25LS09PC  | 1820-2017 | 1921 CD4085BF     |
| 1820-1663 | 1921 CD4095BE    | 1820-1868        | 1698 SN74S197N   | 1820-2018 | 1921 CD4096BF     |
| 1820-1664 | 1921 CD4096BE    | 1820-1869        | 1698 SN74S196N   | 1820-2019 | 2037 MC14584BCP   |
| 1820-1665 | 1921 CD4099BE    | 1820-1870        | 3406 DS8839N     |           |                   |
| 1820-1666 | 1921 CD40181BY   | 1820-1871        | 1698 SN74S283N   | 1820-2021 | 2037 MC14520BCP   |
| 1820-1667 | 1921 CD4060AE    | 1820-1872        | 3406 DM81LS96N   | 1820-2023 | 2037 MC10197P     |
| 1820-1668 | 1698 SN74LS74AJ  | 1820-1873        | 3406 DM81LS98N   | 1820-2024 | 1698 SN74LS244N   |
| 1820-1669 | 1698 SN75452BL   | 1820-1874        | 3406 DM8556N     | 1820-2025 | 3714 ICL7101CPL   |
| 1820-1670 | 2237 75492PC     | 1820-1875        | 2910 8T38N       | 1820-2026 | 1698 SN74LS396N   |
| 1820-1672 | 1921 CD4077BE    | 1820-1976        | 3794 AM74S161N   | 1820-2027 | 2237 3853PC       |
| 1820-1673 | 1698 SN75322N    | 1820-1877        | 3794 AM74S160N   | 1820-2030 | 2037 MC6828P      |
| 1820-1674 | 3406 MM74C30N    | 1820-1878        | 1698 SN5423J     | 1820-2031 | 1921 CD4021BE     |
| 1820-1675 | 1921 CD4016AF    | 1820-1879        | 1698 SN54LS00J   | 1820-2032 | 2237 4104PC       |
| 1820-1676 | 1698 SN74S373N   | 1820-1880        | 1698 SN54LS27J   | 1820-2033 | 2037 MC14561BCP   |
| 1820-1677 | 1698 SN74S374N   | 1820-1881        | 1921 CD4097BF    | 1820-2035 | 3811 P3205        |
| 1820-1681 | 575 TR1602A      | 1820-1882        | 2037 MC10113L    | 1820-2036 | 2037 MC6875L      |
| 1820-1682 | 3334 SAA1027     | 1820-1884        | 2910 N8T97N      | 1820-2037 | 2037 MC14081BCP   |
| 1820-1683 | 1921 CD4514BE    | 1820-1885        | 3406 DM74LS173N  | 1820-2038 | 3406 MM74C00J     |
| 1820-1684 | 2237 9LS192PC    | 1820-1887        | 1698 SN75361AP   | 1820-2039 | 3794 AM8224-4PC   |
| 1520-1685 | 2037 MC10195P    | 1820-1888        | 2037 MC12013L    | 1820-2040 | 3406 MM5315N      |

|           |                  |           |                  |                |                 |      |
|-----------|------------------|-----------|------------------|----------------|-----------------|------|
| 1820-1686 | 2037 MC10103P    | 1820-1889 | 1698 SN74LS26N   | 1828-2041      | 3406 DS3612N    |      |
| 1620-1687 | 2037 MC3443P     | 1820-1890 | 1698 SN74LS258AN | 1820-2042      | 1698 SN54LS221J |      |
| 1820-1688 | 1698 SN74LS247N  | 1820-1891 | 1698 SN74LS00N   | 1820-2043      | 1698 SN54197J   |      |
| 1820-1689 | 1698 MC3446P     | 1820-1892 | 1698 SN74LS367N  | 1820-2044      | 1698 SN75461P   |      |
| 1820-1690 | 2037 MC6850L     | 1820-1897 | 1921 CD4024BF    | 1820-2046      | 1698 SN74LS353N |      |
| 1820-1693 | 2037 MC14508BCL  | 1820-1898 | 1921 CD4021BF    | 1820-2047      | 1590 SPS6228DG  |      |
| 1820-1699 | 2237 74LS175PC   | 1820-1899 | 1921 CD4516BF    | 1820-2049      | 2037 SN74LS196N |      |
| 1820-1700 | 2237 74LS174PC   | 1820-1900 | 1921 CD4520BF    | 1820-2050      | 2037 MC14555BCP |      |
| 1820-1701 | 3794 AM908DA-2DC | 1820-1903 | 2237 9368PC      | 1820-2051      | 2037 MC14528BCL |      |
| 1820-1720 | 3406 DM2504CN    | 1820-1905 | 2237 74LS260PC   | 1820-2053      | 2910 74LS154N   |      |
| 1820-1721 | 2037 MC14549BCP  | 1820-1906 | 2237 340098DC    | 1820-2054      | 2037 MC14040BCL |      |
| 1820-1722 | 2037 MC14559BCP  | 1820-1907 | 2037 MC14077BCL  | 1820-2055      | 2037 MC14015BCL |      |
| 1820-1724 | 2883 D6184BP     | 1820-1908 | 2037 MC14070BCL  | 1820-2056      | 1698 SN74LS378N |      |
| 1820-1725 | 2883 DG508CJ     | 1820-1909 | 2037 MC14075BCL  | 1820-2060      | 39 UPD369C      |      |
| 1820-1728 | 1698 SN74278N    | 1820-1910 | 2037 MC14073BCL  | 1820-2064      | 1698 SN54LS174J |      |
| 1820-1729 | 1698 SN74LS259N  | 1820-1911 | 575 TR16028-05   | 1820-2065      | 3406 MM74C151N  |      |
| 1820-1730 | 1698 SN74LS273   | 1820-1912 | 2037 MC14042BCP  | 1820-2066      | 2037 MC1017BL   |      |
| 1820-1731 | 1698 SN74L73N    | 1820-1914 | 1698 SN74LS374N  | 1820-2067      | 2037 MC10162L   |      |
| 1820-1732 | 3794 AM74LS138N  | 1820-1915 | 2037 MC1204L     | 1820-2068      | 1698 SN74LS325N |      |
| 1820-1733 | 3794 AM74LS175N  | 1820-1917 | 1698 SN74LS240N  | 1820-2069      | 3811 P4040      |      |
| 1820-1735 | 3406 MM74C42N    | 1820-1918 | 1698 SN74LS243N  | 1820-2070      | 3811            | 4289 |
| 1920-1739 | 3406 DM8884AN    | 1820-1919 | 39 UPD8255AD     | 1820-2071      | 3811            | 4201 |
| 1820-1739 | 3406 DS8897N     | 1820-1920 | 39 UPD8228D      | 1820-2072      | 3811 P4265      |      |
| 1820-1740 | 3406 DS8863N     | 1820-1921 | 3794             | 8224 1820-2073 | 3811 P4269      |      |
| 1820-1745 | 2037 MC14001BCP  | 1820-1922 | 1698 SN74LS166N  | 1820-2074      | 3811 P8085A     |      |
| 1820-1746 | 2037 MC14049UBCP | 1820-1924 | 2910 M8T93N      | 1820-2075      | 1698 SN74LS245N |      |
| 1820-1747 | 2037 MC14011BCP  | 1820-1925 | 1921 CD4040AF    | 1820-2076      | 3811            | 3242 |
| 1820-1750 | 1698 SN54LS123J  | 1820-1927 | 2237 9S41PC      | 1820-2077      | 3406 DP8212N    |      |
| 1920-1752 | 2237 93LI0PC     | 1820-1928 | 2237 3850PC      | 1820-2078      | 1698 SN74LS490N |      |

INTEGRATED CIRCUIT CROSS REFERENCE  
15

| HP P/N    | Mfr. | Desc.             |           |                   |           |                   |
|-----------|------|-------------------|-----------|-------------------|-----------|-------------------|
|           |      |                   | 1820-2223 | 2037 MC14032BCP   | 1820-2383 | 2037 MC145698CP   |
|           |      |                   | 1820-2224 | 2037 MC14038BCP   | 1820-2394 | 1698 SN74LS399N   |
| 1820-2079 |      | 2037 MC14002BCP   | 1820-2225 | 1921 CD4041UBF    | 1820-2385 | 2037 MC10189P     |
| 1820-2080 |      | 2037 MC14035BCP - | 1820-2226 | 1921 CD4045BF     | 1920-2389 | 2037 MC2902APC    |
| 1820-2081 |      | 2037 MC68A21P     | 1820-2227 | 1921 CD4000BF     | 1820-2390 | 2237 100101FC     |
| 1820-2082 |      | 1698 SN5442AJ     | 1820-2228 | 2037 MC14044BCP   | 1820-2391 | 2237 100102FC     |
| 1820-2083 |      | 2237 4029BPC      | 1820-2229 | 1921 CD4512BF     | 1820-2392 | 2237 100107FC     |
| 1820-2084 |      | 1921 CD4018BE     | 1820-2230 | 1921 CD4047BF     | 1820-2393 | 2237 100112FC     |
| 1820-2085 |      | 2237 4019BPC      | 1820-2231 | 1921 CD4031BF     | 1820-2394 | 2237 100131FC     |
| 1820-2086 |      | 1921 C04006BE     | 1820-2232 | 2037 MC14034BCP   | 1820-2395 | 2237 100136FC     |
| 1820-2087 |      | 3714 TM6402CDL    | 1820-2233 | 1921 CD4099BF     | 1820-2396 | 2237 100141FC     |
| 1820-2088 |      | 2237 9613TC       | 1820-2234 | 3406 DS3649N      | 1820-2397 | 2237 100151FC     |
| 1820-2089 |      | 2237 9612TC       | 1820-2236 | 1698 SN55453BJG   | 1820-2398 | 2237 100000C      |
| 1820-2090 |      | 2037 MC14082BCP   | 1820-2238 | 3406 IDM2901ADC   | 1820-2399 | 2037 MC10123P     |
| 1820-2091 |      | 2037 MC14075BCP   | 1820-2239 | 3406 DP8304N      | 1820-2400 | 2037 MC10128L     |
| 1820-2092 |      | 1698 TMS3129NC    | 1820-2240 | 2037 MC68A08P     | 1820-2401 | 2037 MC10173P     |
| 1820-2093 |      | 2237 F10010DC     | 1820-2241 | 1921 CD40103BF    | 1820-2402 | 2037 MC10175P     |
| 1820-2094 |      | 2237 9616PC       | 1820-2242 | 2237 950030C      | 1820-2403 | 2037 MC10186P     |
| 1820-2095 |      | 2237 9627PC       | 1820-2243 | 1698 SN75469N     | 1820-2404 | 2237 11C91DC      |
| 1820-2096 |      | 1698 SN74LS393N   | 1820-2244 | 1698 SN74LS379N   | 1820-2405 | 3794 AM25LS2520DC |
| 1820-2097 |      | 2037 MC14543BCP   | 1820-2246 | 3406 MM5369AA/N   | 1820-2407 | 2237 11C01FC      |
| 1820-2098 |      | 3406 DM8099N      | 1820-2247 | 2910 N82S100I     | 1820-2408 | 2237 100164FC     |
| 1820-2099 |      | 2037 MC6802P      | 1820-2248 | 1698 SN54LS08J    | 1820-2409 | 2037 MC10804L     |
| 1820-2100 |      | 2237 3861EPC      | 1820-2249 | 1698 SN54LS10J    | 1820-2410 | 3911 P8291        |
| 1820-2102 |      | 1698 SN74LS373N   | 1820-2250 | 1698 SN54LS30J    | 1820-2411 | 2037 MC6800P      |
| 1820-2103 |      | 3406 DS0056CJ-8   | 1820-2251 | 1698 SN54LS196J   | 1820-2413 | 3406 MM82C19N     |
| 1820-2104 |      | 1698 SN74LS242N   | 1820-2252 | 1698 SN54S30J     | 1820-2414 | 2237 9319PC       |
| 1820-2106 |      | 2237 F11C06DC     | 1820-2253 | 1698 SN54S40J     | 1820-2415 | 2037 MC2918PC     |
| 1820-2107 |      | 2037 SN74LS00N    | 1820-2254 | 1698 SN75492N     | 1820-2416 | 3406 MM5035P      |
| 1820-2108 |      | 2910 N8T31N       | 1820-2257 | 2037 MC14503BCP   | 1820-2417 | 3406 DS88C20N     |
| 1820-2109 |      | 3811 D8253        | 1820-2258 | 2037 MC14174BCP   | 1820-2419 | 575 TR1863A       |
| 1820-2110 |      | 1698 SN75477P     | 1820-2259 | 1698 AC5947NF     | 1920-2420 | 2037 MC10171P     |
| 1820-2111 |      | 1698 SN75468N     | 1820-2260 | 3406 IMD2911 ANC  | 1820-2421 | 2037 MC10163P     |
| 1820-2113 |      | 2037 MC68488L     | 1820-2261 | 1698 SN54LS11J    | 1820-2422 | 3406 IDM2901A-1NC |
| 1820-2114 |      | 2237 FCM7002PC    | 1820-2262 | 3794 AM25LS2539PC | 1820-2423 | 575 TR1863B       |
| 1820-2117 |      | 2237 9636ATC      | 1820-2264 | 2237 4040BPC      | 1820-2424 | 2037 MC3447P      |

|                |                      |                 |                     |                |                   |
|----------------|----------------------|-----------------|---------------------|----------------|-------------------|
| 1820-2118      | 2237 96S02PC         | 1820-2265       | 2237 4008BPC        | 1820-2425      | 8608 SSI104A      |
| 1820-2120      | 3794 AM25LS14DC      | 1820-2266       | 2910 NE590F         | 1820-2426      | 8608 SSI105A      |
| 1820-2121      | 1698 SN74LS348N      | 1820-2267       | 2910 NE591F         | 1820-2428      | 2037 MC68A488P    |
| 1820-2124      | 1921 CD4043BE        | 1820-2268       | 1698 SN74LS645N     | 1920-2429      | 2037 MCC1670      |
| 1820-2125      | 2237 401638PC        | 1820-2270       | 3794 AM25LS2569DC   | 1920-2433      | 3811 C8748-8      |
| 1820-2126      | 3406 MM5313N(76+)    | 1820-2271       | 3811 P8039          | 1820-2434      | 4078 MK3881N-4    |
| 1820-2127      | 1698 SN74276N        | 1820-2273       | 2634 UDN2981A       | 1820-2441      | 3811 08741A       |
| 1820-2128      | 1698 SN75116N        | 1820-2274       | 2634 ULN-20689      | 1820-2442      | 3794 AM2909PC     |
| 1820-2129      | 2634 UHP-407         | 1820-2275       | 3406 MM74C90N       | 1820-2443      | 3406 INS8250N     |
| 1820-2130      | 2634 ULN-20748       | 1820-2276       | 3406 MM74C86N       | 1820-2444      | 2037 MC14562BCP   |
| 1820-2132      | 3714 ICM7218A        | 1820-2277       | 2037 MC14022BAL     | 1820-2445      | 3794 AM25LS161APC |
| 1820-2133      | 2037 MC670P          | 1820-2278       | 3811                | 8748 1920-2446 | 5917 P803520      |
| 1820-2134      | 1698 SN75234N        | 1820-2279       | 2037 MC14175BCP     | 1820-2449      | 2037 MC10165P     |
| 1820-2136      | 3406 DSS973N         | 1820-2282       | 1698 SN55461JG      | 1920-2450      | 2037 MC10189P     |
| 1820-2137      | 2037 MC68A00P        | 1820-2283       | 1698 SN55462JG      | 1920-2451      | 2037 MC10168P     |
| 1820-2138      | 3406 DSS871N         | 1820-2284       | 2037 MC68A50P       | 1820-2452      | 8659 TDC1010J     |
| 1820-2140      | 1590 SP86108DG       | 1820-2285       | 3795 MC6871A-I.0MHZ | 1820-2453      | 1698 SN74LS642N   |
| 1820-2141      | 1698 SN75498N        | 1820-2287       | 2910 N74S253N       | 1820-2454      | 3794 AM25S07DC    |
| 1820-2143      | 3811 P8257           | 1820-2288       | 4078 MK3885P        | 1820-2455      | 2037 MC10172P     |
| 1820-2144      | 2037 MC3486P         | 1820-2289       | 3811 D8251A         | 1820-2456      | 575 FD1791A-02    |
| 1820-2145      | 2037 MC3487P         | 1820-2290       | 3406 DS3632N        | 1820-2457      | 2910 82S100N      |
| 1820-2148      | 2037 MC68A488L       | 1820-2291       | 2037 MC68860P       | 1820-2458      | 3794 AM25S10PC    |
| 1820-2150      | 3811 D8279-5         | 1820-2292       | 1590 SP8611BDG      | 1820-2459      | 3794 AM25S18PC    |
| 1820-2151      | 2037 MC6802L         | 1820-2293       | 2037 MC6880DP       | 1820-2460      | 1698 SN74LS169AN  |
| 1820-2154      | 2237 3816PC          | 1820-2296       | 2037 MC8502P        | 1820-2461      | 2037 MC3447P3     |
| 1820-2155      | 2910                 | 26511 1820-2297 | 2037 MC8500P        | 1820-2462      | 2037 MC14513BCP   |
| 1820-2156      | 3406 MM74C922N       | 1820-2298       | 4078 MK3880N-4      | 1820-2463      | 2037 MC6844P      |
| 1820-2157      | 2037 MC3450P         | 1820-2299       | 4078 MK3883N-4      | 1820-2464      | 1698 SN74LS76AN   |
| 1820-2158      | 2037 MC3452P         | 1820-2300       | 4078 MK3887N-4      | 1820-2465      | 3794 AM25LS2538PC |
| 1820-2159      | 1698 SN75117P        | 1820-2301       | 4078 MK3882N-4      | 1820-2466      | 3714 ICM75551PA   |
| 1820-2160      | 3794 AM74LS244N      | 1820-2304       | 1698 SN7422J        | 1820-2469      | 2037 MC6840P      |
| 1820-2161      | 3406 DS8835N         | 1820-2305       | 1698 SN74LS123J     | 1820-2470      | 2037 MC6850P      |
| 1820-2163      | 2910                 | 26521 1820-2306 | 2037 MC14490VP      | 1820-2473      | 2634 ULN-20650    |
| 1820-2164      | 1698 SN74120N        | 1820-2307       | 2037 MC68A40P       | 1820-2474      | 2037 MC10179P     |
| 1820-2165      | 2037 MC6881P/MC3449P | 1820-2308       | 3811 P8031-6        | 1820-2475      | 2037 MC10133P     |
| 1820-2166      | 2037 MC14412VP       | 1820-2309       | 3406 MM74C923N      | 1820-2476      | 2037 MC10132P     |
| 1820-2168      | 3794 AM2502PC        | 1820-2310       | 4078 MK50399N       | 1820-2477      | 2037 MC10170P     |
| 1820-2170      | 2634 ULN-20648       | 1820-2311       | 3794 AM25LS2521PC   | 1820-2478      | 2037 MC10182P     |
| 1820-2172      | 2237 3852PC          | 1820-2313       | 1698 SN74LS673N     | 1820-2479      | 2037 MC10183L     |
| 1820-2173      | 2237 3854PC          | 1820-2315       | 2237 F3871PC        | 1820-2480      | 2037 MC10194P     |
| 1820-2174      | 3406 DS3631N         | 1820-2321       | 2237 951020C        | 1920-2481      | 2037 MC10180P     |
| 1820-2175      | 2037 MC6852CP        | 1820-2322       | 4078 MK5009P        | 1820-2482      | 2037 MC10129L     |
| 1820-2176      | 3811 P8035L          | 1820-2323       | 2037 MC10166L       | 1820-2483      | 1698 SN75161N     |
| 1820-2177      | 39 UPD8243C          | 1820-2324       | 2037 MC10114P       | 1820-2485      | 1698 SN75160N     |
| 1820-2179      | 1698 SN7405J         | 1820-2326       | 2037 MC14504BCP     | 1820-2487      | 1921 CD4056BE     |
| 1820-2180      | 2037 MC68A21L        | 1820-2327       | 8323 1A03-6001      | 1820-2488      | 1698 SN74ALS74N   |
| 1820-2181      | 1698 SN75417NE       | 1820-2328       | 2910 2661-11        | 1820-2489      | 2037 MC6885P      |
| 1820-2185      | 4092 SN74S373J       | 1820-2329       | 575 FD179LB-02      | 1820-2490      | 2037 MC6809P      |
| 1820-2186      | 1698 SN75497N        | 1820-2330       | 1921 C04068BF       | 1820-2494      | 2910 82S103N      |
| 1820-2187      | 3714 ICM7226A        | 1820-2331       | 1921 CD4078BF       | 1820-2495      | 2037 MC10210P     |
| 1820-2188      | 4078 MK3880N         | 1820-2338       | 1590 SP86178DG      | 1820-2496      | 2037 MC10175L     |
| 1820-2190      | 3794 AM25LS2518PC    | 1820-2339       | 4078 MM3881N        | 1820-2497      | 2037 MC10174L     |
| 1820-2191      | 3811 D8275           | 1820-2340       | 3794 AM9511DC       | 1820-2498      | 2037 MC10173L     |
| 1820-2193      | 2037 MC10176L        | 1920-2343       | 3406 MM74C83N       | 1820-2499      | 2037 MC10172L     |
| 1820-2195      | 2910 74LS04N         | 1820-2344       | 2037 MC14557BCP     | 1820-2500      | 2037 MC10171L     |
| 1820-2198      | 2237 9637ATC         | 1820-2345       | 2883 01399P         | 1820-2501      | 2037 MC10170L     |
| 1820-2199      | 2237 9638TC          | 1820-2346       | 1698 SN74LS221J     | 1820-2502      | 2037 MC10165L     |
| 1820-2200      | 1698 SN74LS147N      | 1820-2347       | 2037 MC10159L       | 1820-2503      | 2037 MC10163L     |
| 1820-2201D1698 | SN74LS322AN          | 1420-2348       | 2037 MC10805L       | 1820-2504      | 2037 MC10161L     |
| 1820-2202      | 1698 SN74LS323N      | 1820-2349       | 1698 TMS9900JL      | 1820-2505      | 2037 MC6800DL     |
| 1820-2203      | 3794 AM26LS32PC      | 1820-2350       | 1698 SN74LS362N     | 1820-2506      | 2237 74F04PC      |
| 1820-2204      | 3714 IM6402-11PL     | 1820-2351       | 1698 SN7438J        | 1820-2507      | 2037 MC10153L     |
| 1820-2205      | 3811 P8085A-2        | 1820-2352       | 1698 SN75119P       | 1820-2508      | 2037 MC10113P     |
| 1820-2206      | 1699 SN74LS640N      | 1820-2353       | 3406 DM8131N        | 1820-2509      | 100122DC          |
| 1820-2207      | 1698 SN75471P        | 1820-2357       | 3811 D8291          | 1820-2510      | 2237 100136DC     |
| 1820-2208      | 1698 SN75462P        | 1820-2358       | 2037 MC6880DL       | 1820-2511      | 2237 100163DC     |
| 1820-2209      | 1921 CD4097BE        | 1820-2359       | 2237 F10014PC       | 1820-2512      | 2237 1001640C     |
| 1820-2210      | 3406 MM74C00N        | 1820-2360       | 3794 AM8279PC       | 1820-2513      | 2237 100179DC     |

|           |                 |                |                 |           |                 |
|-----------|-----------------|----------------|-----------------|-----------|-----------------|
| 1820-2211 | 3406 MM74C04N   | 1820-2361      | 1698 SN75327N   | 1820-2514 | 2237 1001810C   |
| 1820-2212 | 3406 MM74C10N   | 1820-2362      | 1698 SN75159N   | 1820-2515 | 2237 100114DC   |
| 1820-2213 | 3406 MM74C32N   | 1820-2363C3406 | DSS867N         | 1820-2516 | 2037 PC 10231L  |
| 1820-2214 | 3406 MM74C162N  | 1820-2365      | 2237 9644TC     | 1820-2517 | 2037 MC10100P   |
| 1820-2215 | 3406 MM74C373N  | 1820-2366      | 2037 SN74LS569N | 1820-2518 | 4078 MK3884N-4  |
| 1820-2216 | 3406 MM74C374N  | 1820-2369      | 1698 SN74LS629N | 1820-2519 | 3811 P8259A     |
| 1820-2217 | 3406 MM88C29N   | 1820-2375      | 3794 AM25S08PC  | 1820-2520 | 1698 SN75463N   |
| 1820-2218 | 3406 MM88C30N   | 1820-2376      | 2037 MC10198L   | 1820-2521 | 4092 67S376J    |
| 1820-2219 | 2037 MC68488P   | 1820-2377      | 3794 AM2903DC   | 1820-2522 | 2910 GXB10188P  |
| 1820-2220 | 2037 MC14076BCP | 1820-2378      | 3794 AM2910DC   | 1820-2523 | 3406 IDM2911ANC |
| 1820-2221 | 1921 C04067BF   | 1820-2380      | 3811 P8224      | 1820-2526 | 3794 AM74S534PC |
| 1820-2222 | 1921 CD4094BF   | 1820-2381      | 2037 MC10166P   | 1820-2527 | 3794 AM74S533PC |

16  
INTEGRATED CIRCUIT CROSS REFERENCE  
HP P/N Mfr.

| HP P/N    | Mfr. | Desc.            |                |                |           |                  |
|-----------|------|------------------|----------------|----------------|-----------|------------------|
| 1820-2528 |      | 3811 1D8039      | 1820-2690      | 2237 74F32PC   | 1826-0138 | 1698 LM339N      |
| 1820-2529 |      | 1698 SN54LS138J  | 1820-2691      | 2237 74F74PC   | 1826-0139 | 1921 CA1458G     |
| 1820-2536 |      | 1698 SN74LS352N  | 1820-2692      | 2237 74F86PC   | 1826-0140 | 2037 MC1468R     |
| 1820-2537 |      | 3406 MM74C244N   | 1820-26930223T | 74F109PC       | 1826-0141 | 3406 LM319J      |
| 1820-253B |      | 3406 MM74C240N   | 1820-2694      | 2237 74F112PC  | 1826-0142 | 2037 MC1458CP1   |
| 1820-2540 |      | 3406 MM74C925N   | 1820-2695      | 2237 74F158PC  | 1826-0144 | 2037 MC7805CP    |
| 1820-2541 |      | 39 UPD1990C      | 1820-2696      | 2237 74F175PC  | 1826-0145 | 2037 MC7806CP    |
| 1820-2546 |      | 2037 MC6845P     | 1820-2697      | 2237 74F194PC  | 1826-0146 | 2037 MC7808CP    |
| 1820-2547 |      | 1698 SN75162N    | 1820-2698      | 2237 74F240PC  | 1826-0147 | 2037 MC7812CT    |
| 1820-2548 |      | 1698 TMS9914NL   | 1820-2699      | 2237 74F241PC  | 1826-0149 | 2037 MC7818CP    |
| 1820-2550 |      | 1698 SN74LS137N  | 1820-2700      | 2237 74F373PC  | 1826-0150 | 1698 UA7824CKC   |
| 1820-2551 |      | 1698 TMS99144L   | 1820-2701      | 2237 74F374PC  | 1826-0152 | 2569 CDR125BK    |
| 1820-2553 |      | 3794 AMZ8002DC   | 1820-2705      | 3794 AM9513PC  | 1826-0153 | 1921 CA3075      |
| 1820-2556 |      | 3794 AM2901BDC   | 1821-0001      | 1921 CA3046    | 1826-0154 | 2883 DG200BA     |
| 1820-2557 |      | 1698 SN74AS804N  | 1821-0002      | 1921 CA3045    | 1826-0155 | 2037 MC1406L     |
| 1820-2558 |      | 1698 SN74AS808N  | 1821-0006      | 2237 SH6501PC  | 1826-0156 | 3406 MM550H      |
| 1820-2559 |      | 1698 SN54LS669J  | 1826-0002      | 2037 MC1510G   | 1826-0159 | 2037 MC1350P     |
| 1820-2562 |      | 2037 MC6803P     | 1826-0003      | 2037 MC1456CG  | 1826-0160 | 2237 7806KC      |
| 1820-2563 |      | 2037 SN74LS182N  | 1826-0004      | 2237 UA304HC   | 1926-0161 | 2037 MLM324P     |
| 1820-2565 |      | 3794 AM74S244N   | 1826-0006      | 2037 MC1469G   | 1826-0162 | 3406 LM321H      |
| 1820-2566 |      | 3406 MM74C240N   | 1826-0008      | 2180 SSS7258   | 1826-0164 | 2237 742PC       |
| 1820-2567 |      | 1698 AC5948N     | 1826-0009      | 2180 SSS725CJ  | 1826-0165 | 3406 LM4250CH    |
| 1820-2569 |      | 2037 MC3453P     | 1826-0010      | 2237 723HM     | 1826-0167 | 1921 CA30944T    |
| 1820-257D |      | 1698 SN75365N    | 1826-0011      | 1698 SN52741   | 1826-0169 | 3406 LM320K-15   |
| 1820-2571 |      | 2037 MC14569BCL  | 1826-0013      | 2180 SSS741CJ  | 1826-0172 | 3406 LM308N      |
| 1820-2572 |      | 1854 L-13-04     | 1826-0014      | 2037 MC1595L   | 1826-0173 | 3406 LM320K-5.2  |
| 1820-2573 |      | 3406 DMPAL14H4NC | 1826-0015      | 1921 CA3060D   | 1826-0175 | 3406 LM319N      |
| 1820-2574 |      | 3406 DMPAL12L6NC | 1826-0016      | 2037 MLM204G   | 1826-0176 | 3285 AD506JH     |
| 1820-2575 |      | 3406 DMPAL16R8NC | 1826-0017      | 3406 LM205H    | 1826-0177 | 2763 7238E       |
| 1820-2576 |      | 2037 MC14011BCL  | 1826-0019      | 2037 MC1437L   | 1826-0178 | 3406 LM320H-12   |
| 1820-2577 |      | 1795 SYP6551     | 1826-0020      | 2180 DAC-01CY  | 1826-0179 | 3406 LM320H-5.2  |
| 1820-2578 |      | 1698 SN74LS33J   | 1826-0021      | 3406 LM310H    | 1826-0180 | 1698 NE555P      |
| 1820-2579 |      | 1698 SN74LS27J   | 1826-0022      | 2037 MC1439L   | 1826-0181 | 3406 LM323K      |
| 1820-2580 |      | 1698 SN74LS20J   | 1826-0023      | 2037 MC1496L   | 1826-0182 | 3285 AD540J      |
| 1820-2581 |      | 1698 SN74LS08J   | 1826-0024      | 2037 MC1469R   | 1826-0183 | 2237 UA734HC     |
| 1820-2582 |      | 1698 SN74LS04J   | 1826-0025      | 3406 LM208AH   | 1826-0184 | 2237 UA749DC     |
| 1820-2583 |      | 1698 SN74LS00J   | 1826-0026      | 1698 LM311L    | 1826-0185 | 1921 CA3080      |
| 1820-2584 |      | 1698 SN74LS38J   | 1826-0028      | 2037 MC1550G   | 1826-0188 | 2037 MC1408L-8   |
| 1820-2585 |      | 1698 SN74LS32J   | 1826-0029      | 2634 ULN-2111A | 1826-0189 | 2910 NE566H      |
| 1820-2586 |      | 1698 SN7416J     | 1826-0031      | 2237 UA726HC   | 1826-0191 | 3406 LM319H      |
| 1820-2587 |      | 1698 SN74LS86J   | 1826-0032      | 2037 MC1463R   | 1826-0192 | 3406 LM320H-15   |
| 1820-2588 |      | 1921 CD4060BE    | 1826-0033      | 2037 MC1463G   | 1826-0193 | 3714 IH5012CPE   |
| 1820-2589 |      | 1795 SYC6502B    | 1826-0035      | 3406 LM308AH   | 1826-0194 | 2910 NE592A      |
| 1820-2590 |      | 3793 SG3627      | 1826-0036      | 2037 MC1494L   | 1826-0195 | 2883 LD111CJ     |
| 1820-2592 |      | 1698 SN74LS320N  | 1826-0037      | 2037 MC1590G   | 1826-0196 | 2290 RC4195TK    |
| 1820-2593 |      | 1698 SN7407J     | 1826-0038      | 2037 MC1436G   | 1826-0197 | 2180 DAC-100CCQ3 |
| 1820-2596 |      | 3811 D8086-2     | 1826-0D40      | 2910 S5733A    | 1826-0198 | 2037 MFC4000B    |
| 1820-2597 |      | 3811 D8288       | 1826-0041      | 1921 CA3059    | 1826-0200 | 2037 MC1420G     |
| 1820-2598 |      | 3811 D8284       | 1826-0042      | 2037 MCC1741   | 1826-0201 | 3406 LM312J      |
| 1820-2599 |      | 1698 SN74S482J   | 1826-0043      | 1921 CA307T    | 1826-0202 | 3406 LM320K-05   |
| 1820-2600 |      | 2237 96LS02PC    | 1826-0044      | 2237 UA739DC   | 1826-0203 | 2237 7815KC      |
|           |      |                  | 1826-0047      | 2910 NE562B    | 1826-0204 | 2910 NE565A      |
|           |      |                  | 1826-0048      | 2037 MCC1456   | 1826-0205 | 2910 NE566A      |

|           |                   |                |                     |                |                 |
|-----------|-------------------|----------------|---------------------|----------------|-----------------|
| 1820-2601 | 3811 D8259A       | 1826-0049D1698 | UA723CJ             | 1826-0206      | 3406 LM381N     |
| 1820-2602 | 2037 MC68821L     | 1826-0051      | 1698 TL514CN        | 1926-0207      | 1698 LM318P     |
| 1820-2604 | 3794 AM9513CC     | 1826-0055      | 2237 UA711DC        | 1826-0208      | 3406 LM310N     |
| 1820-2605 | 3406 MM74C73N     | 1826-0056      | 2237 UA740HC        | 1826-0209      | 3406 LM380N-8   |
| 1920-2606 | 3406 MM74C76N     | 1826-0058      | 2910 NE501A         | 1826-0210      | 3406 LM361N     |
| 1820-2610 | 1698 SN74LS686N   | 1826-0059      | 1698 LM201AL        | 1826-0212      | 2237 UA776TC    |
| 1820-2611 | 2237 1001010C     | 1826-0060      | 2037 MC1438R        | 1826-0213      | 2910 NE521A     |
| 1820-2612 | 2037 MC6809L      | 1826-0061      | 3793 SG3501AJ       | 1826-0214      | 2037 MC7915CT   |
| 1820-2613 | 1698 SN74LS356N   | 1826-0064      | 2037 MC1733CL       | 1826-0215      | 2037 MC7905.2CT |
| 1820-2614 | 2237 1001020C     | 1826-0065      | 39 UPC311C          | 1826-0217      | 2290 RC4558T    |
| 1820-2619 | 2910 2661-1T REVA | 1826-0067      | 2910 NE531H         | 1826-0218      | 1921 CA3100T    |
| 1820-2620 | 3811 D8088        | 1826-0069      | 2237 LM301AD        | 1826-0219      | 2910 NE567V     |
| 1820-2621 | 1698 SN74S225N    | 1826-007D      | 2037 MC1741CL       | 1826-0220      | 3406 LM320H-05  |
| 1820-2622 | 1698 SN74LS624N   | 1826-0071      | 2037 MC1456G        | 1826-0221      | 1690 UA7912CKC  |
| 1820-2623 | 3406 MM58174N     | 1826-0072      | 2237 UA208H         | 1826-0222      | 2237 UA4136PC   |
| 1820-2624 | 2037 MC68809P     | 1826-0074      | 3285 AD503K(SEL)    | 1826-0224      | 2910 SE555CT    |
| 1820-2625 | 1425 KR2376-ST-P  | 1826-0075      | 1921 CA3079         | 1826-0225      | 3406 LM322N     |
| 1820-2626 | 1698 AC5947N      | 1826-0077      | 3406 LM311F         | 1826-0226      | 2237 78M12HC    |
| 1820-2627 | 1425 CRT5027P     | 1826-0078      | 1921 CA3030         | 1826-0229      | 2180 OP-05CJ    |
| 1820-2630 | 3406 MM74C941N    | 1826-0079      | 3545                | 1321 1826-0230 | 1921 CA3053     |
| 1820-2631 | 6344 M68866-0     | 1826-0081      | 3406 LM318H         | 1826-0231      | 2237 UA760HC    |
| 1820-2634 | 1698 SN74ALS04N   | 1826-0082      | 3285 AD741LH        | 1826-0232      | 3406 LM224J     |
| 1820-2635 | 1698 SN74ALS08N   | 1926-0086      | 2037 MC1776CG       | 1826-0233034D6 | LM220K-15       |
| 1820-2637 | 3794 AMZ8002-1DC  | 1826-0087      | 1821 CA3004         | 1826-0235      | 3406 LM220K-12  |
| 1820-2638 | 3794 AMZ8001-1DC  | 1826-0089      | 3545                | 1322 1826-0237 | 350 XR320       |
| 1820-2641 | 1698 SN74LS374N   | 1826-0090      | 3285 AD741KH(SEL)   | 1826-0238      | 3406 LM325AS    |
| 1820-2644 | 1921 CD4050BE     | 1826-0091      | 6563 GRAM 6.8810    | 1826-0243      | 2037 MC1558G    |
| 1820-2646 | 3714 ICM7227AIP   | 1826-0094      | 1698 SN75235N       | 1826-0244      | 2910 NE529A     |
| 1820-2647 | 3714 ICM7227CIP   | 1826-0098      | 3406 LM211H         | 1826-0245      | 3406 LM370M     |
| 1820-2648 | 2237 1001650C     | 1826-0099      | 2237 7812UC         | 1826-0246      | 2037 MC7805CK   |
| 1820-2649 | 4079 MK3880N-6    | 1826-0100      | 1698 SN72747J       | 1826-0247      | 3780 A-4350     |
| 1820-2650 | 4078 MK38P70/02R  | 1826-0101      | 2910 NE565K         | 1826-0248      | 2037 MC1408L-6  |
| 1820-2651 | 2037 MC6803L-1    | 1826-0102      | 3406 LM312H         | 1826-0249      | 3285 AD504J     |
| 1820-2653 | 3794 AM25LS2569PC | 1826-0103      | 2037 MC1545G        | 1826-0251      | 3285 AD514K     |
| 1820-2654 | 2237 74F157PC     | 1826-0104      | 3406 LM371H         | 1826-0252      | 3285 AD7520JN   |
| 1820-2655 | 1698 SN74LS625N   | 1826-0105      | 2883 DG172BK        | 1826-0253      | 2037 MC3442P    |
| 1820-2656 | 1698 SN74ALS00N   | 1826-0106      | 2037 MC7815CP       | 1926-0254      | 2037 MC1741SCP1 |
| 1820-2657 | 1698 SN74ALS32N   | 1826-0108      | 3406 LH0062CH       | 1826-0256      | 2910 NE522A     |
| 1820-2658 | 1921 CA3161E      | 1826-0109      | 3799 HA2-2625-80593 | 1826-0258      | 3793 SG1502N    |
| 1820-2662 | 1921 CD40116E     | 1826-0110      | 3406 LM212H         | 1826-025902D37 | MFC607D         |
| 1820-2664 | 2037 MC1678L      | 1826-0111      | 1921 CA1458T        | 1826-02620223T | UA7824KC        |
| 1820-2665 | 575 WD8250A       | 1826-0112      | 3406 LM316AH        | 1826-0263      | 3285 AD532JD    |
| 1820-2666 | 1698 SN74S37J     | 1826-0113      | 3406 LM207H         | 1826-0264      | 3285 AD7520LN   |
| 1820-2667 | 3794 AM2901BPC    | 1826-0114      | 2237 710H74         | 1826-0266      | 2180 OP-05EJ    |
| 1820-2668 | 1698 SN75114N     | 1826-0115      | 2910 NE526A         | 1826-0267      | 3406 LH0062CD   |
| 1820-267D | 4092 PALI6L8CN    | 1826-0116      | 2180 CHP-01-CJ      | 1826-0268      | 3406 LM208D     |
| 1820-2671 | 4092 PAL12H6CN    | 1826-0117      | 2237 7812KC         | 1826-0269      | 2910 NE566N     |
| 1820-2672 | 1698 SN74LS623N   | 1826-0119      | 2910 NE555T         | 1826-0270      | 3799 HA-2005A   |
| 1820-2675 | 1698 SN74LS646N   | 1826-0120      | 3406 LM3900N        | 1826-0271      | 1698 SN72741P   |
| 1820-2676 | 2237 74F64PC      | 1826-0121      | 3714 8007C          | 1826-0272      | 3406 LM361H     |
| 1820-2677 | 4092 PAL10H8CN    | 1826-0122      | 2237 7805UC         | 1826-0274      | 2037 MC78LI5ACP |
| 1820-2678 | 4092 PAL14L4CN    | 1826-0123      | 2037 MC7912CK       | 1826-0275      | 2037 MC78L12ACP |
| 1820-2679 | 4092 PAL16H2CN    | 1826-0124      | 2910 NE529K         | 1826-0276      | 2037 MC78L05ACP |
| 1820-2680 | 4092 PALI6R6CN    | 1826-0125      | 2037 MC1514L        | 1826-0277      | 3406 LM320T-15  |
| 1820-2681 | 4092 PAL16R4CN    | 1826-0126      | 2037 MC7818CK       | 1826-0281      | 2037 MC79L15ACP |
| 1820-2682 | 2634 UDN-5703A    | 1826-0127      | 2180 DAC-100BCQ3    | 1826-0282      | 2037 MC79L12ACP |
| 1820-2683 | 2634 UDN-5706A    | 1826-0128      | 2037 MC1468L        | 1826-0283      | 3406 LM325S     |
| 1820-2684 | 2237 74F00PC      | 1826-0129      | 3714 ICL8001CTZ     | 1826-0284      | 2037 MC79L06C   |
| 1820-2685 | 2237 74F02PC      | 1826-0130      | 2910 NE550L         | 1826-0285      | 2037 MC79L05ACP |
| 1820-2686 | 2237 74F08PC      | 1826-0131      | 3714 ICL8008CTY     | 1826-028602D37 | MC79L03C        |
| 1820-2687 | 2237 74F10PC      | 1826-0132      | 2237 UA760DC        | 1826-0289      | 2037 MC3476G    |
| 1820-2688 | 2237 74F11PC      | 1826-0135      | 2237 UA747DM        | 1826-0291      | 3406 LM324F     |
| 1820-2689 | 2237 74F20PC      | 1826-0137      | 2910 NE550N         | 1826-0292      | 1921 CA3085     |

# INTEGRATED CIRCUIT CROSS REFERENCE

|        |      |   |           |                |           |              |
|--------|------|---|-----------|----------------|-----------|--------------|
| 17     |      |   |           |                |           |              |
| HP P/N | Mfr. | d | 1826-0450 | 1698 TL497CN   | 1826-0591 | 6545 LAS 19U |
|        |      |   | 1826-0451 | 2037 MIC7915CK | 1826-0592 | 3406 LM358AH |

|           |                        |                |                    |                |                  |
|-----------|------------------------|----------------|--------------------|----------------|------------------|
| 1826-0293 | 2037 MC1306P           | 1826-0452      | 2883 LD130CJ       | 1826-0593      | 2763 8750CJ      |
| 1826-0294 | 2037 MC7905CT          | 1026-0453      | 2190 DAC-100ACQ3   | 1826-0594      | 3406 LH0044CH    |
| 1826-0295 | 3285 AD533JH           | 1826-0454      | 2910 NE527K        | 1826-0595      | 3285 AD522A(SEL) |
| 1826-0299 | 1698 UA7924CKC         | 1826-0455      | 3714 ICL 8013CC TZ | 1826-0598      | 2037 MC12002P    |
| 1826-0300 | 2237 UA79M12AHC        | 1826-0456      | 2237 UA78GUILC     | 1826-0599      | 2037 MC14568BCP  |
| 1826-0301 | 1698 SN72L022L         | 1826-0457      | 3406 LM325H        | 1826-0600      | 1698 TL074ACN    |
| 1826-0302 | 2037 MC1741SCG         | 1826-0458      | 3406 LF255H        | 1826-0601      | 2100 OP-16FJ     |
| 1826-0303 | 1921 CA741G            | 1826-04590340G | LH0042CD           | 1826-0602      | 3285 AD7506KD    |
| 1826-0304 | 3406 LF355H            | 1826-0460      | 2237 UA78L26AWC    | 1825-0603      | 2237 UA78S4DPC   |
| 1826-0305 | 2237 79MGT2C           | 1826-0462      | 2037 MC3410CL      | 1826-0605      | 2883 DG5088K     |
| 1826-0306 | 3406 LM339AJ           | 1826-0464      | 2037 MC78M15CP     | 1826-0606      | 2883 DG2018K     |
| 1826-0307 | 1921 CA3130T           | 1826-0465      | 1921 CA3140T       | 1926-0607      | 3406 LM340AT-15  |
| 1826-0308 | 3285 AD562KD/BIN       | 1826-0467      | 2037 MC1403P1      | 1826-0609      | 2180 MUX08FQ     |
| 1826-0309 | 3285 AD518J            | 1826-0468      | 2037 MC3423P1      | 1826-06100218D | MUX24FQ          |
| 1826-0311 | 2037 MLM201AP1         | 1826-0469      | 3334 ATF431        | 1826-0611      | 3406 LM2904N     |
| 1826-0312 | 2037 MC3403P           | 1826-0470      | 2037 MC14046BCP    | 1826-0616      | 2180 OP-11EY     |
| 1826-0314 | 3406 LM355-1H          | 1826-0472      | 3406 LH0044ACH     | 1826-0617      | 2910 78HV15CU    |
| 1826-0315 | 3406 LM348N            | 1826-0474      | 2037 MC3467P       | 1826-0620      | 1698 UA7924CKC   |
| 1826-0316 | 3406 LH0070-1H         | 1826-0475      | 2037 MC3468P       | 1826-0621      | 2763 8702CN      |
| 1826-0318 | 6338 TBA231            | 1826-0476      | 1698 TL601CP       | 1826-0622      | 2180 REF-02DJ    |
| 1826-0319 | 2037 LF356G            | 1826-0477      | 1698 TL610CP       | 1826-0623      | 3406 LM334Z      |
| 1826-0320 | 3406 LM395K            | 1826-0478      | 2237 UA7906UC      | 1826-0624      | 5436 VFC32KP     |
| 1826-0321 | 1921 CA3099E           | 1826-0479      | 1698 LM293P        | 1826-0625      | 2910 NE5553N     |
| 1826-0324 | 3406 LM209K            | 1826-0480      | 3406 LF13333N      | 1826-0626      | 1921 CA3130AS    |
| 1826-0325 | 2037 MCC1776           | 1826-0481      | 3406 LH0033CG      | 1826-0627      | 3285 AD542L      |
| 1826-0326 | 2290 RC4558NB          | 1826-0482      | 3714 HA2-2525-5    | 1826-0628      | 2180 OP-IIFY     |
| 1826-0327 | 3285 AD518KH(SEL)      | 1826-0483      | 2237 UA79MGUILC    | 1826-0629      | 1698 UA79M12CKC  |
| 1826-0328 | 2290 RV4558DE          | 1826-0484      | 2237 UA78MGU1C     | 1826-0631      | 3406 LM350K      |
| 1826-0329 | 3406 LM113-2H          | 1826-0495      | 3285 AD7530LN      | 1826-0632      | 3406 LM343D      |
| 1826-0330 | 3406 LM299H            | 1826-0486      | 2037 MC14052BCP    | 1826-0633      | 2910 NE5532AT    |
| 1826-0331 | 2037 XC79L12CG         | 1826-0488      | 3406 LM218H        | 1826-0634      | 3406 LM343H      |
| 1826-0332 | 2037 XC79L05CG         | 1826-0489      | 3714 IH5028CPE     | 1826-0635      | 2180 OP-07CP     |
| 1826-0333 | 2237 78L12AHC          | 1826-0490      | 3714 IH5032CPE     | 1826-0636      | 3285 AD7525KN    |
| 1826-0334 | 2037 MC1445L           | 1826-0491      | 2237 UAF355TC      | 1826-0638      | 3406 LM360N-8    |
| 1826-0336 | 3406 LM13340-1N        | 1826-0492      | 3406 DS3630N       | 1826-0639      | 3285 AD7524JN    |
| 1826-033B | 3794 AM686HC           | 1826-0493      | 2037 MLM308API     | 1826-0640      | 1698 TL061CP     |
| 1826-0342 | 2237 UA749DHC          | 1826-0495      | 2037 MC79L12ACG    | 1826-0641      | 2180 OP-07EY     |
| 1826-0343 | 2037 MC1436CG          | 1826-0496      | 2037 MC79L05ACG    | 1826-0642      | 2037 MC1405L     |
| 1826-0344 | 2037 MC7908CP          | 1826-0497      | 3406 LF311H        | 1826-0643      | 1699 TL431CLP    |
| 1826-0345 | 2237 UA78M12UC         | 1826-0498      | 1698 SN76549N      | 1826-0644      | 3714 HA2-2515-5  |
| 1826-0346 | 3406 LM358N            | 1826-0499      | 3406 LH0091CD      | 1826-0648      | 3406 LM342P-12   |
| 1826-0348 | 3406 LM377N            | 1826-0500      | 3285 AD536K        | 1826-0649      | 1698 UA79M12CKC  |
| 1826-0349 | 2237 UA78M06HL         | 1826-0501      | 2037 MC14053BCP    | 1826-0650      | 3285 AD584KH     |
| 1826-0353 | 2037 MC78L15ACG        | 1826-0502      | 2037 MC14066BCP    | 1926-0651      | 1698 TL500ACN    |
| 1826-0356 | 3285 AD7530JD          | 1826-0503      | 3406 LF398H        | 11126-065      | 1921 CA3240AE    |
| 1826-0357 | 3406 LF357H            | 1826-0504      | 3285 AD7530LD      | 1826-0655      | 3406 LM3914N     |
| 1826-0358 | 3406 LF256H, SEL NOISE | 1826-0505      | 2037 MC1741NCP1    | 1826-0657      | 3285 AD584LH     |
| 1826-0360 | 2037 MC3431P           | 1826-0506      | 1921 CA314DE       | 1A25-0658      | 1921 CD22100E    |
| 1826-0364 | 2037 MC12040P          | 1826-0507      | 2037 SZA266        | 1826-0659      | 3794 AM6081PC    |
| 1826-0365 | 3799 HA2065-5          | 1826-0508      | 3285 A0561JD       | 1826-0661      | 3285 AD590KH     |
| 1826-0367 | 2037 MC78M0SCG         | 1826-0509      | 2037 MC1658P       | 1826-0665      | 3406 LF347BN     |
| 1826-0370 | 3406 LM340K-8          | 1826-0510      | 3406 LF13332N      | 1826-0666      | 3406 LM339AN     |
| 1826-0371 | 3406 LF256H            | 1826-0511      | 1698 UA79M15CLA    | 1826-0667      | 3406 LF351N      |
| 1826-0373 | 3406 LM555CN           | 1826-0512      | 2037 MC78M15CG     | 1825-0668      | 2037 LF356AG     |
| 1826-0374 | 2237 9650-1DC          | 1826-0516      | 2180 OP-17FJ       | 1826-0669      | 2883 DG182BP     |
| 182G-0375 | 3406 LX5700H           | 1826-0517      | 3406 ADCOBOOPCO    | 1826-0672      | 3285 AD518KH     |
| 1826-0377 | 3406 LM320T-18         | 1826-0519      | 1698 TL071CP       | 1826-0673      | 2237 UA217K      |
| 1826-0382 | 2037 MC1355P           | 1826-0520      | 1698 TL071BCP      | 1826-0674      | 3406 DAC120CHCD  |
| 1826-0387 | 3714 ICL 8250 C PE     | 1826-0521      | 1698 TL072CP       | 1826-0675      | 1698 TL182CN     |
| 1826-0388 | 3406 LH0071-1H         | 1826-0522      | 1698 TL 074CN      | 1826-0676      | 1590 SL441A      |
| 1826-0390 | 3406 LM3911N           | 1826-0523      | 3406 LM337K        | 1826-0677      | 3406 LM338K      |
| 1826-0391 | 3714 ICL741C-LN-TY     | 1826-0524      | 3406 LM324AN       | 1826-0678      | 3406 LM358H      |
| 1826-0392 | 3794 AM301AH           | 1826-0526      | 2037 MC3420P       | 1826-0679      | 1921 CA3140AT    |
| 1826-0393 | 1698 LM317KC           | 1826-0527      | 3406 LM337T        | 1826-0682      | 3406 LM386N-1    |
| 1826-0394 | 3406 LM78L10ACH        | 1826-0528      | 3406 LF356BH       | 1826-0683      | 1698 TL062CP     |
| 1826-0396 | 2237 7815UC            | 1826-0529      | 2037 MC3410CP      | 1826-0685      | 3406 LF351H      |
| 1826-0397 | 3406 LM220K-5.0        | 1826-0531      | 2237 UA759T2C      | 1926-0686      | 3406 LF351AH     |
| 1826-0398 | 3406 LM271H            | 1826-0532      | 3799 HA1-4605-5    | 1826-0687      | 3406 LM317HVK    |

|                |                     |           |                  |                |                  |
|----------------|---------------------|-----------|------------------|----------------|------------------|
| 182G-0399      | 2037 MC3340P        | 1826-0533 | 3406 LM326H      | 1826-0688      | 2037 MC7902CT    |
| 1826-0400      | 2037 MC1555G        | 1826-0534 | 1921 CA3080E     | 1826-0689      | 3799 HA2-2535    |
| 1826-0401      | 2883 L144CJ         | 1826-0536 | 3406 LM340AK-5   | 1826-0691      | 6545 L2-OV-20    |
| 1826-0402      | 6545 LAS-1515       | 1826-0537 | 3406 LM220K-5.2  | 1826-0692      | 6545 L2-OV-15    |
| 1826-0403      | 6545 LAS-1815       | 1826-0538 | 1698 TL084BCN    | 1826-0693      | 6545 L2-OV-12    |
| 1826-0404      | 2237 UA7952UC       | 1826-0539 | 3406 LM317H      | 1826-0694      | 6545 L2-OV-5     |
| 1826-0405      | 3406 LH0022CH       | 1826-0540 | 3714 ICL8211CTY  | 1826-0695      | 3406 LF11508D    |
| 1826-0408      | 3714 ICL8212CPA     | 1826-0542 | 2180 OP-14CJ     | 1826-0697      | 3285 AD7541JN    |
| 1826-0409      | 2037 MC1723L        | 1826-0543 | 2180 OP-07CJ     | 1826-0698      | 3285 AD590JH     |
| 1826-0410      | 1698 TL084CN        | 1826-0544 | 2037 MC1403U     | 1826-0699      | 3285 AD7524AD    |
| 1826-0411      | 2037 MC14536BCP     | 1826-0545 | 1698 TL082ACP    | 1826-0700      | 3799 HAI-5195-5  |
| 1826-0412      | 3406 LM393N         | 1826-9546 | 2910 NE592K      | 1826-0701      | 2237 UA79M06AHC  |
| 1826-0413      | 3799 HA2-2605-5     | 1826-0547 | 1698 TL072ACP    | 1826-07030291D | NE570N           |
| 1826-0414      | 3406 LH0070-2H      | 1826-0548 | 3406 LM161J      | 1826-0704      | 3406 LF353H      |
| 1826-04150291D |                     | 1826-0549 | 1921 CA3140H     | 1826-0705      | 3794 AM6012DC    |
| 1826-0416      | 3406 LF13331D       | 1826-0550 | 2237 UA0801EPC   | 192/-0707      | 3285 AD7523JN    |
| 1826-0417      | 3406 LF13333D       | 1826-0551 | 1698 TL7805ACKC  | 1826-07080218D | REF-OICP         |
| 1826-0419      | 2237 UA7912UC       | 1826-0552 | 3406 LF13741H    | 1826-0709      | 3406 LM380N      |
| 1826-0419      | 3406 LM3909N        | 1826-0554 | 3406 LM340LAZ-12 | 1826-0710      | 3406 ADC0816CCN  |
| 1826-0420      | 2037 MC1458SP1      | 1826-0555 | 3406 LM340LAZ-5  | 1826-0711      | 3406 LM725H      |
| 1826-0422      | 3406 LF298H         | 1826-0556 | 2037 MC1458NG    | 1826-0712      | 3406 LF353N      |
| 1826-0423      | 3406 LM317K         | 1826-0557 | 3406 LM348J      | 1826-0713      | 3295 AD7574JN    |
| 1826-0424      | 2037 MC3405P        | 1826-0558 | 3406 LM337H      | 1826-0714      | 3799 HA1-4925-5  |
| 1826-0425      | 3799 HA2-2655-5     | 1826-0559 | 3406 LM340K-24   | 1826-0715      | 2910 NE5534AN    |
| 1826-0426      | 3794 AM687ADL       | 1826-0565 | 1698 TL494CN     | 1826-0716      | 2910 NE5532AFE   |
| 1826-0428      | 1698 SG3524J        | 1826-0567 | 2037 MLMC101A    | 1826-0717      | 3406 ADC0804N    |
| 1826-0429      | 3799 HI1-1818A-5    | 1826-0568 | 3406 LM320H-6    | 1826-0718      | 2037 MC1404U5    |
| 1826-0430      | 3285 AD559KD        | 1826-0569 | 2910 NE5534AT    | 1826-0719      | 350 XR346CJ      |
| 1826-0431      | 2037 MC14433L       | 1826-0572 | 1698 TL084ACN    | 1826-0720      | 2180 SW-02FQ     |
| 1826-0432      | 3714 ICL 8049 CC PE | 1826-0573 | 3714 ICL8069DCQ  | 1826-0721      | 3799 HA3-2607-5  |
| 1826-0433      | 3406 LF356BN        | 1826-0574 | 2237 UA714LHC    | 1826-0726      | 3285 AD565JNVBIN |
| 1826-0434      | 3406 LM341P-8.0     | 1826-0575 | 2763 94000J      | 1826-0727      | 2180 SNP-RIFT    |
| 1826-0435      | 3406 LM341P-12      | 1826-0576 | 2180 OP-16E      | 1826-0728      | 3793 SG1532J     |
| 1826-0436      | 3406 LM341P-24      | 1826-0577 | 2180 DAC-100CCQ4 | 1826-0729      | 3285 AD7522JN    |
| 1826-0437      | 2037 MC1495L        | 1826-0578 | 3794 AM685HL     | 1826-0730      | 3285 AD581LH     |
| 1826-0438      | 3406 LM340LAH-12    | 1826-0579 | 3794 AM686CN     | 1826-0731      | 6545 L6-OV-5     |
| 1826-0439      | 3406 LH-0053CG      | 1826-0580 | 3406 AF134-1CJ   | 1826-0732      | 6545 L6-OV-5     |
| 1826-0440      | 2180 OP-OICJ        | 1826-0581 | 3406 LF13508D    | 1826-0733      | 3406 ADC0803LCD  |
| 1826-0441      | 2237 UA79GU1C       | 1826-0582 | 3406 LF13201D    | 1826-0734      | 3406 LF3538N     |
| 1826-0442      | 3714 IH5027CPE      | 1826-0583 | 2237 UA79MHC     | 1826-0735      | 3799 HA3-2507-5  |
| 1826-0443      | 2237 UA78GKC        | 1826-0584 | 2237 UA78MGHC    | 1826-0736      | 3799 HA3-2627-5  |
| 1826-0444      | 2237 UA79GKC        | 1826-0585 | 3406 LM329DZ     | 1826-0740      | 3714 IH5043CDE   |
| 1826-0445      | 2237 UA7905UC       | 1826-0586 | 2237 UA78L62AWC  | 1826-0741      | 2037 MC34002AG   |
| 1826-0446      | 3714 ICL8052CPD     | 1826-0587 | 2883 LD121CJ     | 1826-0742      | 3285 AD581J      |
| 1826-0447      | 3406 LF257H         | 1826-0588 | 2883 LD120CJ     | 1826-0743      | 2037 MC1741SU    |
| 1826-0449      | 3406 LM320T-8.0     | 1826-0590 | 3406 LF13509D    | 1826-0745      | 3406 LM258H      |

|                                    |      |                   |           |                  |                |
|------------------------------------|------|-------------------|-----------|------------------|----------------|
| 18                                 |      |                   |           |                  |                |
| INTEGRATED CIRCUIT CROSS REFERENCE |      |                   |           |                  |                |
| HP PIN                             | Mfr. | Desc.             |           |                  |                |
| 1826-0746                          |      | 3714 ICL7109CPL   | 1858-0045 | 1921 CA3018A     | 6605L-I        |
| 1826-0747                          |      | 3406 LM4250CN     | 1858-0046 | 1921 CA3097E     | 6753757        |
| 1826-0748                          |      | 3406 LM250K STEEL | 1858-0047 | 2634 ULN-2003A   | 4092 1820-2521 |
| 1826-0750                          |      | 3406 ADC0801LCN   | 1858-0048 | 1921 CA3082E     | 7024C          |
| 1826-0751                          |      | 3406 DAC1202HCD   | 1858-0052 | 2037 SPQ1678     | 709AHM         |
| 1826-0752                          |      | 3285 AD7542BD     | 1858-0055 | 2037 MPQ2369     | 710HM          |
| 1826-0753                          |      | 2037 MC34004BL    | 1858-0057 | 1921 CA3082F     | 711HC          |
| 1826-0754                          |      | 6545 LAS2915      | 1858-0058 | 2037 MPQ3906     | 7151[          |
| 1826-0755                          |      | 2910 NE527N       | 1858-0061 | 2634 ULN-2004A   | 7152 0283B     |
| 1A26-0756                          |      | 3406 ADC0804LCN   | 1858-0062 | 2037 MPQ3762     | 1813-0133      |
| 1826-0757                          |      | 1698 TL170CLP     | 1858-0063 | 1921 CA3102E     | 723HF          |
| 1826-0759                          |      | 2037 LM339J       | 1858-0064 | 1921 CA3045H     | 723HM          |
| 1825-0760                          |      | 3406 LM335AZ      | 1858-0065 | 2634 ULN-2815A-2 | 723PC          |
| 1826-0761                          |      | 3714 ICL7605CJN   | 1859-0066 | 3714 IH401A      | 727HL          |
| 1826-0762                          |      | 3406 LM261H       | 1859-0067 | 2634 ULN-2033A   | 733HC          |
| 1826-0763                          |      | 3406 LM237K       | 1858-0069 | 2634 ULN-2803A   | 7411PC         |
| 1826-0764                          |      | 3285 AD590XF      | 1959-0071 | 2037 MPQ3798     | 74123N         |
|                                    |      |                   | 1858-0072 | 2634 ULN-2813A   | 2910 1820-1585 |
|                                    |      |                   | 1858-0073 | 2634 ULN-2805A   | 74164PC        |
|                                    |      |                   |           |                  | 2237 1820-0294 |
|                                    |      |                   |           |                  | 742PC          |
|                                    |      |                   |           |                  | 2237 1826-0164 |
|                                    |      |                   |           |                  | 74F00PC        |
|                                    |      |                   |           |                  | 2237 1820-2684 |
|                                    |      |                   |           |                  | 74F02PC        |
|                                    |      |                   |           |                  | 2237 1820-2685 |

|           |                    |              |                   |          |                  |
|-----------|--------------------|--------------|-------------------|----------|------------------|
| 1826-0765 | 3714 ICL7611BMTY   | 1858-0074    | 2037 MPQ6100      | 74F04PC  | 2237 1820-2506   |
| 1826-0766 | 3406 LM236H        | 1858-0075    | 2037 MPQ3546      | 74F08PC  | 2237 1820-2686   |
| 1826-0767 | 5436 3528AM        | 1858-0076    | 2037 MPQ2907P     | 74F109PC | 2237 1820-2693   |
| 1826-0768 | 1921 CA258AT       | 1858-0077    | 2037 MPQ2222P     | 74F 10PC | 2237 1820-2687   |
| 1826-0769 | 2883 DG303BP       | 1902-0908    | 3406 LM399H       | 74F112PC | 2237 1820-2694   |
| 1926-0770 | 1688 TL022CP       | 1902-0928    | 3406 LM329        | 74F111PC | 2237 1820-2688   |
| 1826-0772 | 2037 LM317LZ       |              |                   | 74F157PC | 2237 1820-2654   |
| 1826-0773 | 3406 LM10CH        | Desc.        | Mfr. HP PIN       | 74F158PC | 2237 1820-2695   |
| 1826-0774 | 3406 LM385BZ       |              |                   | 74F175PC | 2237 1820-2696   |
| 1826-0776 | 2883 DG302CJ       | 10000DC      | 02237 1820-2398   | 74F194PC | 2237 1820-2697   |
| 1826-0777 | 2883 DG303CJ       | 1001010C     | 02237 1820-2611   | 74F20PC  | 2237 1820-2689   |
|           |                    | 100101FC     | 02237 1820-2390   | 74F240PC | 2237 1820-2699   |
| 1826-0778 | 2883 DG300CJ       | 100102DC     | 02237 1820-2614   | 74F241PC | 2237 1820-2699   |
| 1826-0779 | 3285 AD7502JN      | 100102FC     | 02237 1820-2391   | 74F32PC  | 2237 1820-2690   |
| 1825-0780 | 1921 CA3054        | 100107FC     | 02237 1820-2392   | 74F373PC | 2237 1820-2700   |
| 1826-0781 | 8659 TDC1014J      | 100112FC     | 02237 1820-2393   | 74F374PC | 2237 1820-2701   |
| 1826-0783 | 350 XR5534ACN      | 100114DC     | 02237 1820-2515   | 74F64PC  | 2237 1820-2676   |
| 1826-0784 | 6545 LAS1912       | 100122DC     | 02237 1820-2509   | 74F74PC  | 2237 1820-21591  |
| 1826-0785 | 1698 TL072ACJG     | 100131FC     | 02237 1820-2394   | 74F86PC  | 2237 1820-2692   |
| 1926-0786 | 1698 TL064CN       | 100136DC     | 02237 1820-251D   | 74LS04N  | 2910 1820-2195   |
| 1826-0790 | 3714 IH502DCPA     | 100136FC     | 02237 1820-2395   | Ws 154N  | 2910 1820-2053   |
| 1826-0791 | 3406 Lf398N        | 100141FC     | 02237 1820-2396   | 74LS174P | 2237 1820-1700   |
| 1826-0782 | 3799 HA1-4905-5    | 100151FC     | 02237 1820-2397   | 74LS175P | 2237 1820-1699   |
| 1826-0793 | 2237 UA79M0BAHC    | 100163DC     | 02237 1820-2511   | 74LS260P | 2237 1820-1905   |
| 1826-0794 | 1921 CA3240E       | 1001640C     | 02237 1820-2512   | 74LS393P | 2237 1820-1989   |
| 1826-0798 | 2910 NE5018F       | 100164FC     | 02237 1820-2408   | 74S109DC | 2237 1820-1' _72 |
| 1826-0801 | 2037 LF255N        | 1001650C     | 02237 1820-2648   | 750,     | 8661 I B13-0168  |
| 1826-0802 | 3406 LM129AH       | 1001790C     | 02237 1820-2513   | 751N     | 3285 1813-0048   |
| 1826-0806 | 2910 NE5560N       | 1001810C     | 02237 1820-2' _14 | 75492PC  | 2237 1820-1670   |
| 1826-0810 | 1921 CA3290E       | 10145APC     | 02237 1816-1' _39 | 7805UC   | 2237 1826-0122   |
| 1826-0811 | 2180 SW-01FQ       | 10149F       | 02910 1816-1461   | 7806KC   | 2237 1826-0160   |
| 1926-0812 | 3406 LM103H-2.0    | 106A         | 03285 1820-02218  | 7812KC   | 2237 1826-0117   |
| 1826-0813 | 1921 CA258AG       | 118A         | 03285 1820-0470   | 7812UC   | 2237 1826-0099   |
| 1826-0814 | 1921 CA239AE       | 11C01FC      | 02237 1820-2407   | 7815KC   | 2237 182G-0203   |
| 1826-0819 | 6545 LAS1SA15      | 11C70DC      | 02237 1820-1834   | 7915UC   | 2237 1826-0396   |
| 1826-0820 | 6545 LAS18A15      | 11C9000      | 02237 1820-1780   | 78HV15CU | 2910 1826-0617   |
| 1826-0821 | 3295 AD7512DIJN    | 11C91DC      | 02237 1820-2404   | 78L12AHC | 2237 1826-0333   |
| 1826-0822 | 3285 AD542KH       | 1321         | 03545 1826-0079   | 78M12HC  | 2237 1826-0226   |
| 1826-0823 | 9161 MT8865AE      | 132?         | 03545 1826-0089   | 79MGT2C  | 2237 1826-0305   |
| 1826-0824 | 9161 MT8860AE      | 1AD3-6001    | 08323 1820-2127   | B00 7C   | 3714 1826-0121   |
| 1826-0825 | 3406 LM3999Z       | 2100         | 02585 1820-0494   | SOON     | 2910 1820-2457   |
| 1826-0826 | 3406 LH0070-1H     | 2102L-2PC    | 02237 1820-1078   | 82S103N  | 2910 1820-2494   |
| 1826-0828 | 2180 OP-15GJ       | 2102LHPC     | 02237 1818-0' _48 | 82541A   | 2910 1820-1862   |
| 1826-0829 | 2237 UA79M15AUC    | 21L02FPC     | 02237 1818-0757   | 8702[N   | 2763 1826-0621   |
| 1826-0830 | 3285 AD590LH       | 220-14120z   | 0283B 1820-1362   | 800[7    | 2763 1826-0593   |
| 1826-0832 | 3794 AM6080PC      | 2516N        | 02810 1818-0254   | 8T20     | 2290 1820-1048   |
| 1826-0833 | 2237 UA759U1C      | 25328        | 02910 1820-1220   | 8T38N    | 2910 1820-1875   |
| 1826-0837 | 3406 LM238K(STEEL) | 253314       | 02910 1820-160B   | 8798H    | 2910 1820-1863   |
| 1826-083B | 3285 AD7533JN      | 2602N        | 02910 1820-1228   | 90020[   | 2237 1820-0127   |
| 1825-0839 | 3285 AD566JN       | 26068        | 02910 1818-0155   | 90030[   | 2237 1820-0129   |
| 1826-0840 | 3285 AD583         | 26511        | 0291D 1820-2155   | 9004DC   | 2237 1820-0130   |
| 1826-0841 | 9274 MA-332-CP     | 26521        | 02910 1820-2163   | 9009DC   | 2237 1820-0131   |
| 1826-0842 | 3406 LM2917N       | 2661-11      | 02910 1820-2328   | 9015DC   | 2237 1820-0145   |
| 1826-0843 | 2237 UAF772HC      | 2661-11 REVA | 0291D 1820-2619   | 90160C   | 2237 1820-0132   |
| 1826-0845 | 2180 OP-07EJ       | 2740CF       | 02763 1813-0049   | 90300C   | 2237 1820-0612   |
| 1826-0846 | 3406 LF133320      | 29631ADC     | 02290 1816-1451   | 9112DC   | 2237 1820-0516   |
| 1826-0847 | 2180 REF-02HP      | 310I AN      | 02910 1820-1106   | 911HC    | 2237 1820-0081   |
| 1826-0849 | 2180 MUX-88FQ      | 3112/12C     | 05436 1813-0016   | 923HC    | 2237 1820-0052   |
| 1826-0850 | 2883 DG211CJ       | 320 7N       | 02910 1820-1008   | 9300PC   | 2237 1820-0134   |
| 1826-0851 | 3714 ICL7660CPA    | 3341AOC      | 02237 1818-0279   | 9304PC   | 2237 1920-0357   |
| 1826-8853 | 2180 REF-01HJ      | 33417[       | 02237 1818-0093   | 9305PC   | 2237 1820-0898   |
| 1826-0854 | 1921 CA3162E       | 334CJ        | 02763 1820-1129   | 9313PC   | 2237 1820-1063   |
| 1826-0955 | 3406 LM236AH       | 335113C      | 02237 1818-0422   | 9315PC   | 2237 1820-0231   |
| 1826-0856 | 3794 AM6080APC     | 340098DC     | 02237 1820-1906   | 9318PC   | 2237 1820-0657   |
| 1826-0857 | 3285 AD7522LN      | 347020[      | 02237 1820-1854   | 9319PC   | 2237 1820-2414   |
| 1826-0858 | 3285 AD558JD       | 3528AM       | 05436 1826-0767   | 931HC    | 2237 1820-0313   |
| 1826-0859 | 1698 TL376CNE      | 35392CP      | 08831 1818-1335   | 9321PC   | 2237 1820-0727   |
| 1826-0860 | 3799 HI1-562A-5    | 3816PC       | 02237 1820-2154   | 9322PC   | 2237 1820-0616   |



|           |                         |                                    |                  |          |                |
|-----------|-------------------------|------------------------------------|------------------|----------|----------------|
| 1826-0861 | 3285 AD7533LN           | 3B50PC                             | 02237 1820-1928  | 9324PC   | 2237 1820-0706 |
| 1826-0863 | 3406 LM1877N-9          | 3852PC                             | 02237 1820-2172  | 9324PC   | 2237 1820-0741 |
| 1826-0864 | 2180 DAC-87EX (RELAXED) | 3853PC                             | 02237 1820-2027  | 9334PC   | 2237 1820-0833 |
| 1826-0865 | 3295 AD7541KN           | 3854PC                             | 02237 1820-2173  | 934100C  | 2237 1820-0988 |
| 1826-0866 | 2037 MC1458SG           | 3861EPC                            | 02237 1820-2100  | 934150C  | 2237 1816-0914 |
| 1826-0867 | 3793 SG3547N            | 4008BPC                            | 02237 1820-2265  | 93415PC  | 2237 1816-1015 |
| 1826-0866 | 2634 UT-309             | 40097PC                            | 02237 1820-1266  | 934220C  | 2237 1816-1334 |
| 1826-0869 | 3794 AM686CN            | 4009BPC                            | 02237 1820-1484  | 934490[  | 2237 1816-0993 |
| 1826-0870 | 3406 LM337HVK           | 401189C                            | 02237 1820-1336  | 9348PC   | 2237 1820-0737 |
| 1826-0872 | 3406 LM1524             | 40163BPC                           | 02237 1820-2125  | 9351C    | 2237 1820-1347 |
| 1826-0873 | 350 XR-2209CN           | 40174PC                            | 02237 1820-1466  | 9368PC   | 2237 1820-1903 |
| 1426-0876 | 2763 ICL7107CPL         | 4019BPC                            | 02237 1820-2[85  | 9368PC   | 2237 1820-1979 |
| 1826-0877 | 3285 AD7574KN           | 4027BDC                            | 02237 1820-1813  | 9370PC   | 2237 1820-2002 |
| 1826-0878 | 3285 AD7503JN           | 40298PC                            | 02237 1820-2083  | 9374PC   | 2237 1820-1361 |
| 1825-0879 | 2883 DG301BA            | 4040BPC                            | 02237 1820-2264  | 93L00PC  | 2237 1820-0659 |
| 1826-0880 | 3406 LM335Z             | 4049BPC                            | 02237 1820-2[09  | 93L01PC  | 2237 1820-0627 |
| 1826-0881 | 4114 ADC-856C           | 40K                                | 03285 1813-0013  | 93L08PC  | 2237 1820-0614 |
| 1826-0882 | 1698 TL082CP            | 4104PC                             | 02237 1820-2032  | 93L09PC  | 2237 1820-0708 |
| 1859-0004 | 1921 CA3049             | 4512BPC                            | 02237 1820-1586  | 93L100 M | 2237 1820-1376 |
| 1859-0008 | 2037 MHQ6001            | 4725BPC                            | 02 237 1819-1012 | 93L10PC  | 2237 1820-0669 |
| 1858-0009 | 2037 MHQ2221            | 4JX19A519                          | 01973 1820-0006  | 93L10PC  | 2237 1820-1752 |
| 1859-0010 | 2037 MPQ2906            | 4JX19A555                          | 01973 1820-000I  | 93L11PC  | 2237 1820-0702 |
| 1858-0020 | 2237 SH6401PC           | 4JX19A581                          | 01973 1820-0[10  | 93L12PC  | 2237 1820-0658 |
| 1858-0021 | 1921 CA3083             | 5416DM                             | 02237 1820-1172  | 93L14DM  | 2237 1820-1377 |
| 1858-0022 | 3793 S63821N            | 6300-1J 04092 1816-0129            |                  | 93L14PC  | 2237 1820-070I |
| 1859-0023 | 1921 CA3081E            | 6300-17 PROGRAMMED 04092 1816-0041 |                  | 93L16PC  | 2237 1820-0778 |
| 1858-0032 | 1921 CA3146E            | 6309-1N 04092 1816-1371            |                  | 93L18PC  | 2237 1820-0987 |
| 1858-0034 | 2037 MPQ3725            | 6330-1J 04092 1816-0348            |                  | 93L21PC  | 2237 1820-1017 |
| 1858-0036 | 3285 AD821(SPEC)        | 63357 04092 1816-0994              |                  |          |                |
| 1858-0037 | 2634 ULN2082A           | 6340-1J 04092 1816-0439            |                  |          |                |
| 1858-0040 | 1921 CA3127E            | 6350-1J 04092 1816-1157            |                  |          |                |

INTEGRATED CIRCUIT CROSS REFERENCE

| 19             |      |                           |          |                       |                |
|----------------|------|---------------------------|----------|-----------------------|----------------|
| Desc.          | Mfr. | HP P/N                    | AD7524AD |                       |                |
| 93L22PC        |      | 2237 1820-0710AD7524JN    |          | 3285 1826-0699CA1458T | 1921 1816-0111 |
| 93L24PC        |      | 2237 1820-0904AD7525KN    |          | 3285 1826-0639CA239AE | 1921 1826-0814 |
| 93L28PC        |      | 2237 1820-0709AD7530JD    |          | 3285 1826-0636CA258AG | 1921 1826-0813 |
| 93L34PC        |      | 2237 1820-1358AD7530JN    |          | 3285 1826-0356CA258AT | 1921 1826-0768 |
| 93L40DC        |      | 2237 1820-1111A07530LD    |          | 3285 1810-1789CA3000  | 1921 1810-0297 |
| 93L412PC       |      | 2237 1816-1309AD7530LN    |          | 3285 1826-0504CA3002  | 1921 1820-0417 |
| 93L415PC       |      | 2237 1816-0723AD7533JN    |          | 3285 1826-0485CA3004  | 1921 1816-0087 |
| 93L422PC       |      | 2237 1816-1308AD7533LN    |          | 3285 1826-083BCA3005  | 1921 1820-0046 |
| 971100C        |      | 2277 1820-1373AD75A1JN    |          | 3285 1826-0861CA3010  | 1921 1820-0047 |
| 933120C        |      | 2237 1820-1290AD7541KN    |          | 3285 1826-0697CA3012  | 1921 1820-0474 |
|                |      | 2237 1820-1475A0754280    |          | 3285 1816-0865CA3018  | 1921 1810-0352 |
| 94000J 93S16DC |      | 2763 1826-0575AD7550BD    |          | 3285 1826-0752CA3018A | 1921 1858-0045 |
| 9401PC         |      | 2237 1820-2016AD7574JN    |          | 3285 1810-1995CA301AT | 1921 1820-0223 |
| 9403PC         |      | 2237 1816-0934AD1574KN    |          | 3285 1816-0713CA3020  | 1921 1820-0298 |
| 950030C        |      | 2237 1820-2242AD821(SPEC) |          | 3285 1826-0877CA3023  | 1921 1810-0433 |
| 95 04DC        |      | 2237 1820-1222ADC-856C    |          | 3285 1858-0036CA3026  | 1921 1820-0240 |
| 951020C        |      | 2237 1810-2321ADC0800PCD  |          | 4114 1826-0881CA3028A | 1921 1810-0306 |
| 9520C          |      | 2237 1820-0952ADC0801LCN  |          | 3406 1816-0517CA3028B | 1921 1810-0137 |
| 9520C          |      | 2237 1820-0972ADC0803LCD  |          | 3406 1826-0750CA3029  | 1921 1820-0326 |
| 9530C          |      | 2237 1820-0953ADC0804LCN  |          | 3406 1816-0733CA3030  | 1921 1826-0078 |
| 9570C          |      | 2237 1820-0973ADC0804N    |          | 3406 1826-0756CA3045  | 1921 1821-0002 |
| 9540C          |      | 2237 1820-0954ADC0816CCN  |          | 3406 1826-0717CA3045H | 1921 1858-0064 |
| 9550C          |      | 2237 1820-0955ADC80AG-12  |          | 3406 1826-0710CA3045  | 1921 1821-0001 |
| 956DC          |      | 2237 1810-0956AF134-1CJ   |          | 5436 1813-0098CA3049  | 1921 1858-0004 |
|                |      | 2237 1810-0974AH0019CD    |          | 3406 1816-0580CA3051  | 1921 1820-0249 |
| 9570C 9560C    |      | 2237 1820-0957AH0134CD    |          | 3406 1820-1988CA3053  | 1921 1826-0230 |
| 959DC          |      | 2237 1820-0110AH0152CD    |          | 3406 1820-1370CA3054  | 1921 1816-0780 |
| 95H90DC        |      | 2237 1820-1009AH0154D     |          | 3406 1810-1371CA3059  | 1921 1826-0041 |
| 9600DC         |      | 2237 1820-0875AH5024CN    |          | 3406 1813-0054CA3060D | 1921 1826-0015 |
| 9600C          |      | 2237 1820-0309AM1101A     |          | 3406 1820-1353CA3075  | 1921 1826-0153 |
| 96127C         |      | 2237 1820-2089AM1702AHDC  |          | 3794 1820-1006CA3079  | 1921 1826-0075 |
| 96137C         |      | 2237 1820-2088AM2502PC    |          | 3794 1818-0289CA307T  | 1921 1826-0043 |
| 9616PC         |      | 2237 1820-2094AM2505PC    |          | 3794 1820-2168CA3080  | 1921 1826-0185 |
|                |      |                           |          | 3794 1820-1398CA3080E | 1921 1816-0534 |

|              |                            |                             |                |
|--------------|----------------------------|-----------------------------|----------------|
| 96210C       | 2237 1820-1044AM25L04PC    | 3794 1810-1978CA3081E       | 1921 1858-0023 |
| 96240C       | 2237 1820-1005AM25LS07PC   | 3794 1810-1866CA3082E       | 1921 1858-0048 |
| 9627PC       | 2237 1820-2095AM25LS08PC   | 3794 1820-1865CA3082F       | 1921 1858-0057 |
| 9636ATC      | 2237 1820-2117AM25LS09PC   | 3794 1820-1867CA3083        | 1921 1858-0021 |
| 9637ATC      | 2237 1810-2198AM25LS14DC   | 3794 1810-2120CA3085        | 1921 1826-0292 |
|              | AM25LS14DC                 |                             |                |
| 9638TC       | 2237 1820-2199             | 3794 1820-1992CA3094AT      | 1921 1826-0167 |
| 96447C       | 2237 1820-2365AM25LS161APC | 3794 1820-2445CA3097E       | 1921 1858-0046 |
| 9640C        | 2237 1820-0964AM25LS2518PC | 3794 1810-2190CA3099E       | 1921 1826-0721 |
| 9650-1DC     | 2237 1826-0374AM25LS2520DC | 3794 1820-2405CA3100T       | 1921 1826-0218 |
| 9650C        | 2237 1810-0965AM25LS2521PC | 3794 1820-2311CA3102E       | 1921 1858-0063 |
| 9660C        | 2237 1810-0966AM25LS2538PC | 7794 1820-2465CA3127E       |                |
| 9670C        | 2237 1820-0967AM25LS2539PC | 3794 1820-2262CA31 OAS      | 1921 1816-0626 |
| 9670C        | 2237 1820-0975AM25LS2569DL | 3794 1820-2270CA3130T       | 1921 1826-0307 |
| 9680C        | 2237 1820-0968AM25LS2569PL | 3794 1820-2653CA3140AT      | 1921 1826-0679 |
| 96L02DC      | 2237 1810-0730AM25S07DC    | 3794 1820-2454CA3140E       | 1921 1816-0506 |
|              | AM25S08PC                  | 3794 1820-2375CA3140H       | 1921 1826-0549 |
| 96LS02PC     | 2237 1810-2600AM25S09PC    | 3794 1820-1981CA3140T       | 1921 1826-0465 |
| 96S02PC      | 2237 1820-2118AM25S10PC    | 3794 1820-2458043146E       | 1921 1858-0032 |
| 9710C        | 2237 1810-0971AM25S1 PC    | 3794 1820-2459CA3161E       | 1921 1820-2658 |
| 98060C       | 2237 1810-0520AM26LS32PC   | 3794 1820-2203CA3162E       | 1921 1826-0854 |
| 9816DC       | 2237 1820-0485AM26S02PC    | 3794 1820-1782CA3240AE      | 1921 1826-0653 |
| 98220C       | 2237 1820-0519AM27S07APC   | 3794 181G-1495CA3240E       | 1921 1816-0794 |
| 98340C       | 2237 1820-0486AM27S27DC    | 3794 1816-1406CA3290E       | 1921 1826-0810 |
| 98380C       | 2237 1820-0481AM2803HC     | 3794 1820-1579CA741CT       | 1921 1820-0203 |
| 98420C       | 2237 1820-0488AM2813ADC    | 3794 1818-0277CA74IG        | 1921 1826-0303 |
| 98520C       | 2237 1810-0187AM2901BDC    | 3794 1820-2556CD22100E      | 1921 1826-0658 |
| 98530C       | 2237 1820-0518AM2901BPC    | 3794 1810-2667C04000AE      | 1921 1810-0942 |
|              | 1820-0186                  |                             |                |
| 9856DC       | 2237 AM2903DC              | 3794 1820-2377CD4000BF      | 1921 1810-2227 |
| 9865DC       | 2237 1810-0517AM2909PC     | 3794 1820-2442CD4001AF      | 1921 1820-1534 |
| 9L24DC       | 2237 1820-1085AM2910DC     | 3794 1810-2378CD4001U       | 1921 1810-0946 |
| 9L86PC       | 2237 1810-1117AM301AH      | 3794 1826-0392CD44002A      | 1921 1810-1537 |
| 9LS192PC     | 2237 1810-1684AM31L01PC    | 3794 1816-0913CD4002U       | 1921 1810-0948 |
| 9S41PC       | 2237 1820-1927AM3705CD     | 3406 1820-1357CD4002U       | 1921 1810-0962 |
| A-4350       | 3780 1826-0247AM6012DC     | 3794 1816-0705C040063       | 1921 1810-2086 |
| AC5947N      | 1698 1820-2626AM6080APC    | 3794 1826-0856CD4007AE      | 1921 1810-0978 |
| AC5947NF     | 1698 1820-2169AM6080PC     | 3794 1826-0832CD4008AF      | 1921 1820-0926 |
| AC5948N      | 1698 1820-2567AM6081PC     | 3794 1816-0659CD4008BE      | 1921 1810-1955 |
| AD503K(SELI  | 3285 1816-0074AM685HL      | 3794 1826-0578CD4009AF      | 1921 1820-0979 |
| AD504J       | 3205 1826-0249AM686CN      | 3794 1826-0579CD40103B      | 1921 1810-2241 |
| AD506JH      | 3285 1826-0176AM686CN      | 3794 1816-0869CD4010AF      | 1921 1820-0980 |
| AD514K       | 3285 1816-0161AM686HC      | 3794 1826-0378C040116       | 1921 1820-2662 |
| AD518J       | 3285 1816-0309AM6487ADL    | 3794 1826-0426CD4011AF      | 1921 1810-1538 |
| AD518KH      | 3285 1826-0672AM74LS138N   | 3794 1810-1732CD4013U       | 1921 1820-0949 |
| AD518KH(SEL) | 3285 1826-0327AM74LS175N   | 3794 1810-1733CD4012AF0I921 | 1820-1539      |
| AD522A(SEL)  | 3285 1826-0595AM74LS244N   | 3794 1820-2161CD4012U       | 1921 1810-0950 |
| AD522BD      | 3285 1813-0142AM74S160N    | 3794 1820-1877CD4013AF      | 1921 1810-1531 |
| AD532JD      | 3285 1826-0263AM74S161     | 3794 1820-1876CD4013B       | 1921 1810-1963 |
| AD533JH      | 3285 1826-0295AM74S244N    | 3794 1810-2565CD4013BE      | 1921 1810-0939 |
| AD536K       | 3285 1826-0500AM74S533PC   | 3794 1820-2527CD4014AE      | 1921 1810-0970 |
| AD540J       | 3285 1816-0182AM74S534PC   | 3794 1820-2526CD4014BE      | 1921 1810-1514 |
| AD542KH      | 3285 1826-0822AM8224-4PC   | 3794 1820-2039CD4015AF      | 1921 1820-1541 |
| AD542L       | 3285 1826-0627AM8279PC     | 3794 1820-23610040158E      | 1921 1820-0976 |
| AD558JD      | 3285 1816-0858AM9080A-2DC  | 3794 1820-1701CD4016AE      | 1921 1820-0981 |
| AD559KD      | 3285 1816-0430AM9080A-4DC  | 3794 1810-2006CD4016AF      | 1921 1810-1675 |
| AD561JD      | 3285 1826-0508AM9101DPC    | 3794 1818-0343CD4016BE      | 1921 1820-1958 |
| AD561KD      | 3285 1820-198• AM9102APC   | 3794 1818-023BCD4017AE      | 1921 1820-0933 |
| AD562JD/BIN  | 3285 1820-1838AM9102BPC    | 3794 1818-0335C040,187      | 1921 1810-1666 |
| AD562KD/BIN  | 3285 1816-0308AM9112APC    | 3794 1818-0199CD40181B      | 1921 1810-1659 |
| AD565JN/BIN  | 3285 1826-0726AM9124BDC    | 3794 1818-0913CD4018AF      | 1921 1820-0934 |
| AD566JN      | 3295 1826-0839AM9130EDC    | 3794 1818-0389CD4018AF      | 1921 1810-1529 |
| AD581J       | 3285 1826-0742AM9131CDC    | 3794 1818-0361CD4018BE      | 1921 1820-2084 |
| AD581LH      | 3285 1826-0730AM91L118DC   | 3794 1818-0197CD4019AF      | 1921 1820-1553 |
| A0583        | 3285 1826-0840AM91L12APC   | 3794 1818-0322CD40L98E      | 1921 1820-0951 |
| AD584KH      | 3285 1816-0650AM91L12CPC   | 3794 1818-0294CD4020BE      | 1921 1810-0935 |
| AD584LH      | 3285 1826-0657AM91L30EDC   | 3794 1818-0313CD4021AF      | 1921 1820-0961 |
| AD590JH      | 3285 1826-0698AM93S48PC    | 3794 1820-1968CD4021BE      | 1921 1820-2031 |

|              |       |                           |       |                             |                |
|--------------|-------|---------------------------|-------|-----------------------------|----------------|
| AD590KF      | 032B5 | 1826-0764AM9511DC         |       | 3794 1820-2340CD4021BF0I921 | 1820-1898      |
| AD590KH      |       | 3285 1826-0661AM9513CC    | 037*4 | 1820-260• CD4022BE          | 1921 1810-0929 |
| AD590LH      |       | 3285 1816-0830AM9513PC    |       | 3794 1820-2705CD4023BF      | 1921 1820-1552 |
| AD741KH(SEL) |       | 3285 1826-0090AMZ8001-1DC |       | 3794 1820-263BCD4023U       | 1921 1810-0943 |
| AD741LH      |       | 3285 1826-0082AMZ8002-1DC |       | 3794 1810-2637CD4024BF      | 1921 1820-0936 |
| AD7502JN     |       | 3285 1826-0779AM28002DC   |       | 3794 1810-2553CD4024BF      | 1921 1810-1897 |
| AD7503JN     |       | 3285 1826-0878ATF431      |       | 3334 1826-0469CD4025AF      | 1921 1810-1535 |
| AD7506KD     |       | 3285 1826-0602C2101-1     |       | 3794 1818-0318CD4025U       | 1921 1820-0944 |
| AD7510DIJN   |       | 3285 1820-1374C21074      |       | 3811 1818-0128CD4026AE      | 1921 1820-0930 |
| AD7512DIJN   |       | 3285 1826-0821C2401       |       | 3794 1810-1062CD4027AE      | 1921 1820-1530 |
| AD7520JN     |       | 3285 1816-0162C2716       |       | 3811 1818-0794CD4027BE      | 1921 1810-0938 |
| AD7520LN     |       | 3285 1826-0264C8748-8     |       | 3811 1820-2433CD4027BE      | 1921 1820-1964 |
| AD7522JN     |       | 3285 1826-0729C8755A      |       | 3811 1818-0977CD4028AF      | 1921 1820-0927 |
| AD7522LN     |       | 3265 1826-0857CA 300I     |       | 1921 1820-0192CD4028BE      | 1921 1810-1962 |
| AD7523JN     |       | 3285 1816-0707CA1458G     |       | 1921 1826-0139CD4029BE      | 1921 1820-0931 |

20

# INTEGRATED CIRCUIT CROSS REFERENCE

| Dmc.     | Mfr. | HP P/N         |           |                |                          |
|----------|------|----------------|-----------|----------------|--------------------------|
| CD4029BF |      | 1921 1820-1529 | 02125H-2  | 3811 181B-1660 | DM85S68J 3406 1820-1985  |
| CD4030AE |      | 1921 1820-0947 | D2141-2   | 3811 1818-1215 | DM8678C 3406 1816-1339   |
| CD4030AF |      | 1921 1820-1536 | 02147H-1  | 3811 1818-1586 | DM86L75N 3406 1820-0986  |
| CD4031AE |      | 1921 1820-0963 | D2147H-3  | 3811 181B-1027 | DM86L76N 3406 1820-1057  |
| CD4031BF |      | 1921 1820-2231 | 02148H-3  | 3811 181B-1212 | DM86L99N 3406 1820-1394  |
| CD4032AE |      | 1921 1820-0925 | D2148HL   | 3811 1818-1468 | DM8959N 3406 1820-1587   |
| CD4033AE |      | 1921 1820-0932 | D2709     | 3811 181B-0250 | DM8884A 3406 1820-173B   |
| CD4034AE |      | 1921 1820-0977 | D2716-2   | 3811 1818-2702 | DMPAL12 3406 1820-2574   |
| CD4035AE |      | 1921 1820-0969 | D2732     | 3811 1818-0850 | DMPAL14 3406 1820-2573   |
| CD4035AF |      | 1921 1820-1554 | D2732-6   | 3811 1838-1254 | DMPAL16 3406 1820-2575   |
| CD4036AD |      | 1921 1820-0959 | D2732A    | 3811 1818-1648 | DPS212N 3406 1820-2077   |
| CD4037AE |      | 1921 1820-0945 | D27328    | 3811 1818-1721 | DP8304N 3406 1820-2239   |
| CD4038AE |      | 1921 1820-0924 | D27328-3  | 3811 1818-1633 | DRAM 6.8 065G3 1826-0091 |
| CD4039AD |      | 1921 1820-0960 | D2758     | 3811 1818-1062 | DS0025CN 3406 1820-0718  |
| CD4040AF |      | 1921 1820-1925 | D2764     | 3811 1818-1722 | DS0026C 3406 1820-1065   |
| CD4040BF |      | 1921 1820-0937 | 3242      | 3811 1820-2076 | DS0056CJ 3406 1820-2103  |
| CD4041AE |      | 1921 1820-0928 | 36248     | 3811 1816-0919 | DS3611N 3406 1820-1796   |
| CD4043U  |      | 1921 1820-2225 | 4201      | 3811 1820-2071 | DS3612N 3406 1820-2041   |
| CD4042AF |      | 1921 1820-0958 | 4289      | 3811 1820-2070 | OS3630% 3406 1826-0492   |
| CD40424F |      | 1921 1820-1540 | D8009-1   | 3811 1820-1221 | DS3631N 3406 1820-2174   |
| CD4042BE |      | 1921 1820-1956 | 80808     | 3811 1820-1613 | DS3632N 3406 1820-2290   |
| CD4043AE |      | 1921 1820-0941 | D8086-2   | 3811 1820-2596 | DS3649N 3406 1820-2234   |
| CD4043AE |      | 1921 1820-1533 | D8088     | 3811 1820-2620 | DS8800H 0340G 1820-1021  |
| CD4043BE |      | 1921 1820-2124 | 8224      | 3794 1820-1921 | DS8820AN 3406 1820-0721  |
| CD4044AE |      | 1921 1820-0940 | D82518    | 3911 1820-2289 | DS8822N 0340G 1820-1115  |
| CD4044AE |      | 1921 1820-1532 | D8253     | 3811 1820-2109 | DS8831N 3406 1820-0780   |
| CD4045AE |      | 1921 1820-1318 | D82598    | 3811 1820-2601 | DS8A34N 3406 1820-1845   |
| CD4045BF |      | 1921 1820-2226 | D8275     | 3811 1820-2191 | DS8835N 3406 1820-2161   |
| CD4046AE |      | 1921 1820-1188 | D8279-5   | 3811 1820-2150 | DS8839N 3406 1820-1870   |
| CD4047AE |      | 1921 1820-1317 | D8284     | 3811 1820-2598 | DS8863N 3406 1820-1740   |
| CD4047BF |      | 1921 1820-2230 | 8288      | 3811 1820-2597 | DS8867N 3406 1820-2363   |
| CD4048AE |      | 1921 1820-1316 | D8291     | 3811 1820-2357 | DS8871N 0340G 1820-213B  |
| CD4049AF |      | 1921 1820-1542 | 87418     | 3811 1820-2441 | DS8897N 3406 1820-1739   |
| CD4049U  |      | 1921 1820-1145 | 087, M8   | 3811 1820-2278 | DS88C20N 3406 1820-2417  |
| CD4050AF |      | 1921 1820-1543 | DAC-01CY  | 2180 1826-0020 | DS8973N 3406 1820-213G   |
| CD4050BE |      | 1921 1820-1146 | DAC-0860  | 2180 1820-1934 | ER2051 2713 1818-05G6    |
| CD4050BE |      | 1921 1820-1976 | DAC-100A  | 2190 1826-0453 | F1001000 2237 1820-2093  |
| CD40508E |      | 1921 1820-2644 | DAC-100B  | 2180 1826-0127 | F100142D 2237 1816-1469  |
| CD4051BE |      | 1921 1820-1315 | DAC-100C  | 2180 1826-0197 | F10014PC 2237 1820-2359  |
| CD4051BF |      | 1921 1820-1513 | DAC-100C  | 2180 1826-0577 | F10016DC 2237 1820-1788  |
| CD4052BE |      | 1921 1820-1314 | DAC-87EX  | 2180 1826-0864 | F11C06DC 2237 1820-2106  |
| CD4053BE |      | 1921 1820-1313 | DAC-HA12  | 4114 1813-0147 | F3871PC 2237 1820-2315   |
| CD4053BF |      | 1921 1820-1510 | DAC1200   | 3406 1826-0674 | FCM7002 2237 1820-2114   |
| CD4053BY |      | 1921 1820-1545 | DAC1202   | 3406 1826-0751 | FD1791A- 575 1820-2456   |
| CD4054BE |      | 1921 1820-1331 | DAC12QS   | 3285 0960-0632 | F01791B-0 575 1820-2329  |
| CD4059BE |      | 1921 1820-1646 | DAC16QM   | 3285 0960-0631 | GXB10188 2910 1820-2522  |
| CD4056BE |      | 1921 1820-2487 | DAC372-1  | 3755 1813-0036 | HA-20058 3799 1826-0270  |
| CD4059AD |      | 1921 1820-1649 | DAC80-CB  | 5436 1813-0105 | HA1-4605- 3799 1926-0532 |
|          |      |                | DAC90-CC  | 5436 1813-0092 | HA1-4905- 3799 1826-0792 |
|          |      |                | DDU-4-510 | 6852 1813-0120 | HA1-4925- 3799 1826-0714 |

|           |                |               |                |            |                |
|-----------|----------------|---------------|----------------|------------|----------------|
| CD4060AE  | 1921 1820-1667 | DG172BK       | 2883 1826-0105 | HA1-5195-  | 3799 1826-0700 |
| CD4060BE  | 1921 1820-2588 | DG182BP       | 2883 1826-0669 | HA2-2515-  | 3714 1826-0644 |
| CD4066AE  | 1921 1820-1325 | DG184BP       | 2883 1820-1724 | MA2-2525-  | 3714 1826-0482 |
| CD4066AY  | 1921 1820-1548 | DG200BA       | 2883 1820-1807 | HA2-2535   | 3799 1826-0689 |
| CB4067BF  | 1921 1820-1660 | DG2008A       | 2883 1826-0154 | HA2-2605-  | 3799 1826-0413 |
| CD4067BF  | 1921 1820-2221 | DG201BK       | 2883 1826-0606 | HA2-2625-  | 3799 1826-0109 |
| CB4068BE  | 1921 1820-1410 | DG201CJ       | 2883 1820-1840 | MA2-2655-  | 3799 1826-0425 |
| CD4068BF  | 1921 1820-2330 | DG201CJ       | 2883 1820-1971 | MA2065-5   | 3799 1826-0365 |
| CD4069U   | 1921 1820-1404 | DG211CJ       | 2883 1826-0850 | HA3-2507-  | 3799 1826-0735 |
| CD4070BE  | 1921 1820-1601 | DG300CJ       | 2883 1826-0778 | HA3-2607-  | 3799 1826-0721 |
| CD4071BE  | 1921 1820-1493 | DG301BA       | 288 1826-0879  | HA3-2627-  | 3799 1826-0736 |
| CD4071BF  | 1921 1820-1550 | DG302CJ       | 2883 1826-0776 | HI1-1818A- | 3799 1826-0429 |
| CD4072BE  | 1921 1820-1403 | DG303BP       | 2883 1826-0769 | H11-562A-  | 3799 1826-0860 |
| CD4073BE  | 1921 1820-1408 | DG303CJ       | 2883 1826-0777 | HI2-200-5  | 3799 1820-1781 |
| CD4075BE  | 1921 1820-1405 | DG506BR       | 2883 1820-1841 | HM-6551-9  | 3799 1818-0497 |
| CD4076BE  | 1921 1820-1578 | DG508BK       | 2883 1826-0605 | HM1-6514-  | 3799 1818-1370 |
| CD4076BF  | 1921 1820-1544 | DG508CJ       | 2883 1820-1725 | HMI-6514-  | 3799 1818-0590 |
| CD4077BE  | 1921 1820-1672 | DH0034CD      | 3406 1813-0160 | HM1-6561   | 3799 1818-0439 |
| CD4078BE  | 1921 1820-1407 | DH0035C       | 3406 1820-1797 | HM1-7611-  | 3199 1816-1416 |
| CD4078BF  | 1921 1820-2331 | DM10415       | 3406 1816-1460 | ". .41-2   | 3799 1816-1152 |
| CD4081BE  | 1921 1820-1486 | DM2504C       | 3406 1820-1720 | HMI-76438  | 3799 1816-1429 |
| CD4081BE  | 1921 1820-1498 | DM5406N       | 3406 1820-1043 | HMI17644-  | 3799 1816-0987 |
| CD4081BF  | 1921 1820-1551 | DM74L00N      | 3406 1820-1518 | HMI-7649-  | 3799 1816-1481 |
| CD4082BE  | 1921 1820-1409 | DM74L164      | 3406 1820-0602 | HM10470    | 6347 1816-1459 |
| CD4085BF  | 1921 1820-2017 | DM74L42       | 3406 1820-1047 | HM3-6514-  | 3799 1818-0989 |
| CD04086B  | 1921 1820-2018 | DM74L71N      | 3406 1820-0593 | HM3-6514-  | 3799 1818-0955 |
| CD4089BE  | 1921 1820-1661 | DM74L72N      | 3406 1820-0594 | HM3-7621-  | 3799 1816-1382 |
| C0409384  | 1921 1820-1600 | DM74L73N      | 3406 1820-0595 | HM3-7643-  | 3799 1816-1467 |
| CD4093BF  | 1921 1820-1577 | DM74L74N      | 3406 1820-0596 | HM4334P-   | 6347 1818-1628 |
| CD4094BE  | 1921 1820-1662 | DM74L78N      | 3406 1820-0597 | HM4864-3   | 6347 1818-1559 |
| CD4094BF  | 1921 1820-2222 | DM74L85N      | 3406 1820-0603 | HM6116P-   | 6347 1818-1611 |
| CD4035BE  | 1921 1820-1663 | DM74L90N      | 3406 1820-0600 | HM6147P    | 6347 1818-1667 |
| CD4096BE  | 1921 1820-1664 | DM74L93N      | 3406 1820-0601 | HM6147P-   | 6347 1818-1596 |
| CD4097BE  | 1921 1820-2209 | DM74L95N      | 3406 1820-0599 | "PROM-82   | 3799 1816-0409 |
| CD4097BF  | 1921 1820-1881 | DM74LS1       | 3406 1820-1885 | HPROM1-    | 3799 1816-1056 |
| CD40988E  | 1921 1820-1650 | DM74LS1       | 3406 1816-1089 | HPROM1-    | 3799 1816-0015 |
| CD4099BE  | 1921 1820-1665 | DMA090N       | 3406 1820-1148 | HS-200-1.  | 1417 1813-0167 |
| CD4099BE  | 1921 1820-2233 | DM8094N       | 3406 1820-0846 | HS -400-6  | 1417 1813-0148 |
| CD4508BE  | 1921 1820-1959 | DM8095N       | 3406 1820-1254 | HY-5002    | 7915 1813-0189 |
| CD4511BE  | 1921 1820-1413 | DMS099N 0340G | 1820-2098      | HT-5003    | 7915 1813-0199 |
| CD4911BE  | 1921 1820-1957 | DM8121N       | 3406 1820-1295 | ICL 8013C  | 3714 1826-0455 |
| CD4512BE  | 1921 1820-1241 | DM8123N       | 3406 1820-1294 | ILL 8049 C | 3714 1826-0432 |
| CD4512BF  | 1921 1820-2229 | DM8130N 0340G | 1820-1293      | ICL 8250   | 3714 1826-0387 |
| CD4514BE  | 1921 1820-1683 | OM8131%       | 3406 1820-2353 | ICL7101C   | 3714 1820-2025 |
| CD4516BF  | 1921 1820-1899 | DMS160N       | 3406 1820-1131 | ICL7107C   | 2763 1826-0876 |
| CD4520BF  | 1921 1820-1900 | DM81L23N      | 3406 1820-1167 | ICL7109C   | 3714 1826-0746 |
| CD4555BE  | 1921 1820-1516 | DMS1LS9       | 3406 1820-1794 | ICL741C-L  | 3714 1826-0391 |
| CD4555BF  | 1921 1820-1556 | DM81LS9       | 3406 1820-1672 | ICL7605CJ  | 3714 1826-0761 |
| CD4556BE  | 1921 1820-1515 | DM81LS9       | 3406 1820-1759 | ICL7611B   | 3714 1826-0765 |
| CD4556BF  | 1921 1820-1555 | DM81LS9       | 3406 1820-1873 | ICL7660C   | 3714 1826-0851 |
| CDR125B   | 2569 1826-0152 | DMR200N       | 3406 1820-0623 | ICL8001CT  | 3714 1826-0129 |
| CG725Y    | 2910 1818-0036 | DM8214N       | 3406 1820-0906 | ICL8008CT  | 3714 1826-0131 |
| CMP-01-C  | 2180 1826-0116 | DM8220N       | 3406 1820-0505 | ICL8052C   | 3714 1826-0446 |
| CO-233M   | 3444 1813-0161 | 49520%        | 3406 1820-1292 | ICL8069D   | 3714 1826-0_73 |
| CO-233M   | 3444 1813-0163 | OX8542        | 3406 1820-14G8 | ICL8211CT  | 3714 1826-0540 |
| CO-233M   | 3444 1813-0162 | DM8552N       | 3406 1820-1143 | ICL8212C   | 3714 1826-0408 |
| CRT5027P  | 1425 1820-2627 | DM8553N       | 3406 1820-1113 | ICM7209IP  | 3714 1813-0150 |
| D1398P    | 2883 1820-2345 | DM8554N 0340G | 1820-1291      | ICM7218A   | 3714 1820-2132 |
| D21158    | 3811 1818-0772 | DM8555N       | 3406 1820-1857 | ICM7226A   | 3714 1820-2187 |
| D2115AL   | 3811 1818-0332 | DM8556N       | 3406 1820-1874 | ICM7227AI  | 3714 1820-2646 |
| D2118-4 ( | 3811 1818-1424 | DM8590N       | 3406 1820-02G2 | ICM7227CI  | 3714 1820-2647 |
| D2118-7 ( | 3811 1818-1425 | DM85L51N      | 3406 1820-1166 | ICM7555IP  | 3714 1820-246G |
| D2125AL   | 3811 1818-1026 | DM85L52N      | 3406 1820-1472 | 108039     | 3811 1820-2528 |
| 02125H-1  | 3811 1818-1663 | DM85L54N      | 3406 1820-1349 | IDM2901A   | 3406 1820-2422 |

# INTEGRATED CIRCUIT CROSS REFERENCE

|       |      |        |         |                |                       |
|-------|------|--------|---------|----------------|-----------------------|
| 21    |      |        |         |                |                       |
| Desc. | Mfr. | HP P/N | LF356BN | 3406 1826-0433 | LM338K 3406 1826-0677 |

|             |                |                |                |                 |                 |
|-------------|----------------|----------------|----------------|-----------------|-----------------|
| IDM2901A    | 3406 1820-223B | LF356G         | 2037 1826-0719 | LM339AJ 0340G   | 1826-0306       |
| IDM2911A    | 3406 1820-2523 | LF357H         | 3406 1826-0357 | LM339AN         | 3406 1826-0666  |
| 1H401A      | 3714 1858-0066 | LF398H         | 3406 1826-0503 | LM339J          | 2037 1826-0759  |
| IH5010CP    | 3714 1833-0034 | LF398N         | 3406 1826-0791 | LM339N          | 1698 182G-0138  |
| 1H5012CP    | 3714 1826-0193 | LH-0053..      | 3406 1826-0439 | LM340AK-        | 3406 1826-0536  |
| IH5018CP    | 3714 1826-0193 | LH0002CH       | 3406 1820-0224 | LM340AT-        | 3406 1826-0607  |
| IH5020CP    | 2569 1820-1235 | LH0021CK       | 3406 1:13-0058 | LM340K-2        | 3406 1826-0559  |
| IH5027CP    | 3714 1826-0790 | LH0022CH       | 3406 1826-0405 | LM340K-8        | 3406 1826-0370  |
| IH5028CP    | 3714 1826-0442 | LH0024CH       | 3406 1813-0057 | LM34 0LA        | 3406 1826-0438  |
| 1H5032CP    | 3714 1826-0489 | LH0033CG       | 3406 1826-0481 | LM340LAZ        | 3406 1826-0554  |
| IH5035CP    | 3714 1826-0490 | LH0042CD       | 3406 1826-0459 | LM310LAZ        | 3406 1826-0555  |
| IH5043CD    | 2569 1820-1234 | LH0042CH       | 3406 1813-0041 | LM341P-1        | 3406 1826-0435  |
| IM5013AC    | 3714 1826-0740 | LH0044AC       | 3406 1826-0472 | LM 341P-2       | 3406 1826-0436  |
| 13 COD      | 3714 1820-1363 | LH0044 H       | 3406 1826-0594 | LM341P-8.       | 3406 1826-0434  |
| IM5600CP    | 3714 1820-0781 | LH0062CD       | 3406 1826-0267 | LM342P-1        | 3406 1826-0648  |
| IM5610CP    | 3714 1816-0053 | LH0062CH       | 3406 1826-0108 | LM343D          | 3406 1826-0632  |
| IM5623CP    | 3714 1816-0217 | LH0070-1H      | 3406 1826-031G | LM343H          | 3406 1826-06 34 |
| IM6402-1I   | 3714 1816-1433 | LH0070-1H      | 3406 1826-0826 | LM348J          | 3406 1826-0557  |
| IM6402CD    | 3714 1820-2204 | LM 0070-20340G | 1826-0414      | LM348N          | 3406 1826-0315  |
| IM6508IDE   | 3714 1820-2087 | LH0071-1H      | 3406 1826-0788 | LM350K          | 3406 1826-0631  |
| IM 65X61-   | 3714 1818-0390 | LH0091CD       | 3406 1826-0499 | LM355-1H        | 3406 1826-0314  |
| IM6653JUG   | 3714 1818-1009 | LM103H-2.      | 3406 1826-0812 | LM358AH         | 3406 1826-0592  |
| ii 6654-1IJ | 3714 1818-1520 | LM 10CH        | 3406 1826-0773 | LM358H          | 3406 1826-0678  |
| IM7512CP    | 3714 1818-1351 | LM1113-2H      | 3406 1826-0329 | LM358N          | 3406 1826-0346  |
| IMD2911A    | 3714 1818-0107 | LM129AH        | 3406 1826-0802 | LM360N-8        | 3406 1826-0638  |
| INS8250N    | 3406 1820-2260 | LM13340-       | 3406 1826-0336 | LM361H          | 3406 1826-0272  |
| K1091A-1    | 3406 1820-2443 | LM1524         | 3406 1826-0872 | LM361N          | 3406 1826-0210  |
| K1091A-1    | 3795 1813-0047 | LM161J         | 3406 1826-0548 | LM370N          | 3406 1826-0245  |
| .091A-5     | 3795 1813-0043 | LM1877N-       | 3406 1826-0863 | LM371N          | 3406 1826-0104  |
| K1091A-6.   | 3795 1813-0045 | LM201AL        | 1698 1826-0059 | LM377N          | 3406 1:26-0348  |
| K1091A-7.   | 3795 1:13-0053 | LM205H         | 3406 1826-0017 | LM380N          | 3406 1826-0709  |
| K1100 A     | 3795 1813-0052 | LM207H         | 3406 1826-0113 | LM380N-8        | 3406 1826-0209  |
| K1100A-1.   | 3795 1813-0128 | LM208AH        | 3406 1826-0025 | LM381N          | 3406 1826-0206  |
| K11 00A-1   | 3795 1813-0134 | LM208D         | 3406 1826-0268 | LM385BZ 0340G   | 1826-0774       |
| K1100A-1    | 3795 1813-0117 | LM209K         | 3406 182G-0324 | LM 386N-1       | 3406 1826-0682  |
| K1100A-10   | 3795 0960-0566 | LM211H         | 3406 1826-0098 | LM3900N         | 3406 1826-0120  |
| K11 00A-1   | 3795 1813-0139 | LM212H         | 3406 1826-0110 | LM3909N         | 3406 1826-0419  |
| K1100A-1    | 3795 1813-0062 | LM218H         | 3406 1826-0488 | LM3911N         | 3406 1826-0390  |
| K1100A-1    | 3795 1813-0046 | LM220K-1       | 3406 1826-0235 | LM3914N         | 3406 1826-0655  |
| K1100A-1    | 3795 1813-0135 | LM220K-1       | 3406 1826-0233 | LM393N          | 3406 1826-0412  |
| K1100A-2    | 3795 1813-0164 | LM220K-5.      | 3406 1826-0397 | LM395K          | 3406 1826-0320  |
| K1100A-2    | 3795 0960-0572 | LM220K-5.      | 3406 1826-0537 | LM3999Z         | 3406 1826-0825  |
| K1100A-2    | 3795 1813-0356 | LM224J         | 3406 1826-0232 | LM399H          | 3406 1902-0908  |
| K1100A-2    | 3795 0960-0569 | LM236AH        | 3406 1826-0855 | LM4250CH        | 3406 1826-0165  |
| K1100A-2    | 3795 1:13-0089 | LM236H         | 3406 1826-0766 | LM4250CN        | 3406 1826-0747  |
| K1100A-2    | 3795 1813-0154 | LM237K         | 3406 1826-0763 | LM555CN         | 3406 1826-0373  |
| K1100A-4    | 3795 1813-0119 | LM238K(S       | 3406 1826-0837 | LM709H          | 3406 1820-01G2  |
| K1100A-8.   | 3795 1813-0061 | LM250K S       | 3406 1826-0748 | LM725H          | 3406 1826-0711  |
| K1100A-9.   | 3795 0960-0567 | LM258H         | 3406 1826-0745 | LM78L10A        | 3406 1826-0394  |
| K1100A-9.   | 3795 1813-0116 | LM261H         | 3406 1826-0762 | LX5700H         | 3406 1826-0375  |
| K1114A-1    | 3795 1813-0121 | LM271H         | 3406 1826-0398 | MA-3 32-C       | 9274 1826-0841  |
| K1114A-2    | 3795 0960-0570 | LM2904N        | 3406 1826-0611 | M8 7042N OG344  | 1816-1415       |
| K1115A-1.   | 3795 0960-0581 | LM2917N        | 3406 1826-0842 | MB7072N         | 6344 1816-1398  |
| K1115A-1    | 3795 1813-0067 | LM293P         | 1698 1826-0479 | MB8164E(        | 6344 1818-1717  |
| K1115A-2.   | 3795 1813-0144 | LM299H         | 3406 1826-0330 | M88866-8 06 344 | 1820-2631       |
| K11354      | 3795 1:13-0131 | LM300H         | 3406 1820-0123 | MBM1042         | 6344 1816-1462  |
| K11358      | 3795 1813-0153 | LM301AD        | 2237 1826-0069 | M.,10474        | 6344 1816-1492  |
| K1144A-2    | 3795 1813-0146 | LM301AH,       | 3406 1820-0242 | MC1001P         | 2037 1820-0472  |
| K1145A-2    | 3795 1813-0166 | LM302H         | 3406 1820-0158 | MC1004P         | 2037 1820-0342  |
| K1148A-1    | 3795 1:13-0349 | LM305H         | 3406 1820-0247 | MC1006P         | 2037 1820-0666  |
| KR2376-S    | 1425 1820-2625 | LM306H         | 3406 1820-0475 | MC1007P         | 2037 1820-0147  |
| L-13-04     | 1854 1820-2572 | LM307N         | 3406 1820-0493 | MC10100L        | 2037 1820-1990  |
| L144CJ      | 2883 1826-0401 | LM308AH        | 3406 1826-0035 | MC10100P        | 2037 1820-2517  |
| L2-0V-12    | 6545 1826-0693 | LM308H         | 3406 1820-0478 | MC10101P        | 2037 1820-0801  |
| 1.2-0V-15   | 6545 1826-0692 | LM30 8N        | 3406 1826-0172 | MC10102P        | 2037 1820-0802  |
| L2-0"-20    | 6545 1826-0691 | LM309H         | 2910 1820-0429 | MC10103L        | 2037 1820-1831  |
| L2-0 V-5    | 6545 1826-0694 | LM309K         | 2237 1820-0430 | MC10103P        | 2037 1820-1686  |
| 1.6-D V-5   | 6545 1826-0731 | LM310H         | 3406 1826-0021 | MC10104P        | 2037 1820-1400  |

|                |                       |           |                |          |                 |
|----------------|-----------------------|-----------|----------------|----------|-----------------|
| L6-0 V-5       | 6545 1826-0732        | LM310N    | 3406 1826-0208 | MC10105P | 2037 1820-0803  |
| L8114-4CJ      | 0.577083333 1818-1616 | LM311F    | 7406 1826-0077 | MC10106P | 2037 1820-01104 |
| LAS 19U        | 6545 1826-0`_91       | LM311L    | 1826-0026      | MC10107P | 2037 1:20-0805  |
| LAS-1515       | 6545 1826-0402        | LM312H    | 3406 1826-0102 | MC10109P | 2037 1820-0806  |
| LAS-1815       | 6545 1826-0403        | LM312J    | 3406 1826-0201 | MC1010P  | 2037 1820-0145  |
| LAS15A15       | 6545 1826-0819        | LM316AH   | 3406 1826-0112 | MC10110P | 2037 1820-0807  |
| LA S18A1       | 6545 1826-0820        | LM317H    | 3406 1826-0539 | MC10111P | 2037 1820-0808  |
| LA S1912       | 6545 1826-0784        | LM317HV   | 3406 1826-0687 | MC10113L | 2037 1820-1882  |
| LAS1915        | 6545 1826-0754        | LM317K    | 3406 1826-0423 | MC10113P | 2037 1820-2508  |
| LD 110CJ       | 2883 1820-1252        | LM317KC   | 1698 1826-0393 | MC10114P | 2037 1820-2324  |
| LD111CJ        | 2883 182G-0195        | LM317LZ   | 2037 1826-0772 | MC10115L | 2037 1820-1945  |
| LD114 CJ       | 2883 1820-1474        | LM318H    | 3406 1826-0081 | MC10115P | 2037 1820-0:09  |
| LD120CJ        | 2883 1826-0588        | LM318P    | 1698 1826-0207 | MC10116L | 2037 1820-1308  |
| LD121CJ        | 2883 1826-0587        | LM319H    | 3406 1826-0191 | MC10116P | 2037 1820-0810  |
| LOBO.]         | 2883 1826-0452        | LM319J    | 3406 1826-0141 | MC10117L | 2037 1820-1946  |
| LF11508D       | 3406 1826-0695        | LM319N    | 1826-0175      | MC10117P | 2037 1820-0811  |
| LF13201D       | 3406 1826-0582        | LM320H-0  | 3406 1826-0220 | MC10118P | 2037 1820-0812  |
| LF13201N       | 3406 1820-1941        | LM320H-1  | 3406 1826-0178 | MC10119P | 2037 1820-0813  |
| LF13202N       | 3406 1820-1986        | LM320H-1  | 3406 1826-0192 | MC1011P  | 2037 1820-0582  |
| LF13331        | 3406 1820-1795        | LM320H-5. | 3406 1826-0179 | MC10121P | 2037 1820-0:15  |
| LF13331D       | 3406 1826-0416        | LM320H-6  | 3406 1826-0568 | MC10123P | 2037 1820-2399  |
| LF13332D       | 3406 1826-0846        | LM320K-0  | 3406 1826-0202 | MC10124L | 2037 1:20-1173  |
| LF13332N       | 3406 182G-0510        | LM320K-1  | 3406 1826-0169 | MC10125L | 2037 1820-1052  |
| LF13333D       | 3406 1826-0417        | LM320K-5. | 3406 1826-0173 | MC10128L | 2037 1820-2400  |
| LF13333N       | 3406 1826-0480        | LM320T-15 | 3406 1826-0277 | MC10129L | 2037 1820-2482  |
| LF13508D       | 3406 1826-0581        | LM320T-18 | 3406 1826-0377 | MC10130L | 2037 1820-1944  |
| LF13509D       | 3406 1826-0590        | LM320T-8. | 3406 1826-0449 | MC10130P | 2037 1820-0:16  |
| LF13741H 0340G | 1826-0552             | LM321H    | 3406 182G-0162 | NC1131P  | 2037 1820-0817  |
| LF255H         | 3406 1826-0458        | LM322N    | 3406 1826-0225 | MC10132P | 2037 1820-2476  |
| LF255N         | 2037 1826-0801        | LM323K    | 3406 1826-0181 | MC10133L | 2037 1820-0818  |
| LF256H         | 3406 1826-0371        | LM324AN   | 3406 1826-0524 | MC10133P | 2037 1820-2475  |
| LF256H. S      | 3406 1826-0358        | LM324F    | 3406 1826-0291 | MC10134L | 2037 1820-0819  |
| LF257H         | 3406 1826-0447        | LM325AS   | 3406 182G-0238 | MC10135L | 2037 1820-0P20  |
| LF298H         | 3406 1826-0422        | LM325H    | 3406 1826-0457 | MC10136L | 2037 1820-0821  |
| LF311H         | 3406 1826-0497        | LM325S    | 3406 1826-0283 | MC10137L | 2037 1820-0822  |
| LF347BN        | 3406 1826-0G65        | LM326H    | 3406 1826-0533 | MC10138L | 2037 1820-1383  |
| LF351AH        | 3406 182G-0686        | LM329     | 3406 1902-0928 | MC1013P  | 2037 1820-0102  |
| LF351H         | 3406 1826-0685        | LM329DZ   | 3406 1826-0585 | MC10140  | 2037 1820-0824  |
| LF351N         | 3406 1826-0667        | LM334Z    | 3406 1826-0623 | MC10141L | 2037 1820-0825  |
| LF353BN        | 3406 1826-0734        | LM335AZ   | 3406 182G-0760 | MC1014P  | 2037 1820-0213  |
| LF353H         | 3406 1826-0704        | L M3352   | 1826-0880      | MC10153L | 2037 1820-2507  |
| LF353N         | 3406 1826-0712        | LM337H    | 3406 1826-0558 | MC10158L | 2037 1820-1993  |
| LF355H         | 3406 1826-0304        | LM337HV   | 3406 1826-0870 | MC10159L | 2037 1820-2347  |
| LF356AG        | 2037 1826-0668        | LM337K    | 3406 1826-0523 | MC1015P  | 2037 1820-0180  |
| LF356BH        | 3406 1826-0528        | LM337T    | 3406 1826-0527 | MC10160L | 2037 1820-0826  |

22  
INTEGRATED CIRCUIT CROSS REFERENCE

| WILEX-ANALYTICAL CROSS REFERENCE |      |                 |          |                |         |                |
|----------------------------------|------|-----------------|----------|----------------|---------|----------------|
| Desc.                            | Mfr. | HP P/N          |          |                |         |                |
|                                  |      |                 | MC14024  | 2037 1820-1506 | MC14569 | 2037 1820-2383 |
|                                  |      |                 | MC14025  | 2037 1820-1965 | MC1456C | 2037 1826-0003 |
| MC10161L                         |      | 2037 1820-2504  | MC14025  | 2037 1820-1498 | MC1456G | 2037 1826-0071 |
| MC10161P                         |      | 2037 1820-0827  | MC14027  | 2037 1820-1496 | MC14572 | 2037 1820-1657 |
| MC10162L                         |      | 2037 1820-2067  | MC14028  | 2037 1820-1526 | MC14583 | 2037 1820-1389 |
| MC10162P                         |      | 2037 1820-0828  | MC14028  | 2037 1820-1512 | MC14584 | 2037 1820-2019 |
| MC10163L                         |      | 2037 1820-2`_03 | MC14032  | 2037 1820-2223 | MC14585 | 2037 1820-1340 |
| MC10163P                         |      | 2037 1820-2421  | MC14034  | 2037 1820-2232 | MC1458C | 2037 1826-0142 |
| MC10164L                         |      | 2037 1820-0829  | MC14035  | 2037 1820-2080 | MC1458N | 2037 1826-0556 |
| MC10165L                         |      | 2037 1820-2`_02 | MC14038  | 2037 1820-2224 | MC1458S | 2037 1826-0866 |
| MC10165P                         |      | 2037 1820-2449  | MC1403P1 | 2037 1826-0467 | MC1458S | 2037 1826-0420 |
| MC10166L                         |      | 2037 1820-2323  | MC1403U  | 2037 1826-0544 | MC1460R | 2037 1820-0277 |
| MC10166P                         |      | 2037 1820-2381  | MC14040  | 2037 1820-2054 | MC14636 | 2037 1826-0033 |
| MC10168P                         |      | 2037 1820-2451  | MC14040  | 2037 1820-1495 | MC1463R | 2037 1826-0032 |
| MC1016P                          |      | 2037 1820-0440  | MC14042  | 2037 1820-1501 | MC1468L | 2037 1826-0128 |
| MC10170L                         |      | 2037 1820-2501  | MC14042  | 2037 1820-1912 | MC1468R | 2037 1826-0140 |
| MC1017D                          |      | 2037 1820-2477  | MC14044  | 2037 1820-2228 | MC1469G | 2037 1826-0006 |
| MC10171L                         |      | 2037 1820-2500  | MC14046  | 2037 1826-0470 | MC1469R | 2037 1826-0024 |
| MC10171P                         |      | 2037 1820-2420  | MC14049  | 2037 1820-1505 | MC1488L | 2037 1820-0509 |
| MC10172L                         |      | 2037 1820-2499  | MC14049  | 2037 1820-1746 | MC1489L | 2037 1820-0510 |

|          |                 |          |                 |          |                |
|----------|-----------------|----------|-----------------|----------|----------------|
| MC10172P | 2037 1820-2455  | MC1404U5 | 2037 1826-0718  | MC1494L  | 2037 1826-0036 |
| MC10173L | 2037 1820-2498  | MC14050  | 2037 1820-1521  | MC1495L  | 2037 1826-0437 |
| MC10173P | 2037 1820-2401  | MC14051  | 2037 1820-1547  | MC1496G  | 2037 1820-0427 |
| MC10174L | 2037 1820-2497  | MC14051  | 2037 1820-2013  | MC1496L  | 2037 1826-0023 |
| MC10174P | 2037 1820-1359  | MC14052  | 2037 1820-1546  | MC1510G  | 2037 1826-0002 |
| MC10175L | 2037 1820-2496  | MC14052  | 2037 1826-0486  | MC1514L  | 2037 1826-0125 |
| MC10175P | 2037 1820-2402  | MC14053  | 2037 1826-0501  | MC1531G  | 2037 1820-0050 |
| MC10176L | 2037 1820-2193  | MC1405L  | 2037 1826-0642  | MC1545G  | 2037 1826-0103 |
| MC10176P | 2037 1820-1399  | MC14066  | 2037 1826-0502  | MC1550G  | 2037 1826-0028 |
| MC10178L | 2037 1820-2066  | MC14068  | 2037 1820-1931  | MC1555G  | 2037 1826-0400 |
| MC10178P | 2037 1820-1632  | MC14069  | 2037 1820-1592  | MC1558G  | 2037 1826-0243 |
| MC10179L | 2037 1820-0830  | MC14069  | 2037 1820-2014  | MC1590G  | 2037 1826-0037 |
| MC10179P | 2037 1820-2474  | MC1406L  | 2037 1826-0155  | MC1595L  | 2037 1826-0014 |
| MC1017P  | 2037 1820-0146  | MC14070  | 2037 1820-1908  | MC1648L  | 2037 1820-1119 |
| MC10180P | 2037 1820-2481  | MC14070  | 2037 1820-2015  | MC1648P  | 2037 1820-1108 |
| MC10181L | 2037 1820-0831  | MC14071  | 22037 1820-1970 | MC1650L  | 2037 1820-0919 |
| MC10182P | 2037 1820-2478  | MC14071  | 2037 1820-1388  | MC1658P  | 2037 1826-0509 |
| MC10183L | 2037 1820-2479  | MC14073  | 2037 1820-1910  | MC1660L  | 2037 1820-0790 |
| MC10186P | 2037 1820-2403  | MC14075  | 2037 1820-1909  | MC1662L  | 2037 1820-0796 |
| MC10189P | 2037 1820-2385  | MC14075  | 2037 1820-2091  | MC1664L  | 2037 1820-0795 |
| MC10189P | 2037 1820-2450  | MC14076  | 2037 1820-2220  | MC1670L  | 2037 1820-0794 |
| MC101BP  | 2037 1820-0144  | MC14077  | 2037 1820-1907  | MC1672L  | 2037 1820-0797 |
| MC10194P | 2037 1820-2480  | MC14078  | 2037 1820-1930  | MC1674L  | 2037 1820-0793 |
| MC10195P | 2037 1820-1685  | MC14081  | 2037 1820-2037  | MC1678L  | 2637 1820-2664 |
| MC10197P | 2037 1820-2023  | MC14082  | 2037 1820-2090  | MC1690L  | 2037 1820-1132 |
| MC10198L | 2037 1820-2376  | MC1408L- | 2037 1826-02248 | MC1692L  | 2037 1820-0920 |
| MC1019P  | 2037 1820-1036  | MC1408L- | 2037 1826-0188  | MC1694L  | 2037 1820-1334 |
| MC1020P  | 2037 1820-02212 | MC14093  | 2037 1820-1936  | MC1697P  | 2037 1820-1852 |
| MC1021DL | 2037 1820-1830  | MC14174  | 2037 1820-2258  | MC1723C  | 2037 1820-0196 |
| MC10210P | 2037 1820-2495  | MC14175  | 2037 1820-2279  | MC1723L  | 2037 1826-0409 |
| MC10211P | 2037 1820-1482  | MC1420G  | 2037 1826-0200  | MC1733CL | 2037 1826-0064 |
| MC10212L | 2037 1820-1832  | MC1431P  | 2037 1820-0160  | MC1741CL | 2037 1826-0070 |
| MC10212P | 2037 1820-1950  | MC1433G  | 2037 1820-0316  | MC1741N  | 2037 1826-0505 |
| MC10216L | 2037 1820-1320  | MC1433L  | 2037 1820-0181  | MC1741S  | 2037 1826-0302 |
| MC10216P | 2037 1820-1224  | MC1433P  | 2037 1820-0317  | MC1741S  | 2037 1826-0254 |
| MC1022P  | 2037 1820-0272  | MC1436C  | 2037 1826-0343  | MC1741S  | 2037 1826-0743 |
| MC10231L | 2037 1820-2516  | MC1436G  | 2037 1826-0038  | MC1776C  | 2037 1826-0086 |
| MC10231P | 2037 1820-1225  | MC1437L  | 2037 1826-0019  | MC1800P  | 2037 1820-0985 |
| MC1023P  | 2037 1820-0157  | MC1438R  | 2037 1826-0060  | MC1801L  | 2037 1820-0868 |
| MC1024P  | 2037 1820-0578  | MC1439G  | 2037 1820-0201  | MC1801P  | 2037 1820-0441 |
| MC1025P  | 2037 1820-0444  | MC1439L  | 2037 1826-0022  | MC1805P  | 2037 1820-0454 |
| MC1026P  | 2037 1820-0252  | MC14411P | 2037 1820-1779  | MC1806P  | 2037 1820-0273 |
| MC1027P  | 2037 1820-0143  | MC14412  | 2037 1820-2166  | MC1808P  | 2037 1820-0274 |
| MC1030P  | 2037 1820-0200  | MC14433L | 2037 1826-0431  | MC1810P  | 2037 1820-0238 |
| MC1031P  | 2037 1820-0235  | MC1445L  | 2037 1826-0334  | MC1812P  | 2037 1820-0418 |
| MC1032P  | 2037 1820-0581  | MC14490F | 2037 1820-1947  | MC1814P  | 2037 1820-0665 |
| MC1033P  | 2037 1820-0276  | MC14490  | 2037 1820-2306  | MC2257L  | 2037 1820-1156 |
| MC1034P  | 2037 1820-0101  | MC14501  | 2037 1820-1079  | MC2259L  | 2037 1820-1157 |
| MC1035P  | 2037 1820-0253  | MC14502  | 2037 1820-1635  | MC2902A  | 2037 1820-2389 |
| MC1037P  | 2037 1820-1227  | MC14502  | 2037 1820-1385  | MC2918P  | 2037 1820-2415 |
| MC1039P  | 2037 1820-0275  | MC14503  | 2037 1820-2257  | MC3001P  | 2037 1820-0141 |
| MC1040P  | 2037 1820-0667  | MC14504  | 2037 1820-2326  | MC3002P  | 2037 1820-0239 |
| MC1043P  | 2037 1820-0792  | MC14506  | 2037 1820-1386  | MC3002P  | 2037 1820-0923 |
| MC1047P  | 2037 1820-0897  | MC14507  | 2037 1820-1330  | MC3003P  | 2037 1820-0205 |
| MC1048P  | 2037 1820-0473  | MC14508  | 2037 1820-1693  | MC3006P  | 2037 1820-0204 |
| MC1062P  | 2037 1820-0916  | MC14510  | 2037 1820-1189  | MC3007P  | 2037 1820-1031 |
| MC1065P  | 2037 1820-0917  | MC14513  | 2037 1820-2462  | MC3022P  | 2037 1820-0617 |
| MC1068P  | 2037 1820-0791  | MC14515  | 2037 1820-1329  | MC3025P  | 2037 1820-0604 |
| MC10804L | 2037 1820-2409  | MC14516  | 2037 1820-1114  | MC3026P  | 2037 1820-0140 |
| MC10805L | 2037 1820-2348  | MC14517  | 2037 1820-1815  | MC3029P  | 2037 1820-0700 |
| MC12002P | 2037 1826-0598  | MC14518  | 2037 1820-1591  | MC3060P  | 2037 1820-0449 |
| MC12012L | 2037 1820-1242  | MC14518  | 2037 1820-1122  | MC3061P  | 2037 1820-0609 |
| MC12013L | 2037 1820-1888  | MC14519  | 2037 1820-1387  | MC3062P  | 2037 1820-0451 |
| MC12040L | 2037 1820-1344  | MC14520  | 2037 1820-1150  | MC3103L  | 2037 1820-1375 |
| MC12040P | 2037 1826-0364  | MC145208 | 2037 1820-2021  | MC3245L  | 2037 1820-1758 |
| MC1204L  | 2037 1820-1915  | MC14522  | 2037 1820-1181  | MC3340P  | 2037 1826-0399 |
| MC12061P | 2037 1820-1977  | MC14522  | 2037 1820-1175  | MC34002  | 2037 1826-0741 |
| MC1210L  | 2037 1820-1025  | MC14526  | 2037 1820-1328  | MC34004  | 2037 1826-0753 |

|         |                |         |                |          |                |
|---------|----------------|---------|----------------|----------|----------------|
| MC1213L | 2037 1820-1026 | MC14527 | 2037 1820-1265 | MC3403P  | 2037 1826-0312 |
| MC1306P | 2037 1826-0293 | MC14528 | 2037 1820-2051 | MC3405P  | 2037 1826-0424 |
| MC1350P | 2037 1826-0159 | MC14530 | 2037 1820-1356 | MC3410CL | 2037 1826-0462 |
| MC1355P | 2037 1826-0382 | MC14532 | 2037 1820-1327 | MC3410C  | 2037 1826-0529 |
| MC14001 | 2037 1820-1745 | MC14532 | 2037 1820-1570 | MC3420P  | 2037 1826-0526 |
| MC14001 | 2037 1820-1499 | MC14534 | 2037 1820-1355 | MC3423P1 | 2037 1826-0468 |
| MC14002 | 2037 1820-2079 | MC14536 | 2037 1820-1855 | MC3431P  | 2037 1826-0360 |
| MC14002 | 2037 1820-1511 | MC14538 | 2037 1826-0411 | MC3440P  | 2037 1820-1522 |
| MC14007 | 2037 1820-1503 | MC14538 | 2037 1820-1569 | MC3441A  | 2037 1820-1558 |
| MC14008 | 2037 1820-1525 | MC14539 | 2037 1820-1932 | MC3442P  | 2037 1820-1842 |
| MC14011 | 2037 1820-2576 | MC14539 | 2037 1820-1549 | MC3442P  | 2037 1826-0253 |
| MC14011 | 2037 1820-1747 | MC14541 | 2037 1820-1471 | MC3443P  | 2037 1820-1687 |
| MC14011 | 2037 1820-1500 | MC14543 | 2037 1820-1658 | MC3446P  | 1698 1820-1689 |
| MC14012 | 2037 1820-1960 | MC14549 | 2037 1620-2097 | MC3447P  | 2037 1820-2424 |
| MC14012 | 2037 1820-1507 | MC14553 | 2037 1820-1721 | MC3447P3 | 2037 1820-2461 |
| MC14013 | 2037 1820-1497 | MC14555 | 2037 1620-1479 | MC3450P  | 2037 1820-2157 |
| MC14015 | 2037 1820-2055 | MC14556 | 2037 1820-2050 | MC3452P  | 2037 1820-2158 |
| MC14015 | 2037 1820-1176 | MC14557 | 2037 1820-1412 | MC3453P  | 2037 1820-2569 |
| MC14015 | 2037 1820-1502 | MC14558 | 2037 1820-2344 | MC3459C  | 2037 1820-1786 |
| MC14015 | 2037 1820-2008 | MC14559 | 2037 1820-1573 | MC3460P  | 2037 1820-1810 |
| MC14016 | 2037 1820-1504 | MC14560 | 2037 1820-1722 | MC3467P  | 2037 1826-0474 |
| MC14017 | 2037 1820-1508 | MC14561 | 2037 1820-1850 | MC3468P  | 2037 1826-0475 |
| MC14020 | 2037 1820-1494 | MC14562 | 2037 1820-2033 | MC3476G  | 2037 1826-0289 |
| MC14022 | 2037 1820-2277 | MC14566 | 2037 1820-2444 | MC3486P  | 2037 1820-2144 |
| MC14022 | 2037 1820-1527 | MC14568 | 2037 1820-1588 | MC3487P  | 2037 1820-2145 |
| MC14023 | 2037 1820-1961 | MC14569 | 2037 1826-0599 | MC352G   | 2037 1820-0013 |
| MC14023 | 2037 1820-1509 |         | 2037 1820-2571 | MC4001P  | 2037 1820-0639 |

# INTEGRATED CIRCUIT CROSS REFERENCE

| 23       |      |                |          |                |           |                |
|----------|------|----------------|----------|----------------|-----------|----------------|
| Desc.    | Mfr. | HP P/N         |          |                |           |                |
|          |      |                | MC849L   | 2037 1820-0866 |           |                |
|          |      |                | MC8500P  | 2037 1820-2297 | MM74C15   | 3406 1820-2065 |
| MC4002P  |      | 2037 1820-0843 | MC8502P  | 2037 1820-2296 | MM74C15   | 3406 1820-1827 |
| MC4006P  |      | 2037 1820-0608 | MC850P   | 2037 1820-0087 | MM74C15   | 3406 1820-1365 |
| MC4007P  |      | 2037 1820-0724 | MC851L   | 2037 1820-0860 | MM74C16   | 3406 1820-1390 |
| MC4008P  |      | 2037 1820-0842 | MC853P   | 2037 1820-0122 | MM74C16   | 3406 1820-1391 |
| MC4010P  |      | 2037 1820-0836 | MC857P   | 2037 1820-0257 | MM74C16   | 3406 1820-2214 |
| MC4012P  |      | 2037 1820-0607 | MC858L   | 2037 1820-0863 | MM74C16   | 3406 1820-1493 |
| MC4015P  |      | 2037 1820-0437 | MC8601P  | 2037 1820-0207 | MM74C16   | 3406 1820-1559 |
| MC 4016P |      | 2037 1820-1183 | MC8602L  | 2037 1820-1524 | MM74C16   | 3406 1820-1560 |
| MC4018P  |      | 2037 1820-1332 | MC8602P  | 2037 1820-0515 | MM74C17   | 3406 1820-1190 |
| MC4022P  |      | 2037 1820-1109 | MC889P   | 2037 1820-0323 | MM74C17   | 3406 1820-1562 |
| MC4024P  |      | 2037 1820-0567 | MC8T26A  | 2037 1820-1081 | MM74C19   | 3406 1820-1575 |
| MC4038P  |      | 2037 1820-0834 | MCC1456  | 2037 1826-0048 | MM74C19   | 3406 1820-1561 |
| MC4044P  |      | 2037 1820-0630 | MCC1670  | 2037 1820-2429 | MM74C20   | 3406 1820-1626 |
|          |      |                |          |                | MM74C22   | 3406 1820-1612 |
|          |      |                |          |                | MM74C221J |                |
| MC650P   |      | 2037 1820-1520 | MCC1741  | 2037 1826-0042 | MM74C22   | 3406 1820-1485 |
| MC662P   |      | 2037 1820-0288 | MCC1776  | 2037 1826-0325 | MM74C24   | 3406 1820-2538 |
| MC663P   |      | 2037 1820-1519 | MCM1C13  | 2037 1816-1447 | MM74C24   | 3406 1820-2566 |
| MC666P   |      | 2037 1820-0625 | MCM1014  | 2037 1816-1435 | MM74C24   | 3406 1820-2537 |
| MC667P   |      | 2037 1820-1606 | MCM1014  | 2037 1816-1053 | MM74C24   | 3406 1820-2537 |
| MC668P   |      | 2037 1820-1605 | MCM1014  | 2037 1816-1430 | MM74C30   | 3406 1820-1674 |
| MC670P   |      | 2037 1820-2133 | MCM1014  | 2037 1816-1434 | MM74C32   | 3406 1820-2213 |
| MC672P   |      | 2037 1820-0287 | MCM1014  | 2037 1816-1390 | MM74C37   | 3406 1820-2215 |
| MC68000L |      | 2037 1820-2505 | MCM1014  | 2037 1816-1456 | MM74C37   | 3406 1820-2216 |
| MC6800L  |      | 2037 1820-1480 | MCM1015  | 2037 1816-1335 | MM74C42   | 3406 1820-1735 |
| MC6800P  |      | 2037 1820-2411 | MCM1453  | 2037 1816-1335 | MM74C73   | 3406 1820-2605 |
| MC6802L  |      | 2037 1820-2151 | MCM2147  | 2037 1818-0695 | MM74C74   | 3406 1820-1933 |
| MC6802P  |      | 2037 1820-2099 | MCM4256  | 2037 1818-0849 | MM74C74   | 3406 1820-1753 |
| MC6803L- |      | 2037 1820-2651 | MCM5004  | 2037 1820-1020 | MM74C76   | 3406 1820-2606 |
| MC6803P  |      | 2037 1820-2562 | MCM6572  | 2037 1816-0660 | MM74C83   | 3406 1820-1937 |
| MC6809L  |      | 2037 1820-2612 | MCM6581  | 2037 1818-0336 | MM74C83   | 3406 1820-2343 |
| MC6809P  |      | 2037 1820-2490 | MCM6810  | 2037 1818-0700 | MM74C85   | 3406 1820-1806 |
| MC6821L  |      | 2037 1820-1481 | MCM68A1  | 2037 1818-0328 | MM74C86   | 3406 1820-2276 |
| MC6828P  |      | 2037 1820-2030 | MCM68A1  | 2037 1818-0135 | MM74C89   | 3406 1820-1392 |
| MC6840P  |      | 2037 1820-2469 | MCM68A7  | 2037 1818-0701 | MM74C90   | 3406 1820-1651 |
| MC6844P  |      | 2037 1820-2463 | MFC40008 | 2037 1818-0912 | MM74C90   | 3406 1820-1652 |
| MC6845P  |      | 2037 1820-2546 | MFC6070  | 2037 1826-0198 | MM74C90   | 3406 1820-1653 |
|          |      |                |          | 2037 1826-0259 | MM74C90   | 3406 1820-1654 |



|          |                |          |                |          |                |
|----------|----------------|----------|----------------|----------|----------------|
| MC68488L | 2037 1820-2113 | MH0007C  | 3406 1820-0832 | MM74C90  | 3406 1820-1935 |
| MC68488P | 2037 1820-2219 | MHQ2221  | 2037 1858-0009 | MM74C90  | 3406 1820-1655 |
| MC6850L  | 2037 1820-1690 | MHQ6001  | 2037 1858-000B | MM74C90  | 3406 1820-1656 |
| MC6850P  | 2037 1820-2470 | MHW592   | 2037 1813-0138 | MM74C90  | 3406 1820-2275 |
| MC6852C  | 2037 1820-2175 | MK2302P  | 4078 1816-0355 | MM74C91  | 3406 1818-0754 |
| MC6870A  | 3795 1820-1637 | MK3880N  | 4078 1820-2188 | MM74C91  | 3406 1820-1778 |
| MC6871A- | 3795 1820-2285 | MK3880N- | 4078 1820-2298 | MM74C92  | 3406 1818-0753 |
| MC6875L  | 2037 1820-2036 | MK3880N- | 4078 1820-2649 | MM74C92  | 3406 1820-2156 |
| MC6881P/ | 2037 1820-2165 | MK3881N  | 4078 1820-2339 | MM74C92  | 3406 1820-2309 |
| MC6885P  | 2037 1820-2489 | MK3881N- | 4078 1820-2434 | MM74C92  | 3406 1820-2540 |
| MC68A00  | 2037 1820-2137 | MK3882N- | 4078 1820-2301 | MM74C94  | 3406 1820-2630 |
| MC68A08  | 2037 1820-2240 | MK3883N- | 4078 1820-2299 | MM80C95  | 3406 1820-1402 |
| MC68A21L | 2037 1820-2180 | MK3884N- | 4078 1820-2518 | MM80C97  | 3406 1820-1823 |
| MC68A21  | 2037 1820-2081 | MK3885P  | 4078 1820-2288 | MM82C19  | 3406 1820-2413 |
| MC68A40  | 2037 1820-2307 | MK3887N- | 4078 1820-2300 | MM88C29  | 3406 1820-2217 |
| MC68A48  | 2037 1820-2148 | MK38P70/ | 4078 1820-2650 | MM89C30  | 3406 1820-2218 |
| MC68A48  | 2037 1820-2428 | MK4096-3 | 4078 1818-0114 | MMH0026  | 2037 1820-1288 |
| MC68A50  | 2037 1820-2284 | MK4102P- | 4078 1818-0327 | MMH0026  | 2037 1820-1366 |
| MC68B00L | 2037 1820-2358 | MK4118N- | 4078 1818-1214 | MMH0026  | 2037 1820-1170 |
| MC68B00  | 2037 1820-2293 | MK4118N- | 4078 1818-1177 | MPQ2222  | 2037 1858-0077 |
| MC68B09  | 2037 1820-2624 | MK4118N- | 4078 1818-1178 | MPQ2369  | 2037 1858-0055 |
| MC68821L | 2037 1820-2602 | MK4118P- | 4078 1818-1162 | MPQ2906  | 2037 1858-0010 |
| MC68B60  | 2037 1820-2291 | MK4118P- | 4078 1818-1114 | MPQ2907  | 2037 1858-0076 |
| MC7242P  | 2037 1820-0719 | MK4118P- | 4078 1818-1213 | MPQ3546  | 2037 1858-0075 |
| MC7250P  | 2037 1820-0786 | MK4332P- | 4078 1818-1334 | MPQ3725  | 2037 1858-0034 |
| MC7270P  | 2037 1820-0984 | MK4801A  | 4078 1818-1662 | MPQ3762  | 2037 1858-0062 |
| MC7441A  | 2037 1820-0100 | MK4801A  | 4078 1818-1614 | MPQ3798  | 2037 1858-0071 |
| MC7479P  | 2037 1820-0908 | MK4801P- | 4078 1818-1372 | MPQ3906  | 2037 1858-0058 |
| MC7805C  | 2037 1826-0246 | MK4802-3 | 4078 1818-1643 | MPQ6100  | 2037 1858-0074 |
| MC7805C  | 2037 1826-0144 | MK4802N- | 4078 1818-1718 | MPQ6842  | 2037 1820-1804 |
| MC7806C  | 2037 1826-0145 | MK5009N  | 4078 1820-1123 | MT8860AE | 9161 1826-0824 |
| MC780BC  | 2037 1826-0146 | MK5009P  | 4078 1820-2322 | MT8865AE | 9161 1826-0823 |
| MC7812CT | 2037 1826-0147 | MK50399N | 4078 1820-2310 | MUX-88FQ | 2180 1826-0849 |
| MC7815C  | 2037 1826-0106 | MK6036P  | 4078 1820-0993 | MUXO8FQ  | 2180 1826-0609 |
| MC7818C  | 2037 1826-0126 | MLM201A  | 2037 1826-0311 | MUX24FQ  | 2180 1826-0610 |
| MC7818C  | 2037 1826-0149 | MLM204G  | 2037 1826-0016 | MWA110   | 2037 1813-0211 |
| MC78L05  | 2037 1826-0276 | MLM308A  | 2037 1826-0493 | MWA120   | 2037 1813-0212 |
| MC78L12  | 2037 1826-0275 | MLM324P  | 2037 1826-0161 | MWA130   | 2037 1813-0213 |
| MC78LI5A | 2037 1826-0353 | MLMC101  | 2037 1826-0567 | MWA210   | 2037 1813-0214 |
| MC78L15  | 2037 1826-0274 | MM1101A/ | 3406 1818-0134 | MWA220   | 2037 1813-0215 |
| MC78M05  | 2037 1826-0367 | MM1402A  | 3406 1820-0733 | MWA230   | 2037 1813-0216 |
| MC78M15  | 2037 1826-0512 | MM2102A  | 3406 1818-0198 | MWA310   | 2037 1813-0217 |
| MC78M15  | 2037 1826-0464 | MM2114N- | 3406 1818-0643 | MWA320   | 2037 1813-0218 |
| MC7902CT | 2037 1826-0688 | MM5006H  | 3406 1820-0770 | MWA330   | 2037 1813-0219 |
| MC7905.2 | 2037 1826-0215 | MM5013N  | 3406 1820-1165 | N74S253N | 2910 1820-2287 |
| MC7905CT | 2037 1826-0294 | MM5035P  | 3406 1820-2416 | N8162N   | 2910 1820-0457 |
| MC7908C  | 2037 1826-0344 | MM5040H  | 3406 1820-1236 | N8200N   | 2910 1820-1337 |
| MC7912C  | 2037 1826-0123 | MM5050A  | 3406 1820-1237 | N8202N   | 2910 1820-0508 |
| MC7915C  | 2037 1826-0451 | MM5052   | 3406 1820-0717 | N8220N   | 2910 1820-0845 |
| MC7915CT | 2037 1826-0214 | MM5057N  | 3406 1820-1162 | N8233N   | 2910 1820-0543 |
| MC79L03C | 2037 1826-0286 | MM507    | 3406 1820-0410 | N8234N   | 2910 1820-0542 |
| MC79L05  | 2037 1826-0496 | MM5204D  | 3406 1818-1336 | N8235N   | 2910 1820-0575 |
| MC79L05  | 2037 1826-0285 | MM5241A  | 3406 1818-0061 | N8243N   | 2910 1820-0569 |
| MC79L06C | 2037 1826-0284 | MM5260N  | 3406 1820-1149 | N8251N   | 2910 1820-0462 |
| MC79L12  | 2037 1826-0495 | MM5261N  | 3406 1818-0106 | N8263N   | 2910 1820-0507 |
| MC79L12  | 2037 1826-0282 | MM5269N  | 3406 1818-0440 | N8267N   | 2910 1820-0835 |
| MC79L15  | 2037 1826-0281 | MM5280J- | 3406 1818-0508 | N8271N   | 2910 1820-0989 |
| MC815P   | 2037 1820-0325 | MM5307A  | 3406 1820-2001 | N8273N   | 2910 1820-1045 |
| MC816P   | 2037 1820-0106 | MM5307N  | 3406 1820-1348 | N8280N   | 2910 1820-0322 |
| MC817P   | 2037 1820-0411 | MM5312N  | 3406 1820-1756 | N8281N   | 2810 1820-0400 |
| MC824P   | 2037 1820-0324 | MM5313N( | 3406 1820-1364 | N8284N   | 2910 1820-0536 |
| MC8266P  | 2037 1820-0506 | MM5313N( | 3406 1820-2126 | N8288N   | 2910 1820-0455 |
| MC8301P  | 2037 1820-0111 | MM5315N  | 3406 1820-2040 | N8290N   | 2910 1820-0450 |
| MC8307P  | 2037 1820-0914 | MM5369A  | 3406 1820-2246 | N8291N   | 2910 1820-0492 |
| MC8308P  | 2037 1820-0742 | MM5371N  | 3406 1820-1755 | N8292N   | 2910 1820-0703 |
| MC8309P  | 2037 1820-0610 | MM550H   | 3406 1826-0156 | N8293N   | 2910 1820-0789 |
| MC8310P  | 2037 1820-0705 | MM58174  | 3406 1820-2623 | N82S09I  | 2910 1816-0728 |
| MC8312P  | 2037 1820-0615 | MM5873   | 2023 1820-1849 | N82S100I | 2910 1820-2247 |

|         |                |         |                |          |                |
|---------|----------------|---------|----------------|----------|----------------|
| MC8314P | 2037 1820-0626 | MM74C00 | 3406 1820-2038 | N82S115F | 2910 1816-0605 |
| MC835L  | 2037 1820-0869 | MM74C00 | 3406 1820-2210 | N82S123F | 2910 1816-0016 |
| MC835P  | 2037 1820-0479 | MM74C02 | 3406 1820-1627 | N82S123F | 2910 1816-0916 |
| MC838P  | 2037 1820-0533 | MM74C04 | 3406 1820-2211 | N82S123N | 2910 1816-1032 |
| MC839P  | 2037 1820-0260 | MM74C08 | 3406 1820-1603 | N82S126F | 2910 1816-0917 |
| MC840P  | 2037 1820-0259 | MM74C10 | 3406 1820-1576 | N82S129F | 2910 1816-0782 |
| MC844L  | 2037 1820-0865 | MM74C10 | 3406 1820-2212 | N82S129F | 2910 1816-1418 |
| MC846L  | 2037 1820-0861 | MM74C14 | 3406 1820-1590 | N82S130F | 2910 1816-0918 |
| MC848L  | 2037 1820-0862 | MM74C14 | 3406 1820-1563 | N82S131F | 2910 1816-0710 |

24

# INTEGRATED CIRCUIT CROSS REFERENCE

| UNCLASSIFIED SINGLE CROSS REFERENCE |      |                |           |                |          |                |
|-------------------------------------|------|----------------|-----------|----------------|----------|----------------|
| Mc.                                 | Mfr. | HP PIN         |           |                |          |                |
| N82S131F                            |      | 2910 1816-1482 | P4002-1   | 3811 1818-0499 | SN54H106 | 1698 1820-1595 |
| N82S136F                            |      | 2910 1816-0930 | P4040     | 3811 1820-2069 | SN54H11J | 1698 1820-1067 |
| N82S137A                            |      | 2910 1816-1475 | P4265     | 3811 1820-2072 | SN54H30J | 1698 1820-1068 |
| N82S137F                            |      | 2910 1816-0931 | P4269     | 3811 1820-2073 | SN54H40J | 1698 1820-1069 |
| N82S140F 02 910                     |      | 1816-0928      | P5101L-3  | 3811 1818-0319 | SN54H74J | 1698 1820-1071 |
| N82S141F                            |      | 2910 1816-0929 | P8035L    | 3811 1820-2176 | SN54LS00 | 1698 1820-1879 |
| N82S141F                            |      | 2910 1816-1142 | P8039     | 3811 1820-2271 | SN54LS02 | 1698 1820-1799 |
| N82S141F                            |      | 2910 1816-1163 | P8039-6   | 3811 1820-2308 | SN54LS08 | 1698 1820-2248 |
| N82SL80F                            |      | 2910 1816-1240 | P8085A    | 3811 1820-2074 | SN54LS10 | 1698 1820-2249 |
| N82S181F                            |      | 2910 1816-1160 | P8085A-2  | 3811 1820-2205 | SN54LS11 | 1698 1820-2261 |
| N82S181N                            |      | 2910 1816-1162 | PS 155    | 3811 1818-0735 | SN54LS12 | 1698 1820-1750 |
| N82S185F                            |      | 2910 1816-1054 | P8216     | 3811 1820-1557 | SN54LS13 | 1698 1820-2529 |
| N82S191I                            |      | 2910 1816-1299 | P8224     | 3811 1820-2380 | SN54LS17 | 1698 1820-2064 |
| N82S19I                             |      | 2910 1816-1458 | P8257     | 3811 1820-2143 | SN54LS19 | 1698 1820-2251 |
| N82S23F                             |      | 2910 1816-0915 | P8259A    | 3811 1820-2519 | SN54LS22 | 1698 1820-2042 |
| N82S2708                            |      | 2910 1816-1193 | P8291     | 3811 1820-2410 | SN54LS27 | 1698 1820-1880 |
| N82S31N                             |      | 2910 1820-1980 | PALIOHB   | 4092 1820-2677 | SN54LS30 | 1698 1820-2250 |
| N82S33N                             |      | 2910 1820-1249 | PAL 12H6  | 4092 1820-2671 | SN54LS66 | 1698 1820-2559 |
| N82S42N                             |      | 2910 1820-1073 | PAL14L4C  | 4092 1820-2678 | SN54LS74 | 1698 1820-1798 |
| N82S50N                             |      | 2910 1820-1338 | PAL16H2   | 4092 1820-2679 | SN54S00J | 1698 1820-1253 |
| N82S62N                             |      | 2910 1820-1140 | PAL16L8C  | 4092 1820-2670 | SN54S30J | 1698 1820-2252 |
| N82S83N                             |      | 2910 1820-1467 | PAL16R4   | 4092 1820-2681 | SN54S40J | 1698 1820-2253 |
| N82S83N                             |      | 2910 1820-1777 | PAL16R6   | 4092 1820-2680 | SN55453B | 1698 1820-2236 |
| N82S90N                             |      | 2910 1820-1155 | PBD3520   | 5917 1820-2446 | SN55461J | 1698 1820-2282 |
| N8440N                              |      | 2910 1820-0459 | PE-21217  |                | SN55462J | 1698 1820-2283 |
| N8480N                              |      | 2910 1820-0460 | PIC600    | 2598 1813-0115 | SM72710L | 1698 1820-0321 |
| N8815N                              |      | 2910 1820-0837 | PIC601    | 2598 1813-0083 | SN72710N | 1698 1820-0398 |
|                                     |      |                | PIC611    | 2598 1813-0084 | SN72741P | 1698 1826-0271 |
|                                     |      |                | PIC625    | 2598 1813-0109 | SN72747J | 1698 1826-0100 |
|                                     |      |                | PIC626    | 2598 1813-0110 | SN72L022 | 1698 1826-0301 |
|                                     |      |                | PIC645    | 2598 1813-0114 | SN7400J  | 1698 1820-0856 |
| N8816N                              |      | 2910 1820-0466 |           |                |          |                |
| N8825N                              |      |                |           |                |          |                |
| N8826N                              |      | 2910 1820-0209 | PIC646    | 2598 1813-0082 | SN7400N  | 1698 1820-0054 |
| N8855N                              |      | 2910 1820-0456 | PR1472B-  | 575 1818-0094  | SN7401N  | 1698 1820-0327 |
| N8875N                              |      | 2910 1820-0637 | PT1482B-  | 575 1818-0095  | SM7402N  | 1698 1820-0328 |
| N8880N                              |      | 2910 1820-0461 | RO-3-2513 | 2713 1818-0237 | SN7403J  | 1698 1820-0864 |
| N8881N                              |      | 2910 1820-0467 | RATA      | 1973 1820-0044 | SN7403N  | 1698 1820-0269 |
| N8H70N                              |      | 2910 1820-0463 | RC4195TK  | 2290 1826-0196 | SN7404J  | 1698 1820-0994 |
| N8H80N                              |      | 2910 1820-0465 | RC4558NB  | 2290 1826-0326 | SN7404N  | 1698 1820-0174 |
| N8H90N                              |      | 2910 1820-0464 | RC4958T   | 2290 1826-0217 | SN7404W  | 1698 1820-1004 |
| N8T09N                              |      | 2910 1820-1084 | RC8T23M   | 2290 1820-1007 | SN7405J  | 1698 1820-2179 |
| N8T09N                              |      | 2910 1820-1360 | RC8T24M   | 2290 1820-1030 | SN7405N  | 1698 1820-0175 |
| N8T14N                              |      | 2910 1820-1289 | REF-01C   | 2190 1826-0708 | SN7406N  | 1698 1820-0471 |
| N8T28N                              |      | 2910 1820-1828 | REF-01HJ  | 2180 1826-0853 | SN7407J  | 1698 1820-2593 |
| N8T31N                              |      | 2910 1820-2108 | REF-02DJ  | 2180 1826-0622 | SN7407N  | 1698 1820-0668 |
| N8T37N                              |      | 2910 1820-1817 | REF-02HP  | 2180 1826-0847 | SN7408J  | 1698 1820-0870 |
| N8T80N                              |      | 2910 1820-0195 | 8V45580   | 2290 1826-032B | SN7408N  | 1698 1820-0511 |
| N8T90N                              |      | 2910 1820-0121 | 52350-2   | 3677 1820-1754 | SN7409N  | 1698 1820-0513 |
| N8T93N                              |      | 2910 1820-1924 | S52       | 3545 1820-013B | SN74100N | 1698 1820-0425 |
| N8T95N                              |      | 2910 1820-1477 | S5733A    | 2910 1826-0040 | SN741 OA | 1698 1820-1002 |
| N8T96N                              |      | 2910 1820-1476 | S8280F    | 2910 1820-0419 | SN74107N | 1698 1820-0281 |
| N8T97N                              |      | 2910 1820-1884 | S8292F    | 2910 1820-1098 | SN74109N | 1698 1820-1116 |
| NCM7040L                            |      | 4183 1818-0630 | SAA1027   | 3334 1820-1682 | SN7410N  | 1698 1820-0068 |
| NE5018F                             |      | 2910 1826-0798 | S050008   | 2910 1826-0415 | SN74111N | 1698 1820-1229 |
| NE501A                              |      | 2910 1826-0058 | SDMB57K   | 5436 1813-0140 | SN74116N | 1698 1820-1793 |
| NE521A                              |      | 2910 1826-0213 | SE555CT   | 2910 1826-0224 | SN74120N | 1698 1820-2164 |

|           |                |              |                |          |                |
|-----------|----------------|--------------|----------------|----------|----------------|
| NE522A    | 2910 1826-0256 | SG1502N      | 3793 1826-0258 | SN74121N | 1698 1820-0261 |
| NE526A    | 2910 1826-0115 | SG1532J      | 3793 1826-072B | SN74122N | 1698 1820-0704 |
| NE527K    | 2910 1826-0454 | SG3501AJ     | 3793 1826-0061 | SN74123N | 1698 1820-0579 |
| NE527N    | 2910 1826-0755 | SG3524J      | 1698 1826-042R | SN 74125 | 1698 1820-1121 |
| NE529A    | 2910 1826-0244 | SG3547N      | 3793 1826-0867 | SN74126N | 1698 1820-1214 |
| NE529K    | 2910 1826-0124 | 563627       | 3793 1820-2590 | SN74128N | 1698 1820-1074 |
| NE531H    | 2910 1826-0067 | SG3821N      | 3793 1858-0022 | SN7412N  | 1698 1820-0907 |
| NE550L    | 2910 1826-0130 | SH6401PC     | 2237 1858-0020 | SN74132N | 1698 1820-1056 |
| NE550N    | 2910 1826-0137 | SH6501PC     | 2237 1821-0006 | SN74136N | 1698 1820-1250 |
| NE5532AF  | 2910 1826-0716 | SL441A 01,90 | 1826-0676      | SN7413N  | 1698 1820-0537 |
| NE5532AT  | 2910 1826-0633 | SMP-BIFY     | 2180 1826-0727 | SN74141N | 1698 1820-0707 |
| NE5534AT  | 2910 1826-0569 | SN156094     | 1698 1820-0341 | SN74143J | 1698 1820-1271 |
| NE5553N   | 2910 1826-0625 | SN158097     | 1698 1820-0342 | SN74143N | 1698 1820-1171 |
| NE555P    | 1698 1826-0180 | SN15809N     | 1698 1820-1137 | SN74145N | 1698 1820-0491 |
| NE555T    | 2910 1826-0119 | SN15830N     | 1698 1820-0086 | SN74147N | 1698 1820-1082 |
| NE5560N   | 2910 1826-0606 | SN15832N     | 1698 1820-0096 | SN74148N | 1698 1820-1473 |
|           | 2910 1826-0205 | SN15833N     | 1698 1820-0346 | SN7414N  | 1698 1820-1053 |
| NE556A    | 2910 1826-0047 | SN15836N     | 1698 1820-0307 | SN74150N | 1698 1820-0640 |
| NE562B    | 2910 1826-0204 | SN15837N     | 1698 1820-012B | SN74151A | 1698 1820-0622 |
| NE565A    | 2910 1826-0101 | SN15844N     | 1698 1820-0348 | SN74153N | 1698 1820-0620 |
| NE565K    |                |              |                |          |                |
| NE566H    | 2910 1826-0189 | SN15845N     | 1698 1820-0308 | SN74154N | 1698 1820-0495 |
| NE566H    | 2910 1826-0269 | SN15846N     | 1698 1820-0094 | SN74155N | 1698 1820-0738 |
| NE567V    | 2910 1826-0219 | SN15848N     | 1698 1820-009  | SN74156N | 1698 1820-1046 |
| NE570N    | 2910 1826-0703 | SN15849N     | 1698 1820-0349 | SN74157N | 1698 1820-0762 |
| NE590F    | 2910 1820-2266 | SN15851N     | 1698 1820-0088 | SN74159N | 1698 1820-1257 |
| NE591F    | 2910 1820-2267 | SN15858N     | 1698 1820-0256 | SN74160N | 1698 1820-0899 |
| NE592A    | 2910 1826-0194 | SN15861N     | 1698 1820-0350 | SN74161N | 1698 1820-0716 |
| NE592K    | 2910 1826-0546 | SN15862N     | 1698 1820-0310 | SN74162N | 1698 1820-1185 |
| NE5S34A   | 2910 1826-0715 | SN15863N     | 1698 1820-0351 | SN74163N | 1698 1820-0713 |
| OP-01CJ   | 2180 1826-0440 | SN15882N     | 1698 1820-0258 | SN74164N | 1698 1820-1064 |
| OP-05CJ   | 2180 1826-0229 | SN4935N      | 1698 1820-0361 | SM74165N | 1698 1820-1042 |
| OP-05EJ   | 2180 1826-0266 | SN52741      | 1698 1826-0011 | SN74166N | 1698 1820-1107 |
| OP-07CJ   | 2180 1826-0543 | SN5400J      | 1698 1820-1093 | SN74167N | 1698 1820-0909 |
| OP-07CP   | 2180 1826-0635 | SN5400N      | 1698 1820-0448 | SN7416J  | 1698 1820-2586 |
| OP-07EJ   | 2180 1826-0845 | SN5402J      | 1698 1820-1101 | SN7416N  | 1698 1820-0577 |
| OP-07EY   | 2180 1826-0641 | SN5402N      | 1698 1820-0445 | SN74170J | 1698 1820-0725 |
| OP-11EY   | 2180 1826-0616 | SN5404J      | 1698 1820-1097 | SN74170N | 1698 1820-1459 |
| OP-11FY   | 2180 1826-0628 | SN5404N      | 1698 1820-1022 | SN74173N | 1698 1820-0574 |
| OP-14CJ   | 2180 1826-0542 | SN5408J      | 1698 1820-1099 | SN74173N | 1698 1820-1192 |
| OP-1567   | 2180 1826-0828 | SN5408N      | 1698 1820-1379 | SN74174N | 1698 1820-0788 |
| OP-16E    | 2180 1826-0576 | SN5410J      | 1698 1820-1094 | SN74175N | 1698 1820-0639 |
| OP-16FJ   | 2180 1826-0601 | SN5410N      | 1698 1820-0447 | SN74178N | 1698 1820-1259 |
| OP-17FJ   | 2180 1826-0516 | SN54121J     | 1698 1820-1092 | SN74179N | 1698 1820-1259 |
| P1103A    | 3677 1818-0115 | SN5413J      | 1698 1820-1091 | SM7417N  | 1698 1820-0618 |
|           | 3794 1818-0320 | SN54160N     | 1698 1820-1024 | SN74180N | 1698 1820-0435 |
| P2101-2   | 3811 1818-0425 | SN54192N     | 1698 1820-1378 | SN74181N | 1698 1820-0606 |
| P21014-2  |                |              |                |          |                |
| P2101A-4  | 3811 1818-0342 | SN54196J     | 1698 1820-1096 | SN74182N | 1698 1820-0611 |
| P2114A-4  | 3811 1818-0492 | SN54197J     | 1698 1820-2043 | SN74184N | 1698 1820-1267 |
| P2114A-5  | 3811 1818-0562 | SN54199J     | 1698 1820-1083 | SN74185A | 1698 1820-1141 |
| P2114AL-2 | 3811 1818-163B | SN5423J      | 1698 1820-1878 | SN74188A | 1698 1816-1141 |
| P2114AL-3 | 3811 1818-123B | SN5430J      | 1698 1820-1070 | SN74190N | 1698 1820-0734 |
| P2141L-3  | 3811 1818-1090 | SN5432N      | 1698 1820-1381 | SN74191N | 1698 1820-0545 |
| P2142     | 3811 1818-0895 | SN5442AJ     | 1698 1820-2082 | SN74192N | 1698 1820-0546 |
| P2142L    | 3811 1818-1153 | SN5474J      | 1698 1820-1095 | SN74193N | 1698 1820-0233 |
|           | 3811 1820-2035 | SN5474N      | 1698 1820-0446 | SN74194N | 1698 1820-0743 |
| P3205     | 3911 1820-1087 | SN5490N      | 1698 1820-0992 | SN74195N | 1698 1820-1027 |
| P3208A    |                |              |                |          |                |
| P3212     | 3811 1820-1864 | SN5493N      | 1698 1820-1023 | SN74196N | 1698 1820-0751 |
| P3404     | 3811 1820-1395 | SN5495AN     | 1698 1820-1594 | SN74197N | 1698 1820-0765 |
| P3604L-6  | 3811 1816-0868 | SN5496N      | 1698 1820-1380 | SN74198N | 1698 1820-1032 |

# INTEGRATED CIRCUIT CROSS REFERENCE

25

| Desc.    | Mfr. | HP P/N         | SN74H73N | 1698 1820-0391SN74LS24 | 1696 1620-1688   |
|----------|------|----------------|----------|------------------------|------------------|
|          |      |                | SN74H74N | 1698 1820-0512SN74LS24 | 1698 1620 -16 44 |
| SN74199N |      | 1698 1820-0726 | SN74H76N | 1698 1820-0752SN74LS24 | 1698 1820-1643   |

|           |                           |                         |                 |
|-----------|---------------------------|-------------------------|-----------------|
| SN74200N  | 1698 1820-0783SN74H87N    | 1698 1820-0740SN74LS25  | 1698 1820-1298  |
| SN7420J   | 1698 1820-0657SN74L00N    | 1698 1820-0583SI174LS25 | 1698 1820-1238  |
| SN7420N   | 1698 1820-0069SN74L02N    | 1698 1820-0584SN74LS25  | 1698 1820-1438  |
| SN74221N  | 1698 1820-1260SN74L03N    | 1698 1820-0565SN74LS25  | 1696 1820-1439  |
| SN7422J   | 1698 1820-2304SN74L04N    | 1698 1820-0586SN74LS25  | 1698 1820-1890  |
| SN7422N   | 1698 1820-1256SN74L10N    | 1698 1820-0587SN74LS25  | 1698 1820-1729  |
| SN7423N   | 1698 1820-053BSN74L121N   | 1698 1820-1270SN74LS26  | 1698 1820-1785  |
| SN74247N  | 1698 1820-1580SN74L122N   | 1698 1820-0913SN74LS26  | 1698 1620-1297  |
| SN7425N   | 1698 1820-0655SN74L123N   | 1698 1820-1247SN74LS26  | 1698 L820-1417  |
| SN74265N  | 1698 1820-1460SN74L153N   | 1698 1820-1163SN74LS26  | 1698 1820-1669  |
| SN7426N   | 1698 1820-0514SN74L154N   | 1698 1820-1949SN74LS27  | 1698 1820-1730  |
| SN74273   | 1698 1820-1461SN74L157N   | 1698 1820-1218SN74LS27  | 1698 1820-1440  |
| SN74276N  | 1698 1820-2127SN74L157N   | 1696 1820-1269SN74LS27  | 1698 1820-2579  |
| SN74278N  | 1698 1820-172BSN74L164M   | 1698 1820-0903SN74LS27  | 1698 1820-1206  |
| SN74279N  | 1698 1820-1089SN74L192N   | 1698 1820-0911SN74LS28  | 1698 1820-1859  |
| SN7427J   | 1698 1820-1787SN74L193N   | 1698 1820-0912SN74LS28  | 1698 1.20-1441  |
| SN7427N   | 1698 1820-0782SN74L20N    | 1820-0588SN74LS28       | 1698 1820-1273  |
| SN74283N  | 1698 1820-1261SN74L30N    | 1698 1820-0589SN74LS29  | 1698 1820-1442  |
| SN74284N  | 1698 1820-1791SN74L142N   | 1698 1820-0777SN74LS29  | 169 1820-1443   |
| SN74285N  | 1698 1820-1792SN74L46N    | 1698 1820-1142SN74LS29  | 1698 1820-1296  |
| SN7426N   | 169 1820-1184SN74L47N     | 1698 1820-1233SN74LS29  | 1698 1820-1444  |
| SN74290N  | 1698 1820-1262SN74L51N    | 1698 1820-0590SN74LS29  | 1698 1820-1987  |
| SN74293M  | 1698 1820-1264SN74L54N    | 1698 1820-0591SN74LS30  | 1696 1820-1207  |
| SN74298N  | 1698 1620-1100SN74L55N    | 1698 1820-0592SN74LS32  | 1698 1820-2592  |
| SN7430N   | 1698 1820-0070SN74L73N    | 1698 1820-1731SN74LS32  | 1698 1820-2201  |
| SN7432N   | 1698 1820-0661SN74L75N    | 1698 1820-0876SN74LS32  | 1698 1820-2202  |
| SN7433N   | 1698 1820-1124SM74L85N    | 1698 1820-1268SN74LS32  | 1698 1820-1642  |
| SN74351N  | 1698 1820-1462SN74L86N    | 1698 1820-0598SN74LS32  | 1698 1820-2068  |
| SN74365N  | 1698 1820-2007SN74L93N    | 1698 1820-0443SN74LS32  | 1698 1820-2585  |
| SN74366N  | 1698 1820-1368SN74L95N    | 1698 1820-0497SN74LS32  | 1698 1820-1208  |
| SN74367N  | 1698 1820-1049SN74L98N    | 1698 1.20-0656 SN74LS33 | 1698 1820-2578  |
| SN74368N  | 1698 1820-1255SN74L500J   | 1698 1.20-2583 SN74LS33 | 1698 1820-1272  |
| SN7437N   | 1698 1820-0539SN74L500N   | 1698 1820-1197SN74LS34  | 1698 1620-2121  |
| SN7438J   | 1698 1820-2351SN74L500N   | 1698 1820-1891SN74LS35  | 1698 1620-2536  |
| SN7438N   | 1698 1820-0621SN74LS00N   | 2037 1820-2107SN74LS35  | 1698 1620-2046  |
| SN7 4390N | 1698 1820-1463SN74LS02J   | 1698 1620-1647SN74LS35  | 1698 1820-2613  |
| SN74393N  | 1698 1820-1464SN74LS02N   | 1696 1820-1144SN74LS36  | 1698 1820-2350  |
| SN7440N   | 1698 1820-0071SN74LS03N   | 1698 1820-1196SN74LS36  | 1698 1820-1641  |
| SN7442AN  | 1698 1820-0214SN74LS04J   | 6169 1820-2582SN74LS36  | 1698 1820-1640  |
| SN7445N   | 1698 1820-0468SN7 4LS04N  | 1820-1199SN74LS36       | 1698 1820-1491  |
| SN7446AN  | 1698 1820-1037SN74LS05N   | 1820-1200SN74LS36       | 1698 1820-1892  |
| SN7447AN  | 1698 1820-0995SN74LS08J   | 1698 1820-2581SN74LS36  | 1698 1820-1492  |
| SN7448N   | 1698 1820-1038SN74LS08N   | 1698 1820-1201SN74LS37  | 1698 1820-2102  |
| SN74490N  | 1696 1820-1465SN74LS097   | 1698 1820-1246SN74LS37  | 1696 1620-1997  |
| SN7450N   | 1698 1820-0072SN74LS107AN | 1698 1820-1469SN74LS37  | 1698 1820-2641  |
| SN7451N   | 1698 1820-0063SN74LS109AN | 1698 1820-1282SN74LS37  | 1698 1620-1445  |
| SN7453N   | 1698 1820-0084SN74LS10N   | 1698 1820-1202SN7 4LS3  | 1696 1820-10 SO |
| SN7454N   | 1698 1820-0074SN74LS112AN | 1698 1820-1212SN74LS 7  | 1698 1620-2056  |
| SN7460N   | 1698 1820-0085SN74LS113AN | 1698 1820-1213SN74LS37  | 1698 1820-2244  |
| SN7470N   | 1698 1820-0065SN74LS113AN | 1698 1820-1821SN74LS37  | 1698 1820-1287  |
| SN7472N   | 1698 1820-0304SN74LS11N   | 1698 1820-1203SN74LS38  | 1690 1020-2564  |
| SN7473N   | 1698 1820-0075SN74LS122N  | 1698 1820-1422SN74LS38  | 1698 1620-1209  |
| SN7474J   | 1698 1820-0859SN74LS123J  | 1698 1.20-2305 SM74LS3  | 1696 1820-1991  |
| SN7474N   | 1698 1820-0077SN74LS123N  | 1698 1820-1423SN74LS39  | 1698 1820-2096  |
| SN7475N   | 1698 1820-0301SN74LS124N  | 1698 1820-1424SN74LS39  | 1698 1620-1446  |
| SN7 476J  | 1698 1820-0858SN74LS125AN | 1698 1820-1568SN74LS39  | 1698 1820-2026  |
| SN7476N   | 1698 1820-0076SN74LS126AN | 1698 1820-1645SM74LS3   | 1698 1620-2384  |
| SN7480N   | 1698 1820-0362SN74LS12N   | 1698 1820-1414SN74LS40  | 1698 1820-1286  |
| SN7481AN  | 1698 1820-0365SN74LS132N  | 1698 1820-1425SN74LS42  | 1698 1820-1418  |
| SN7482N   | 1698 1820-0363SN74LS136N  | 1698 1820-1215SN74LS47  | 169 1816-1421   |
| SN7483AN  | 1698 1820-0305SN74LS137N  | 1698 1820-2550SN74LS47  | 1698 1820-1602  |
| SN7484AN  | 1698 1820-0484SN74LS138N  | 1698 1820-1216SN74LS48  | 1698 1820-1604  |
| SN7485N   | 1698 1820-0921SN74LS139N  | 1698 1820-1281SN74LS49  | 169 1820-2078   |
| SN7486N   | 1698 1820-0282SN74LS13N   | 1698 1820-1415SN74LS51  | 1698 1820-1210  |
| SN74 89N  | 1698 1820-0628SN74LS145N  | 1698 1820-1426SN74LS54  | 1698 1320-1285  |
| SN7490AN  | 1696 1820-0055SN74LS14N:  | 1698 1820-2200SN74LS55  | 1698 1820-1204  |
| SN7491AN  | 1698 1820-0364SN74LS148   | 1698 1820-1851SN74LSS   | 2037 1820-2366  |
| SN7492AN  | 1698 1820-0056SN74LS14N   | 1698 1820-1416SN74LS62  | 1698 1820-2672  |

0 698

016,98 01698

|             |        |                           |        |                               |                |
|-------------|--------|---------------------------|--------|-------------------------------|----------------|
| SN7493N     |        | 1698 1820-0099SN74LS151N  |        | 1698 1820-1217SN74LS62        | 1698 1820-2622 |
| SN7494N     |        | 1698 1820-0366SN74LS153N  |        | 1698 1820-1244SN74LS62        | 1696 1820-2655 |
| SN7495AN    |        | 1698 1820-0367SN74LS155N  |        | 1698 1820-1245SN74LS62        | 1690 1820-2369 |
| SN7496N     |        | 1698 1820-0368SN74LS156N  |        | 1698 1820-1427SN74LS64        | 1698 1820-2206 |
| SN7497N     |        | 1698 1820-0744SN74LS157N  |        | 1698 1820-1470SN74LS64        | 1696 1820-2453 |
| SN74ALS00N  |        | 1698 1820-2656SN74LS158N  |        | 1698 1820-1426SN74LS64        | 1698 1820-2268 |
| SN74ALS04N  |        | 1698 1820-2634SN74LS15N   |        | 1698 1820-1243                | 1698 1820-2675 |
| SN74ALS08N  |        | 1698 1820-2635SN74LS160AN |        | 1698 1820-1429SN74LS66        | 1698 1820-1434 |
| SN74ALS32N  |        | 1698 1820-2657SN74LS161AN |        | 1698 1820-1430SN74LS66        | 1698 1820-1435 |
| SN7 4ALS74N |        | 1698 1820-2488SN74LS162AN |        | 1698 1820-1431SN74LS67        | 1698 1820-1447 |
| SN74AS804N  |        | 1698 1820-2557SN74LS163AN |        | 1698 1820-1432SN74LS67        | 169 1820-2313  |
| SN74AS808N  |        | 1696 1820-2558SN74LS164N  |        | 1698 1820-1433SN74LS68        | 1698 1820-2610 |
| SN74H00N    |        | 1698 1820-0370SN74LS165N  |        | 1698 1820-1975SN74LS73        | 1698 1620-1574 |
| SN74H01N    |        | 1698 1620-0605SN74LS166N  |        | 1698 1620-1922SN74LS74        | 1698 1820-1666 |
| SN74H04N    |        | 1698 1820-0424SN74LS169AN |        | 1698 1820-2460SN74LS7         | 1698 1820-1112 |
| SN74H05N    |        | 1698 1820-0613SN74LS170N  |        | 1698 1820-1436SN74LS75        | 1698 1820-1411 |
| SN74H101N   |        | 1698 1820-0739SN74LS174N  |        | 1698 1620-1196SN74LS76        | 1698 1820-2464 |
| SN7 4H102N  |        | 1698 1820-0469SN74LS174N  |        | 169 1620-1914SN74LS83         | 1698 1820-6910 |
| SN74H103N   |        | 1698 1820-0544SN74LS175N  |        | 1698 1820-1195SN74LS85        | 1698 1820-1419 |
| SN74H106N   | _01698 | 1820-0715SN7 4LS181N      |        | 1698 1820-1260SN74LS86        | 1698 1820-2587 |
| SN74H108N   |        | 1698 1820-0631SN74LS182N  |        | 2037 1820-2563SN74LS86        | 1696 1820-1211 |
| SN74H10N    |        | 1698 1820-0371SN74LS190N  |        | 1698 1820-1279SN74LS90        | 169 1820-1490  |
| SN74H11N    | 01 698 | 1620-0372SN74LS191N       |        | 1698 1820-1278SN74LS91        | 1698 1820-1784 |
| SN74H15N    |        | 1696 1820-1263SN74LS192N  | 01 f9. | 1820-1277SN74LS92             | 1698 1820-1420 |
| SN7 183N    |        | 1698 1820-0847SN74LS193   |        | 1698 1820-1194SN74LS93        | 1698 1820-1478 |
| SN7 4H20N   |        | 169 1820-0373SN74LS194AN  |        | 1698 1820-1276SN74LS95        | 1698 1820-1283 |
| SN74H21N    |        | 1696 1820-0374SN74LS195AN |        | 1698 1820-1300SN74LS96        | 169 1820-1421  |
| SN74H22N    |        | 1698 1820-0619SN74LS196N  |        | 1698 1820-1251SN74S00N        | 1698 1820-0681 |
| SN74H30N    |        | 1698 1820-0375SW 74LS196N |        | 2037 1820-2049SN74S02N        | 1698 1820-1322 |
| SN74H40J    |        | 1698 1820-0867SRI 4LS197N |        | 1698 1820-1193SN74S03N        | 1698 1820-0682 |
| SN74H40N    |        | 1696 1820-0376SN74 LS20J  |        | 1698 1820-2580SN74S04N        | 1698 1820-0683 |
| SN74H50N    |        | 1698 1820-0377SN74LS20N   |        | 1698 1820-1204SN74S05N        | 1698 1820-0664 |
| SN74H51N    |        | 1698 1820-0378SN74LS21N   |        | 1698 1820-1205SN74S08N        | 1698 1820-1367 |
| SN74H52     |        | 1698 1820-0379SN74LS221J  |        | 1698 1820-2346SN74S09N        | 1698 1820-1448 |
| SN74H53N    |        |                           |        |                               |                |
|             |        | 1698 1820-0380SN74LS221N  |        | 1698 1820-1437SN74S10N        | 1698 1820-0685 |
| SN74H54N    |        | 1698 1820-0381SN74LS22N   |        | 1698 1820-1274SN74S112        | 1698 1820-0629 |
| SN74H55N    |        | 1698 1620-0038SN74LS240N  |        | 169 1820-1917SN74S113         | 1698 1620-0695 |
| SN74H60N    |        | 1698 1820-0383SN74LS241N  |        | 1698 1620-19183 74S114N       | 1698 1620-0696 |
| SN74H61N    |        | 1698 1820-0384SN74LS242N  |        | 1698 1820-2104SN74S11N        | 1698 1820-0686 |
| SN74H62N    |        | 1698 1820-0385SN74LS243N  |        | 1698 1820-1994SN74S124        | 1698 1620-1324 |
| SN74H71N    |        | 1698 1820-0386SN74LS244N  |        | 1698 1820-2024SN74S132        | 1698 1820-1307 |
| SN74H72N    |        | 1698 1820-0387SN74LS245N  |        | 1698 1820-2075SN7 4S13 016 98 | 1820-1130      |

|          |                |                            |                |                |                         |
|----------|----------------|----------------------------|----------------|----------------|-------------------------|
| •        | I•             |                            |                |                |                         |
| I 26     |                | 1 INTEGRATED CIRCUIT CROSS | REFERENCE      |                |                         |
| •        | I•             |                            |                |                |                         |
| Desc.    | Mfr.           | HP PIN                     | SP380N         | 2910 1820-1187 | UA201HC 2237 1820-0104  |
|          |                |                            | SP616N         | 2910 1820-0318 | UA208H 2237 1826-0072   |
|          |                |                            | SP620N         | 2910 1820-0078 | UA217K 2237 1826-0673   |
| SN74S134 | 1698 1820-1306 |                            | SP6235B        | 3795 1813-0129 | UA304HC 2237 1826-0004  |
| SN74S135 | 1698 1820-1639 |                            | SP629N         | 2910 1820-0319 | UA4136PC 2237 1826-0222 |
| SN74S138 | 1698 1820-1240 |                            | SP631N         | 2910 1820-0067 | UA709CN 1698 1820-0397  |
| SN74S139 | 1698 1820-1072 |                            | SP659N         | 2910 1820-0320 | UA711DC 2237 1826-0055  |
| SN74S140 | 1698 1820-0697 |                            | SP670N         | 2910 1820-0302 | UA714LHC 2237 1826-0574 |
| SN74S151 | 1698 1820-1319 |                            | SP680N         | 2910 1820-0303 | UA723CJ 1698 1826-0049  |
| SN74S153 | 1698 1820-0998 |                            | SP8610B        | 1590 1820-2140 | UA726HC 2237 1826-0031  |
| SN74S157 | 1698 1820-1077 |                            | SP8611B        | 1590 1820-2292 | UA734HC 2237 1826-0183  |
| SN74S158 | 1698 1820-1015 |                            | SP8617B        | 1590 1820-233B | UA739DC 2237 1826-0044  |
| SM74S15  | 1698 1820-0687 |                            | SP8622B        | 1590 1820-2047 | UA740HC 2237 1826-0056  |
| SN74S162 | 1698 1820-1452 |                            | SP8641B        | 1590 1820-1384 | UA747DM 2237 1826-0135  |
| SN74S163 | 1698 1820-1942 |                            | SPQ1678        | 2037 1858-0052 | UA749DC 2237 1826-0184  |
| SN74S163 | 1698 1820-1453 |                            | SS 1104A 0860B | 1820-2425      | UA749DH 2237 1826-0342  |
| SN74S168 | 1698 1820-1454 |                            | SS 1105A       | 8608 1820-2426 | UA759T2C 2237 1826-0531 |
| SM74S16  | 1698 1820-1943 |                            | SSS725B        | 2180 1826-0008 | UA759U1C 2237 1826-0833 |
| SN74S169 | 1698 1820-1455 |                            | SSS 725C       | 2180 1826-0009 | UA760DC 2237 1826-0132  |
| SN74S174 | 1698 1820-1076 |                            | SSS741CJ       | 2180 1826-0013 | UA760HC 2237 1826-0231  |
| SN74S175 | 1698 1820-1191 |                            | SW-01FQ        | 2180 1826-0811 | UA776TC 2237 1826-0212  |

|          |                    |           |                |           |                |
|----------|--------------------|-----------|----------------|-----------|----------------|
| SN74S181 | 1698 1820-1974     | SW-02FQ   | 2180 1826-0720 | UA7824C   | 1698 1826-0150 |
| SB74S181 | 1698 1820-0999     | SYC6502B  | 1795 1820-2589 | UA7824KC  | 2237 1826-0262 |
| SN74S182 | 1698 1820-1305     | SYM1404   | 1795 1820-0763 | UA78GKC   | 2237 1826-0443 |
| SN74S189 | 1698 1816-0640     | SYP2111   | 1795 1818-0381 | UA78GU1   | 2237 1826-0456 |
| SN74S189 | 1698 1816-0724     | SYP2112A  | 1795 1818-0553 | UA78H05   | 2237 1813-0100 |
| SN74S194 | 1698 1820-1304     | SYP2112   | 1795 1818-0140 | UA78H12   | 2237 1813-0093 |
| SN74S195 | 1698 1820-1303     | SYP6551   | 1795 1820-2577 | UA78H15   | 2237 1813-0124 |
| SN74S196 | 1698 1820-1869     | SZA266    | 2037 1826-0507 | UA78H GK  | 2237 1813-0123 |
| SN74S197 | 1698 1820-1868     | TOA 2709  | 1991 1820-0058 | UA78L26A  | 2237 1826-0460 |
| SN74S200 | 1698 1816-0598     | TBA231    | 6338 1826-0318 | UA78L62A  | 2237 1826-0586 |
| SN74S20N | 1698 1820-0688     | TBP14S10  | 1698 1816-1137 | UA78M06   | 2237 1826-0349 |
| SN74S225 | 1698 1820-2621     | TBP14SA   | 1698 1816-1358 | UA78M12   | 2237 1826-0345 |
| SN74S22N | 1698 1820-0689     | T8P18S03  | 1698 1816-1468 | UA78M GH  | 2237 1826-0584 |
| SN74S240 | 1698 1820-1633     | TBP18S03  | 1698 1816-1153 | UA78M GU  | 2237 1826-0484 |
| SN74S241 | 1698 1820-1624     | TBP18S22  | 1698 1816-138B | UA78S40   | 2237 1826-0603 |
| SN74S251 | 1698 1820-1302     | TBP18S42  | 1698 1816-1008 | UA7905UC  | 2237 1826-0445 |
| SN74S257 | 1698 1820-1301     | TBP18S42  | 1698 1816-1055 | UA7906UC  | 2237 1826-0478 |
| SN74S258 | 1698 1820-1309     | TBP18S46  | 1698 1816-1329 | UA7912C   | 1698 1826-0221 |
| SN74S260 | 1698 1820-1275     | TBP18SA   | 1698 1816-1174 | UA7912UC  | 2237 1826-0418 |
| SN74S280 | 1698 1820-1638     | TC5504P-1 | 6354 1818-1583 | UA7924C   | 1698 1826-0299 |
| SN74S281 | 1698 1820-1456     | TC5514P   | 6354 1818-1350 | UA7924C   | 1698 1826-0620 |
| SN74S283 | 1698 1820-1871     | TDC1010J  | 8659 1820-2452 | UA7952UC  | 2237 1826-0404 |
| SN74S289 | 1698 1816-0787     | TDC1014J  | 8659 1826-0781 | UA79GKC   | 2237 1826-0444 |
| SN74S299 | 1698 1820-1457     | TI XL105  | 1698 1820-0279 | UA79GU1   | 2237 1826-0441 |
| SN74S30N | 1698 1820-1323     | TL022CP   | 1698 1826-0770 | UA79HGK   | 2237 1813-0127 |
| SN74S32N | 1698 1820-1449     | TL061CP   | 1698 1826-0640 | UA79M06   | 2237 1826-0701 |
| SN74S373 | 4092 1820-2185     | TL062CP   | 1698 1826-0683 | UA79M08   | 2237 1826-0793 |
| SN74S373 | 1698 1820-1676     | TL064CN   | 1698 1826-0786 | UA79M12   | 2237 1826-0300 |
| SN74S374 | 1698 1820-1677     | TL071BCP  | 1698 1826-0520 | UA79M12   | 1698 1826-0629 |
| SN74S37J | 1698 1820-2666     | TL071CP   | 1698 1826-0519 | UA79M12   | 1698 1826-0649 |
| SN74S37N | 1698 1820-1450     | TL072ACJ  | 1698 1826-0785 | UA79M15   | 2237 1826-0829 |
| S%74S381 | 1698 1820-1458     | TL072ACP  | 1698 1826-0547 | UA79M15   | 1698 1826-0511 |
| SN74S38N | 1698 1820-1451     | TL072CP   | 1698 1826-0521 | UA79M GH  | 2237 1826-0583 |
| SN74S40N | 1698 1820-0690     | TL074ACN  | 1698 1826-0600 | UA79M GU  | 2237 1826-0483 |
| SN74S482 | 1698 1820-2594     | TL074CN   | 1698 1826-0522 | UAF355TC  | 2237 1826-0491 |
| SN74S51N | 1698 1820-1158     | TL082ACP  | 1698 1826-0545 | UAF772H   | 2237 1826-0843 |
| SN74S64N | 1698 1820-0691     | TL082CP   | 1698 1826-0882 | UDN-5703  | 2634 1820-2682 |
| SN74S65N | 1698 1820-0692     | TL084ACN  | 1698 1826-0572 | UDN-5706  | 2634 1820-2683 |
| SN74S74N | 1698 1820-0693     |           | 1698 1826-0538 | UDN-5707  | 2634 1820-2020 |
| SN74S85N | 1698 1820-1321     | TL084CN   | 1698 1826-0410 | UDN2981A  | 2634 1820-2273 |
| SN74S86N | 1698 1820-0694     | TL170CLP  | 1698 1826-0757 | UHP-402   | 2634 1820-1120 |
| SN75107A | 1,00E+98 1820-0723 | TL182CN   | 1698 1826-0675 | UHP-407   | 2634 1820-2129 |
| SN75108B | 1698 1820-1310     | TL376CNE  | 1698 1826-0859 | UHP-408   | 2634 1820-1086 |
| SN75109N | 1698 1820-0722     | TL431CLP  | 1698 1826-0643 | ULN-2003  | 2634 1858-0047 |
| SN7510L  | 1698 1820-0083     | TL494CN   | 1698 1826-0565 | ULN-2004  | 2634 1858-0061 |
| SN75110A | 1698 1820-1110     | TL497CN   | 1698 1826-0450 | ULN-2033  | 2634 1858-0067 |
| SN75112N | 1698 1820-1826     | TL500ACN  | 1698 1826-0651 | ULN-2064  | 2634 1820-2170 |
| SN75114N | 1698 1820-2668     | TL514CN   | 1698 1826-0051 | ULN-20658 | 2634 1820-2473 |
| SN75116N | 1698 1820-2128     | TL601CP   | 1698 1826-0476 | ULN-2068  | 2634 1820-2274 |
| SN75117P | 1698 1820-2159     | TL604IP   | 1698 1820-1973 | ULN-20748 | 2634 1820-2130 |
| SN75119P | 1698 1820-2352     | TL607CP   | 1698 1820-1948 | ULN-2111  | 2634 1826-0029 |
| SN75121N | 1698 1820-1080     | TL610CP   | 1698 1826-0477 | ULN-2803  | 2634 1858-0069 |
| SN75150P | 1698 1820-1075     | TL702CN   | 1698 1820-0396 | ULN-2805  | 2634 1858-0073 |
| SN75159N | 1698 1820-2362     | TL7805AC  | 1698 1826-0551 | ULN-2813  | 2634 1858-0072 |
| SN75160N | 1698 1820-2485     | TMS-4024  | 1698 1820-1174 | ULN-2815  | 2634 1858-0065 |
| SN75161N | 1698 1820-2483     | TMS0105   | 1698 1820-1232 | ULN2082A  | 2634 1858-0037 |
| SN75162N | 1,00E+98 1820-2547 | TMS2114   | 1698 1818-0438 | UM1500    | 4200 1820-0498 |
| SN75183N | 1698 1820-0720     | TMS2516-  | 1698 1818-0851 | UP416C-1( | 39 1818-1467   |
| SN75189A | 1698 1820-0990     | TMS2516J  | 1698 1818-0498 | UP416C-2( | 39 1818-1396   |
| SN75234N | 1698 1820-2134     | TMS2532J  | 1698 1818-1581 | UP416C-3( | 39 1818-1397   |
| SN75235N | 1698 1826-0094     | TMS2532J  | 1698 1818-0762 | UPC301A   | 39 1820-0477   |
| SN75322N | 1698 1820-1673     | TMS2716J  | 1698 1818-0743 | UPC311C   | 39 1826-0065   |
| SN75325N | 1698 1820-0568     | TMS27L0   | 1698 1818-0491 | UPD1990C  | 39 1820-2541   |
| SN75327N | 1698 1820-2361     | TMS3002L  | 1698 1820-0211 | UPD2114L  | 39 1818-1300   |
| SN75361A | 1698 1820-1833     | TMS3113   | 1698 1820-1186 | UPD2114L  | 39 1818-0443   |
| SN75361A | 1698 1820-1887     | TMS3120   | 1698 1820-1346 | UPD369C   | 39 1820-2060   |
| SN75363N | 1698 1820-1982     | TMS3122   | 1698 1820-1178 | UPD416D-  | 39 1818-0341   |
| SN75365N | 1698 1820-2570     | TMS3129   | 1698 1820-2092 | UPD444/6  | 39 1818-1346   |

|               |                |          |                |          |                |
|---------------|----------------|----------|----------------|----------|----------------|
| SN75367N      | 1698 1820-1611 | TMS4027- | 1698 1818-0317 | UPD444C- | 39 1818-1330   |
| SN75417N      | 1698 1820-2181 | TMS4027- | 1698 1818-0334 | UPD5101L | 39 1818-0708   |
| SN75450B      | 1698 1820-0902 | TMS4030J | 1698 1818-0103 | UPD8228D | 39 1820-1920   |
| SN75451B      | 1698 1820-0535 | TMS4044  | 1698 1818-1398 | UPD8243C | 39 1820-2177   |
| SN75452B      | 1698 1820-1800 | TMS4050- | 1698 1818-0181 | UPD8251D | 39 1820-1844   |
| SN75452B      | 1698 1820-1669 | TMS4050J | 1698 1818-0146 | UPD8253D | 39 1820-2005   |
| SN75452B      | 1698 1820-0799 | TMS4050  | 1698 1918-0147 | UPD8255  | 39 1820-1919   |
| SN75453B      | 1698 1820-1016 | TMS4060- | 1698 1818-0247 | UT-309   | 2634 1826-0868 |
| SN75454B      | 1698 1820-1050 | TMS4060J | 1698 1818-0165 | VFC32KP  | 5436 1826-0E24 |
| SN75461P      | 1698 1820-2044 | TMS4103  | 1698 1818-0102 | WD8250A  | 575 1820-2665  |
| SN75462P      | 1698 1620-2208 | TMS4116- | 1698 1818-0509 | XC79L05C | 2037 1826-0332 |
| SN75463N      | 1698 1820-2520 | TMS4116- | 1698 1818-0340 | XC79L12C | 2037 1826-0331 |
| SN75468N      | 1698 1820-2111 | TMS8080  | 1698 1820-1783 | XR-2207C | 350 1820-1648  |
| SN75469N      | 1698 1820-2243 | TMS9900J | 1698 1820-2349 | XR-2209C | 350 1826-0873  |
| SN75471P      | 1698 1820-2207 | TMS9914J | 1698 1820-2551 | XR2240   | 350 1820-162B  |
| SN75477P      | 1698 1820-2110 | TMS9914  | 1698 1820-2548 | XR320    | 350 1826-0237  |
| SN75491N      | 1698 1820-1230 | TDA3709V | 1991 1820-0113 | XR346CJ  | 350 1826-0719  |
| SN75492N      | 1698 1820-1231 | TR1602A  | 575 1920-1219  | XR5534AC | 350 1826-0783  |
| SN75492N      | 1698 1820-2254 | TR1602A  | 575 1820-1681  | Z0440    | 2882 1813-0040 |
| SN75497N01(98 | 1820-2186      | TR1602B- | 575 1820-1911  | Z0441    | 2882 1813-0039 |
| SN75498N      | 1698 1820-2141 | TR1863A  | 575 1820-2419  |          |                |
| SN76549N      | 1698 1826-0498 | TR1863B  | 575 1820-2423  |          |                |
| SNG82N        | 1698 1820-0844 | TTLDM-10 | 7397 1813-0197 |          |                |
| S"228         | 2910 1820-0202 | TTLDM-20 | 7397 1813-0193 |          |                |
| SP370N        | 2910 1820-0900 | TTLOM-40 | 7397 1813-0229 |          |                |
| SP374N        | 2910 1820-0774 | UAD801E  | 2237 1826-0550 |          |                |