






Forces - force diagram: Resultant has zero magnitude (equilibrium) 100 g0 6 50 g0_0 0 g0 5 -50g0_2 -100g0_**3** -150**-**75 -50-2525 50 75 -1000 100
















Forces - force diagram: Resultant has zero magnitude (equilibrium) 100 50 a0.20 -50-100-150-100**-**75 -50-2525 50 75 100

Forces - force diagram: Resultant has zero magnitude (equilibrium) 100 50 0 -50-100-150-100**-**75 -50-2525 50 75 100





Forces - force diagram: Resultant has zero magnitude (equilibrium) 100 50 0 -50-100-150-100**-**75 -50-2525 50 75 100

Results: normal force distribution in system

