ME 333 Final Project

Marshall Johnson

 $March\ 17,\ 2022$

Homework 10

28.4.12 Trajectory Tracking


1) Turn in your best plots of following the step and cubic trajectories in Figure 28.5 with the load attached. Indicate the control gains you used, as well as their units.

 $\mathrm{Ki} = 100.0$

Kd = 0.0

 $\mathrm{Kp} = 1000.0$

Step



Cubic

