

PORT OPERATIONS

Local Notice to Mariners 52/19

Tidal Streams Dover Harbour

All mariners are hereby advised of the results of a tidal survey commissioned to establish any changes to tidal streams resulting from the DWDR construction works. This notice contains the mean spring and neap tidal current diagrams for information of port users until the current UKHO Dover Harbour Tidal Stream Diagrams have been updated.

Steve Masters Harbour Master 3rd September 2019

Notices Remaining In Force:

46/16 - Granville Dock Marina Depths

08/19 - Decommissioned mooring equipment

11/19 - Rock armour SE corner of wick Channel

21/19 - Pier 'F' mooring bollards.

23/19 - DWDR restricted Area

29/19 - Fairway Buoy Positions

32/19 - New Navigation Marks west side of Prince of Wales Pier

38/19 - Discontinuance of Fog Sirens


48/19 – ED6 stern fender limitation


50/19 - Temporary Suspension of the Wick Channel Traffic Lights

51/19 - Intermittent fault East Buoy

52/19 - Tidal Streams Dover Harbour

MEAN SPRING TIDE TIDAL CURRENTS





MEAN NEAP TIDE TIDAL CURRENTS

