

SA287-01




REPLACEMENT

- I. REPLACE COMPANION FLANGE DUST DEFLECTOR, IF NECESSARY
- (a) Using SST and a press, remove the dust deflector. SST 09950-00020, 09950-60010 (09951-00400), 09950-70010 (09951-07100)




- (b) Using SST and a press, install a new dust deflector. SST 09223-00010
- 2. REPLACE SIDE GEAR SHAFT DUST COVER, IF NEC-ESSARY
- (a) 1G-FE Engine:Using screwdriver and hammer, remove the dust cover.



(b) 2JZ-GE Engine:

Using SST and a press, remove the dust cover. SST 09950-00020




(c) 1G-FE Engine:

Using a steel plate and press, install a new dust cover.

NOTICE:


Be careful not to deform the dust cover.



(d) 2JZ-GE Engine:


Using SST and a press, install a new dust cover. SST 09502-24010, 09950-60020 (09951-00780), 09950-70010 (09951-07150)

LEXUS IS300/IS200 SUP (RM870E)



3. REPLACE SIDE GEAR SHAFT SERRATION BOLT, IF NECESSARY

(a) Using a press, remove the serration bolt.



(b) Using a press, install a new serration bolt.