EQUIPMENT

PP0TX-06

Ohmmeter	
Caliper gauge	Center bearing
Dial indicator	Commutator runout
Micrometer	Planetary shaft
Press	Magnetic switch terminal kit
Pull scale	Brush spring
Sandpaper	Commutator
Torque wrench	
V-block	Commutator
Vernier calipers	Commutator, Brush